

Inspection Report (On-Highway Dump Truck)

General Info

Year	2011
Make	Peterbilt
Model	367
Serial Number	1NP - TLUOX - 6 - BD127977
Truck Odometer Reading	443,015
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	30'2"
Width (ft and inches)	8'2"
Height (ft and inches)	12'10"
Wheelbase (ft and inches)	20'8"
GVWR (lbs)	66,000



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans Mounted Muncie
Engine Brake	Yes
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Dump Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



General Appearance Inspection Points

General Appearance




Front	3 - Normal Wear & Tear
Front Condition	No visible damage

Inspection Report (On-Highway Dump Truck)

Front Photos






Inspection Report (On-Highway Dump Truck)

	
	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage, Other (see comments)
Rear Photos	

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage	
Left Photos		
		

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
Right	3 - Normal Wear & Tear	
Right Condition	No visible damage	
Right Photos		
		




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Upper Photos	
	




Inspection Report (On-Highway Dump Truck)

		
		
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear	
Body Panel Condition	No visible damage, good paint condition and panel fitment	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Doors / Canopy Latches Photos		




Inspection Report (On-Highway Dump Truck)

	
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Steps / Ladders Photos	
	




Inspection Report (On-Highway Dump Truck)

	
	
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Handrail Photos	




Inspection Report (On-Highway Dump Truck)

		
Glass Condition	3 - Normal Wear & Tear	
Glass Condition Notes	Glass intact, no visible damage	
Glass Condition Photos		
		

Inspection Report (On-Highway Dump Truck)

	
	
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage
Mirrors Photos	

Inspection Report (On-Highway Dump Truck)

		
Lighting System	3 - Normal Wear & Tear	
Lighting System Condition	No visible damage, lighting system is operational	
Lighting System Photos		
		

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)



Cab Inspection Points

On Highway - Cab




Inspection Report (On-Highway Dump Truck)

Serial Number Plate Photo	
Operator Cabin	3 - Normal Wear & Tear
Operator Cabin Photos	
	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
	
<p>Operator's Seat & Arm Rests</p>	<p>3 - Normal Wear & Tear</p>
<p>Operator's Seat & Arm Rests Photos</p>	

Inspection Report (On-Highway Dump Truck)

	
	
Seat Belt	3 - Normal Wear & Tear
Seat Belt Photos	
Cabin Lights	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)




Cabin Lights Photos	
	
	
Controls & Switches	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)




Controls & Switches Photos






Inspection Report (On-Highway Dump Truck)

	
	
Odometer Activity	3 - Normal Wear & Tear
Odometer Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)


<p>Other Gauge Activity Photos</p>	
	
<p>Heater & A/C</p>	<p>3 - Normal Wear & Tear</p>
<p>Heater & A/C Photos</p>	
<p>Fans / Vents</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (On-Highway Dump Truck)




Fans / Vents Photos	
	
	
Horn	3 - Normal Wear & Tear
Reverse Alarm / Backup Signal	3 - Normal Wear & Tear
Backup Camera	3 - Normal Wear & Tear
Other Electronic Devices	0
Fire Extinguisher	0
First Aid Kit	0

Engine Inspection Points




Inspection Report (On-Highway Dump Truck)

Engine	
Engine Type (Make, Model, Cylinders, Hp)	CAT - C13 - 470HP - 6CYL -12.5L
Emissions Tier	Tier 4i
Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	




Inspection Report (On-Highway Dump Truck)

		
		
		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	




Inspection Report (On-Highway Dump Truck)

Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	
	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	

Inspection Report (On-Highway Dump Truck)

	
	
	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension



Inspection Report (On-Highway Dump Truck)

Belt Photos	
	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Hose Photos	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)

	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Water Pump Photos	
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	Yes
Oil Leak Notes	No oil leaks seen, Dried oil seepages seen
Oil Leak Photos	

Inspection Report (On-Highway Dump Truck)

		
		
		
Oil Color / Appearance	3 - Normal Wear & Tear	
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level	
Fuel Leaks	No	
Equipped with DPF (Diesel Particulate Filter)	Yes	
DPF Condition	3 - Normal Wear & Tear	
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated	

Inspection Report (On-Highway Dump Truck)




DPF Photos	
	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Engine clean, minor leakage at oil pan, rear housing area

Drivetrain Inspection Points




Drivetrain

Transmission Info (Make/Model)	Eaton Fuller 10 Speed
Drive Type	6X4
Overdrive	No
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations




Inspection Report (On-Highway Dump Truck)

Transmission Condition Photos	
	
	
Clutch	3 - Normal Wear & Tear
Clutch Condition	Clutch is functioning as expected
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation

Inspection Report (On-Highway Dump Truck)

Rear Differential Photos	
	
	
Front Differential	3 - Normal Wear & Tear
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation

Inspection Report (On-Highway Dump Truck)




Front Differential Photos	
	
	
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)


Air Brake System Photos



Inspection Report (On-Highway Dump Truck)

	
	
	
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function


Inspection Report (On-Highway Dump Truck)

Foot Brake Photos	
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in good condition. Drivetrain well maintained, most major components in great condition.

Chassis & Axle Inspection Points

Chassis


Frame

Frame Condition	3
Frame Photos	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




Suspension

Suspension	3
------------	---

Inspection Report (On-Highway Dump Truck)

Suspension Photos



Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

Steering

Steering Components	3
Steering Components Photos	




Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)

		
		
		
Steer Axle Condition	3	




Inspection Report (On-Highway Dump Truck)

Steer Axle Photos	
	




Wheels & Tires

Wheels & Hub Condition	3
Wheels & Hub Photos	




Inspection Report (On-Highway Dump Truck)

	
	
	
Tire Brand	(Front) Yokohama (Rear) generic recap
Tire Size	(Front) 315/80R/22.5 (Rear) 11R22.5
Front Left Tire - Ratio Remaining	30%




Inspection Report (On-Highway Dump Truck)

<p>Front Left Tire Photos</p>	
<p>Front Right Tire - Ratio Remaining</p>	<p>30%</p>
<p>Front Right Tire Photos</p>	
	
<p>Rear Right Tire - Ratio Remaining</p>	<p>30%</p>

Inspection Report (On-Highway Dump Truck)

<p>Rear Right Tire Photos</p>		
		
		
<p>Rear Left Tire - Ratio Remaining</p>	<p>10%</p>	

Inspection Report (On-Highway Dump Truck)

<p>Rear Left Tire Photos</p>	
	
	

Brake Components


<p>Brake Shoe Thickness</p>	<p>10%</p>
-----------------------------	------------

Inspection Report (On-Highway Dump Truck)

Brake Shoe Photos



Inspection Report (On-Highway Dump Truck)



Overall Chassis Condition



Overall Chassis	3
-----------------	---

Inspection Report (On-Highway Dump Truck)

Overall Chassis & Undercarriage
Photos



Inspection Report (On-Highway Dump Truck)

		
		
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.	

Addition Axle Inspection

Additional Axle

Instructions	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
Axle Description & Position	Rear Dump Body Mounted Drop Down
Steerable?	No
Drop Axle?	Yes
Super Dump?	Yes
Weight Rating	12,000 Lbs.
Axle Condition	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)

Axle Condition Photos



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




Wheels & Tires

3 - Normal Wear & Tear

Wheels & Tires Photos




Inspection Report (On-Highway Dump Truck)

		
Tire Brand	Maxisteel	
Tire Size	11R22.5	
Left Tire(s) Ratio Remaining	70%	
Right Tire(s) Ratio Remaining	70%	

Additional Inspection Points

On Highway - Dump Truck

Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

Dump Body Make & Material	Rogue	
Dump Body Length (ft and inches)	15'	
Dump Body Height (ft and inches)	5'3	
Bed Body	3 - Normal Wear & Tear	
Bed Body Photos		

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




		
Tailgate	3 - Normal Wear & Tear	
Tailgate Photos		
		
Tailgate Latch	3 - Normal Wear & Tear	

Inspection Report (On-Highway Dump Truck)




Tailgate Latch Photos





Inspection Report (On-Highway Dump Truck)

		
		
		
<p>Support Frame</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (On-Highway Dump Truck)

Support Frame Photos	
	
Hinge Points	3 - Normal Wear & Tear
Hinge Point Photos	

Inspection Report (On-Highway Dump Truck)

	
Tarp	3 - Normal Wear & Tear
Tarp Photos	

Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.
Hydraulic Tank	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Hydraulic Cylinders	3 - Normal Wear & Tear
Cylinder Pins and Bushings	3 - Normal Wear & Tear
Hydraulic Function	3 - Normal Wear & Tear
Comments	Hydraulic cylinder operating well

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Overall Functional Test Comments	Truck fires right up, and travels great. Hydraulic dump bed lift and retract function works great. 3rd axle works well. Tarp functions normal.

Inspection Report (On-Highway Dump Truck)

Operating Video	Click to Download
-----------------	-----------------------------------

Inspection Summary

Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	This truck is well maintained by a professional, experienced shop that does not cut corners. All their trucks are treated the same and it shows. Very few issues found.
What Needs Work	Few cosmetic issues with clearcoat. Tires need to be replaced soon and some brake shoes getting low.
Date/Time	11-15-2022