

Inspection Report (On-Highway Service Truck)

General Info

Year	2015
Make	Chevrolet
Model	2500
Serial Number	1GB2CUEG2FZ547955
Truck Odometer Reading	182,741
Current Inspection / State Cert / DOT	N/A
Previous Application (e.g., earth moving, mining, demolition, etc)	Billboard Services

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	N/A
Width (ft and inches)	N/A
Height (ft and inches)	N/A
Wheelbase (ft and inches)	N/A
GVWR (lbs)	9,500 Lbs.

Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X2
Overdrive	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	Yes
Cruise Control	Yes
PTO	No
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	No
Welder	No

Inspection Report (On-Highway Service Truck)

Air Compressor	No
Crane	No
Stabilizer Jacks	No
Other Configuration Details / Features / Notes	Extra long bed

Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



General Appearance Inspection Points

General Appearance

Inspection Report (On-Highway Service Truck)

Close-up Exterior Photos



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	0
Handrails	0
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

Cab Inspection Points

On Highway - Cab

VIN/Serial Number Plate Photo



Inspection Report (On-Highway Service Truck)

Odometer Photo




Cab Interior Photos



Inspection Report (On-Highway Service Truck)




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)


		
		
Odometer Activity	3 - Normal Wear & Tear	
Odometer Condition	Odometer is working and in good condition	
Controls/Switches/Gauges	3 - Normal Wear & Tear	
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning	
Brake System Type	Hydraulic	
Clutch	0	
Horn	3 - Normal Wear & Tear	
Horn Condition	Horn is functioning as expected	
Reverse Alarm / Backup Camera	0	
Heater & A/C	3 - Normal Wear & Tear	
Heat & A/C Condition	Heater and A/C work as expected	
Interior Lights	3 - Normal Wear & Tear	
Interior Lights Condition	All interior lights are installed and functioning	
Seats/Seat Belts	3 - Normal Wear & Tear	
Seats/Seat Belt Condition	Seat(s) in good condition, no stains or tears in upholstery	
Cab Interior Overall Rating	3 - Normal Wear & Tear	

Inspection Report (On-Highway Service Truck)

Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Chevy - 6.0L - V8 - 360HP
Emissions Tier	Undetermined
Engine Serial Number	N/A
Engine Fuel Type	Gasoline
Engine Photos	  

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

		
		
		
Blow-by (Visual Observation Check)	N/A	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	

Inspection Report (On-Highway Service Truck)

Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Engine in solid, well maintained condition with no active leaks observed during the inspection.

Chassis & Drivetrain Inspection Points

On-Highway: Undercarriage Components

Chassis Inspection Points

Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.
----------------------------------	--


Inspection Report (On-Highway Service Truck)

<p>Chassis & Undercarriage Photos</p>		
		
		

Inspection Report (On-Highway Service Truck)




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

	
	
Frame	3 - Normal Wear & Tear
Suspension	3 - Normal Wear & Tear
Steer Axle Condition	0
Steering Components	3 - Normal Wear & Tear
Overall Chassis Condition	3 - Normal Wear & Tear
Overall Chassis Comments	Chassis in good condition. Suspension and rear axle look healthy. No problems observed underneath vehicle.

Drivetrain Inspection Points

Transmission Info (Make/Model)	Automatic 6 Speed
Transmission	3 - Normal Wear & Tear

Inspection Report (On-Highway Service Truck)

Transmission Condition	No unusual noises or vibrations
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Brake Shoe Thickness	50%
Air Brake System Leaks	No
Air Brake Hose Condition	0
Overall Drivetrain Condition	3 - Normal Wear & Tear

Additional Undercarriage Components

Equipped with DPF (Diesel Particulate Filter)	No
---	----

Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hub Condition	3
Wheel Seal Leaks	N/A
Tire Brand	Michelin
Tire Size	LT245/75/R17
Front Left Tire - Ratio Remaining	90%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	90%

Inspection Report (On-Highway Service Truck)

Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Brakes	3 - Normal, Operating as Expected

Inspection Report (On-Highway Service Truck)

Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	This truck is in good looking condition. Tires are like new and all trucks functions work great.
What Needs Work	Few scuff marks on exterior and a few stains on interior.
Date/Time	02-02-2023