

Inspection Report (On-Highway Service Truck)

General Info

Year	2016
Make	Freightliner
Model	M2
Serial Number	3ALACXCYOGDHF7409
Truck Odometer Reading	11,925 Miles
Current Inspection / State Cert / DOT	N/A
Previous Application (e.g., earth moving, mining, demolition, etc)	Masonry General Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	29'6"
Width (ft and inches)	8'3"
Height (ft and inches)	10'4"
Wheelbase (ft and inches)	20'
GVWR (lbs)	33,000 Lbs

Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X2
Overdrive	No
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Chelsea Transmission Mounted
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	No

Inspection Report (On-Highway Service Truck)

Generator	No
Welder	No
Air Compressor	No
Crane	No
Stabilizer Jacks	No
Other Configuration Details / Features / Notes	13' Hydraulic Actuated Dump Body & Multiple Custom Tool Storage Boxes

Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



General Appearance Inspection Points

General Appearance

Inspection Report (On-Highway Service Truck)

Close-up Exterior Photos




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	3 - Normal Wear & Tear
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

Cab Inspection Points

On Highway - Cab

VIN/Serial Number Plate Photo



Inspection Report (On-Highway Service Truck)

<p>Odometer Photo</p>	 <p>The image shows the instrument cluster of a truck. The central digital display shows 'ENG 664.3 HRS' and '11925.9 MI'. To the left are gauges for oil pressure (0-50), water level (0-200), and temperature (275-350). The tachometer shows 0-350 RPM, and the speedometer shows 0-85 km/h.</p>
<p>Cab Interior Photos</p>	 <p>A view of the cab interior from the driver's side door. The interior is grey and black. A sign on the back of the seat reads 'GP CONCRETE'. The steering wheel and dashboard are visible.</p>
	 <p>A close-up view of the cab interior showing the seat and floor. The seat is grey and black. The floor has a blue mat with a circular pattern. A red fire extinguisher is visible on the floor.</p>


Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

	
	
Odometer Activity	3 - Normal Wear & Tear
Odometer Condition	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Clutch	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is functioning as expected
Reverse Alarm / Backup Camera	2 - Above Average Wear
Reverse Alarm / Backup Camera Condition	Reverse alarm is configured but inoperable
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C Condition	Heater and A/C work as expected
Interior Lights	3 - Normal Wear & Tear
Interior Lights Condition	All interior lights are installed and functioning

Inspection Report (On-Highway Service Truck)

Seats/Seat Belts	3 - Normal Wear & Tear
Seats/Seat Belt Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat belt secures properly
Cab Interior Overall Rating	3 - Normal Wear & Tear

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Cummins - ISL9 - 6Cyl. - 350 HP -
Emissions Tier	Tier 4F
Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced

Inspection Report (On-Highway Service Truck)

Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine in great condition. Very clean appearance with no active leaks observed during the inspection.

Chassis & Drivetrain Inspection Points

On-Highway: Undercarriage Components

Chassis Inspection Points

Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.
---------------------------	--

Inspection Report (On-Highway Service Truck)

Chassis & Undercarriage Photos



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

		
		
Frame	3 - Normal Wear & Tear	
Suspension	3 - Normal Wear & Tear	
Steer Axle Condition	3 - Normal Wear & Tear	
Steering Components	3 - Normal Wear & Tear	
Overall Chassis Condition	3 - Normal Wear & Tear	
Overall Chassis Comments	Overall chassis in solid shape and all components look to be in low use condition. No problems seen with Chassis due the inspection.	

Drivetrain Inspection Points

Transmission Info (Make/Model)	Allison Automatic 5 Speed
Transmission	3 - Normal Wear & Tear

Inspection Report (On-Highway Service Truck)

Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	
	
	

Inspection Report (On-Highway Service Truck)

		
PTO	3 - Normal Wear & Tear	
Differential	Check condition of the differential(s). Take photos and notes as relevant.	
Rear Differential	3 - Normal Wear & Tear	
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation	
Rear Differential Photos		
		

Inspection Report (On-Highway Service Truck)

	
Front Differential	0
Brake Shoe Thickness	90%
Comments	All brake shoes in great, low use condition .
Air Brake System Leaks	Yes
Comments	Minor leak exist (could not hear where small leak coming from)
Air Brake Hose Condition	3 - Normal Wear & Tear
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Overall drivetrain has great, well maintained appearance.


Wheels & Tires Inspection Points

Wheels & Tires

Wheels & Tires Inspection Points

Wheels & Hub Condition	3
Wheels & Hub Photos	

Inspection Report (On-Highway Service Truck)

		
		
Wheel Seal Leaks	No	
Tire Brand	Goodyear	
Tire Size	295/75R/22.5	
Front Left Tire - Ratio Remaining	70%	
Front Left Tire Photos		
Front Right Tire - Ratio Remaining	70%	
Front Right Tire Photos		

Inspection Report (On-Highway Service Truck)

Rear Right Tire - Ratio Remaining	90%
Rear Right Tire Photos	
Rear Left Tire - Ratio Remaining	90%
Rear Left Tire Photos	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Additional Inspection Points

Service Truck Body

Additional Inspection Points: Tool Truck

Tool Truck Body	Check the condition of the tool truck bed body, tool boxes (interior and exterior), and lift gate (if equipped).
Bed Body	3
Comments	Bed body 13'Lx8'Wx3'6"H (7'3" Dump Height)

Inspection Report (On-Highway Service Truck)

Bed Body Photos



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)




Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)

	
	
Toolboxes	3
Liftgate Function	0

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Brakes	3 - Normal, Operating as Expected
Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected
Overall Functional Test Comments	Truck fired right up and had no operational concerns with transmission or PTO. All functions on truck are in great condition.
Operating Video	Click to Download

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear



Inspection Report (On-Highway Service Truck)

Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	This Custom built utility service truck is well equipped and not even 12,000 total miles accumulated. It's custom built to store large tools and has a dump body that's perfect for construction materials and demo hauling. It's in great condition in and out.
What Needs Work	Minor paint chips and normal wear and tear scuff marks . Backup Alarm may be disconnected. DOT Inspection recommended
Date/Time	02-17-2023