


Inspection Report (Skid Steer)

General Info

Year	2003
Make	Bobcat
Model	763
Serial Number	512266975
Hour Meter Reading	2,563 Hours
Previous Application (e.g., earth moving, mining, demolition, etc)	Masonry General Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	10'8"
B. Width (ft and inches)	5'6"
C. Height (ft and inches)	6'5"
Operational Weight (lbs)	5,368 Lbs

Features and Configuration

Control Station Type	Canopy
Bucket	Yes
Bucket Specs	CAT 74" GP Bucket
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior Walkaround Photos

Exterior 360 Walkaround

Inspection Report (Skid Steer)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)



General Appearance Inspection Points

General Appearance

Inspection Report (Skid Steer)

Close-up Exterior Photos



Inspection Report (Skid Steer)



Inspection Report (Skid Steer)




Inspection Report (Skid Steer)

	
	
Body Panels	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	3 - Normal Wear & Tear
Glass Condition	Glass intact, no visible damage
Mirrors	0
Exterior Lights	3 - Normal Wear & Tear
Exterior Lights Condition	No visible damage, lighting system is operational

Control Station Inspection Points

Control Station

Inspection Report (Skid Steer)

<p>Control Station</p>	<p>Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.</p>
<p>Serial Number Plate Photo</p>	
<p>Operator Cabin Photos</p>	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)



Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Seat	3 - Normal Wear & Tear
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	0
Travel Alarm	2 - Above Average Wear

Inspection Report (Skid Steer)

Travel Alarm Condition	System is configured but not operating correctly
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Kubota - 4Cyl. - 48HP - 2.2L
Emissions Tier	Tier 1
Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination
Fuel Leaks	No

Inspection Report (Skid Steer)

Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine appearance in good shape with no active leaks observed and sounds healthy running under load.

Drivetrain Inspection Points

Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
Hydrostatic Transmission?	Yes
2 Speed?	No
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Machine travels well in all directions. Parking brake works as expected when engaged.

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Frame Photos	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

		
		
Stance	3 - Normal Wear & Tear	
Wheels & Tires	3 - Normal Wear & Tear	
Comments	Tires in good condition	
Wheels & Tires Photos		

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
Tire Brand	N/A
Tire Size	N/A
Front Left Tire - Ratio Remaining	50%
Rear Left Tire - Ratio Remaining	50%
Front Right Tire - Ratio Remaining	50%
Rear Right Tire - Ratio Remaining	50%
Lift Arm	3 - Normal Wear & Tear
Chassis to Arm Pins	3 - Normal Wear & Tear
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler Photos	

Inspection Report (Skid Steer)


		
		
		
Quick Coupler to Arms Pins	3 - Normal Wear & Tear	
Overall Chassis	3 - Normal Wear & Tear	
Overall Chassis Comments	Overall chassis in good shape with frame and implements being in solid condition.	

Hydraulics Cylinders Inspection Points


Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Lift Cylinder: Mounting Pin	3	
Lift Cylinder: Oil Leaks	No	

Inspection Report (Skid Steer)

Lift Cylinder Photos



Inspection Report (Skid Steer)

	
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Bucket Cylinder: Mounting Pin	3
Bucket Cylinder: Oil Leaks	No
Bucket Cylinder Photos	
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinder: Mounting Pin	0
Bucket Inspection Points	
Bucket Condition	3 - Normal Wear & Tear

Inspection Report (Skid Steer)

Bucket Photos



Inspection Report (Skid Steer)

		
		
		
Bucket Edge / Deflectors	3 - Normal Wear & Tear	

Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Lift / Tilt	3 - Normal, Operating as Expected
Bucket Functionality	3 - Normal, Operating as Expected
Overall Functional Test Comments	Machine's main functions working normal with no operating issues observed.

Inspection Report (Skid Steer)

Operating Video	Click to Download
-----------------	-----------------------------------

Inspection Summary

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	The machine has been well maintained and runs great. No active leaks seen during the inspection.
What Needs Work	Backup alarm needs to be repaired.
Date/Time	02-17-2023