

## Inspection Report (On-Highway Service Truck)

### General Info

Year	2015
Make	Ford
Model	F350
Serial Number	1FDBF3A64FEC15562
Truck Odometer Reading	130,495
Current Inspection / State Cert / DOT	N/A
Previous Application (e.g., earth moving, mining, demolition, etc)	Concrete Cutting General Contractor

### Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	16'
Width (ft and inches)	7'
Height (ft and inches)	6'
Wheelbase (ft and inches)	11'5"
GVWR (lbs)	10,000 Lbs.

### Features and Configuration


Features	Enter in and/or verify the following information regarding the features of this equipment.
Drive Type	4X2
Overdrive	N/A
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	No
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	Yes
Liftgate Make & Model	Tommy Gate

## Inspection Report (On-Highway Service Truck)

Liftgate Capacity (lbs)	1000 Lbs.
Generator	No
Welder	No
Air Compressor	Yes
Air Compressor Make & Model	Vanguard 16HP Gas Powered Air Compressor with 30 Gal.Tank
Crane	No
Stabilizer Jacks	No

### Exterior 360 Walkaround

### Exterior 360 Walkaround

<b>Instructions</b>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
<b>Exterior Walkaround Photos</b>	

### Inspection Report (On-Highway Service Truck)



## Inspection Report (On-Highway Service Truck)



### General Appearance Inspection Points

#### General Appearance

## Inspection Report (On-Highway Service Truck)

Close-up Exterior Photos



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)







Inspection Report (On-Highway Service Truck)





Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



## Inspection Report (On-Highway Service Truck)

		
		
<b>Body Panels</b>	3 - Normal Wear & Tear	
<b>Body Panel Condition</b>	No visible damage, good paint condition and panel fitment	
<b>Doors / Canopy Latches</b>	3 - Normal Wear & Tear	
<b>Doors / Canopy Latches Condition</b>	No visible damage	
<b>Steps / Ladders</b>	3 - Normal Wear & Tear	
<b>Steps / Ladders Condition</b>	Steps/ladders are fully intact and appear structurally sound	
<b>Handrails</b>	3 - Normal Wear & Tear	
<b>Handrails Condition</b>	Handrails are fully intact and appear structurally sound	
<b>Glass</b>	3 - Normal Wear & Tear	
<b>Glass Condition</b>	Glass intact, no visible damage	
<b>Mirrors</b>	3 - Normal Wear & Tear	
<b>Mirror Condition</b>	Mirrors present and intact, no visible damage	
<b>Exterior Lights</b>	3 - Normal Wear & Tear	
<b>Exterior Lights Condition</b>	No visible damage, lighting system is operational	

### Cab Inspection Points

#### On Highway - Cab

## Inspection Report (On-Highway Service Truck)

<p>VIN/Serial Number Plate Photo</p>	 <p>INCOMPLETE VEHICLE MANUFACTURED BY FORD MOTOR COMPANY</p> <p>DATE: 11/14      GVWR: 4536 KG (10000 LB)</p> <p>FRONT GAWR:      REAR GAWR:</p> <p>1792 KG (3950 LB)      WITH 2853 KG (6290 LB)      WITH</p> <p>LT245/75R17E 121/118S      TIRES LT245/75R17E 121/118S      TIRES</p> <p>17x7.5J      RIMS 17x7.5J      RIMS</p> <p>AT 450 kPa/ 65 PSI COLD      AT 550 kPa/ 80 PSI COLD</p> <p>VIN: 1FDBF3A64FEC15562</p>  <p>EXT PNT: Z1      RC: 71      DSO:</p> <p>WB INT TR TP/PS R AXLE TR SPR</p> <p>137 15 5 37 P GGMM</p> <p>UNC ©USA-1520472-8A</p>
<p>Odometer Photo</p>	 <p>130495 mi</p>
<p>Cab Interior Photos</p>	 <p>Interior view of the cab showing the dashboard, seats, and windows.</p>

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)





**Inspection Report (On-Highway Service Truck)**



**Inspection Report (On-Highway Service Truck)**



## Inspection Report (On-Highway Service Truck)



Odometer Activity	3 - Normal Wear & Tear
Odometer Condition	Odometer is working and in good condition
Controls/Switches/Gauges	3 - Normal Wear & Tear
Controls/Switches/Gauges Condition	All switches/gauges are in good condition and functioning
Brake System Type	Hydraulic
Clutch	0
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is functioning as expected
Reverse Alarm / Backup Camera	0
Heater & A/C	3 - Normal Wear & Tear
Heat & A/C Condition	Heater and A/C work as expected
Interior Lights	3 - Normal Wear & Tear
Interior Lights Condition	All interior lights are installed and functioning
Seats/Seat Belts	3 - Normal Wear & Tear
Seats/Seat Belt Condition	Seat(s) in good condition, no stains or tears in upholstery
Cab Interior Overall Rating	3 - Normal Wear & Tear

### Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Ford - V8 - 6.2L - 316HP
Emissions Tier	Undetermined
Engine Serial Number	N/A
Engine Fuel Type	Gasoline

### Inspection Report (On-Highway Service Truck)


Engine Photos



Inspection Report (On-Highway Service Truck)



## Inspection Report (On-Highway Service Truck)

	
<b>Blow-by (Visual Observation Check)</b>	No
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Unusual Noise Notes</b>	No unusual noises heard
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke Notes</b>	No engine smoke issues observed
<b>Engine Exhaust Color</b>	Clear
<b>Battery</b>	3 - Normal Wear & Tear
<b>Battery Condition</b>	Clean & dry appearance, tight connections
<b>Radiator</b>	3 - Normal Wear & Tear
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Water Pump</b>	3 - Normal Wear & Tear
<b>Water Pump Condition</b>	No unusual pump noises heard
<b>Cooling System Leaks</b>	No
<b>Coolant Color / Appearance</b>	3 - Normal Wear & Tear
<b>Coolant Color/Appearance Notes</b>	Normal Translucent appearance, no visual signs of contamination
<b>Oil Leaks</b>	No
<b>Oil Color / Appearance</b>	3 - Normal Wear & Tear
<b>Oil Color / Appearance Notes</b>	Clean oil appearance, no signs of cross contamination, Appropriate oil level
<b>Fuel Leaks</b>	No



## Inspection Report (On-Highway Service Truck)

Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine has well maintained appearance and no issues observed during inspection.




### Chassis & Drivetrain Inspection Points

#### On-Highway: Undercarriage Components

#### Chassis Inspection Points

Chassis Inspection Points	Take photos of all undercarriage and chassis components including frame, suspension, axles, steering, and brake components. Note any damage or wear.	
Chassis & Undercarriage Photos		
		

### Inspection Report (On-Highway Service Truck)

		
		
		
<b>Frame</b>	3 - Normal Wear & Tear	
<b>Suspension</b>	3 - Normal Wear & Tear	
<b>Steer Axle Condition</b>	0	
<b>Steering Components</b>	3 - Normal Wear & Tear	
<b>Overall Chassis Condition</b>	3 - Normal Wear & Tear	
<b>Overall Chassis Comments</b>	Overall Chassis in good shape. Suspension and rear axle have no signs of issues. Frame solid and steering components working well.	

### Drivetrain Inspection Points




## Inspection Report (On-Highway Service Truck)

Transmission Info (Make/Model)	Automatic 5 speed
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
PTO	0
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Front Differential	0
Brake Shoe Thickness	50%
Comments	Unable to see clear view
Air Brake System Leaks	N/A
Air Brake Hose Condition	0
Overall Drivetrain Condition	3 - Normal Wear & Tear
Overall Drivetrain Comments	Drivetrain in good shape. Normal condition for the amount of miles and no major issues seen during inspection.

## Wheels & Tires Inspection Points

### Wheels & Tires

## Wheels & Tires Inspection Points

Wheels & Hub Condition	3
Wheels & Hub Photos	




Inspection Report (On-Highway Service Truck)






Inspection Report (On-Highway Service Truck)



### Inspection Report (On-Highway Service Truck)

	
<b>Wheel Seal Leaks</b>	No
<b>Tire Brand</b>	Firestone
<b>Tire Size</b>	LT245/75R/17
<b>Front Left Tire - Ratio Remaining</b>	30%
<b>Front Left Tire Photos</b>	
	
<b>Front Right Tire - Ratio Remaining</b>	30%

## Inspection Report (On-Highway Service Truck)




<b>Front Right Tire Photos</b>	
<b>Rear Right Tire - Ratio Remaining</b>	30%
<b>Rear Right Tire Photos</b>	
<b>Rear Left Tire - Ratio Remaining</b>	30%
<b>Rear Left Tire Photos</b>	
<b>Additional Axles</b>	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

### Additional Inspection Points

#### Service Truck Body

#### Additional Inspection Points: Tool Truck

## Inspection Report (On-Highway Service Truck)

Tool Truck Body	Check the condition of the tool truck bed body, tool boxes (interior and exterior), and lift gate (if equipped).
Bed Body	3
Comments	Pacific 8' Utility Body with Top Storage Cabinets and Liftgate
Bed Body Photos	
	
	

Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)





Inspection Report (On-Highway Service Truck)



Inspection Report (On-Highway Service Truck)



### Inspection Report (On-Highway Service Truck)



Toolboxes	3
Liftgate Function	3

### Inspection Report (On-Highway Service Truck)

Liftgate Photos




Inspection Report (On-Highway Service Truck)




### Inspection Report (On-Highway Service Truck)



### Additional Features

Air Compressor Condition	3 - Normal Wear & Tear
Air Compressor Functionality	Partial or abnormal function
Comments	Engine Choke needs minor linkage repair
Air Compressor Photos	

## Inspection Report (On-Highway Service Truck)



### Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Steering	3 - Normal, Operating as Expected
Brakes	3 - Normal, Operating as Expected
Engine	3 - Normal, Operating as Expected
Controls	3 - Normal, Operating as Expected
Overall Functional Test Comments	Overall truck in solid shape and all main core functions work well. No active leaks observed and air compressor runs good.

## Inspection Report (On-Highway Service Truck)

Operating Video	<a href="#">Click to Download</a>
Additional Video	<a href="#">Click to Download</a>

### Inspection Summary

Overall Assessment	
Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	4 - Like New, Recently Replaced
Quality Rating	4 - Like New, Recently Replaced
Functionality Rating	4 - Operating Within Factory Spec
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	This service truck is well taken care of and has a solid service utility body with an electric powered lift gate. No obvious problems observed with engine, transmission or suspension. The rear body is in good shape and the air compressor is perfect for field service repairs.
What Needs Work	Choke cable for air compressor needs minor repair and the tires need to be replaced soon.
Date/Time	03-01-2023