


Inspection Report (Scissor Lift)

General Info

Year	2012
Make	Genie
Model	GS-2669
Serial Number	GS6912-994
Hour Meter Reading	1,981Hrs.
Previous Application (e.g., earth moving, mining, demolition, etc)	Equipment Rental

Dimensions

Measurement Guide	
E. Overall Length (ft and inches)	10'3"
D. Overall Width (ft and inches)	5'9"
F. Stowed Height - Rails Up (ft and inches)	8'6"
D. Platform Length (ft and inches)	9'2"
E. Platform Width (ft and inches)	5'3"
Wheelbase (ft and inches)	7'6"
Operational Weight (lbs)	7,300 Lbs.



Features and Configuration

Max Lift Height	26'
Max Lift Capacity	1,500 Lbs.
Electric Powertrain	No
Hydraulic Leveling	Yes
Power to Platform	Yes
Deck Extensions	Yes
Outriggers	No
Additional Attachment(s)?	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

Inspection Report (Scissor Lift)

Exterior 360 Walkaround

Exterior 360 Walkaround

<p>Instructions</p>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
<p>Exterior Walkaround Photos</p>	
	

Inspection Report (Scissor Lift)






Inspection Report (Scissor Lift)



General Appearance Inspection Points

Front	3 - Normal Wear & Tear
-------	------------------------

Inspection Report (Scissor Lift)

Front Photos	
	
	
Rear	3 - Normal Wear & Tear

Inspection Report (Scissor Lift)

<p>Rear Photos</p>	
	
<p>Left</p>	<p>3 - Normal Wear & Tear</p>
<p>Left Photos</p>	




Inspection Report (Scissor Lift)

		
		
<p>Right</p>	<p>3 - Normal Wear & Tear</p>	
<p>Right Photos</p>		

Inspection Report (Scissor Lift)



Inspection Report (Scissor Lift)

		
Upper	3 - Normal Wear & Tear	
Upper Photos		
Body Panels (Any Damage?)	3 - Normal Wear & Tear	
Scissor Linkage	3 - Normal Wear & Tear	
Scissor Linkage Photos		




Inspection Report (Scissor Lift)



Inspection Report (Scissor Lift)





Inspection Report (Scissor Lift)

	
	
	
<p>Hand Rails</p>	<p>3 - Normal Wear & Tear</p>

Control Station Inspection Points

Inspection Report (Scissor Lift)

Serial Number Plate	
Hour Meter Activity	3 - Normal Wear & Tear
Other Gauge Activity	3 - Normal Wear & Tear
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Photos	
Horn	3 - Normal Wear & Tear
Travel Alarm	2 - Above Average Wear
Comments	Travel alarm weak and should be replaced
Safety Lock Out / Stop	3 - Normal Wear & Tear
Platform Safety Rails & Appearance	3 - Normal Wear & Tear

Inspection Report (Scissor Lift)

Platform Safety Rails & Appearance Photos



Inspection Report (Scissor Lift)



Inspection Report (Scissor Lift)




Platform Floor

3 - Normal Wear & Tear

Platform Floor Photos



Inspection Report (Scissor Lift)



Platform Controls

3 - Normal Wear & Tear

Platform Controls Photos




Inspection Report (Scissor Lift)





Powertrain Inspection Points



Engine

Engine Type (Make, Model, Cylinders, Hp)	Kubota - 3Cyl. - 58.7 CU.IN. - 32HP
Emissions Tier	Tier 4F
Engine Serial Number	N/A
Engine Fuel Type	Dual-Fuel (Gas, LPG)
Engine Photos	

Inspection Report (Scissor Lift)



Inspection Report (Scissor Lift)



	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks

Inspection Report (Scissor Lift)


Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine has well maintained appearance & operating well under load.

Drivetrain Inspection Points

Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.	
Drivetrain Photos		
		


Inspection Report (Scissor Lift)

	
Hydrostatic Transmission?	Yes
2 Speed?	N/A
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	4 - Like New, Recently Replaced
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Drivetrain In good condition and no operating issues observed during inspection.




Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Frame Photos	

Inspection Report (Scissor Lift)






Inspection Report (Scissor Lift)

	
	
Stance	3 - Normal Wear & Tear
Stance Photos	
Drive Motors	3 - Normal Wear & Tear
Front Axle Appearance	3 - Normal Wear & Tear




Inspection Report (Scissor Lift)

Front Axle Appearance Photos	
	
	
Rear Axle Appearance	3 - Normal Wear & Tear

Inspection Report (Scissor Lift)

Rear Axle Appearance Photos	
	
Wheels & Tires	3 - Normal Wear & Tear
Comments	Tires are foam filled
Wheels & Tires Photos	

Inspection Report (Scissor Lift)

		
		
		
Tire Brand	OTR Outrigger	
Tire Size	26x12x380	
Front Left Tire - Ratio Remaining	30%	
Rear Left Tire - Ratio Remaining	30%	
Front Right Tire - Ratio Remaining	30%	
Rear Right Tire - Ratio Remaining	30%	
Overall Chassis	3 - Normal Wear & Tear	




Inspection Report (Scissor Lift)

Overall Chassis Comments	Overall chassis in good shape with all main mechanical structures working well.
--------------------------	---




Hydraulics Overall Inspection Points

Hydraulics Overall

Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.
------------------	--




Hydraulic System Photos	
	
	

Inspection Report (Scissor Lift)




	
	
	
Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3 - Normal Wear & Tear
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation

Hydraulics Cylinders Inspection Points

Inspection Report (Scissor Lift)

Lift Cylinders	Check the lift cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinders: Mounting Pin	3
Lift Cylinders: Oil Leaks	No
Lift Cylinders Photos	  
Frame Leveling Cylinders	Check the frame leveling cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Frame Leveling Cylinders: Mounting Pin	3
Frame Leveling Cylinders: Oil Leaks	No

Inspection Report (Scissor Lift)

Frame Leveling Cylinders Photos	
	
Outrigger Cylinders	Check the outrigger cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders	Check the steering cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders: Mounting Pin	3
Steering Cylinders: Oil Leaks	No
Steering Cylinders Photos	

Inspection Report (Scissor Lift)



Functional Test

Forward & Reverse	3 - Normal, Operating as Expected
Scissor Extension & Retraction	3 - Normal, Operating as Expected
Outrigger Leveling	3 - Normal, Operating as Expected
Overall Functional Test Comments	Machine operating well all around.
Operating Video	Click to Download

Overall Assessment

Overall Assessment

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear
Functionality Rating	3 - Normal, Operating as Expected
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Machine has been well taken care of and it shows. Engine and hydraulics worked normal with no operating issues. No active leaks observed and tires are foam filled.
What Needs Work	Minor cosmetic scuff marks all around and travel alarm faulty.
Date/Time	03-08-2023