

## Inspection Report (Generator)

### General Info

Year	2021
Make	Sutech
Model	ST-CIOOGF
Serial Number	20210202B60
Hour Meter Reading	30
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

### Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	13'
Width (ft and inches)	6'5"
Height (ft and inches)	7'
Operating Weight (lbs)	4,410

### Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Towable	Yes
Current Inspection / State Cert / DOT	N/A
Trailer VIN	RA22200801403-072
Hitch Type	Pintle Ring
Standby Power Rating (kW/KVA)	100KVA
Phase Type	Three Phase
OMM (Operator & Maintenance Manual)	Yes
Telematics	No


### OMM Specifications

#### OMM Specifications


Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

## Inspection Report (Generator)

OMM Spec Photos



## Inspection Report (Generator)






### General Appearance

#### General Appearance

Front	4 - Like New, Recently Replaced
Front Condition	No visible damage

## Inspection Report (Generator)

<b>Front Photos</b>	
	
<b>Rear</b>	4 - Like New, Recently Replaced
<b>Rear Condition</b>	No visible damage
<b>Rear Photos</b>	

### Inspection Report (Generator)

	
	
	
<b>Left</b>	4 - Like New, Recently Replaced
<b>Left Condition</b>	No visible damage

### Inspection Report (Generator)




Left Photos	
	
	
<b>Right</b>	4 - Like New, Recently Replaced
<b>Right Condition</b>	No visible damage

### Inspection Report (Generator)

Right Photos






### Inspection Report (Generator)


		
Upper	4 - Like New, Recently Replaced	
Upper Condition	No visible damage	
Upper Photos		
		




### Inspection Report (Generator)

		
		
<b>Body Panels (Any Rust Damage?)</b>	4 - Like New, Recently Replaced	
<b>Doors / Canopy Latches</b>	4 - Like New, Recently Replaced	
<b>Doors / Canopy Latches Condition</b>	No visible damage	
<b>Doors / Canopy Latches Photos</b>		

Inspection Report (Generator)



## Inspection Report (Generator)

		
Glass Condition	0	
Mirrors	0	
Lighting System	4 - Like New, Recently Replaced	
Lighting System Condition	No visible damage, lighting system is operational, Other (see comments)	
Comments	Unable to test, visually in great condition	

## Exterior 360 Walkaround




### Exterior 360 Walkaround

Front	4 - Like New, Recently Replaced	
Front Condition	No visible damage	
Front Photos		




### Inspection Report (Generator)

	
	
<b>Rear</b>	4 - Like New, Recently Replaced
<b>Rear Condition</b>	No visible damage
<b>Rear Photos</b>	
<b>Left</b>	4 - Like New, Recently Replaced
<b>Left Condition</b>	No visible damage

## Inspection Report (Generator)

<b>Left Photos</b>		
<b>Right</b>	4 - Like New, Recently Replaced	
<b>Right Condition</b>	No visible damage	
<b>Right Photos</b>		
<b>Upper</b>	4 - Like New, Recently Replaced	
<b>Upper Condition</b>	No visible damage	
<b>Upper Photos</b>		




### Inspection Report (Generator)

		
		
		
<b>Body Panels (Any Rust Damage?)</b>	4 - Like New, Recently Replaced	
<b>Body Panel Condition</b>	No visible damage, good paint condition and panel fitment	
<b>Doors / Canopy Latches</b>	4 - Like New, Recently Replaced	
<b>Glass Condition</b>	0	
<b>Mirrors</b>	0	
<b>Lighting System</b>	0	


### Engine Inspection Points

## Inspection Report (Generator)

### Engine



<b>Engine Type (Make, Model, Cylinders, Hp)</b>	Cummins - 4BTA-LQ-S006 - 4 CYL. - 98HP
<b>Emissions Tier</b>	Tier 4F
<b>Engine Serial Number</b>	82226297
<b>Engine Fuel Type</b>	Diesel
<b>Engine Photos</b>	
	
	

Inspection Report (Generator)











## Inspection Report (Generator)

	
	
<b>Blow-by (Visual Observation Check)</b>	No
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No
<b>Unusual Noise Notes</b>	No unusual noises heard
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No
<b>Engine Smoke Notes</b>	No engine smoke issues observed
<b>Engine Exhaust Color</b>	Clear
<b>Battery</b>	4 - Like New, Recently Replaced
<b>Battery Condition</b>	Like new, recently replaced



## Inspection Report (Generator)

<b>Battery Condition Photos</b>	
<b>Radiator</b>	4 - Like New, Recently Replaced
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Radiator Photos</b>	
	

### Inspection Report (Generator)

	
	
<b>Belts</b>	4 - Like New, Recently Replaced
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension
<b>Hoses</b>	4 - Like New, Recently Replaced
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Hose Photos</b>	

### Inspection Report (Generator)



<b>Water Pump</b>	4 - Like New, Recently Replaced
<b>Water Pump Condition</b>	No unusual pump noises heard
<b>Cooling System Leaks</b>	No
<b>Coolant Color / Appearance</b>	4 - Like New, Recently Replaced
<b>Coolant Color/Appearance Notes</b>	Normal Translucent appearance, no visual signs of contamination
<b>Oil Leaks</b>	No
<b>Oil Color / Appearance</b>	4 - Like New, Recently Replaced




## Inspection Report (Generator)

Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	4 - Like New, Recently Replaced
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	4 - Like New, Recently Replaced
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine in great condition. Priming pump handle broken, besides that the rest of the engine looks solid.


## Electrical Connections

Wire Harness	4 - Like New, Recently Replaced
Wire Harness Photos	 

### Inspection Report (Generator)

		
		
<p>Controls &amp; Switches</p>	<p>4 - Like New, Recently Replaced</p>	
<p>Controls &amp; Switches Photos</p>		

## Inspection Report (Generator)

	
Disconnect Switch	4 - Like New, Recently Replaced
Disconnect Switch Photos	

## Generator Panel

110V	Yes
110V Outlet Condition	2 - Above Average Wear
240V	Yes
240V Outlet Condition	2 - Above Average Wear
480V	Yes
480V Outlet Condition	2 - Above Average Wear

## Gauges & Meters




Hour Meter	4 - Like New, Recently Replaced
RPM Display	4 - Like New, Recently Replaced
Volt Display	4 - Like New, Recently Replaced
Pressure Display	4 - Like New, Recently Replaced
Menu Display	4 - Like New, Recently Replaced
Display Screen Appearance	4 - Like New, Recently Replaced

## Trailer & Fuel Tanks

## Inspection Report (Generator)

### Trailer Inspection Points

#### Frame & Body



<b>Frame Condition</b>	4 - Like New, Recently Replaced
<b>Frame Photos</b>	
	
	




Inspection Report (Generator)






## Inspection Report (Generator)

	
<b>Fenders</b>	4 - Like New, Recently Replaced
<b>Fender Photos</b>	
<b>Mud Flaps</b>	0
<b>Trailer Lights/Wiring (Stop, Tail, Turn)</b>	0
<b>Reflectors</b>	0

## Hitch

<b>Hitch Type</b>	Pintle
<b>Hitch Condition</b>	4 - Like New, Recently Replaced
<b>Hitch Photos</b>	

### Inspection Report (Generator)




		
		
		

Drawbar	4 - Like New, Recently Replaced
Strand Wear?	No

### Suspension

Springs	0
U-Bolts	0
Torque Arms	4



### Inspection Report (Generator)

<p>Torque Arms Photos</p>		
		
		

### Inspection Report (Generator)



### Wheels & Tires

Wheels & Hub Condition	4 - Like New, Recently Replaced
Wheels & Hub Photos	
	
Loose Lugs	No
Tire Brand	GOODRIDE
Tire Size	205R14LT
Front Left Tire - Ratio Remaining	90%
Front Right Tire - Ratio Remaining	90%


## Inspection Report (Generator)

Rear Right Tire - Ratio Remaining	10%
Rear Left Tire - Ratio Remaining	10%

### Brake Components

Brake Type	Other (see comments)
Comments	No harness on unit
Brake Controller	No
Brake Shoe Thickness	10%
Comments	No brakes
Emergency Brake/Break-Away	0

### Overall Trailer Condition

Overall Trailer	4 - Like New, Recently Replaced
Overall Trailer Comments	Overall trailer in great condition , no lights or brakes on unit
Overall Trailer & Undercarriage Photos	
Fuel Tank Condition	4 - Like New, Recently Replaced
Fuel Lines & Hoses	4 - Like New, Recently Replaced

### Functional Test

Instructions	Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):  4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required
Engine	4 - Like New, Recently Replaced
Controls	4 - Like New, Recently Replaced
Gauges & Meters	4 - Like New, Recently Replaced
Power Output	4 - Like New, Recently Replaced
Outlets	4 - Like New, Recently Replaced
Trailer	4 - Like New, Recently Replaced

## Inspection Report (Generator)

Overall Functional Test Comments	Overall generator functions like new
Operating Video	<a href="#">Click to Download</a>

## Inspection Summary

Overall Assessment	
Exterior Rating	4
Interior Rating	4
Safety Rating	3
Quality Rating	4
Functionality Rating	4
Overall Rating	4
What's Great About the Machine	Machine has hardly any use. Still has new look to it and all functions work as expected.
What Needs Work	No trailer lights or brakes so trailer needs work.
Date/Time	10-20-2022