

Location: Boom and Bucket

**TRUCK AND EQUIPMENT CONSULTING LLC - FLATBED TRUCK**

Date 3/28/2023  
(Y/M/D)

Inspector E.C.  
Initials

(Basic Information)	
(Make)	Ford
(Model)	F750 SD Dual Rear Wheel Rollback truck
(Serial Number)	3FRXF7FE9FV662381
(Year of Manufacturing)	2015 (built 6/2014)
(Color)	White / Gray
(Mileage) / (Hours)	222,350 Miles
(Engine)	Cummins ISB 6.7L 240Hp I6 TurboDiesel
(Transmission)	Allison XMSN 2500 Automatic 6 Spd

Specification and Dimensions	
GVWR	GVWR 33,000 lbs Class 7
PTO	PTO-4 Upper + Lower w/digital psi gauge
Current Inspection/State Certificate	Arizona AG 44884
Bed Type	Todd Equipment Wood deck
Front / Rear Axle	Front =12,000 lbs/Rear Meritor MS-21 =21,000 lbs
Tire Size	275 / 75R22.5
Air Brake	Yes
Wheelbase	Side controls bed travel + tilt + stabilizer
Origin	Mexico
Other	Winch, Hydraulic Rear Stabilizer, Chains
Other	Side locking tool box, Overhead safety beacon
Other	Dual Right + Left Rear Side Bed Controls

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X				Good appearance, grille+bumper Level stance Good panel gaps No damage
	(General Appearance-Rear)		X				Good appearance rear hydraulic stabilizer, rear components, No damage
	(General Appearance-Right)		X	X			Good appearance Fiberglass cracked lower right fender near door+latch
	(General Appearance-Left)		X				Good appearance surface paint cosmetics side fuel tank No damage
	(General Appearance-Upper)		X				Cab and roof structure good No Damage No Rust Deck Good Appearance
	(Major / Minor Surface Rust)		X				No rust issues
	(Body Panels / Covers - Rust Damage / Cancer)		X				Good panel gaps No rust No cancer No damage
	(Visible Weld Repairs / Stress Cracks)		X				No weld repairs or patch repairs seen No cracks
	(Glass Condition)		X				Good Glass
	(Chassis / Undercarriage Damage)		X				Straight and dry appearance No damage seen Good Appearance
OPERATOR'S COCKPIT	(Operator Cabin)		X				Clean and Straight, Solid floors Good panels All display sharp+clear
	(Operator Controls and Switches)		X				Complete and Good function
	(Odometer Activity)		X				Working
	(Other Gauge Activity)		X				Gauges working
	(Door / Canopy Latches)		X				Good function
	(Safety - Horn / First Aid Kit)		X				Working
	(Operator Seat Condition)		X	X			Seat cover has splits on bottom
	(Other)		X				No error codes System diagnostics Good function
ENGINE	(Oil Color / Fluid Appearance)		X				Clean No signs of cross contamination
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start No unusual noises at startup or shutdown Good idle
	(Engine Exhaust Color - White / Blue / Black / Clear)		X				Clear and Clear at operating temp No blow by seen
	(Oil / Fuel Leaks)		X				No active leaks seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues
	(Coolant Color / Fluid Appearance)		X				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No seepages or active leaks seen
	(Coolant Leaks from Radiator)		X				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		X	X			Clean and Dry Some tape repairs to hoses
	(Maintenance Records)						not labeled

ELECTRICAL	(Lighting System Condition)	X				Working
	(Reverse Alarm / Backup Signal)		X			N/A No Reverse Alarm
	(Battery Condition)	X				Batteries Good-AboveAverage appearance
	(Other Electric Device Condition)	X				All aux displays and gauges working
TIRES TOW BODY	TRACTOR TIRES	X				Front Tractor Tires =B / B-good appearance
	TRAILER TIRES	X				X2 Rear Trailer Tires =B good appearance
	ROLLBACK/ FLATBED BODY	X				Good appearance wood deck, Good side frame rails Good crossmembers
	OTHER	X				Rear Headboard Good Appearance Air Bag suspension Good appearance
TRANSMISSION	(Clutch Noise / Function)	X				No Transmission noises or banging
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	( Other Remarks)	X				Good Tranmssion Function
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard Dry appearance of diff
B R A K E S	(Foot Brake)	X				Good
	(AIR BRAKE)	X				Working
	(Parking Brake)	X				Good function
LIFT + LOAD HYDRAULICS	LIFT + LOWER (Noises ? Vibrations ?0	X				No pump noises or vibrations during liftgate operations (No weight loaded)
	HYDRAULICS	X				Good Hydraulic appearance of hoses, cylinders, and fittings
	REAR STABILIZER	X				Rear stabilizer Good Function
	CONTROLS	X				Controls Good Function and Response
OPERATION	FORWARD & REVERSE	X				Good Forward and Reverse
	STEERING + BRAKES	X				Good Steering and Brakes
	ENGINE	X				Good Idle and function
	CONTROLS	X				Controls Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X				Good panel gaps, good chassis+frame surfaces, no deck damage
	COMMENTS	X				Engine dry+clean, no signs accident repairs or damage, no leaks no rust
	OVERALL PERFORMANCE INSPECTION	X				Good travel function engine, transmsion, steering, brakes, displays
	COMMENTS	X				Good hydraulic function of rear bed tilt + bed travel, and stabilizer

OVERALL EXTERIOR RATING:   B        QUALITY:   B    
 OVERALL INTERIOR RATING:   B        SAFETY:   B    
 OVERALL PERFORMANCE:   B        FUNCTIONALITY:   B    
**OVERALL GRADE EVALUATION: B**  
 FLUID SAMPLE REQUEST (Y/N)   n   OIL   n   COOLANT   n  

**TIRES**  
 \*A:Remaining Ratio      90% or more  
 \*B:Remaining Ratio      70% or more  
 \*C:Remaining Ratio      50% or more  
 \*D:Remaining Ratio      20% or more  
 \*E:Remaining Ratio      20% or less