


General Info

| General into | | | |
|---------------------|---|--|--|
| Category | Forklift | | |
| Travel System | Wheels & Tires | | |
| Comments | | | |
| Year | 2013 | | |
| Make | Genie | | |
| Model | S40 | | |
| Serial Number | S4013-18140 | | |
| Serial Number Plate | Model: S-40 Serial number: \$4013-18140 Manufacture date: \$65/33/13 Model year: 2013 Electrical schematic number: ES0422 Machine unlader weight: 11937 ibs / 5415 kg Peam Tire Veight Add-On 1560 ibs / 71 kg Peam Tire Veight Add-On 1560 ibs / 71 kg Peam Tire Veight Add-On 1560 ibs / 71 kg Peam Tires Required No Rated work load/including occupants): \$50 ibs / 227 kg Maximum allowable inclination of the chassis: 0 Maximum allowable inclination of the chassis: 0 Maximum platform height: 40 ft 12 19 m Maximum platform reach: 31 the 92 ibs / 30 ft Maximum platform reach: 31 the 92 ibs / 30 ft Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 30 ft 12 19 m Maximum platform of the 40 ft 12 19 m Maximum platform of the 50 ft 12 19 m Maximum platform of the 60 ft 12 19 m Maximum pl | | |
| Hour Meter Reading | 3953 | | |
| Tiodi Meter Redding | 5555 | | |





Features & Configuration

| Control Station Type | Platform |
|----------------------|----------|
| Comments | |
| A/C | |
| Heat | |
| Radio | |
| Reverse Camera | |

Powered by 🍫 fastfield Page 2 of 48



| High Flow | No |
|--|-------------------------------------|
| Pilot Controls | Yes |
| Auxiliary Hydraulics | No |
| Quick Coupler | No |
| Hydraulic Thumb | No |
| Bucket | Yes |
| Blade | No |
| Forks | No |
| Outriggers | No |
| OMM (Operator & Maintenance Manual) | Yes |
| Other Configuration Details / Attachment Specs | The S40 features full 360° rotation |

360 Walkaround Photos

Exterior Walkaround Photos



Powered by *** fastfield**







Powered by 🍫 fastfield Page 4 of 48







Powered by 🍫 fastfield Page 5 of 48







Powered by 🍫 fastfield Page 6 of 48













Inspection Rating Criteria

Powered by 🍫 fastfield Page 8 of 48



| Inspection Rating Criteria | Rating Scale | Explanation |
|----------------------------|---------------------------------|---|
| | 1 - Service Required | Requires immediate repairs to function as expected. |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. |

General Appearance

Close-Up Exterior Photos









Powered by 🍫 fastfield Page 10 of 48







Powered by 🍫 fastfield Page 11 of 48








Powered by 🍫 fastfield Page 12 of 48






Powered by 🍫 fastfield Page 13 of 48





Powered by 🍫 fastfield Page 14 of 48





Control Station



Powered by 🍫 fastfield Page 15 of 48





Powered by 🍫 fastfield Page 16 of 48





faded gauge, but it works and is readable



areas of rust/missing paint

Powered by 🍫 fastfield Page 17 of 48






area of rust and can not see all of the instructions for the switches/controls



above normal wear and tear

Powered by 🍫 fastfield Page 18 of 48






Engine

Engine Compartment







Powered by 🍫 fastfield Page 20 of 48







Powered by 🍫 fastfield Page 21 of 48





small wet spot, no dripping or pooling of fluids seen







Drivetrain Components

Drivetrain Photos









Powered by 🍫 fastfield Page 24 of 48








Powered by 🍫 fastfield Page 25 of 48





Hydraulics

Hydraulic Pump/Fittings/Hoses









Powered by 🍫 fastfield Page 27 of 48







Powered by 🍫 fastfield Page 28 of 48








Powered by 🍫 fastfield Page 29 of 48





Powered by 🍫 fastfield Page 30 of 48






Hydraulic Cylinders & Mounting Pins







Powered by 🍫 fastfield Page 32 of 48









Powered by 🍫 fastfield Page 33 of 48






Powered by 🍫 fastfield Page 34 of 48





Powered by 🍫 fastfield Page 35 of 48





Chassis

Powered by 🍫 fastfield Page 36 of 48



Chassis Photos











Powered by 🍫 fastfield Page 38 of 48







| Chassis Rating | 3 - Normal Wear & Tear |
|----------------|--|
| Comments | The chassis is in good working condition |

Track Undercarriage Inspection Points

| Undercarriage Photos | |
|------------------------|---|
| Undercarriage Rating | 0 |
| Undercarriage Comments | |

Undercarriage Inspection Points

| Underbody Photos | |
|--------------------|---|
| Underbody Rating | 0 |
| Underbody Comments | |

Attachments

Powered by 🍫 fastfield Page 39 of 48



Attachment Photos





Powered by 🍫 fastfield Page 40 of 48





areas of rust/missing paint











areas of rust/missing paint



2 wires are broken

Powered by 🍫 fastfield Page 43 of 48







exposed wires












Powered by 🍫 fastfield Page 46 of 48





Functionality Assessment

| Operating Video | |
|-----------------------------------|------------------------------------|
| Additional Video | |
| Engine | 3 - Normal Wear & Tear |
| Transmission/Drivetrain | 3 - Normal Wear & Tear |
| Travel (Forward/Reverse/Steering) | 3 - Normal Wear & Tear |
| Brakes | 3 - Normal Wear & Tear |
| Hydraulic System | 3 - Normal Wear & Tear |
| Controls | 2 - Above Average Wear & Tear |
| Safety Systems | 3 - Normal Wear & Tear |
| Attachments | 2 - Above Average Wear & Tear |
| Overall Functional Test Comments | The machine performed well overall |

Overall Assessment

Overall Assessment

Powered by 🍫 fastfield Page 47 of 48



| Rating Scale | Rating Scale | Explanation | | |
|--------------------------------------|--|---|--|--|
| | 1 - Service Required | Requires immediate repairs to function as expected. | | |
| | 2 - Above Average Wear & Tear | Exhibits greater wear than expected given age and usage. While operable, further diagnosis may be needed. | | |
| | 3 - Normal Wear & Tear | Exhibits wear that is consistent with age and usage. Operation is normal, and as expected. | | |
| | 4 - Very Light or Minimal Wear | Exhibits very minimal wear. Operation is better than expected given age and usage. | | |
| | 5 - Like New, Recently Replaced | Excellent condition, free of visible wear or damage. Operation is within factory specifications. | | |
| Exterior Rating | 3 - Normal Wear & Tear | | | |
| Interior Rating | 0 | | | |
| Safety Rating | 3 - Normal Wear & Tear | 3 - Normal Wear & Tear | | |
| Quality Rating | 3 - Normal Wear & Tear | | | |
| Functionality Rating | 3 - Normal Wear & Tear | | | |
| Overall Rating | 3 - Normal Wear & Tear | | | |
| What's Great About the Machine | The machine has a boom that moves 360° and is in good working conditions | | | |
| What Needs Work | Some hoses looked cracked and dry and the basket controls had above normal wear and tear | | | |
| Any Additional Info from the Seller? | | | | |
| Date/Time | 05-15-2023 | | | |

Powered by 🍫 fastfield Page 48 of 48