

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Refrigeration Unit Serial Number	6001360879	
Hour Meter / Odometer	7900 hrs	
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders		
v3 General Appearance # 1		
v3 General Appearance # 2		

v3 General Appearance # 3




Air System		
Item	Assessment	Photo
Air Valve	Not operationally checked	
Air Tank	Not operationally checked	
Air Lines	Not operationally checked	
Limited Function Check	The air system was not operationally checked.	
Air System #1		
Air System #2		


Trailer Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Frame Rails/ Main Beams Condition	★★★★☆ No visible damage	
Axle Condition	★★★★☆	
Suspension Air Bags	Not operationally checked	
Brake Lines/Hoses	Not operationally checked	
Limited Function Check - Brakes	The brakes were not operationally checked.	
Tire Condition		
Tires	Left front outer: 11/32", Left front inner: 12/32", Left rear outer: 7/32", Left rear inner: 10/32", Right rear outer: 13/32", Right rear inner: 11/32", Right front outer: 12/32", Right front inner: 12/32"	
Wheel Condition	★★★★☆	
Wheel Studs	★★★★☆	
Tongue/ Hitch Condition	★★★★☆ No visible damage	

Power Receptacle Functional	Not operationally checked	
Lights/Wiring Condition	Not operationally checked	
Marker Lights Functional	Not operationally checked	
Brake Lights Functional	Not operationally checked	
License Plate Light Functional	Not operationally checked	
Landing Gear / Tongue Jack	★★★★☆	
Deck/ Floor Condition	★★★★☆	

Refrigeration Unit	Operational, Diesel engine driven compressor	
Trailer Chassis #1		
Trailer Chassis #2		
Trailer Chassis #3		
Trailer Chassis #4		
Trailer Chassis #5		
Trailer Chassis #6		

Trailer Chassis #7		
Trailer Chassis #8		
Trailer Chassis #9		
Trailer Chassis #10		
Trailer Chassis #11		
Trailer Chassis #12		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved