



Hyundai Tucson blue Intro Edition 2WD

EZ 10/2016 | 4X4 | Diesel | Manual transmission | 228,644km

Taxation: Differential taxation (§25a UStG)

Vehicle location: 41***

Fahrzeug aufgenommen am: 21.07.2026



Vehicle data

Manufacturer Hyundai	Type/Sales name Tucson blue Intro Edition 2WD [DE - SUV5 1.7 CRDi DPF EU6, Intro Edition blue 2WD, 2015 - 2016]		
Category 4X4	FIN TMAJ3815AHJ192110	Registration number -	Mileage 228,644km
Main inspection till / General inspection report available - / Not available	Cushion Substance	Performance 116 PS (85 KW)	Fuel Diesel
Number of keys 2	Service booklet Yes	Full service history No	
Cubic capacity 1.685 ccm	Vehicle document folder is present	Last service 185,124km	Last service on 01/2025
Emissions class Euro 6	Seats 5	Doors 4/5	Transmission type Manual transmission
EZ 10/2016	Colour Grey	Total number of known holders 1	
Import vehicle Not a reimport vehicle	CoC documents available No	Country of last approval Germany	
Unusual prior usage None		CO2 emissions 119g/km (NEDC)	Fuel consumption 4.6l/100 km (NEDC)

Notes on the status report

Viewing conditions

The present condition report and the evaluation of the technical components as well as the car service were based exclusively on a visual inspection. A proper visual inspection in difficult weather conditions or contamination of the body can only be carried out to a limited extent. In these cases, further damage cannot be excluded.

When viewing the vehicle, no test drive was carried out and no lifting platform was used. The vehicle may have defects corresponding to mileage and age. Previous damage was not known to CarOnSale, unless otherwise stated in the report.

Tyre condition

1. Set (Mounted)

Tyre type: All-weather tyres
Rim: Light metal (Inches: 16)

Front left



(3 mm)
Scratch

Front right



(3 mm)

Rear left



(5 mm)

Rear right



(5 mm)
Scratch

2. Set

Tyre type: Summer tyres
Rim: Light metal (Inches: 17)

Front left



(3 mm)

Front right



(3 mm)

Rear left



(3 mm)

Rear right



(3 mm)

Paint values

 Anomaly

Vehicle part	Lacquer layer thickness (in µm)	Vehicle part	Lacquer layer thickness (in µm)
Driver door	145	Passenger door	130
Mudguard front left	115	Mudguard front right	120
Door rear left	115	Door rear right	130
Side panel rear left	210	Side panel rear right	130
Engine bonnet	130	Boot lid	130
Roof	120		



Technical condition

Lower engine area	No abnormalities;
Manual/automatic transmission	No abnormalities;
Steering	No abnormalities;
Battery	No abnormalities;
Differential	No abnormalities;
Air conditioning	Insufficient cooling capacity ;

Other technical defects

None

Additional information

Service/maintenance due;

Wear parts

Braking system	No abnormalities;
Clutch	No abnormalities;
Chassis	No abnormalities;



Standard equipment

- 6 speaker(s)
- active engine hood
- airbag driver side/passenger side
- airbag passenger side deactivatable
- alarm system
- antilock braking system (ABS)
- Audio system: radio RDS
- audio-DVD navigation system with colour touchscreen
- audio/radio remote control at steering wheel
- automatic air-conditioning system 2-zone
- automatic door locking (Dead Lock)
- automatic switch-on for driving light / light sensor
- baggage net in trunk/load space
- body: 5-door
- brake assistant
- bumper fascia rear center, silver
- center armrest front
- cornering lights
- counter steering support (Vehicle Stability Management, VSM)
- cruise control (cruise control)
- daytime running lights LED
- diesel particulate filter
- door handles outside vehicle colour
- driver assistance system: blind-spot assistant
- driver assistance system: driving-profile selection (Drive mode)
- driver assistance system: hill descent control
- driver assistance system: hill start assist feature
- driver assistance system: lane assist, warning system (LDWS, Lane Departure Warning System)
- driver assistance system: parking aid front and rear
- driver assistance system: traffic sign assistant
- dual tailpipe exhaust system
- electr. brake force distribution

• electronic stability control (ESC) with brake assistant	• Electronic Stability Control (ESP)
• engine 1,7 liter - 85 kW CRDi catalyst	• exterior mirror electrically adjustable and heated, both
• exterior mirror electrically folding	• exterior mirror painted
• front fog lights	• glazing tinted
• glove box illuminated	• glove box with cooling function
• hands-free system Bluetooth	• head airbag system
• headlight leveling control	• immobilizer (electronic)
• interior mirror with automatic dimming	• Isofix mounts for child seat
• low emissions according to emission standard Euro 6	• lumbar support seat front left, electrically adjustable
• model variant CO2-optimised (Blue / Blue Drive)	• parking brake electric (EPB)
• power steering	• radiator grille chrome-plated
• radio reception digital (DAB)	• rear fog light
• rear lights LED	• rear seat backrest split/folding
• rear window heated	• rear window wiper
• roof rails	• seat belts front height-adjustable
• seat covers/upholstery: cloth	• seat front left height-adjustable
• seat heating front	• shift/selector lever leather
• side window from B-pillar darkened	• side-impact protection
• sidebag front	• start/stop system
• steering column (steering wheel) adjustable (vertical / axial)	• steering wheel (leather)
• steering wheel heated	• sun visors with mirror (illuminated)
• tire pressure control system	• tire repair kit
• transmission 6-speed	• trip computer with TFT colour display, high-resolution
• Type of drive: front-wheel drive	• underride protection (silver)
• USB connection + AUX-IN interface	• vehicle speed limiter (Speed-Limiter)
• wheelbase 2670 mm	• window lifter electr. with pinch protection
• window lifter electric front + rear	• window trim strips chrome-plated
• windshield fogging detection / control	• windshield laminated glass
• windshield wiper defroster front	• windshield wiper with rain sensor
• tweeter	• reversing camera
• parking aid rear	• Original vehicle color: MICRON/PEPPER GREY



Extras

The data of the standard and optional equipment will be taken from the DAT database. No liability can be assumed for the completeness and accuracy

Vehicle photos











120.000-km-Wartung	150.000-km-Wartung	180.000-km-Wartung
Diebstahlversicherung nach 30.000 km Fahrleistung oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: 122406 Datum: 03.09.22 HYUNDAI 1888 Authaus Louis Diesel GmbH & Co. KG Aachenener Strasse 225 41061 Mönchengladbach Telefon 0 21 61 3 75 00 Ausgeführt durch Hyundai Service Fachwerkstatt - Dienstleistungen Es wird bestätigt, dass die Wartung fachgerecht nach Herstellervorgaben durchgeführt wurde. Eine Kopie der Wartungs-Checkliste wurde ausgehändigt. Nächster Service: 30.000 km oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: oder Datum: Sep. 2024	Diebstahlversicherung nach 30.000 km Fahrleistung oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: 154518 Datum: 21.11.23 HYUNDAI 1888 Authaus Louis Diesel GmbH & Co. KG Aachenener Strasse 225 41061 Mönchengladbach Telefon 0 21 61 3 75 00 Ausgeführt durch Hyundai Service Fachwerkstatt - Dienstleistungen Es wird bestätigt, dass die Wartung fachgerecht nach Herstellervorgaben durchgeführt wurde. Eine Kopie der Wartungs-Checkliste wurde ausgehändigt. Nächster Service: 30.000 km oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: 180000 oder Datum: Okt. 2025	Diebstahlversicherung nach 30.000 km Fahrleistung oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: 185924 Datum: 02.01.25 HYUNDAI 1888 Authaus Louis Diesel GmbH & Co. KG Aachenener Strasse 225 41061 Mönchengladbach Telefon 0 21 61 3 75 00 Ausgeführt durch Hyundai Service Fachwerkstatt - Dienstleistungen Es wird bestätigt, dass die Wartung fachgerecht nach Herstellervorgaben durchgeführt wurde. Eine Kopie der Wartungs-Checkliste wurde ausgehändigt. Nächster Service: 30.000 km oder 3 Jahren nach der vorangegangenen Wartung, je nachdem was zuerst eintritt. Kilometerstand: 210000 oder Datum: 01.27

Achtung: Als Hinweis für Karosserie- und Unterboden-Prüfung denken. Des weiteren ist die Betriebsstofffüllung auf Seite 7 zu beachten!
 HYUNDAI Motor Deutschland GmbH empfiehlt **TOTAL**



Vehicle damage photos (exterior)



Front bumper (Scratch)



Wheel (Scratch)



Wheel (Scratch)



Driver door (Scratch)



Passenger door (Delle)



Passenger door (Delle)



Passenger door (Scratch)



Passenger door (Scratch)



Door rear left (Scratch)



Door rear left (Other damage): It won't open.



Door rear right (Scratch)



Rear bumper (Scratch)



Side panel rear left (Delle)



Side panel rear right (Delle)

Vehicle damage photos (interior)



Interior (Pollution)



Interior (Pollution)



Interior (Wear)



Interior (Scratch)