Assembly Instruction

Note: For better clarity, this Instruction does not always show the undersurface pedestal or other undersurface components.

Place the end support base in desired position on the underside of the upper worksurface. Attach with Sixteen (16) #12 x 7/8" Flat Head Screws (Figure A).

Attach with 16 #12 x 7/8" Flat Head Screws, eight (8) per side.


End Support Base

Recommended Tools

- Drill with 5/16" bit
- Phillips head screwdriver
- Tape Measure
- 2-3" wide masking tape
- Pencil

In the desired location, position the upper worksurface with the attached end support base placed on the lower unit.

Note: Place 2-3" wide masking tape where the end support base intersects with the lower unit. Using a pencil mark the location of the ends and sides of the end support base (Figure B).



Package Contents Qty.

1

- End Support Base
- #12 x 7/8" Flat Head Screw
- 1/4-20 x 2 1/2" Flat Head Machine Screw

Using a tape measure and pencil mark the locations shown in (Figure C). for boring holes for two (2) 1/4-20 x 2 1/2" Flat Head Machine Screws.

Drill two (2) 5/16" holes through the lower worksurface.




Figure C

NATIONAL


Furniture with Personality

Telephone 800.482.1717 Fax 812.482.8800 www.NationalOfficeFurniture.com

Part #2379236 Rev,-

Printed in U.S.A © 2011 Kimball International, Inc.

With the upper and lower units positioned in the desired locations, install two (2) 1/4-20 x 2 1/2" Flat Head Machine screws through the lower worksurface into the end support base (Figure D).



Two (2) 1/4-20 x 2 1/2" FH Machine Screws

Proper product installation, in accordance with these instructions, is the responsibility of the installing agent. If you have any questions concerning these instructions, please call National Customer Service 800.482.1717.