

Assembly Instructions



Installation

- 1. Carefully flip the workstation upside-down onto a non-abrasive surface. This may require 2-3 people.
- 2. Orient the modesty panel and corners as shown and lock together. Figure 1.
- 3. Place the mounting bracket inside the panel pocket. Figure 2.



- 4. Align the modesty panel, bracket, and worksurface mounting holes. Figure 3.
- Attach to worksurface with (8) #14 x 7/8" PHSM screws. Figure 4.
 Secure mounting bracket with (1) #8 x 5/8" PHSM screw.

