

Figure 2

S<u>PECTRUM</u> INDUSTRIES INC.

- 3. Align the modesty panel, bracket, and worksurface mounting holes. Figure 3.
- 4. Attach to worksurface with (11) #8 x 3/4" PHSM screws. Figure 4.

