# R&S®ZNL I/Q Analyzer (Option R&S®ZNL3|4| 6-B1) User Manual





This manual applies to the following R&S®ZNL models with firmware version 1.35 and higher:

- R&S®ZNL3, 5 kHz to 3 GHz, 2 ports, N(f) connectors, order no. 1323.0012.03
- R&S®ZNL4, 5 kHz to 4.5 GHz, 2 ports, N(f) connectors, order no. 1323.0012.04
- R&S®ZNL6, 5 kHz to 6 GHz, 2 ports, N(f) connectors, order no. 1323.0012.06

The following firmware options are described:

- R&S®ZNL3-B1 Spectrum Analysis (1323.1802.02)
- R&S®ZNL4-B1 Spectrum Analysis (1303.8099.02)
- R&S®ZNL6-B1 Spectrum Analysis (1323.2067.02)

In addition to the I/Q Analyzer application, the following options are described:

- R&S®FPL1-B5, Additional Interfaces (1323.1883.02)
- R&S®FPL1-K9 Power Sensor Support (1323.1754.02)
- R&S®FPL1-B40, Bandwidth extension 40 MHz (1323.1931.02)

© 2020 Rohde & Schwarz GmbH & Co. KG Mühldorfstr. 15, 81671 München, Germany

Phone: +49 89 41 29 - 0
Email: info@rohde-schwarz.com
Internet: www.rohde-schwarz.com

Subject to change – Data without tolerance limits is not binding. R&S^ $^{\circledR}$  is a registered trademark of Rohde & Schwarz GmbH & Co. KG.

Trade names are trademarks of the owners.

1178.5989.02 | Version 09 | R&S®ZNL

Throughout this manual, products from Rohde & Schwarz are indicated without the ® symbol, e.g. R&S®ZNL is indicated as R&S ZNL.

# Contents

1	Preface	5
1.1	Documentation-Overview	5
1.2	Conventions Used in the Documentation	7
2	Welcome to the I/Q Analyzer Application	9
2.1	Starting the I/Q Analyzer Application	9
2.2	Understanding the Display Information	10
3	Measurement and Result Displays	13
4	Basics on I/Q Data Acquisition and Processing	17
4.1	Processing Analog I/Q Data from RF Input	17
4.2	Basics on FFT	20
4.3	Basics on Input from I/Q Data Files	26
4.4	I/Q Data Import and Export	26
5	Configuration	28
5.1	Configuration Overview	28
5.2	Import/Export Functions	30
5.3	Receiving Data Input and Providing Data Output	33
5.4	Amplitude	42
5.5	Frequency Settings	46
5.6	Trigger Settings	48
5.7	Data Acquisition and Bandwidth Settings	51
5.8	Display Configuration	57
5.9	Adjusting Settings Automatically	57
6	Analysis	. 61
6.1	Trace Settings	61
6.2	Spectrogram Settings	65
6.3	Trace / Data Export Configuration	70
6.4	Marker Usage	73
7	How to Perform Measurements in the I/Q Analyzer Application	. 96
7.1	How to Capture Baseband (I/Q) Data as RF Input	96

7.2	How to Analyze Data in the I/Q Analyzer	. 97
8	How to Export and Import I/Q Data	.98
9	Remote Commands to Perform Measurements with I/Q Data	100
9.1	Introduction	100
9.2	Common Suffixes	105
9.3	Activating I/Q Analyzer Measurements	105
9.4	Configuring I/Q Analyzer Measurements	110
9.5	Configuring the Result Display	145
9.6	Capturing Data and Performing Sweeps	152
9.7	I/Q Analysis	158
9.8	Retrieving Results	206
9.9	Importing and Exporting I/Q Data and Results	217
9.10	Programming Examples	218
	Annex2	222
A	Formats for Returned Values: ASCII Format and Binary Format2	222
В	Reference: Format Description for I/Q Data Files	223
С	I/Q Data File Format (iq-tar)	225
C.1	I/Q Parameter XML File Specification	226
C.2	I/Q Data Binary File	229
	List of Commands	231
	Index2	237

**Documentation-Overview** 

# 1 Preface

This chapter provides safety-related information, an overview of the user documentation and the conventions used in the documentation.

# 1.1 Documentation-Overview

This section provides an overview of the R&S ZNL user documentation. Unless specified otherwise, you find the documents on the R&S ZNL product page at:

www.rohde-schwarz.com/manual/ZNL or www.rohde-schwarz.com/manual/ZNLE.

# 1.1.1 Getting Started Manual

Introduces the R&S ZNL and describes how to set up and start working with the product. Includes basic operations, typical measurement examples, and general information, e.g. safety instructions, etc.

A printed version is delivered with the instrument. A PDF version is available for download on the Internet.

# 1.1.2 User Manuals and Help

Separate user manuals are provided for the base unit and the firmware applications:

- Base unit manual
   Contains the description of all instrument modes and functions. It also provides an introduction to remote control, a complete description of the remote control commands with programming examples, and information on maintenance, instrument interfaces and error messages. Includes the contents of the getting started manual.
- Firmware application manual
   Contains the description of the specific functions of a firmware application, including remote control commands. Basic information on operating the R&S ZNL is not included.

The contents of the user manuals are available as help in the R&S ZNL. The help offers quick, context-sensitive access to the complete information for the base unit and the firmware applications.

All user manuals are also available for download or for immediate display on the Internet.

**Documentation-Overview** 

# 1.1.3 Service Manual

Describes the performance test for checking the rated specifications, module replacement and repair, firmware update, troubleshooting and fault elimination, and contains mechanical drawings and spare part lists.

The service manual is available for registered users on the global Rohde & Schwarz information system (GLORIS):

https://gloris.rohde-schwarz.com

# 1.1.4 Instrument Security Procedures

Deals with security issues when working with the R&S ZNL in secure areas. It is available for download on the Internet.

# 1.1.5 Basic Safety Instructions

Contains safety instructions, operating conditions and further important information. The printed document is delivered with the instrument.

# 1.1.6 Data Sheets and Brochures

The data sheet contains the technical specifications of the R&S ZNL. It also lists the firmware applications and their order numbers, and optional accessories.

The brochure provides an overview of the instrument and deals with the specific characteristics.

See www.rohde-schwarz.com/brochure-datasheet/ZNL or www.rohde-schwarz.com/brochure-datasheet/ZNLE.

# 1.1.7 Release Notes and Open Source Acknowledgment (OSA)

The release notes list new features, improvements and known issues of the current firmware version, and describe the firmware installation.

The open-source acknowledgment document provides verbatim license texts of the used open source software.

See www.rohde-schwarz.com/firmware/ZNL or www.rohde-schwarz.com/firmware/ZNLE.

# 1.1.8 Application Notes, Application Cards, White Papers, etc.

These documents deal with special applications or background information on particular topics.

Conventions Used in the Documentation

See www.rohde-schwarz.com/application/ZNL or www.rohde-schwarz.com/application/ZNLE.

# 1.1.9 Calibration Certificate

The document is available on https://gloris.rohde-schwarz.com/calcert. You need the device ID of your instrument, which you can find on a label on the rear panel.

# 1.2 Conventions Used in the Documentation

# 1.2.1 Typographical Conventions

The following text markers are used throughout this documentation:

Convention	Description	
"Graphical user interface elements"	All names of graphical user interface elements on the screen, such as dialog boxes, menus, options, buttons, and softkeys are enclosed by quotation marks.	
[Keys]	Key and knob names are enclosed by square brackets.	
Filenames, commands, program code	Filenames, commands, coding samples and screen output are distinguished by their font.	
Input	Input to be entered by the user is displayed in italics.	
Links	Links that you can click are displayed in blue font.	
"References"	References to other parts of the documentation are enclosed by quotation marks.	

# 1.2.2 Conventions for Procedure Descriptions

When operating the instrument, several alternative methods may be available to perform the same task. In this case, the procedure using the touchscreen is described. Any elements that can be activated by touching can also be clicked using an additionally connected mouse. The alternative procedure using the keys on the instrument or the on-screen keyboard is only described if it deviates from the standard operating procedures.

The term "select" may refer to any of the described methods, i.e. using a finger on the touchscreen, a mouse pointer in the display, or a key on the instrument or on a keyboard.

Conventions Used in the Documentation

# 1.2.3 Notes on Screenshots

When describing the functions of the product, we use sample screenshots. These screenshots are meant to illustrate as many as possible of the provided functions and possible interdependencies between parameters. The shown values may not represent realistic usage scenarios.

The screenshots usually show a fully equipped product, that is: with all options installed. Thus, some functions shown in the screenshots may not be available in your particular product configuration.

Starting the I/Q Analyzer Application

# 2 Welcome to the I/Q Analyzer Application

The R&S FPL1 I/Q Analyzer is a firmware application that adds functionality to perform I/Q data acquisition and analysis to the R&S ZNL.

The R&S FPL1 I/Q Analyzer features:

- Acquisition of analog I/Q data
- Import of stored I/Q data from other applications
- Spectrum, magnitude, I/Q vector and separate I and Q component analysis of any I/Q data on the instrument
- Export of I/Q data to other applications



# Availability of the I/Q Analyzer

The I/Q Analyzer becomes available when you equip the R&S ZNL3, R&S ZNL4 or R&S ZNL6 with the optional Spectrum Analyzer hardware (R&S ZNL3|4|6-B1).

This user manual contains a description of the functionality that the application provides, including remote control operation.

All functions not discussed in this manual are the same as in the base unit and are described in the R&S ZNL User Manual. The latest version is available for download at the product homepage http://www.rohde-schwarz.com/product/ZNL.

# **Additional information**

Several application notes discussing I/Q analysis are available from the Rohde & Schwarz website:

1EF85: Converting R&S I/Q data files

1EF92: Wideband Signal Analysis

1MA257: Wideband mm-Wave Signal Generation and Analysis

1EF84: Differential measurements with Spectrum Analyzers and Probes

# Installation

The R&S FPL1 I/Q Analyzer application is part of the optional Spectrum application and requires no further installation.

# 2.1 Starting the I/Q Analyzer Application

The I/Q Analyzer is an application on the R&S ZNL.

# To activate the I/Q Analyzer application

1. Select the [MODE] key.

Understanding the Display Information

A dialog box opens that contains all applications currently available on your R&S ZNL.

2. Select the "I/Q Analyzer" item.



The R&S ZNL opens a new channel setup for the I/Q Analyzer application.

The measurement is started immediately with the default settings.

It can be configured in the I/Q Analyzer "Overview" dialog box, which is displayed when you select the "Overview" softkey from any menu (see Chapter 5.1, "Configuration Overview", on page 28).

# **Multiple Channel Setups and Sequencer Function**

When you activate an application, a new channel setup is created which determines the measurement settings for that application (channel setup). The same application can be activated with different measurement settings by creating several channel setups for the same application.

The number of channel setups that can be configured at the same time depends on the available memory on the instrument.

Only one measurement can be performed at any time, namely the one in the currently active channel setup. However, in order to perform the configured measurements consecutively, a Sequencer function is provided.

If activated, the measurements configured in the currently defined channel setups are performed one after the other in the order of the tabs. The currently active measurement is indicated by a \$\mathbb{Q}\$ symbol in the tab label.

The result displays of the individual channel setups are updated in the tabs (as well as the "MultiView") as the measurements are performed. Sequential operation itself is independent of the currently *displayed* tab.

For details on the Sequencer function see the R&S ZNL User Manual.

# 2.2 Understanding the Display Information

The following figure shows a measurement diagram during I/Q Analyzer operation. All different information areas are labeled. They are explained in more detail in the following sections.

Understanding the Display Information




Figure 2-1: Screen elements in the I/Q Analyzer application

- 1 = Channel Setup bar for firmware and measurement settings
- 2+3 = Window title bar with diagram-specific (trace) information
- 4 = Diagram area with marker information
- 5 = Diagram footer with diagram-specific information, depending on result display
- 6 = Instrument status bar with error messages and date/time display

# **Channel Setup bar information**

In the I/Q Analyzer application, the R&S ZNL shows the following settings:

Table 2-1: Information displayed in the channel setup bar for the I/Q Analyzer application

Ref Level	Reference level
(m.+el.)Att	(Mechanical and electronic) RF attenuation
Ref Offset	Reference level offset
Freq	Center frequency
Meas Time	Measurement time
Rec Length	Defined record length (number of samples to capture)
SRate	Defined sample rate for data acquisition
RBW	(Spectrum evaluation only) Resolution bandwidth calculated from the sample rate and record length

In addition, the channel setup bar also displays information on instrument settings that affect the measurement results even though this is not immediately apparent from the display of the measured values (e.g. transducer or trigger settings). This information is displayed only when applicable for the current measurement. For details see the R&S ZNL Getting Started manual.

Understanding the Display Information

# Window title bar information

For each diagram, the header provides the following information:



Figure 2-2: Window title bar information in the I/Q Analyzer application

- 1 = Window number
- 2 = Window type
- 3 = Trace color
- 4 = Trace number
- 5 = Detector
- 6 = Trace mode

# **Diagram footer information**

The information in the diagram footer (beneath the diagram) depends on the evaluation:

- Center frequency
- Number of sweep points
- Range per division (x-axis)
- Span (Spectrum)

# Status bar information

Global instrument settings, the instrument status and any irregularities are indicated in the status bar beneath the diagram.

# 3 Measurement and Result Displays

Access: "Overview" > "Display Config"

Or: [MEAS] > "Display Config"

The I/Q Analyzer can capture I/Q data. The I/Q data that was captured by or imported to the R&S ZNL can then be evaluated in various different result displays. Select the result displays using the SmartGrid functions.


For details on working with the SmartGrid see the R&S ZNL Getting Started manual.

# Result displays for I/Q data:

Magnitude	13
Spectrum	
I/Q-Vector	
Real/Imag (I/Q)	15
Marker Table	
Marker Peak List	

# Magnitude

Shows the level values in time domain.




# Remote command:

LAY: ADD: WIND? '1', RIGH, MAGN, see LAYout: ADD[:WINDow]? on page 146 Results:

TRACe<n>[:DATA]? on page 211

# Spectrum

Displays the frequency spectrum of the captured I/Q samples.



The specified Analysis Bandwidth is indicated by vertical blue lines.

Note that a peak search is performed only within the indicated Analysis Bandwidth, unless you specify Search Limits (Left / Right) in the marker settings.


# Remote command:

LAY: ADD: WIND? '1', RIGH, FREQ, see LAYOut: ADD[:WINDow]? on page 146 Results:

TRACe<n>[:DATA]? on page 211

# I/Q-Vector

Displays the captured samples in an I/Q-plot. The samples are connected by a line.



**Note:** For the I/Q vector result display, the number of I/Q samples to record ("Record Length") must be identical to the number of trace points to be displayed ("Sweep Points"; for I/Q Analyzer: 10001). For record lengths outside the valid range of sweep points the diagram does not show valid results.


# Remote command:

LAY: ADD: WIND? '1', RIGH, VECT, see LAYOut: ADD[:WINDow]? on page 146 Results:

TRACe < n > [:DATA]? on page 211

# Real/Imag (I/Q)

Displays the I and Q values in separate diagrams.



# Remote command:

LAY: ADD: WIND? '1', RIGH, RIM, see LAYout: ADD[: WINDow]? on page 146 Results:

TRACe<n>[:DATA]? on page 211

# **Marker Table**

Displays a table with the current marker values for the active markers.

This table is displayed automatically if configured accordingly.

(See "Marker Table Display" on page 77).



**Tip**: To navigate within long marker tables, simply scroll through the entries with your finger on the touchscreen.

# Remote command:

LAY: ADD? '1', RIGH, MTAB, see LAYout: ADD[:WINDow]? on page 146 Results:

CALCulate<n>:MARKer<m>:X on page 177
CALCulate<n>:MARKer<m>:Y on page 216

# **Marker Peak List**

The marker peak list determines the frequencies and levels of peaks in the spectrum or time domain. How many peaks are displayed can be defined, as well as the sort order. In addition, the detected peaks can be indicated in the diagram. The peak list can also be exported to a file for analysis in an external application.

3 Marker Peak List					
Wnd	2	X-Value	Y-Value		
2	1	1.086245 ms	-75.810 dBm		
2	2	2.172490 ms	-6.797 dBm		
2	3	3.258736 ms	-76.448 dBm		
2	4	4.831918 ms	-76.676 dBm		
2	5	6.255274 ms	-76.482 dBm		
2	6	6.798397 ms	-6.800 dBm		
2	7	9.233084 ms	-76.519 dBm		
2	8	10.075861 ms	-76.172 dBm		
2	9	11.405574 ms	-6.801 dBm		

# Remote command:

LAY: ADD? '1', RIGH, PEAK, see LAYout: ADD[:WINDow]? on page 146 Results:

CALCulate<n>:MARKer<m>:X on page 177
CALCulate<n>:MARKer<m>:Y on page 216

# 4 Basics on I/Q Data Acquisition and Processing

Some background knowledge on basic terms and principles used when describing I/Q data acquisition on the R&S ZNL in general, and in the I/Q Analyzer application in particular, is provided here for a better understanding of the required configuration settings.

The I/Q Analyzer provides various possibilities to acquire the I/Q data to be analyzed:

- Capturing analog I/Q data from the [RF Input] connector
- Importing I/Q data from a file

Background information for all these scenarios and more is provided in the following sections.

•	Processing Analog I/Q Data from RF Input	.17
•	Basics on FFT	.20
•	Basics on Input from I/Q Data Files	26
•	I/Q Data Import and Export	26

# 4.1 Processing Analog I/Q Data from RF Input

#### Complex baseband data

In the telephone systems of the past, baseband data was transmitted unchanged as an analog signal. In modern phone systems and in radio communication, however, the baseband data is modulated on a carrier frequency, which is then transmitted. The receiver must demodulate the data based on the carrier frequency. When using modern modulation methods (e.g. QPSK, QAM etc.), the baseband signal becomes complex. Complex data (or: I/Q data) consists of an imaginary (I) and a real (Q) component.

# Sweep vs sampling

The standard Spectrum application on the R&S ZNL performs frequency sweeps on the input signal and measurements in the frequency and time domain. Other applications on the R&S ZNL, such as the I/Q Analyzer, sample and process the individual I and Q components of the complex signal.

# I/Q Analyzer - processing complex data from RF input

The I/Q Analyzer is a standard application used to capture and analyze I/Q data on the R&S ZNL. By default, it assumes the I/Q data is modulated on a carrier frequency and input via the "RF Input" connector on the R&S ZNL.

The A/D converter samples the IF signal at a rate of 100 MHz. The digital signal is down-converted to the complex baseband, lowpass-filtered, and the sample rate is

Processing Analog I/Q Data from RF Input

reduced. The analog filter stages in the analyzer cause a frequency response which adds to the modulation errors. An **equalizer filter** before the **resampler** compensates for this frequency response. The continuously adjustable sample rates are realized using an optimal decimation filter and subsequent resampling on the set sample rate.

A dedicated memory (**capture buffer**) is available in the R&S ZNL for a maximum of 25 Msamples (25\*1000\*1000) of complex samples (pairs of I and Q data). The number of complex samples to be captured can be defined (for restrictions refer to Chapter 4.1.1, "Sample Rate and Maximum Usable I/Q Bandwidth for RF Input", on page 18).

The block diagram in Figure 4-1 shows the analyzer hardware from the IF section to the processor.

# Data aquisition hardware




Figure 4-1: Block diagram illustrating the R&S ZNL signal processing for analog I/Q data (without bandwidth extension options)

# 4.1.1 Sample Rate and Maximum Usable I/Q Bandwidth for RF Input

#### **Definitions**

- Input sample rate (ISR): the sample rate of the useful data provided by the device connected to the input of the R&S ZNL
- (User, Output) Sample rate (SR): the user-defined sample rate (e.g. in the "Data Acquisition" dialog box in the "I/Q Analyzer" application) which is used as the basis for analysis or output
- Usable I/Q (Analysis) bandwidth: the bandwidth range in which the signal remains undistorted in regard to amplitude characteristic and group delay; this range can be used for accurate analysis by the R&S ZNL
- Record length: Number of I/Q samples to capture during the specified measurement time; calculated as the measurement time multiplied by the sample rate

For the I/Q data acquisition, digital decimation filters are used internally in the R&S ZNL. The passband of these digital filters determines the *maximum usable I/Q bandwidth*. In consequence, signals within the usable I/Q bandwidth (passband)

Processing Analog I/Q Data from RF Input

remain unchanged, while signals outside the usable I/Q bandwidth (passband) are suppressed. Usually, the suppressed signals are noise, artifacts, and the second IF side band. If frequencies of interest to you are also suppressed, try to increase the output sample rate, which increases the maximum usable I/Q bandwidth.



# **Bandwidth extension options**

You can extend the maximum usable I/Q bandwidth provided by the R&S ZNL in the basic installation by adding options. These options can either be included in the initial installation (B-options) or updated later (U-options). The maximum bandwidth provided by the individual option is indicated by its number, for example, B40 extends the bandwidth to 40 MHz.

As a rule, the usable I/Q bandwidth is proportional to the output sample rate. Yet, when the I/Q bandwidth reaches the bandwidth of the analog IF filter (at very high output sample rates), the curve breaks.

• Relationship Between Sample Rate, Record Length and Usable I/Q Bandwidth... 19

# 4.1.1.1 Relationship Between Sample Rate, Record Length and Usable I/Q Bandwidth

Up to the maximum bandwidth, the following rule applies:

Usable I/Q bandwidth = 0.8 \* Output sample rate

Regarding the record length, the following rule applies:

Record length = Measurement time \* sample rate

# Maximum record length for RF input

The maximum record length is the maximum number of samples that can be captured.

Table 4-1: Maximum record length

Sample rate	Maximum record length
100 Hz to 100 MHz	25 Msamples

The Figure 4-2 shows the maximum usable I/Q bandwidths depending on the output sample rates.





Figure 4-2: Relationship between maximum usable I/Q bandwidth and output sample rate

# 4.2 Basics on FFT

The I/Q Analyzer measures the power of the signal input over time. To convert the time domain signal to a frequency spectrum, an FFT (Fast Fourier Transformation) is performed which converts a vector of input values into a discrete spectrum of frequencies.



# 4.2.1 Window Functions

The Fourier transformation is not performed on the entire captured data in one step. Only a limited number of samples is used to calculate an individual result. This process is called windowing.

After sampling in the time domain, each window is multiplied with a specific window function. Windowing helps minimize the discontinuities at the end of the measured signal interval and thus reduces the effect of spectral leakage, increasing the frequency resolution.

Various different window functions are provided in the R&S ZNL to suit different input signals. Each of the window functions has specific characteristics, including some advantages and some trade-offs. Consider these characteristics to find the optimum solution for the measurement task.



# Ignoring the window function - rectangular window


The rectangular window function is in effect not a function at all, it maintains the original sampled data. This may be useful to minimize the required bandwidth. However, be aware that if the window does not contain exactly one period of your signal, heavy sidelobes may occur, which do not exist in the original signal.

Table 4-2: Characteristics of typical FFT window functions

Window type	Frequency resolution	Magnitude resolution	Sidelobe sup- pression	Measurement recommendation
Rectangular	Best	Worst	Worst	No function applied. Separation of two tones with almost equal amplitudes and a small frequency distance
Blackman-Harris (default)	Good	Good	Good	Harmonic detection and spurious emission detection
Gauss (Alpha = 0.4)	Good	Good	Good	Weak signals and short duration
Flattop	Worst	Best	Good	Accurate single tone measurements
5-Term	Good	Good	Best	Measurements with very high dynamic range

# 4.2.2 Overlapping

The I/Q Analyzer calculates multiple FFTs per measurement by dividing one captured record into several windows. Furthermore, the I/Q Analyzer allows consecutive windows to overlap. Overlapping "reuses" samples that were already used to calculate the preceding FFT result.



In advanced FFT mode with averaging, the overlapping factor can be set freely. The higher the overlap factor, the more windows are used. This leads to more individual results and improves detection of transient signal effects. However, it also extends the duration of the calculation. The size of the window can be defined manually according to the record length, the overlap factor, and the FFT length.

An FFT overlap of 67%, for example, means the second FFT calculation uses the last 67% of the data of the first FFT. It uses only 33% new data. The third FFT still covers 33% of the first FFT and 67% of the second FFT, and so on.




Figure 4-3: Overlapping FFTs


In "Manual" or "Auto" FFT mode, an FFT length of 4096 and a window length of 4096 (or the record length, if shorter) is used to calculate the spectrum.

# Combining results - trace detector

If the record length permits, multiple overlapping windows are calculated and combined to create the final spectrum using the selected trace detector. If necessary, the trace detector is also used to reduce the number of calculated frequency points (defined by the FFT length) to the defined number of sweep points. By default, the Autopeak trace detector is used.



Since the frequency points are reduced to the number of sweep points, using a detector other than "Auto Peak" and fewer than 4096 sweep points can lead to false level results.



# 4.2.3 Dependencies Between FFT Parameters

FFT analysis in the R&S ZNL is highly configurable. Several parameters, including the resolution bandwidth, record length, and FFT length, are user-definable. Note, however, that several parameters are correlated and not all can be configured independently of the others.

# Record Length

Defines the number of I/Q samples to capture. By default, the number of sweep points is used. The record length is calculated as the measurement time multiplied by the sample rate.

If you change the record length, the Meas Time is automatically changed, as well.

For FFTs using only a single window ("Single" mode), the record length (which is then identical to the FFT length) must not exceed 512k.

# **FFT Length**

Defines the number of frequency points determined by each FFT calculation. The more points are used, the higher the resolution in the spectrum becomes, but the longer the calculation takes.

In "Auto" or "Manual" mode, an FFT length of 4096 is used.

If the FFT length is longer than the Window Length the sample data is filled up with zeros up to the FFT length. The FFT is then performed using interpolated frequency points.

For an FFT length that is not a power of 2, a DFT (discrete Fourier transform) is performed, which requires more time for calculation, but avoids the effects of interpolation.

To display all calculated frequency points (defined by the FFT length), the number of sweep points is set to the FFT length automatically in advanced FFT mode.

# Window Length

Defines the number of samples to be included in a single window in averaging mode. (In single mode, the window length corresponds to the "Record Length" on page 53.)

Values from 3 to 4096 are available in "Manual" mode; in "Advanced" FFT mode, values from 3 to 524288 are available. However, the window length must not be longer than the FFT Length.

If the window length is shorter than the FFT Length, the sample data is filled up with zeros up to the FFT length.

If the window length is longer than the Record Length (that is, not enough samples are available), a window length the size of the Record Length is used for calculation.

The window length and the Window Overlap determine how many FFT calculations must be performed for each record in averaging mode (see "TransformationAlgorithm" on page 54).

# 4.2.4 Frequency Resolution of FFT Results - RBW

The **resolution bandwidth** defines the minimum frequency separation at which the individual components of a spectrum can be distinguished. Small values result in high precision, as the distance between two distinguishable frequencies is small. Higher values decrease the precision, but increase measurement speed.

The RBW is determined by the following equation:

$$RBW = Normalized Bandwidth * \frac{Sample Rate}{Window Length}$$

#### Equation 4-1: Definition of RBW

(Note: The normalized bandwidth is a fixed value that takes the noise bandwidth of the window function into consideration.)

The maximum RBW is restricted by the Analysis Bandwidth, or by the following equation, whichever is higher:

$$RBW_{max} = \frac{Normalized Bandwidth * Sample Rate}{3}$$

If a higher spectral resolution is required, the number of samples must be increased by using a higher sample rate or longer record length.

The minimum achievable RBW depends on the sample rate and record length, according to the following equation:

# $RBW_{min} = \frac{NormalizedBandwidth*Sample Rate}{min(4096, Re cord Length)}$

To simplify operation, some parameters are coupled and automatically calculated, such as record length and RBW.

# **RBW** mode

Depending on the selected RBW mode, the resolution bandwidth is either determined automatically or can be defined manually.

#### Auto mode:

This is the default mode in the I/Q Analyzer. The RBW is determined automatically depending on the Sample Rate and Window Length, where the window length corresponds to the Record Length, or a maximum of 4096.

If the record length is larger than the window length, multiple windows are combined; the FFT length is 4096.

A Flatop window function is used.

#### Manual mode:

The RBW is user-definable.

The Window Length is adapted to comply with Equation 4-1. Since only window lengths with integer values can be employed, the Sample Rate is adapted, if necessary, to obtain an integer window length value.

If the record length is larger than the window length, multiple windows are combined; the FFT length is 4096.

A Flatop window function is used.

# **Advanced FFT mode**

The RBW is determined by the advanced FFT parameters, depending on the selected FFT Calculation Methods method.

# 4.2.5 FFT Calculation Methods

FFT calculation can be performed using different methods.

# Single

In single mode, one FFT is calculated for the entire record length, that means the window length is identical to the record length.

If the defined FFT Length is larger than the record length, zeros are appended to the captured data to reach the FFT length.

I/Q Data Import and Export



Figure 4-4: FFT parameters for single FFT calculation

# **Averaging**

In averaging mode, several overlapping FFTs are calculated for each record; the results are combined to determine the final FFT result for the record.

The number of FFTs to be combined is determined by the Window Overlap and the Window Length.



Figure 4-5: FFT parameters for averaged FFT calculation

# 4.3 Basics on Input from I/Q Data Files

The I/Q data to be evaluated in a particular R&S ZNL application can not only be captured by the application itself, it can also be loaded from a file, provided it has the correct format. The file is then used as the input source for the application.

The I/Q data must be stored in a format with the file extension .iq.tar. For a detailed description see Chapter C, "I/Q Data File Format (iq-tar)", on page 225.



An application note on converting Rohde & Schwarz I/Q data files is available from the Rohde & Schwarz website:

1EF85: Converting R&S I/Q data files

When using input from an I/Q data file, the [RUN SINGLE] function starts a single measurement (i.e. analysis) of the stored I/Q data, while the [RUN CONT] function repeatedly analyzes the same data from the file.

# 4.4 I/Q Data Import and Export

Baseband signals mostly occur as so-called complex baseband signals, i.e. a signal representation that consists of two channels; the in phase (I) and the quadrature (Q)

I/Q Data Import and Export

channel. Such signals are referred to as I/Q signals. The complete modulation information and even distortion that originates from the RF, IF or baseband domains can be analyzed in the I/Q baseband.

Importing and exporting I/Q signals is useful for various applications:

- Generating and saving I/Q signals in an RF or baseband signal generator or in external software tools to analyze them with the R&S ZNL later
- Capturing and saving I/Q signals with an RF or baseband signal analyzer to analyze them with the R&S ZNL or an external software tool later

As opposed to storing trace data, which may be averaged or restricted to peak values, I/Q data is stored as it was captured, without further processing. The data is stored as complex values in 32-bit floating-point format. Multi-channel data is not supported. The I/Q data is stored in a format with the file extension .iq.tar.



An application note on converting Rohde & Schwarz I/Q data files is available from the Rohde & Schwarz website:

1EF85: Converting R&S I/Q data files

The import and export functions are available in the "Save/Recall" menu which is displayed when you select the ■ "Save" or ▼ "Open" icon in the toolbar (see Chapter 5.2, "Import/Export Functions", on page 30).

Configuration Overview

# 5 Configuration

Access: [MODE] > "I/Q Analyzer"

The I/Q Analyzer is a special application on the R&S ZNL.

For details see the "Operating Modes, Applications, Channel Setups, and Result Displays" chapter in the R&S ZNL User Manual.

When you switch to an I/Q Analyzer channel setup the first time, a set of parameters is passed on from the currently active application. After initial setup, the parameters for the channel setup are stored upon exiting and restored upon re-entering the channel setup. Thus, you can switch between applications quickly and easily.

When you activate a channel setup for the I/Q Analyzer application, data acquisition from the input signal is started automatically with the default configuration. The "I/Q Analyzer" menu is displayed and provides access to the most important configuration functions.

The remote commands required to perform these tasks are described in Chapter 9, "Remote Commands to Perform Measurements with I/Q Data", on page 100.



# Importing and Exporting I/Q Data

The I/Q data to be evaluated in the I/Q Analyzer application can not only be captured by the I/Q Analyzer itself, it can also be imported to the R&S ZNL, provided it has the correct format. Furthermore, the captured I/Q data from the I/Q Analyzer can be exported for further analysis in external applications.

For details see Chapter 4.4, "I/Q Data Import and Export", on page 26.

Configuration Overview	28
	30
	ing Data Output33
	42
	46
	48
Data Acquisition and Bandwidth	Settings51
	57
	57

# 5.1 Configuration Overview



Access: all menus

Throughout the channel setup configuration, an overview of the most important currently defined settings is provided in the "Overview".

Configuration Overview



# Multiple access paths to functionality

The easiest way to configure a channel setup is via the "Overview" dialog box, which is available from all menus.

Alternatively, you can access the individual dialog boxes from the corresponding menu items, or via tools in the toolbars, if available.

In this documentation, only the most convenient method of accessing the dialog boxes is indicated - usually via the "Overview".



Figure 5-1: Configuration Overview for I/Q Analyzer Master

In addition to the main measurement settings, the "Overview" provides quick access to the main settings dialog boxes. The individual configuration steps are displayed in the order of the data flow. Thus, you can easily configure an entire channel setup from input over processing to output and analysis by stepping through the dialog boxes as indicated in the "Overview".

The "Overview" for the I/Q Analyzer provides quick access to the following configuration dialog boxes (listed in the recommended order of processing):

- Input settings
   See Chapter 5.3.1, "Radio Frequency Input", on page 33
- Amplitude settings
   See Chapter 5.4, "Amplitude", on page 42
- Frequency settings
   See Chapter 5.5, "Frequency Settings", on page 46
- Optionally, Trigger/Gate settings
   See Chapter 5.6, "Trigger Settings", on page 48
- 5. Bandwidth settings

Import/Export Functions

See Chapter 5.7, "Data Acquisition and Bandwidth Settings", on page 51

Analysis settings and functionsSee Chapter 6, "Analysis", on page 61

Display configuration
 See Chapter 5.8, "Display Configuration", on page 57

# To configure settings

Select any button in the "Overview" to open the corresponding dialog box.
Select a setting in the channel bar (at the top of the channel setup tab) to change a specific setting.

For step-by-step instructions on configuring I/Q Analyzer measurements, see Chapter 7, "How to Perform Measurements in the I/Q Analyzer Application", on page 96.

# **Preset Channel Setup**

Select the "Preset Channel" button in the lower left-hand corner of the "Overview" to restore all measurement settings in the current channel setup to their default values.

Do not confuse the "Preset Channel" button with the [Preset] *key*, which restores the entire instrument to its default values and thus closes **all channel setups** on the R&S ZNL (except for the default channel setup)!

# Remote command:

SYSTem: PRESet: CHANnel [: EXEC] on page 109

#### Specifics for

The channel setup may contain several windows for different results. Thus, the settings indicated in the "Overview" and configured in the dialog boxes vary depending on the selected window.

Select an active window from the "Specifics for" selection list that is displayed in the "Overview" and in all window-specific configuration dialog boxes.

The "Overview" and dialog boxes are updated to indicate the settings for the selected window.

# 5.2 Import/Export Functions



Access: "Save"/ "Open" icon in the toolbar > "Import" / "Export"



The R&S ZNL provides various evaluation methods for the results of the performed measurements. However, you may want to evaluate the data with further, external applications. In this case, you can export the measurement data to a standard format file (ASCII or XML). Some of the data stored in these formats can also be re-imported to the R&S ZNL for further evaluation later, for example in other applications.

The following data types can be exported (depending on the application):

- Trace data
- Table results, such as result summaries, marker peak lists etc.

Import/Export Functions

• I/Q data

The following data types can be imported (depending on the application):

I/Q data



I/Q data can only be imported and exported in applications that process I/Q data, such as the I/Q Analyzer or optional applications.

See the corresponding user manuals for those applications for details.



These functions are only available if no measurement is running.

Import	31
Export	
L Export Trace to ASCII File	31
L File Type	
L Decimal Separator	
L File Explorer	
L Trace Export Configuration	
L I/Q Export	
L File Explorer	

# ☐ Import

Access: "Save/Recall" > Import

Provides functions to import data.

# Export


Access: "Save/Recall" > Export

Opens a submenu to configure data export.

# **Export Trace to ASCII File ← Export**

Saves the selected trace or all traces in the currently active result display to the specified file and directory in the selected ASCII format.

Import/Export Functions



# Remote command:

MMEMory:STORe<n>:TRACe on page 215

# File Type ← Export Trace to ASCII File ← Export

Determines the format of the ASCII file to be imported or exported.

Depending on the external program in which the data file was created or is evaluated, a comma-separated list (CSV) or a plain data format (DAT) file is required.

#### Remote command:

FORMat:DEXPort:FORMat on page 214

# **Decimal Separator** ← **Export Trace to ASCII File** ← **Export**

Defines the decimal separator for floating-point numerals for the data export/import files. Evaluation programs require different separators in different languages.

#### Remote command:

FORMat:DEXPort:DSEParator on page 214

# File Explorer ← Export Trace to ASCII File ← Export

Opens the Microsoft Windows File Explorer.

Receiving Data Input and Providing Data Output

Remote command: not supported

# **Trace Export Configuration** ← **Export**

Opens the "Traces" dialog box to configure the trace and data export settings.

#### I/Q Export ← Export

Opens a file selection dialog box to define an export file name to which the I/Q data is stored. This function is only available in single sweep mode.

It is not available in the Spectrum application, only in applications that process I/Q data, such as the I/Q Analyzer or optional applications.

For details, see the description in the R&S ZNL I/Q Analyzer User Manual ("Importing and Exporting I/Q Data").

**Note:** Storing large amounts of I/Q data (several Gigabytes) can exceed the available (internal) storage space on the R&S ZNL. In this case, it can be necessary to use an external storage medium.

#### Remote command:

MMEMory:STORe<n>:IQ:STATe on page 218
MMEMory:STORe<n>:IQ:COMMent on page 217

# File Explorer ← I/Q Export ← Export

Opens the Microsoft Windows File Explorer.

Remote command: not supported

# 5.3 Receiving Data Input and Providing Data Output


The R&S ZNL can analyze signals from different input sources and provide various types of output (such as noise source control signals).

•	Radio Frequency Input	33
•	Power Sensors	35
	Output Settings	11

# 5.3.1 Radio Frequency Input

Access: "Overview" > "Input" > "Input Source" > "RadioFrequency"

Receiving Data Input and Providing Data Output





# **RF Input Protection**

The RF input connector of the R&S ZNL must be protected against signal levels that exceed the ranges specified in the data sheet. Therefore, the R&S ZNL is equipped with an overload protection mechanism. This mechanism becomes active as soon as the power at the input mixer exceeds the specified limit. It ensures that the connection between RF input and input mixer is cut off.

When the overload protection is activated, an error message is displayed in the status bar ("INPUT OVLD"), and a message box informs you that the RF Input was disconnected. Furthermore, a status bit (bit 3) in the STAT: QUES: POW status register is set. In this case you must decrease the level at the RF input connector and then close the message box. Then measurement is possible again. Reactivating the RF input is also possible via the remote command INPut<ip>:ATTenuation: PROTection: RESet.



The power sensor functions are described in the R&S ZNL User Manual.

Radio Frequency State	3
Impedance	34

# **Radio Frequency State**

Activates input from the "RF Input" connector.

# Remote command:

INPut<ip>:SELect on page 111

# **Impedance**

For some measurements, the reference impedance for the measured levels of the R&S ZNL can be set to 50  $\Omega$  or 75  $\Omega$ .

Receiving Data Input and Providing Data Output

Select 75  $\Omega$  if the 50  $\Omega$  input impedance is transformed to a higher impedance using a 75  $\Omega$  adapter of the RAZ type. (That corresponds to 25 $\Omega$  in series to the input impedance of the instrument.) The correction value in this case is 1.76 dB = 10 log (75 $\Omega$ / 50 $\Omega$ ).

This value also affects the unit conversion (see "Reference Level" on page 43).

# Remote command:

INPut<ip>: IMPedance on page 111

# 5.3.2 Power Sensors

The R&S ZNL can also analyze data from a connected power sensor.



The "Sensor" connector is provided by the "Additional Interfaces" option R&S FPL1-B5. Additionally, the power sensor measurement requires the option R&S FPL1-K9.

#### 5.3.2.1 Basics on Power Sensors

For precise power measurement, up to 4 power sensors can be connected to the instrument via the optional power sensor interface (on the rear panel) or the USB connectors. Both manual operation and remote control are supported.



For a detailed list of supported sensors, see the data sheet.




Figure 5-2: Power sensor support – standard test setup



# Using the power sensor with several applications

The power sensor cannot be used from the R&S ZNL firmware and the R&S Power Viewer Plus (virtual power meter for displaying results of the R&S NRP power sensors) simultaneously.

Receiving Data Input and Providing Data Output

# Result display

The results of the power sensor measurements are displayed in the marker table. For each power sensor, a row is inserted. The sensor index is indicated in the "Type" column.




# 5.3.2.2 Power Sensor Settings


Access: "Overview" > "Input" > "Power Sensor" tab



The power sensor measurement requires the option R&S FPL1-K9.

Each sensor is configured on a separate tab.





Receiving Data Input and Providing Data Output

#### State

Switches the power measurement for all power sensors on or off. Note that in addition to this general setting, each power sensor can be activated or deactivated individually by the Select setting on each tab. However, the general setting overrides the individual settings.

#### Remote command:

```
[SENSe:]PMETer[:STATe] on page 120
```

# **Continuous Value Update**

If activated, the power sensor data is updated continuously during a sweep with a long sweep time, and even after a single sweep has completed.

This function cannot be activated for individual sensors.

#### Remote command:

```
[SENSe:]PMETer:UPDate[:STATe] on page 120
```

#### Select

Selects the individual power sensor for usage if power measurement is generally activated (State function).

The detected **serial numbers** of the power sensors connected to the instrument are provided in a selection list. For each of the four available power sensor indexes ("Power Sensor 1"..."Power Sensor 4"), which correspond to the tabs in the configuration dialog, one of the detected serial numbers can be assigned. The physical sensor is thus assigned to the configuration setting for the selected power sensor index.

By default, serial numbers not yet assigned are automatically assigned to the next free power sensor index for which "Auto Assignment" is selected.

Alternatively, you can assign the sensors manually by deactivating the "Auto" option and selecting a serial number from the list.

# Remote command:

```
[SENSe:]PMETer[:STATe] on page 120
SYSTem:COMMunicate:RDEVice:PMETer:DEFine on page 113
SYSTem:COMMunicate:RDEVice:PMETer:CONFigure:AUTO[:STATe]
on page 113
SYSTem:COMMunicate:RDEVice:PMETer:COUNt? on page 113
```

#### **Zeroing Power Sensor**

Starts zeroing of the power sensor.

For details on the zeroing process refer to the R&S ZNL User Manual.

# Remote command:

```
CALibration: PMETer: ZERO: AUTO ONCE on page 115
```

# **Frequency Manual**

Defines the frequency of the signal to be measured. The power sensor has a memory with frequency-dependent correction factors. This allows extreme accuracy for signals of a known frequency.

# Remote command:

```
[SENSe:] PMETer:FREQuency on page 117
```

Receiving Data Input and Providing Data Output

# **Frequency Coupling**

Selects the coupling option. The frequency can be coupled automatically to the center frequency of the instrument or to the frequency of marker 1.

#### Remote command:

```
[SENSe:] PMETer:FREQuency:LINK on page 117
```

#### Unit/Scale

Selects the unit with which the measured power is to be displayed. Available units are dBm, dB, W and %.

If dB or % is selected, the display is relative to the reference value that is defined with either the "Meas -> Ref" setting or the "Reference Value" setting.

## Remote command:

```
UNIT<n>:PMETer:POWer on page 120
UNIT<n>:PMETer:POWer:RATio on page 121
```

## Meas Time/Average

Selects the measurement time or switches to manual averaging mode. In general, results are more precise with longer measurement times. The following settings are recommended for different signal types to obtain stable and precise results:

"Short" Stationary signals with high power (> -40dBm), because they require

only a short measurement time and short measurement time provides

the highest repetition rates.

"Normal" Signals with lower power or modulated signals

"Long" Signals at the lower end of the measurement range (<-50 dBm) or

Signals with lower power to minimize the influence of noise

"Manual" Manual averaging mode. The average count is set with the Average

Count (Number of Readings) setting.

#### Remote command:

```
[SENSe:]PMETer:MTIMe on page 118
[SENSe:]PMETer:MTIMe:AVERage[:STATe] on page 119
```

#### **Setting the Reference Level from the Measurement Meas -> Ref**

Sets the currently measured power as a reference value for the relative display. The reference value can also be set manually via the Reference Value setting.

# Remote command:

```
CALCulate<n>:PMETer:RELative[:MAGNitude]:AUTO ONCE on page 115
```

# **Reference Value**

Defines the reference value in dBm used for relative power meter measurements.

#### Remote command:

```
CALCulate<n>:PMETer:RELative[:MAGNitude] on page 115
```

# **Use Ref Level Offset**

If activated, takes the reference level offset defined for the analyzer into account for the measured power (see "Shifting the Display (Offset)" on page 43).

If deactivated, takes the Sensor Level Offset into account.

Receiving Data Input and Providing Data Output

#### Remote command:

```
[SENSe:] PMETer:ROFFset[:STATe] on page 119
```

#### Sensor Level Offset

Takes the specified offset into account for the measured power. Only available if Use Ref Level Offset is disabled.

#### Remote command:

```
[SENSe:]PMETer:SOFFset on page 119
```

## **Average Count (Number of Readings)**

Defines the number of readings (averages) to be performed after a single sweep has been started. This setting is only available if manual averaging is selected (Meas Time/Average setting).

The values for the average count range from 0 to 256 in binary steps (1, 2, 4, 8, ...). For average count = 0 or 1, one reading is performed. The general averaging and sweep count for the trace are independent from this setting.

Results become more stable with extended average, particularly if signals with low power are measured. This setting can be used to minimize the influence of noise in the power sensor measurement.

#### Remote command:

```
[SENSe:]PMETer:MTIMe:AVERage:COUNt on page 118
```

# **Duty Cycle**

Sets the duty cycle to a percent value for the correction of pulse-modulated signals and activates the duty cycle correction. With the correction activated, the sensor calculates the signal pulse power from this value and the mean power.

# Remote command:

```
[SENSe:]PMETer:DCYCle[:STATe] on page 116
[SENSe:]PMETer:DCYCle:VALue on page 117
```

# 5.3.2.3 How to Work With a Power Sensor

The following step-by-step instructions demonstrate how to set up a power sensor. For details on individual functions and settings see Chapter 5.3.2.2, "Power Sensor Settings", on page 36.

The remote commands required to perform these tasks are described in Chapter 9.4.1.3, "Working with Power Sensors", on page 112.

# How to Set Up a Power Sensor

Up to 4 external power sensors can be configured separately and used for precise power measurement. All power sensors can be activated and deactivated individually.

The following procedure describes in detail how to configure and activate power sensors.

- 1. To display the "Power Sensor" tab of the "Input" dialog box, do one of the following:
  - Select "Input" from the "Overview".

Receiving Data Input and Providing Data Output

- Select the [INPUT/OUTPUT] key and then the "PowerSensorConfig" softkey.
- 2. Select the tab for the power sensor index you want to configure, e.g. "Power Sensor 1".
- Press "Select" to analyze the power sensor data according to the current configuration when power measurement is activated.
- 4. From the selection list with serial numbers of connected power sensors, select the sensor you want to configure.
  - To have newly connected power sensors assigned to a tab automatically (default), select "Auto".
- 5. Define the frequency of the signal whose power you want to measure.
  - a) To define the frequency manually, select "Frequency Manual" and enter a frequency.
  - b) To determine the frequency automatically, select "Frequency Coupling" and then either "Center", to use the center frequency, or "Marker", to use the frequency defined by marker 1.
- 6. Select the unit for the power result display.
- Select the measurement time for which the average is calculated, or define the number of readings to average. To define the number of readings to be taken into account manually, select "Manual" and enter the number in the "Number of Readings" field.
- 8. To activate the duty cycle correction, select "DutyCycle" and enter a percentage as the correction value.
- 9. If you selected "dB" or "%" as units (relative display), define a reference value:
  - To set the currently measured power as a reference value, press the "Meas -> Ref" button.
  - b) Alternatively, enter a value manually in the "Reference Value" field.
  - c) Optionally, select the "Use Ref Level Offset" option to take the reference level offset set for the analyzer into account for the measured power.
- 10. If necessary, repeat steps 3-10 for another power sensor.
- 11. Set the "Power Sensor State" at the top of the "Power Sensor" tab to "On" to activate power measurement for the selected power sensors.

The results of the power measurement are displayed in the marker table (Function: "Sensor <1...4>").

#### How to Zero the Power Sensor

- 1. To display the "Power Sensor" tab of the "Input" dialog box, do one of the following:
  - Select "Input" from the "Overview".
  - Select the [INPUT/OUTPUT] key and then the "PowerSensorConfig" softkey.
- 2. Select the tab that is assigned to the power sensor you want to zero.

Receiving Data Input and Providing Data Output


- Press the "Zeroing Power Sensor" button.
   A dialog box is displayed that prompts you to disconnect all signals from the input of the power sensor.
- 4. Disconnect all signals sending input to the power sensor and press [ENTER] to continue.
- Wait until zeroing is complete.
   A corresponding message is displayed.

# 5.3.3 Output Settings

Access: "Overview" > "Output"

The R&S ZNL can provide signals to different output connectors.

For details on connectors, refer to the R&S ZNL Getting Started manual, "Front / Rear Panel View" chapters.



Noise Source Control......41

# **Noise Source Control**

The R&S ZNL provides a connector ("NOISE SOURCE CONTROL") with a 28 V voltage supply for an external noise source. By switching the supply voltage for an external noise source on or off in the firmware, you can enable or disable the device as required.

External noise sources are useful when you are measuring power levels that fall below the noise floor of the R&S ZNL itself, for example when measuring the noise level of an amplifier.

In this case, you can first connect an external noise source (whose noise power level is known in advance) to the R&S ZNL and measure the total noise power. From this value you can determine the noise power of the R&S ZNL. Then when you measure the power level of the actual DUT, you can deduct the known noise level from the total power to obtain the power level of the DUT.

# Remote command:

DIAGnostic:SERVice:NSOurce on page 121

Amplitude

# 5.4 Amplitude

Access: "Overview" > "Amplitude"

Amplitude settings are identical to the Spectrum application, except for a new scaling function for I/Q Vector and Real/Imag results (see "Y-Axis Max" on page 46).

For background information on amplitude settings see the R&S ZNL User Manual.




The "Auto Settings" are described in Chapter 5.9, "Adjusting Settings Automatically", on page 57.

# 5.4.1 Amplitude Settings

Access: "Overview" > "Amplitude"

Amplitude settings determine how the R&S ZNL must process or display the expected input power levels.



Referer	nce Level	43
L	Shifting the Display (Offset)	43
	- Unit	
	Setting the Reference Level Automatically (Auto Level)	
	ation Mode / Value	
Impeda	ince	44
Impeda	INCE	44

**Amplitude** 

#### Reference Level

Defines the expected maximum reference level. Signal levels above this value may not be measured correctly. This is indicated by an "IF Overload" status display.

The reference level can also be used to scale power diagrams; the reference level is then used as the maximum on the y-axis.

Since the hardware of the R&S ZNL is adapted according to this value, it is recommended that you set the reference level close above the expected maximum signal level. Thus you ensure an optimum measurement (no compression, good signal-to-noise ratio).

# Remote command:

DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RLEVel on page 123

## Shifting the Display (Offset) ← Reference Level

Defines an arithmetic level offset. This offset is added to the measured level. In some result displays, the scaling of the y-axis is changed accordingly.

Define an offset if the signal is attenuated or amplified before it is fed into the R&S ZNL so the application shows correct power results. All displayed power level results are shifted by this value.

The setting range is ±200 dB in 0.01 dB steps.

Note, however, that the *internal* reference level (used to adjust the hardware settings to the expected signal) ignores any "Reference Level Offset". Thus, it is important to keep in mind the actual power level the R&S ZNL must handle. Do not rely on the displayed reference level (internal reference level = displayed reference level - offset).

# Remote command:

DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RLEVel:OFFSet on page 124

#### Unit ← Reference Level

The R&S ZNL measures the signal voltage at the RF input.

The following units are available and directly convertible:

- dBm
- dBmV
- dBµV
- dBµA
- dBpW
- Volt
- Ampere
- Watt

#### Remote command:

INPut<ip>:IMPedance on page 111
CALCulate<n>:UNIT:POWer on page 123

# Setting the Reference Level Automatically (Auto Level) ← Reference Level

Automatically determines a reference level which ensures that no overload occurs at the R&S ZNL for the current input data. At the same time, the internal attenuators are adjusted so the signal-to-noise ratio is optimized, while signal compression and clipping are minimized.

**Amplitude** 

To determine the required reference level, a level measurement is performed on the R&S ZNL.

If necessary, you can optimize the reference level further. Decrease the attenuation level manually to the lowest possible value before an overload occurs, then decrease the reference level in the same way.

You can change the measurement time for the level measurement if necessary (see "Changing the Automatic Measurement Time (MeastimeManual)" on page 59).

# Remote command:

[SENSe:]ADJust:LEVel on page 144

#### **Attenuation Mode / Value**

The RF attenuation can be set automatically as a function of the selected reference level (Auto mode). This ensures that no overload occurs at the RF Input connector for the current reference level. It is the default setting.

In "Manual" mode, you can set the RF attenuation in 10 dB steps down to 0 dB. Other entries are rounded to the next integer value. The range is specified in the data sheet. If the defined reference level cannot be set for the defined RF attenuation, the reference level is adjusted accordingly and the warning "limit reached" is displayed.

**NOTICE!** Risk of hardware damage due to high power levels. When decreasing the attenuation manually, ensure that the power level does not exceed the maximum level allowed at the RF input, as an overload may lead to hardware damage.

#### Remote command:

```
INPut<ip>:ATTenuation on page 124
INPut<ip>:ATTenuation:AUTO on page 125
```

## **Impedance**

For some measurements, the reference impedance for the measured levels of the R&S ZNL can be set to 50  $\Omega$  or 75  $\Omega$ .

Select 75  $\Omega$  if the 50  $\Omega$  input impedance is transformed to a higher impedance using a 75  $\Omega$  adapter of the RAZ type. (That corresponds to 25 $\Omega$  in series to the input impedance of the instrument.) The correction value in this case is 1.76 dB = 10 log (75 $\Omega$ / 50 $\Omega$ ).

This value also affects the unit conversion (see "Reference Level" on page 43).

#### Remote command:

```
INPut<ip>:IMPedance on page 111
```


# 5.4.2 Scaling the Y-Axis

The individual scaling settings that affect the vertical axis are described here.

```
Access: "Overview" > "Amplitude" > "Scale" tab
```

Or: [AMPT] > "ScaleConfig"

Amplitude



Range	45
Ref Level Position.	45
Scaling	45
Y-Axis Max	

# Range

Defines the displayed y-axis range in dB.

The default value is 100 dB.

Remote command:

DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe] on page 125

#### **Ref Level Position**

Defines the reference level position, i.e. the position of the maximum AD converter value on the level axis in %.

0 % corresponds to the lower and 100 % to the upper limit of the diagram.

Values from -120 % to +600 % are available. Larger values are useful for small scales, such as a power range of 10 dB or 20 dB, and low signal levels, for example 60 dB below the reference level. In this case, large reference level position values allow you to see the trace again.

Remote command:

DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RPOSition on page 126

#### Scaling

Defines the scaling method for the y-axis.

Frequency Settings

"Logarithmic" Logarithmic scaling (only available for logarithmic units - dB..., and A,

V, Watt)

"Linear with

Linear scaling in the unit of the measured signal

Unit"

"Linear Per- Linear scaling in percentages from 0 to 100

cent"

"Absolute" The labeling of the level lines refers to the absolute value of the refer-

ence level (not available for "Linear Percent")

"Relative" The scaling is in dB, relative to the reference level (only available for

logarithmic units - dB...). The upper line of the grid (reference level) is

always at 0 dB.

#### Remote command:

```
DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing on page 127
DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y[:SCALe]:MODE
on page 126
```

#### Y-Axis Max

Defines the maximum value of the y-axis in the currently selected diagram in either direction (in Volts). Thus, the y-axis scale starts at -<Y-Axis Max> and ends at +<Y-Axis Max>.

The maximum y-axis value depends on the current reference level. If the reference level is changed, the "Y-Axis Max" value is automatically set to the new reference level (in V).

This command is only available if the evaluation mode for the I/Q Analyzer is set to "I/Q-Vector" or "Real/Imag (I/Q)".


#### Remote command:

```
DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe] on page 125
```

# 5.5 Frequency Settings

Access: "Overview" > "Frequency"

Frequency Settings



Center Frequency	47
Center Frequency Stepsize	47
Frequency Offset	47

## **Center Frequency**

Defines the center frequency of the signal in Hertz.

The allowed range of values for the center frequency depends on the frequency span.

$$span > 0: span_{min}/2 \le f_{center} \le f_{max} - span_{min}/2$$

f<sub>max</sub> and span<sub>min</sub> depend on the instrument and are specified in the data sheet.

# Remote command:

[SENSe:] FREQuency:CENTer on page 128

# **Center Frequency Stepsize**

Defines the step size by which the center frequency is increased or decreased using the arrow keys.

The step size can be coupled to another value or it can be manually set to a fixed value.

"= Center" Sets the step size to the value of the center frequency. The used

value is indicated in the "Value" field.

"Manual" Defines a fixed step size for the center frequency. Enter the step size

in the "Value" field.

#### Remote command:

[SENSe:] FREQuency:CENTer:STEP on page 128

# **Frequency Offset**

Shifts the displayed frequency range along the x-axis by the defined offset.

This parameter has no effect on the instrument's hardware, or on the captured data or on data processing. It is simply a manipulation of the final results in which absolute frequency values are displayed. Thus, the x-axis of a spectrum display is shifted by a constant offset if it shows absolute frequencies. However, if it shows frequencies relative to the signal's center frequency, it is not shifted.

**Trigger Settings** 

A frequency offset can be used to correct the display of a signal that is slightly distorted by the measurement setup, for example.

The allowed values range from -1 THz to 1 THz. The default setting is 0 Hz.

Remote command:

[SENSe:] FREQuency:OFFSet on page 129

# 5.6 Trigger Settings

**Access**: "Overview" > "Trigger"( > "Trigger In/Out")

Trigger settings determine when the input signal is measured.





Conventional gating as in the Spectrum application is not available for the I/Q Analyzer; however, a special gating mode is available in remote control, see Chapter 9.4.4.2, "Configuring I/Q Gating", on page 133.

For step-by-step instructions on configuring triggered measurements, see the R&S ZNL User Manual.

Irigger Source	49
L Trigger Source	49
L Free Run	49
L ExternalTrigger 1	49
L IF Power	49
L I/Q Power	
L Time	
L Trigger Level	50
L Repetition Interval	
L Drop-Out Time	50
L Trigger Offset	50
L Hysteresis	50
L Trigger Holdoff	5′
L Slope	

**Trigger Settings** 

## **Trigger Source**

The trigger settings define the beginning of a measurement.

# **Trigger Source ← Trigger Source**

Selects the trigger source. If a trigger source other than "Free Run" is set, "TRG" is displayed in the channel bar and the trigger source is indicated.

#### Remote command:

TRIGger[:SEQuence]:SOURce on page 132

# Free Run ← Trigger Source ← Trigger Source

No trigger source is considered. Data acquisition is started manually or automatically and continues until stopped explicitly.

# Remote command:

TRIG: SOUR IMM, see TRIGger[:SEQuence]: SOURce on page 132

# **ExternalTrigger 1** ← **Trigger Source** ← **Trigger Source**

Data acquisition starts when the TTL signal fed into the trigger input connector of the R&S ZNL meets or exceeds the specified trigger level.

(See "Trigger Level" on page 50).

#### Remote command:

TRIG:SOUR EXT

See TRIGger [:SEQuence]:SOURce on page 132

## **IF Power** ← **Trigger Source** ← **Trigger Source**

The R&S ZNL starts capturing data as soon as the trigger level is exceeded around the third intermediate frequency.

For frequency sweeps, the third IF represents the start frequency. The trigger bandwidth at the third IF depends on the RBW and sweep type.

For measurements on a fixed frequency (e.g. zero span or I/Q measurements), the third IF represents the center frequency.

This trigger source is only available for RF input.

For details on available trigger levels and trigger bandwidths, see the data sheet.

#### Remote command:

TRIG:SOUR IFP, see TRIGger[:SEQuence]:SOURce on page 132

#### I/Q Power ← Trigger Source ← Trigger Source

This trigger source is only available in the I/Q Analyzer application and in applications that process I/Q data.

Triggers the measurement when the magnitude of the sampled I/Q data exceeds the trigger threshold.

The trigger bandwidth corresponds to the bandwidth setting for I/Q data acquisition.

## Remote command:

TRIG:SOUR IQP, see TRIGger[:SEQuence]:SOURce on page 132

# Time ← Trigger Source ← Trigger Source

Triggers in a specified "Repetition Interval" on page 50.

**Trigger Settings** 

# Remote command:

TRIG: SOUR TIME, see TRIGger[:SEQuence]: SOURce on page 132

# **Trigger Level ← Trigger Source**

Defines the trigger level for the specified trigger source.

For details on supported trigger levels, see the data sheet.

# Remote command:

```
TRIGger[:SEQuence]:LEVel:IFPower on page 131
TRIGger[:SEQuence]:LEVel:IQPower on page 131
TRIGger[:SEQuence]:LEVel[:EXTernal<port>] on page 131
```

# **Repetition Interval** ← **Trigger Source**

Defines the repetition interval for a time trigger. The shortest interval is 2 ms.

The repetition interval should be set to the exact pulse period, burst length, frame length or other repetitive signal characteristic.

#### Remote command:

```
TRIGger[:SEQuence]:TIME:RINTerval on page 133
```

# **Drop-Out Time** ← **Trigger Source**

Defines the time the input signal must stay below the trigger level before triggering again.

# Remote command:

```
TRIGger[:SEQuence]:DTIMe on page 129
```

# **Trigger Offset** ← **Trigger Source**

Defines the time offset between the trigger event and the start of the sweep.

Offset > 0:	Start of the sweep is delayed
Offset < 0:	Sweep starts earlier (pretrigger)  Only possible for zero span (e.g. I/Q Analyzer application) and gated trigger switched off  Maximum allowed range limited by the sweep time:  Pretrigger <sub>max</sub> = sweep time <sub>max</sub>

**Tip:** To determine the trigger point in the sample (for "External" or "IF Power" trigger source), use the TRACe: IQ: TPISample? command.

For the "Time" trigger source, this function is not available.

#### Remote command:

```
TRIGger[:SEQuence]:HOLDoff[:TIME] on page 130
```

#### Hysteresis ← Trigger Source

Defines the distance in dB to the trigger level that the trigger source must exceed before a trigger event occurs. Setting a hysteresis avoids unwanted trigger events caused by noise oscillation around the trigger level.

This setting is only available for "IF Power" trigger sources. The range of the value is between 3 dB and 50 dB with a step width of 1 dB.

Data Acquisition and Bandwidth Settings

#### Remote command:

TRIGger[:SEQuence]:IFPower:HYSTeresis on page 130

# **Trigger Holdoff** ← **Trigger Source**

Defines the minimum time (in seconds) that must pass between two trigger events. Trigger events that occur during the holdoff time are ignored.

#### Remote command:

TRIGger[:SEQuence]:IFPower:HOLDoff on page 130

# Slope ← Trigger Source

For all trigger sources except time, you can define whether triggering occurs when the signal rises to the trigger level or falls down to it.

For gated measurements in "Edge" mode, the slope also defines whether the gate starts on a falling or rising edge.

#### Remote command:

TRIGger[:SEQuence]:SLOPe on page 132

# 5.7 Data Acquisition and Bandwidth Settings

Access: "Overview" > "Bandwidth"

•	Data Acquisition	5	1
•	Sweep Settings	5	5

# 5.7.1 Data Acquisition

Access: "Overview" > "Bandwidth" > "Data Acquisition" tab

The data acquisition settings define which parts of the input signal are captured for further evaluation in the applications.

Data Acquisition and Bandwidth Settings




Figure 5-3: Data acquisition settings with advanced FFT parameters

Sample Rate	52
Analysis Bandwidth	
Meas Time	
Record Length	53
Swap I/Q.	53
RBW	
Advanced FFT mode / Basic Settings	54
L TransformationAlgorithm	54
L FFT Length	54
L Window Function	
L Window Overlap	55
L Window Length	

# Sample Rate

Defines the I/Q data sample rate of the R&S ZNL. This value is dependent on the defined Analysis Bandwidth and the defined signal source.

sample rate = analysis bandwidth / 0.8

Remote command:

TRACe: IQ: SRATe on page 141

# **Analysis Bandwidth**

Defines the flat, usable bandwidth of the final I/Q data. This value is dependent on the defined Sample Rate and the defined signal source.

analysis bandwidth = 0.8 \* sample rate

Remote command:

TRACe: IQ: BWIDth on page 139

Data Acquisition and Bandwidth Settings

#### **Meas Time**

Defines the I/Q acquisition time. By default, the measurement time is calculated as the number of I/Q samples ("Record Length") divided by the sample rate. If you change the measurement time, the Record Length is automatically changed, as well.

#### Remote command:

```
[SENSe:] SWEep:TIME on page 157
```

## **Record Length**

Defines the number of I/Q samples to record. By default, the number of sweep points is used. The record length is calculated as the measurement time multiplied by the sample rate. If you change the record length, the Meas Time is automatically changed, as well.

**Note:** For the I/Q vector result display, the number of I/Q samples to record ("Record Length") must be identical to the number of trace points to be displayed ("Sweep Points"). Thus, the sweep points are not editable for this result display. If the "Record Length" is edited, the sweep points are adapted automatically.

#### Remote command:

```
TRACe: IQ: RLENgth on page 139
TRACe: IQ: SET on page 140
```

#### Swap I/Q

Activates or deactivates the inverted I/Q modulation. If the I and Q parts of the signal from the DUT are interchanged, the R&S ZNL can do the same to compensate for it.

On	I and Q signals are interchanged Inverted sideband, Q+j*I	
Off	I and Q signals are not interchanged  Normal sideband, I+j*Q	

# Remote command:

```
[SENSe:]SWAPiq on page 139
```

#### **RBW**

Defines the resolution bandwidth for Spectrum results. The available RBW values depend on the sample rate and record length.

```
(See Chapter 4.2.4, "Frequency Resolution of FFT Results - RBW", on page 24).
```

Depending on the selected RBW mode, the value is either determined automatically or can be defined manually. As soon as you enter a value in the input field, the RBW mode is changed to "Manual".

If the "Advanced Fourier Transformation Params" option is enabled, advanced FFT mode is selected and the RBW cannot be defined directly.

Note that the RBW is correlated with the Sample Rate and Record Length (and possibly the Window Function and Window Length). Changing any one of these parameters may cause a change to one or more of the other parameters. For more information see Chapter 4.2, "Basics on FFT", on page 20.

Data Acquisition and Bandwidth Settings

"Auto mode" (Default) The RBW is determined automatically depending on the

Sample Rate and Record Length.

"Manual mode" The RBW can be defined by the user.

The user-defined RBW is used and the Window Length (and possibly

Sample Rate) are adapted accordingly.

"Advanced This mode is used if the "Advanced Fourier Transformation Params"

FFT mode" option is enabled.

The RBW is determined by the advanced FFT parameters.

# Remote command:

```
[SENSe:]IQ:BWIDth:MODE on page 136
[SENSe:]IQ:BWIDth:RESolution on page 137
```

## Advanced FFT mode / Basic Settings

Shows or hides the "Advanced Fourier Transformation" parameters in the "Data Acquisition" dialog box.

Note that if the advanced FFT mode is used, the RBW settings are not available.

# $\textbf{TransformationAlgorithm} \leftarrow \textbf{Advanced FFT mode} \ / \ \textbf{Basic Settings}$

Defines the FFT calculation method.

"Single" One FFT is calculated for the entire record length; if the FFT Length

is larger than the record length, zeros are appended to the captured

data

"Averaging" Several overlapping FFTs are calculated for each record; the results

are combined to determine the final FFT result for the record. The number of FFTs to be averaged is determined by the Window Overlap

and the Window Length.

# Remote command:

```
[SENSe:] IQ:FFT:ALGorithm on page 137
```

# FFT Length ← Advanced FFT mode / Basic Settings

Defines the number of frequency points determined by each FFT calculation. The more points are used, the higher the resolution in the spectrum becomes, but the longer the calculation takes.

Note: If you enter the value manually, any integer value from 3 to 524288 is available.

# Remote command:

```
[SENSe:] IQ:FFT:LENGth on page 138
```

# Window Function ← Advanced FFT mode / Basic Settings

In the I/Q analyzer you can select one of several FFT window types.

The following window types are available:

- Blackman-Harris
- Flattop
- Gauss
- Rectangular
- 5-Term

Data Acquisition and Bandwidth Settings

#### Remote command:

[SENSe:]IQ:FFT:WINDow:TYPE on page 138

## Window Overlap ← Advanced FFT mode / Basic Settings

Defines the part of a single FFT window that is re-calculated by the next FFT calculation when using multiple FFT windows.

#### Remote command:

[SENSe:]IQ:FFT:WINDow:OVERlap on page 138

#### Window Length ← Advanced FFT mode / Basic Settings

Defines the number of samples to be included in a single FFT window in averaging mode. (In single mode, the window length corresponds to the "Record Length" on page 53.)


However, the window length may not be longer than the FFT Length.

#### Remote command:

[SENSe:]IQ:FFT:WINDow:LENGth on page 138

# 5.7.2 Sweep Settings

Access: "Overview" > "Bandwidth" > "Sweep" tab



Sweep Points	ა5
Sweep/Average Count5	56
Continuous Sweep / Run Cont5	
Single Sweep / Run Single5	
ContinueSingleSweep5	
Continuedingleoweep	,,

## **Sweep Points**

In the I/Q Analyzer application, a specific frequency bandwidth is swept for a specified measurement time. During this time, a defined number of samples (= "Record Length") are captured. These samples are then evaluated by the applications. Therefore, in this case the number of sweep points does not define the amount of data to be acquired, but rather the number of trace points that are evaluated and displayed in the result diagrams.

**Note:** For some result displays, the sweep points may not be editable as they are determined automatically, or restrictions may apply. For the I/Q vector result display, the number of I/Q samples to record ("Record Length") must be identical to the number

Data Acquisition and Bandwidth Settings

of trace points to be displayed ("Sweep Points"). Thus, the sweep points are not editable for this result display. If the "Record Length" is edited, the sweep points are adapted automatically. For record lengths outside the valid range of sweep points, i.e. less than 101 points or more than 100001 points, the diagram does not show valid results. Using fewer than 4096 sweep points with a detector other than "Auto Peak" may lead to wrong level results. For details see "Combining results - trace detector" on page 22.

#### Remote command:

[SENSe:]SWEep[:WINDow<n>]:POINts on page 156

# **Sweep/Average Count**

Defines the number of sweeps to be performed in the single sweep mode. Values from 0 to 200000 are allowed. If the values 0 or 1 are set, one sweep is performed.

The sweep count is applied to all the traces in all diagrams.

If the trace modes "Average", "Max Hold" or "Min Hold" are set, this value also determines the number of averaging or maximum search procedures.

In continuous sweep mode, if "Sweep Count" = 0 (default), averaging is performed over 10 sweeps. For "Sweep Count" =1, no averaging, maxhold or minhold operations are performed.

# Remote command:

```
[SENSe:]SWEep:COUNt on page 156
[SENSe:]AVERage<n>:COUNt on page 163
```

## Continuous Sweep / Run Cont

After triggering, starts the sweep and repeats it continuously until stopped. This is the default setting.

While the measurement is running, the "Continuous Sweep" softkey and the [RUN CONT] key are highlighted. The running measurement can be aborted by selecting the highlighted softkey or key again. The results are not deleted until a new measurement is started.

**Note:** Sequencer. If the Sequencer is active, the "Continuous Sweep" softkey only controls the sweep mode for the currently selected channel setup. However, the sweep mode only takes effect the next time the Sequencer activates that channel setup, and only for a channel-defined sequence. In this case, a channel setup in continuous sweep mode is swept repeatedly.

Furthermore, the [RUN CONT] key controls the Sequencer, not individual sweeps. [RUN CONT] starts the Sequencer in continuous mode.

#### Remote command:

INITiate<n>:CONTinuous on page 154

#### Single Sweep / Run Single

After triggering, starts the number of sweeps set in "Sweep Count". The measurement stops after the defined number of sweeps has been performed.

While the measurement is running, the "Single Sweep" softkey and the [RUN SINGLE] key are highlighted. The running measurement can be aborted by selecting the highlighted softkey or key again.

**Note:** Sequencer. If the Sequencer is active, the "Single Sweep" softkey only controls the sweep mode for the currently selected channel setup. However, the sweep mode

Adjusting Settings Automatically

only takes effect the next time the Sequencer activates that channel setup, and only for a channel-defined sequence. In this case, the Sequencer sweeps a channel setup in single sweep mode only once.

Furthermore, the [RUN SINGLE] key controls the Sequencer, not individual sweeps. [RUN SINGLE] starts the Sequencer in single mode.

If the Sequencer is off, only the evaluation for the currently displayed channel setup is updated.

For details on the Sequencer, see the R&S ZNL User Manual.

Remote command:

INITiate<n>[:IMMediate] on page 154

# ContinueSingleSweep

After triggering, repeats the number of sweeps set in "Sweep Count", without deleting the trace of the last measurement.

While the measurement is running, the "ContinueSingleSweep" softkey and the [RUN SINGLE] key are highlighted. The running measurement can be aborted by selecting the highlighted softkey or key again.

Remote command:

INITiate<n>:CONMeas on page 153

# 5.8 Display Configuration



Access: "Overview" > "Display Config"

The captured signal can be displayed using various evaluation methods. All evaluation methods available for the current application are displayed in the evaluation bar in SmartGrid mode.

For a description of the available evaluation methods see Chapter 3, "Measurement and Result Displays", on page 13.




Up to 6 evaluations can be displayed in the I/Q Analyzer at any time, including several graphical diagrams, marker tables or peak lists.

The selected evaluation method not only affects the result display in a window, but also the results of the trace data query in remote control (see TRACe < n > [:DATA]? on page 211).

# 5.9 Adjusting Settings Automatically

Access: "Overview" > "Amplitude"/"Frequency" > "Auto Settings"

Adjusting Settings Automatically



Some settings can be adjusted by the R&S ZNL automatically according to the current measurement settings. In order to do so, a measurement is performed. You can configure this measurement.



# Adjusting settings automatically during triggered measurements

When you select an auto adjust function, a measurement is performed to determine the optimal settings. If you select an auto adjust function for a triggered measurement, you are asked how the R&S ZNL should behave:

- (default:) The measurement for adjustment waits for the next trigger
- The measurement for adjustment is performed without waiting for a trigger.
   The trigger source is temporarily set to "Free Run". After the measurement is completed, the original trigger source is restored. The trigger level is adjusted as follows:
  - For IF Power and RF Power triggers:
     Trigger Level = Reference Level 15 dB
  - For Video trigger:Trigger Level = 85 %

#### Remote command:

[SENSe:] ADJust:CONFigure:TRIGger on page 144

Adjusting all Determinable Settings Automatically (Auto All)	. 58
Adjusting the Center Frequency Automatically (Auto Frequency)	
Setting the Reference Level Automatically (Auto Level)	59
Resetting the Automatic Measurement Time (MeastimeAuto)	59
Changing the Automatic Measurement Time (MeastimeManual)	
Upper Level Hysteresis	60
Lower Level Hysteresis	

# Adjusting all Determinable Settings Automatically (Auto All)

Activates all automatic adjustment functions for the current measurement settings.

This includes:

Adjusting Settings Automatically

- Auto Frequency
- Auto Level

# Remote command:

[SENSe:]ADJust:ALL on page 142

## Adjusting the Center Frequency Automatically (Auto Frequency)

The R&S ZNL adjusts the center frequency automatically.

The optimum center frequency is the frequency with the highest S/N ratio in the frequency span. As this function uses the signal counter, it is intended for use with sinusoidal signals.

#### Remote command:

[SENSe:] ADJust: FREQuency on page 144

## **Setting the Reference Level Automatically (Auto Level)**

Automatically determines a reference level which ensures that no overload occurs at the R&S ZNL for the current input data. At the same time, the internal attenuators are adjusted so the signal-to-noise ratio is optimized, while signal compression and clipping are minimized.

To determine the required reference level, a level measurement is performed on the R&S ZNL.

If necessary, you can optimize the reference level further. Decrease the attenuation level manually to the lowest possible value before an overload occurs, then decrease the reference level in the same way.

You can change the measurement time for the level measurement if necessary (see "Changing the Automatic Measurement Time (MeastimeManual)" on page 59).

#### Remote command:

[SENSe:]ADJust:LEVel on page 144

#### Resetting the Automatic Measurement Time (MeastimeAuto)

Resets the measurement duration for automatic settings to the default value.

#### Remote command:

[SENSe:] ADJust:CONFigure:DURation:MODE on page 143

# Changing the Automatic Measurement Time (MeastimeManual)

This function allows you to change the measurement duration for automatic setting adjustments. Enter the value in seconds.

**Note:** The maximum possible measurement duration depends on the currently selected measurement and the installed (optional) hardware. Thus, the measurement duration actually used to determine the automatic settings may be shorter than the value you define here.

# Remote command:

```
[SENSe:] ADJust:CONFigure:DURation:MODE on page 143 [SENSe:] ADJust:CONFigure:DURation on page 142
```

Adjusting Settings Automatically

# **Upper Level Hysteresis**

When the reference level is adjusted automatically using the Auto Level function, the internal attenuators are also adjusted. To avoid frequent adaptation due to small changes in the input signal, you can define a hysteresis. This setting defines an upper threshold the signal must exceed (compared to the last measurement) before the reference level is adapted automatically.

#### Remote command:

[SENSe:]ADJust:CONFigure:HYSTeresis:UPPer on page 144

# **Lower Level Hysteresis**

When the reference level is adjusted automatically using the Auto Level function, the internal attenuators are also adjusted. To avoid frequent adaptation due to small changes in the input signal, you can define a hysteresis. This setting defines a lower threshold the signal must fall below (compared to the last measurement) before the reference level is adapted automatically.

#### Remote command:

[SENSe:]ADJust:CONFigure:HYSTeresis:LOWer on page 143

**Trace Settings** 

# 6 Analysis

Access: "Overview" > "Analysis"

General result analysis settings concerning the trace, markers etc. are identical to the analysis functions in the Spectrum application, except for the lines and special marker functions, which are not available for I/Q data.

The remote commands required to perform these tasks are described in Chapter 6, "Analysis", on page 61.

•	Trace Settings	61
	Spectrogram Settings	
	Trace / Data Export Configuration	
•	Marker Usage	73

# 6.1 Trace Settings

Access: "Overview" > "Analysis" > "Traces"

Or: [TRACE] > Trace


You can configure the settings for up to 6 individual traces.



Trace data can also be exported to an ASCII file for further analysis. For details see Chapter 6.3, "Trace / Data Export Configuration", on page 70.

For I/Q Vector evaluation mode, only 1 trace is available and the detector is not editable.

**Trace Settings** 





# Trace 1/Trace 2/Trace 3/Trace 4/Trace 5/Trace 6

Selects the corresponding trace for configuration. The currently selected trace is highlighted.

# Remote command:

Selected via numeric suffix of:TRACe<1...6> commands

DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>[:STATe] on page 160

# TraceMode

Defines the update mode for subsequent traces.

"Clear/ Write"

Overwrite mode (default): the trace is overwritten by each sweep.

The maximum value is determined over several sweeps and displayed. The R&S ZNL saves each trace point in the trace memory only if the new value is greater than the previous one.

The minimum value is determined from several measurements and displayed. The R&S ZNL saves each trace point in the trace memory only if the new value is lower than the previous one.

"Average" The average is formed over several sweeps.

The Sweep/Average Count determines the number of averaging pro-

cedures.

**Trace Settings** 

"View" The current contents of the trace memory are frozen and displayed.

"Blank" Removes the selected trace from the display.

Remote command:

DISPlay[:WINDow<n>]:TRACe<t>:MODE on page 158

#### Detector

Defines the trace detector to be used for trace analysis.

The trace detector is used to combine multiple FFT window results to create the final spectrum. (Note: in previous versions of the R&S ZNL, the I/Q Analyzer always used the linear average detector.) If necessary, the trace detector is also used to reduce the number of calculated frequency points (defined by the FFT length) to the defined number of sweep points. By default, the Autopeak trace detector is used.

**Note:** Using a detector other than Auto Peak and fewer than 4096 sweep points may lead to wrong level results. For details see "Combining results - trace detector" on page 22.

"Auto" Selects the optimum detector for the selected trace and filter mode.

This is the default setting.

"Type" Defines the selected detector type.

# Remote command:

```
[SENSe:][WINDow<n>:]DETector<t>[:FUNCtion] on page 162
[SENSe:][WINDow<n>:]DETector<t>[:FUNCtion]:AUTO on page 162
```

#### Hold

If activated, traces in "Min Hold", "Max Hold" and "Average" mode are not reset after specific parameter changes have been made.

Normally, the measurement is started again after parameter changes, before the measurement results are analyzed (e.g. using a marker). In all cases that require a new measurement after parameter changes, the trace is reset automatically to avoid false results (e.g. with span changes). For applications that require no reset after parameter changes, the automatic reset can be switched off.

The default setting is off.

#### Remote command:

```
DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:MODE:HCONtinuous
on page 159
```

#### **Average Mode**

Defines the mode with which the trace is averaged over several sweeps.

This setting is generally applicable if trace mode "Average" is selected. For FFT sweeps, the setting also affects the VBW (regardless of whether or not the trace is averaged).

(See the chapter on ACLR power measurements in the R&S ZNL User Manual.)

How many sweeps are averaged is defined by the "Sweep/Average Count" on page 56.

**Trace Settings** 

"Linear" The power level values are converted into linear units prior to averag-

ing. After the averaging, the data is converted back into its original

unit.

"Logarithmic" For logarithmic scaling, the values are averaged in dBm. For linear

scaling, the behavior is the same as with linear averaging.

"Power" Activates linear power averaging.

The power level values are converted into unit Watt prior to averaging. After the averaging, the data is converted back into its original

unit.

Use this mode to average power values in Volts or Amperes correctly. In particular, for small VBW values (smaller than the RBW), use power averaging mode for correct power measurements in FFT

sweep mode.

# Remote command:

[SENSe:] AVERage<n>: TYPE on page 161

# **Predefined Trace Settings - Quick Config**

Commonly required trace settings have been predefined and can be applied very quickly by selecting the appropriate button.

Function	Trace Settings	
Preset All Traces	Trace 1:	Clear Write
	Traces 2-6:	Blank
Set Trace Mode	Trace 1:	Max Hold
Max   Avg   Min	Trace 2:	Average
	Trace 3:	Min Hold
	Traces 4-6:	Blank
Set Trace Mode	Trace 1:	Max Hold
Max   ClrWrite   Min	Trace 2:	Clear Write
	Trace 3:	Min Hold
	Traces 4-6:	Blank

# Trace 1/ Trace 2/ Trace 3/ Trace 4 (Softkeys)

Displays the "Traces" settings and focuses the "Mode" list for the selected trace.

# Remote command:

DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>[:STATe] on page 160

# **Copy Trace**

Access: "Overview" > "Analysis" > "Traces" > "Copy Trace"

Or: [TRACE] > "Copy Trace"

Copies trace data to another trace.

Spectrogram Settings

The first group of buttons (labeled "Trace 1" to "Trace 6") selects the source trace. The second group of buttons (labeled "Copy to Trace 1" to "Copy to Tace 6") selects the destination.

# Remote command:

TRACe<n>: COPY on page 163

# 6.2 Spectrogram Settings

Access: [TRACE] > "Spectrogram Config"

The individual settings available for spectrogram display are described here. For settings on color mapping, see Chapter 6.2.2, "Color Map Settings", on page 68.

Settings concerning the frames and how they are handled during a sweep are provided as additional sweep settings for spectrogram display.

See Chapter 5.7.2, "Sweep Settings", on page 55.


Search functions for spectrogram markers are described in Chapter 6.4.2.2, "Marker Search Settings for Spectrograms", on page 81.

# 6.2.1 General Spectrogram Settings

Access: [TRACE] > "Spectrogram Config"

This section describes general settings for spectrogram display.

Spectrogram Settings



State	66
3D Spectrogram State	66
Select Frame	67
History Depth	67
3-D Display Depth	67
Time Stamp	67
Color Mapping	67
Continuous Sweep / Run Cont	67
Single Sweep / Run Single	68
Clear Spectrogram	68

# **State**

Activates and deactivates a Spectrogram subwindow.

"On" Displays the Spectrogram as a subwindow in the original result dis-

play.

"Off" Closes the Spectrogram subwindow.

Remote command:

CALCulate<n>:SPECtrogram:LAYout on page 167

# **3D Spectrogram State**

Activates and deactivates a 3-dimensional spectrogram. As opposed to the common 2-dimensional spectrogram, the power is not only indicated by a color mapping, but also in a third dimension, the z-axis.

For details see the R&S ZNL User Manual.

R&S<sup>®</sup>ZNL Analysis

Spectrogram Settings

#### Remote command:

CALCulate<n>:SPECtrogram:THReedim[:STATe] on page 167

#### **Select Frame**

Selects a specific frame, loads the corresponding trace from the memory, and displays it in the Spectrum window.

Note that activating a marker or changing the position of the active marker automatically selects the frame that belongs to that marker.

This function is only available in single sweep mode or if the sweep is stopped, and only if a spectrogram is selected.

The most recent frame is number 0, all previous frames have a negative number.

For more details see the R&S ZNL User Manual.

#### Remote command:

CALCulate<n>:SPECtrogram:FRAMe:SELect on page 166

# **History Depth**

Sets the number of frames that the R&S ZNL stores in its memory.

The maximum number of frames depends on the "Sweep Points" on page 55.

For an overview of the maximum number of frames depending on the number of sweep points, see the R&S ZNL User Manual.

If the memory is full, the R&S ZNL deletes the oldest frames stored in the memory and replaces them with the new data.

#### Remote command:

CALCulate<n>:SPECtrogram:HDEPth on page 166

# 3-D Display Depth

Defines the number of frames displayed in a 3-dimensional spectrogram.

For details see the R&S ZNL User Manual.

# **Time Stamp**

Activates and deactivates the timestamp. The timestamp shows the system time while the measurement is running. In single sweep mode or if the sweep is stopped, the timestamp shows the time and date of the end of the sweep.

When active, the timestamp replaces the display of the frame number.

# Remote command:

```
CALCulate<n>:SPECtrogram:TSTamp[:STATe] on page 169 CALCulate<n>:SPECtrogram:TSTamp:DATA? on page 168
```

# **Color Mapping**

Opens the "Color Mapping" dialog.

For details see the R&S ZNL User Manual.

### Continuous Sweep / Run Cont

After triggering, starts the sweep and repeats it continuously until stopped. This is the default setting.

R&S<sup>®</sup>ZNL Analysis

Spectrogram Settings

While the measurement is running, the "Continuous Sweep" softkey and the [RUN CONT] key are highlighted. The running measurement can be aborted by selecting the highlighted softkey or key again. The results are not deleted until a new measurement is started.

**Note:** Sequencer. If the Sequencer is active, the "Continuous Sweep" softkey only controls the sweep mode for the currently selected channel setup. However, the sweep mode only takes effect the next time the Sequencer activates that channel setup, and only for a channel-defined sequence. In this case, a channel setup in continuous sweep mode is swept repeatedly.

Furthermore, the [RUN CONT] key controls the Sequencer, not individual sweeps. [RUN CONT] starts the Sequencer in continuous mode.

# Remote command:

INITiate<n>:CONTinuous on page 154

## Single Sweep / Run Single

After triggering, starts the number of sweeps set in "Sweep Count". The measurement stops after the defined number of sweeps has been performed.

While the measurement is running, the "Single Sweep" softkey and the [RUN SINGLE] key are highlighted. The running measurement can be aborted by selecting the highlighted softkey or key again.

**Note:** Sequencer. If the Sequencer is active, the "Single Sweep" softkey only controls the sweep mode for the currently selected channel setup. However, the sweep mode only takes effect the next time the Sequencer activates that channel setup, and only for a channel-defined sequence. In this case, the Sequencer sweeps a channel setup in single sweep mode only once.

Furthermore, the [RUN SINGLE] key controls the Sequencer, not individual sweeps. [RUN SINGLE] starts the Sequencer in single mode.

If the Sequencer is off, only the evaluation for the currently displayed channel setup is updated.

For details on the Sequencer, see the R&S ZNL User Manual.

#### Remote command:

INITiate<n>[:IMMediate] on page 154

# **Clear Spectrogram**

Resets the spectrogram result display and clears the history buffer.

This function is only available if a spectrogram is selected.

Remote command:

CALCulate<n>:SPECtrogram:CLEar[:IMMediate] on page 165

# 6.2.2 Color Map Settings

Access: "Overview" > "Analysis" > "Traces" > "Spectrogram" > "Color Mapping"
or: [TRACE] > "Spectrogram Config" > "Color Mapping"

In addition to the available color settings, the dialog box displays the current color map and provides a preview of the display with the current settings.

Spectrogram Settings




Figure 6-1: Color Mapping dialog box

- 1 = Color map: shows the current color distribution
- 2 = Preview pane: shows a preview of the spectrogram with any changes that you make to the color scheme
- 3 = Color curve pane: graphical representation of all settings available to customize the color scheme
- 4/5 = Color range start and stop sliders: define the range of the color map or amplitudes for the spectrogram
- 6 = Color curve slider: adjusts the focus of the color curve
- 7 = Histogram: shows the distribution of measured values
- 8 = Scale of the horizontal axis (value range)

Start / Stop	
Shape	
Hot/Cold/Radar/Grayscale	70
Auto	
Set to Default	
Close	70

#### Start / Stop

Defines the lower and upper boundaries of the value range of the spectrogram.

# Remote command:

DISPlay[:WINDow<n>]:SPECtrogram:COLor:LOWer on page 170
DISPlay[:WINDow<n>]:SPECtrogram:COLor:UPPer on page 170

#### **Shape**

Defines the shape and focus of the color curve for the spectrogram result display.

"-1 to <0" More colors are distributed among the lower values
"0" Colors are distributed linearly among the values
">0 to 1" More colors are distributed among the higher values

#### Remote command:

DISPlay[:WINDow<n>]:SPECtrogram:COLor:SHAPe on page 170

Trace / Data Export Configuration

#### Hot/Cold/Radar/Grayscale

Sets the color scheme for the spectrogram.

Remote command:

DISPlay[:WINDow<n>]:SPECtrogram:COLor[:STYLe] on page 171

#### Auto

Defines the color range automatically according to the existing measured values for optimized display.

#### **Set to Default**

Sets the color mapping to the default settings.

Remote command:

DISPlay[:WINDow<n>]:SPECtrogram:COLor:DEFault on page 170

#### Close

Saves the changes and closes the dialog box.

# 6.3 Trace / Data Export Configuration



Access: "Save" > "Export" > "Trace Export Configuration"


Or: [TRACE] > Trace > "Trace / Data Export"

The R&S ZNL provides various evaluation methods for the results of the performed measurements. However, you may want to evaluate the data with other, external applications. In this case, you can export the measurement data to an ASCII file.



The standard data management functions (e.g. saving or loading instrument settings) that are available for all R&S ZNL applications are not described here.

Trace / Data Export Configuration



Export all Traces and all Table Results	71
Include Instrument & Measurement Settings	71
Trace to Export	71
Decimal Separator	72
Export Trace to ASCII File	72
L File Type	72
L File Type  L Decimal Separator  L File Explorer.	73
L File Explorer	73

#### **Export all Traces and all Table Results**

Selects all displayed traces and result tables (e.g. Result Summary, marker table etc.) in the current application for export to an ASCII file.

Alternatively, you can select one specific trace only for export (see Trace to Export).

The results are output in the same order as they are displayed on the screen: window by window, trace by trace, and table row by table row.

#### Remote command:

FORMat: DEXPort: TRACes on page 215

# **Include Instrument & Measurement Settings**

Includes additional instrument and measurement settings in the header of the export file for result data.

# Remote command:

FORMat: DEXPort: HEADer on page 214

# **Trace to Export**

Defines an individual trace to be exported to a file.

This setting is not available if Export all Traces and all Table Results is selected.

Trace / Data Export Configuration

# **Decimal Separator**


Defines the decimal separator for floating-point numerals for the data export/import files. Evaluation programs require different separators in different languages.

# Remote command:

FORMat: DEXPort: DSEParator on page 214

# **Export Trace to ASCII File**

Saves the selected trace or all traces in the currently active result display to the specified file and directory in the selected ASCII format.



# Remote command:

MMEMory:STORe<n>:TRACe on page 215

# File Type ← Export Trace to ASCII File

Determines the format of the ASCII file to be imported or exported.

Depending on the external program in which the data file was created or is evaluated, a comma-separated list (CSV) or a plain data format (DAT) file is required.

# Remote command:

FORMat: DEXPort: FORMat on page 214

Marker Usage

#### **Decimal Separator** ← **Export Trace to ASCII File**

Defines the decimal separator for floating-point numerals for the data export/import files. Evaluation programs require different separators in different languages.

#### Remote command:

FORMat: DEXPort: DSEParator on page 214

#### File Explorer ← Export Trace to ASCII File

Opens the Microsoft Windows File Explorer.

Remote command: not supported

### 6.4 Marker Usage

Access: "Overview" > "Analysis"

The following marker settings and functions are available in the I/Q Analyzer application.



For "I/Q-Vector" displays markers are not available.



In the I/Q Analyzer application, the resolution with which the frequency can be measured with a marker is always the filter bandwidth, which is derived from the defined sample rate.

•	Marker Settings	.73
	Marker Search Settings and Positioning Functions	
•	Marker Search Settings for Spectrograms	.86
•	Marker Functions	80

#### 6.4.1 Marker Settings

Or: [MKR] > "MarkerConfig"


The remote commands required to define these settings are described in Chapter 9.7.3.1, "Setting Up Individual Markers", on page 172.

•	Individual Marker Setup	. 73
•	General Marker Settings	77

#### 6.4.1.1 Individual Marker Setup

Up to 17 markers or delta markers can be activated for each window simultaneously. Initial marker setup is performed using the "Marker" dialog box.

Marker Usage



The markers are distributed among 3 tabs for a better overview. By default, the first marker is defined as a normal marker, whereas all others are defined as delta markers with reference to the first marker. All markers are assigned to trace 1, but only the first marker is active.

Selected Marker	74
Marker State	74
Marker Position X-value	75
Frame (Spectrogram only)	75
Marker Type	75
Reference Marker	75
Linking to Another Marker	75
Assigning the Marker to a Trace	76
Select Marker	76
All Markers Off	76

#### **Selected Marker**

Marker name. The marker which is currently selected for editing is highlighted orange.

Remote command:

Marker selected via suffix <m> in remote commands.

#### **Marker State**

Activates or deactivates the marker in the diagram.

#### Remote command:

CALCulate<n>:MARKer<m>[:STATe] on page 176
CALCulate<n>:DELTamarker<m>[:STATe] on page 174

R&S<sup>®</sup>ZNL Analysis

Marker Usage

#### **Marker Position X-value**

Defines the position (x-value) of the marker in the diagram. For normal markers, the absolute position is indicated. For delta markers, the position relative to the reference marker is provided.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X on page 177
CALCulate<n>:DELTamarker<m>:X on page 175
```

#### Frame (Spectrogram only)

Spectrogram frame the marker is assigned to.

#### Remote command:

```
CALCulate<n>:MARKer<m>:SPECtrogram:FRAMe on page 184
CALCulate<n>:DELTamarker<m>:SPECtrogram:FRAMe on page 189
```

#### **Marker Type**

Toggles the marker type.

The type for marker 1 is always "Normal", the type for delta marker 1 is always "Delta". These types cannot be changed.

**Note:** If normal marker 1 is the active marker, switching the "Mkr Type" activates an additional delta marker 1. For any other marker, switching the marker type does not activate an additional marker, it only switches the type of the selected marker.

"Normal" A normal marker indicates the absolute value at the defined position

in the diagram.

"Delta" A delta marker defines the value of the marker relative to the speci-

fied reference marker (marker 1 by default).

#### Remote command:

```
CALCulate<n>:MARKer<m>[:STATe] on page 176
CALCulate<n>:DELTamarker<m>[:STATe] on page 174
```

#### **Reference Marker**

Defines a marker as the reference marker which is used to determine relative analysis results (delta marker values).

If the reference marker is deactivated, the delta marker referring to it is also deactivated.

#### Remote command:

```
CALCulate<n>:DELTamarker<m>:MREFerence on page 174
```

#### **Linking to Another Marker**

Links the current marker to the marker selected from the list of active markers. If the x-axis value of the initial marker is changed, the linked marker follows to the same position on the x-axis. Linking is off by default.

Using this function you can set two markers on different traces to measure the difference (e.g. between a max hold trace and a min hold trace or between a measurement and a reference trace).

Marker Usage

#### Remote command:

CALCulate<n>:MARKer<ms>:LINK:TO:MARKer<md> on page 176

CALCulate<n>:DELTamarker<ms>:LINK:TO:MARKer<md> on page 173

CALCulate<n>:DELTamarker<m>:LINK on page 172

#### **Assigning the Marker to a Trace**

The "Trace" setting assigns the selected marker to an active trace. The trace determines which value the marker shows at the marker position. If the marker was previously assigned to a different trace, the marker remains on the previous frequency or time, but indicates the value of the new trace.

If a trace is turned off, the assigned markers and marker functions are also deactivated.

#### Remote command:

CALCulate<n>:MARKer<m>:TRACe on page 177

#### **Select Marker**

The "Select Marker" function opens a dialog box to select and activate or deactivate one or more markers quickly.



#### Remote command:

CALCulate<n>:MARKer<m>[:STATe] on page 176
CALCulate<n>:DELTamarker<m>[:STATe] on page 174

#### **All Markers Off**

Deactivates all markers in one step.


#### Remote command:

CALCulate<n>:MARKer<m>:AOFF on page 175

Marker Usage

#### 6.4.1.2 General Marker Settings

Some general marker settings allow you to influence the marker behavior for all markers.



Marker Table Display	77
Marker Info	77
Marker Stepsize	

#### **Marker Table Display**

Defines how the marker information is displayed.

"On" Displays the marker information in a table in a separate area beneath

the diagram.

"Off" No separate marker table is displayed.

If Marker Info is active, the marker information is displayed within the

diagram area.

"Auto" (Default) If more than two markers are active, the marker table is dis-

played automatically.

If Marker Info is active, the marker information for up to two markers

is displayed in the diagram area.

#### Remote command:

DISPlay[:WINDow<n>]:MTABle on page 178

#### **Marker Info**

Turns the marker information displayed in the diagram on and off.



Marker Usage

#### Remote command:

DISPlay[:WINDow<n>]:MINFo[:STATe] on page 178

#### **Marker Stepsize**

Defines the size of the steps that the marker position is moved using the rotary knob.

"Standard" The marker position is moved in steps of (Span/1000), which corre-

sponds approximately to the number of pixels for the default display of 1001 sweep points. This setting is most suitable to move the

marker over a larger distance.

"Sweep Points" The marker position is moved from one sweep point to the next. This setting is required for a very precise positioning if more sweep points are collected than the number of pixels that can be displayed on the

screen. It is the default mode.

#### Remote command:

CALCulate<n>:MARKer<m>:X:SSIZe on page 178

#### 6.4.2 Marker Search Settings and Positioning Functions

Access: "Overview" > "Analysis" > "Marker" > "Search"

or: [MKR TO]

Several functions are available to set the marker to a specific position very quickly and easily, or to use the current marker position to define another characteristic value. In order to determine the required marker position, searches may be performed. The search results can be influenced by special settings.

For more information on searching for signal peaks see Chapter 6.4.4.2, "Marker Peak List", on page 92.



In I/Q Analyzer mode, the search settings for "Real/Imag (I/Q)" evaluation include an additional parameter, see "Branch for Peaksearch" on page 81.

Note that in the Spectrum diagram in I/Q mode, a peak search is performed only within the indicated Analysis Bandwidth, unless you specify Search Limits (Left / Right) in the marker settings.

The remote commands required to define these settings are described in Chapter 9.7.3.5, "Positioning the Marker", on page 193.

#### 6.4.2.1 Marker Search Settings


Access: [MKR TO] > "Search Config"

Marker Usage

Markers are commonly used to determine peak values, i.e. maximum or minimum values, in the measured signal. Configuration settings allow you to influence the peak search results.



For Spectrograms, special marker settings are available, see Chapter 6.4.2.2, "Marker Search Settings for Spectrograms", on page 81.



Search Mode for Next Peak	79
Exclude LO	
Peak Excursion	80
Auto Max Peak Search / Auto Min Peak Search	80
Search Limits	80
L Search Limits (Left / Right)	80
L Search Threshold	
L Use Zoom Limits	81
L Deactivating All Search Limits	81
Branch for Peaksearch	

#### **Search Mode for Next Peak**

Selects the search mode for the next peak search.

"Left" Determines the next maximum/minimum to the left of the current

peak.

"Absolute" Determines the next maximum/minimum to either side of the current

peak.

"Right" Determines the next maximum/minimum to the right of the current

peak.

#### Remote command:

Chapter 9.7.3.5, "Positioning the Marker", on page 193

Marker Usage

#### **Exclude LO**

If activated, restricts the frequency range for the marker search functions.

"On" The minimum frequency included in the peak search range is ≥ 5 ×

resolution bandwidth (RBW).

Due to the interference by the first local oscillator to the first intermediate frequency at the input mixer, the LO is represented as a signal at 0 Hz. To avoid the peak marker jumping to the LO signal at 0

Hz, this frequency is excluded from the peak search.

"Off" No restriction to the search range. The frequency 0 Hz is included in

the marker search functions.

#### Remote command:

CALCulate<n>:MARKer<m>:LOEXclude on page 179

#### **Peak Excursion**

Defines the minimum level value by which a signal must rise or fall so that it is identified as a maximum or a minimum by the search functions.

Entries from 0 dB to 80 dB are allowed; the resolution is 0.1 dB. The default setting for the peak excursion is 6 dB.

For Analog Modulation Analysis, the unit and value range depend on the selected result display type.

For more information, see Chapter 6.4.4.2, "Marker Peak List", on page 92.

#### Remote command:

CALCulate<n>:MARKer<m>:PEXCursion on page 179

#### Auto Max Peak Search / Auto Min Peak Search

If activated, a maximum or minimum peak search is performed automatically for marker 1 after each sweep.

For spectrogram displays, define which frame the peak is to be searched in.

#### Remote command:

```
CALCulate<n>:MARKer<m>:MAXimum:AUTO on page 193
CALCulate<n>:MARKer<m>:MINimum:AUTO on page 195
```

#### **Search Limits**

The search results can be restricted by limiting the search area or adding search conditions.

#### Search Limits (Left / Right) ← Search Limits

If activated, limit lines are defined and displayed for the search. Only results within the limited search range are considered.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:LEFT on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:RIGHt on page 182
```

Marker Usage

#### Search Threshold ← Search Limits

Defines an absolute threshold as an additional condition for the peak search. Only peaks that exceed the threshold are detected.

#### Remote command:

CALCulate<n>: THReshold on page 183

#### Use Zoom Limits ← Search Limits

If activated, the peak search is restricted to the active zoom area defined for a single zoom.

#### Remote command:

CALCulate<n>:MARKer<m>:X:SLIMits:ZOOM[:STATe] on page 182

#### **Deactivating All Search Limits ← Search Limits**

Deactivates the search range limits.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181 CALCulate<n>:THReshold:STATe on page 183
```

#### **Branch for Peaksearch**

Defines which data is used for marker search functions in I/Q data.

This function is only available for the display configuration "Real/Imag (I/Q)" (see "Real/Imag (I/Q)" on page 15).

**Note:** The search settings apply to all markers, not only the currently selected one.

"Real"

Marker search functions are performed on the real trace of the I/Q

measurement.

"Imag"

Marker search functions are performed on the imaginary trace of the

I/Q measurement.

"Magnitude"

Marker search functions are performed on the magnitude of the I and

Q data.

#### Remote command:

CALCulate<n>:MARKer<m>:SEARch on page 180

#### 6.4.2.2 Marker Search Settings for Spectrograms


```
Access: "Overview" > "Analysis" > "Markers" > "Search"
```

or: [MKR TO] > "Search Config"

Spectrograms show not only the current sweep results, but also the sweep history. Thus, when searching for peaks, you must define the search settings within a single time frame (x-direction) and within several time frames (y-direction).

These settings are only available for spectrogram displays.

Marker Usage



Search Mode for Next Peak in X-Direction	82
Search Mode for Next Peak in Y-Direction	82
Marker Search Type	83
Marker Search Area	83
Peak Excursion.	83
Search Limits	84
L Search Limits (Left / Right)	84
L Search Threshold	
L Use Zoom Limits	
L Deactivating All Search Limits	

#### **Search Mode for Next Peak in X-Direction**

Selects the search mode for the next peak search within the currently selected frame.

"Left" Determines the next maximum/minimum to the left of the current

peak.

"Absolute" Determines the next maximum/minimum to either side of the current

peak.

"Right" Determines the next maximum/minimum to the right of the current

peak.

#### Remote command:

Chapter 9.7.3.5, "Positioning the Marker", on page 193

#### **Search Mode for Next Peak in Y-Direction**

Selects the search mode for the next peak search within all frames at the current marker position.

"Up" Determines the next maximum/minimum above the current peak (in

more recent frames).

Marker Usage

"Absolute" Determines the next maximum/minimum above or below the current

peak (in all frames).

"Down" Determines the next maximum/minimum below the current peak (in

older frames).

#### Remote command:

```
CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:ABOVe on page 186 CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:ABOVe on page 190
```

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:BELow on page 186
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:BELow

#### on page 191

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:NEXT on page 186
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:NEXT on page 191
CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:ABOVe on page 187
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:ABOVe

#### on page 191

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:BELow on page 187
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:BELow

#### on page 192

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:NEXT on page 187
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:NEXT on page 192

#### **Marker Search Type**

Defines the type of search to be performed in the spectrogram.

"X-Search" Searches only within the currently selected frame.

"Y-Search" Searches within all frames but only at the current frequency position.

"XY-Search" Searches in all frames at all positions.

#### Remote command:

Defined by the search function, see Chapter 9.7.3.4, "Marker Search (Spectrograms)", on page 183

#### **Marker Search Area**

Defines which frames the search is performed in.

"Visible" Only the visible frames are searched.

"Memory" All frames stored in the memory are searched.

#### Remote command:

```
CALCulate<n>:MARKer<m>:SPECtrogram:SARea on page 185
CALCulate<n>:DELTamarker<m>:SPECtrogram:SARea on page 189
```

#### **Peak Excursion**

Defines the minimum level value by which a signal must rise or fall so that it is identified as a maximum or a minimum by the search functions.

Entries from 0 dB to 80 dB are allowed; the resolution is 0.1 dB. The default setting for the peak excursion is 6 dB.

For Analog Modulation Analysis, the unit and value range depend on the selected result display type.

Marker Usage

For more information, see Chapter 6.4.4.2, "Marker Peak List", on page 92.

#### Remote command:

CALCulate<n>:MARKer<m>:PEXCursion on page 179

#### **Search Limits**

The search results can be restricted by limiting the search area or adding search conditions.

#### Search Limits (Left / Right) ← Search Limits

If activated, limit lines are defined and displayed for the search. Only results within the limited search range are considered.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:LEFT on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:RIGHt on page 182
```

#### Search Threshold ← Search Limits

Defines an absolute threshold as an additional condition for the peak search. Only peaks that exceed the threshold are detected.

#### Remote command:

CALCulate<n>: THReshold on page 183

#### **Use Zoom Limits ← Search Limits**

If activated, the peak search is restricted to the active zoom area defined for a single zoom.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits:ZOOM[:STATe] on page 182
```

#### **Deactivating All Search Limits ← Search Limits**

Deactivates the search range limits.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181 CALCulate<n>:THReshold:STATe on page 183
```

#### **6.4.2.3 Positioning Functions**

#### Access: [MKR ->]

The following functions set the currently selected marker to the result of a peak search or set other characteristic values to the current marker value.

Peak Search	85
Search Next Peak	85
Search Minimum.	85
Search Next Minimum	85
Center Frequency = Marker Frequency	85
Reference Level = Marker Level	

R&S<sup>®</sup>ZNL Analysis

Marker Usage

#### **Peak Search**

Sets the selected marker/delta marker to the maximum of the trace. If no marker is active, marker 1 is activated.

#### Remote command:

```
CALCulate<n>:MARKer<m>:MAXimum[:PEAK] on page 194
CALCulate<n>:DELTamarker<m>:MAXimum[:PEAK] on page 197
```

#### **Search Next Peak**

Sets the selected marker/delta marker to the next (lower) maximum of the assigned trace. If no marker is active, marker 1 is activated.

#### Remote command:

```
CALCulate<n>:MARKer<m>:MAXimum:NEXT on page 194

CALCulate<n>:MARKer<m>:MAXimum:RIGHt on page 194

CALCulate<n>:MARKer<m>:MAXimum:LEFT on page 193

CALCulate<n>:DELTamarker<m>:MAXimum:NEXT on page 197

CALCulate<n>:DELTamarker<m>:MAXimum:RIGHt on page 197

CALCulate<n>:DELTamarker<m>:MAXimum:RIGHt on page 197
```

#### Search Minimum

Sets the selected marker/delta marker to the minimum of the trace. If no marker is active, marker 1 is activated.

#### Remote command:

```
CALCulate<n>:MARKer<m>:MINimum[:PEAK] on page 196
CALCulate<n>:DELTamarker<m>:MINimum[:PEAK] on page 198
```

#### **Search Next Minimum**

Sets the selected marker/delta marker to the next (higher) minimum of the selected trace. If no marker is active, marker 1 is activated.

For spectrogram displays, define which frame the next minimum is to be searched in.

#### Remote command:

```
CALCulate<n>:MARKer<m>:MINimum:NEXT on page 195

CALCulate<n>:MARKer<m>:MINimum:LEFT on page 195

CALCulate<n>:MARKer<m>:MINimum:RIGHt on page 196

CALCulate<n>:DELTamarker<m>:MINimum:NEXT on page 198

CALCulate<n>:DELTamarker<m>:MINimum:LEFT on page 198

CALCulate<n>:DELTamarker<m>:MINimum:RIGHt on page 198
```

#### **Center Frequency = Marker Frequency**

Sets the center frequency to the selected marker or delta marker frequency. A peak can thus be set as center frequency, for example to analyze it in detail with a smaller span.

This function is not available for zero span measurements.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:CENTer on page 127
```

#### Reference Level = Marker Level

Sets the reference level to the selected marker level.

Marker Usage

#### Remote command:

CALCulate<n>:MARKer<m>:FUNCtion:REFerence on page 123


#### 6.4.3 Marker Search Settings for Spectrograms

Access: "Overview" > "Analysis" > "Markers" > "Search"

or: [MKR TO] > "Search Config"

Spectrograms show not only the current sweep results, but also the sweep history. Thus, when searching for peaks, you must define the search settings within a single time frame (x-direction) and within several time frames (y-direction).

These settings are only available for spectrogram displays.



Search Mode for Next Peak in X-Direction	86
Search Mode for Next Peak in Y-Direction	87
Marker Search Type	87
Marker Search Area	87
Peak Excursion	88
Search Limits	88
L Search Limits (Left / Right)	88
L Search Threshold	88
L Use Zoom Limits	88
L Deactivating All Search Limits	88
- Carlotte and the Carlotte	

#### **Search Mode for Next Peak in X-Direction**

Selects the search mode for the next peak search within the currently selected frame.

"Left" Determines the next maximum/minimum to the left of the current peak.

Marker Usage

"Absolute" Determines the next maximum/minimum to either side of the current

peak.

"Right" Determines the next maximum/minimum to the right of the current

neak.

#### Remote command:

Chapter 9.7.3.5, "Positioning the Marker", on page 193

#### Search Mode for Next Peak in Y-Direction

Selects the search mode for the next peak search within all frames at the current marker position.

"Up" Determines the next maximum/minimum above the current peak (in

more recent frames).

"Absolute" Determines the next maximum/minimum above or below the current

peak (in all frames).

"Down" Determines the next maximum/minimum below the current peak (in

older frames).

#### Remote command:

```
CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:ABOVe on page 186
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:ABOVe
on page 190
CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:BELow on page 186
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:BELow
on page 191
```

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:NEXT on page 186

CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:NEXT on page 191

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:ABOVe on page 187

CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:ABOVe

#### on page 191

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:BELow on page 187 CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:BELow on page 192

CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:NEXT on page 187
CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:NEXT on page 192

#### Marker Search Type

Defines the type of search to be performed in the spectrogram.

"X-Search" Searches only within the currently selected frame.

"Y-Search" Searches within all frames but only at the current frequency position.

"XY-Search" Searches in all frames at all positions.

#### Remote command:

Defined by the search function, see Chapter 9.7.3.4, "Marker Search (Spectrograms)", on page 183

#### Marker Search Area

Defines which frames the search is performed in.

"Visible" Only the visible frames are searched.

Marker Usage

"Memory" All frames stored in the memory are searched.

#### Remote command:

```
CALCulate<n>:MARKer<m>:SPECtrogram:SARea on page 185
CALCulate<n>:DELTamarker<m>:SPECtrogram:SARea on page 189
```

#### **Peak Excursion**

Defines the minimum level value by which a signal must rise or fall so that it is identified as a maximum or a minimum by the search functions.

Entries from 0 dB to 80 dB are allowed; the resolution is 0.1 dB. The default setting for the peak excursion is 6 dB.

For Analog Modulation Analysis, the unit and value range depend on the selected result display type.

For more information, see Chapter 6.4.4.2, "Marker Peak List", on page 92.

#### Remote command:

```
CALCulate<n>:MARKer<m>:PEXCursion on page 179
```

#### **Search Limits**

The search results can be restricted by limiting the search area or adding search conditions.

#### Search Limits (Left / Right) ← Search Limits

If activated, limit lines are defined and displayed for the search. Only results within the limited search range are considered.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:LEFT on page 181
CALCulate<n>:MARKer<m>:X:SLIMits:RIGHt on page 182
```

#### Search Threshold ← Search Limits

Defines an absolute threshold as an additional condition for the peak search. Only peaks that exceed the threshold are detected.

#### Remote command:

```
CALCulate<n>: THReshold on page 183
```

#### **Use Zoom Limits ← Search Limits**

If activated, the peak search is restricted to the active zoom area defined for a single zoom.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits:ZOOM[:STATe] on page 182
```

#### **Deactivating All Search Limits ← Search Limits**

Deactivates the search range limits.

#### Remote command:

```
CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] on page 181
CALCulate<n>:THReshold:STATe on page 183
```

Marker Usage

#### 6.4.4 Marker Functions

Some special marker functions are available in the I/Q Analyzer application.

#### 6.4.4.1 Measuring the Power in a Channel (Band Power Marker)

Access: "Overview" > "Analysis" > "Marker Functions" > "Band Power" > "BandPower-Config"

or: [MKR] > "Select Marker Function" > "Band Power"

To determine the noise power in a transmission channel, you can use a noise marker and multiply the result with the channel bandwidth. However, the results are only accurate for flat noise.

Band power markers allow you to measure the integrated power for a defined span (band) around a marker (similar to ACP measurements). By default, 5 % of the current span is used. The span is indicated by limit lines in the diagram. You can easily change the span by moving the limit lines in the diagram. They are automatically aligned symmetrically to the marker frequency. They are also moved automatically if you move the marker on the screen.

The results can be displayed either as a power (dBm) or density (dBm/Hz) value and are indicated in the marker table for each band power marker.



#### Relative band power markers

The results for band power markers which are defined as *delta* markers and thus have a reference value can also be calculated as reference power values (in dB).

In this case, the result of the band power deltamarker is the difference between the absolute power in the band around the delta marker and the absolute power for the reference marker. The powers are subtracted logarithmically, so the result is a dB value.

[Relative band power (Delta2) in dB] = [absolute band power (Delta2) in dBm] - [absolute (band) power of reference marker in dBm]

The measured power for the reference marker may be an absolute power at a single point (if the reference marker is not a band power marker), or the power in a band (if the reference marker is a band power marker itself).


If the reference marker for the band power marker is also a delta marker, the absolute power level for the reference marker is used for calculation.



For the I/Q Analyzer application, band power markers are only available for Spectrum displays.

The entire band must lie within the display. If it is moved out of the display, the result cannot be calculated (indicated by "- - -" as the "Function Result"). However, the width of the band is maintained so that the band power can be calculated again when it returns to the display.


Marker Usage



All markers can be defined as band power markers, each with a different span. When a band power marker is activated, if no marker is active yet, marker 1 is activated. Otherwise, the currently active marker is used as a band power marker (all other marker functions for this marker are deactivated).

If the detector mode for the marker trace is set to "Auto", the RMS detector is used.

The individual marker settings correspond to those defined in the "Marker" dialog box (see Chapter 6.4.1.1, "Individual Marker Setup", on page 73). Any settings to the marker state or type changed in the "Marker Function" dialog box are also changed in the "Marker" dialog box and vice versa.



Marker Usage

#### Remote commands:

CALCulate <n>:MARKer<m>:FUNCtion:BPOWer[:STATe] on page 200</m></n>	
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:RESult? on page 200</m></n>	
Band Power Measurement StateSpan	
Power Mode	
Switching All Band Power Measurements Off	92

#### **Band Power Measurement State**

Activates or deactivates band power measurement for the marker in the diagram.

Band power markers are only available for standard frequency measurements (not zero span) in the Spectrum application.

If activated, the markers display the power or density measured in the band around the current marker position.

For details see Chapter 6.4.4.1, "Measuring the Power in a Channel (Band Power Marker)", on page 89.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:BPOWer[:STATe] on page 200
CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer[:STATe] on page 202
```

#### Span

Defines the span (band) around the marker for which the power is measured.

The span is indicated by lines in the diagram. You can easily change the span by moving the limit lines in the diagram. They are automatically aligned symmetrically to the marker frequency. They are also moved automatically if you move the marker on the screen.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:SPAN on page 200
CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:SPAN on page 202
```

#### **Power Mode**

Defines the mode of the power measurement result.

For Analog Modulation Analysis, the power mode is not editable for AM, FM, or PM spectrum results. In this case, the marker function does not determine a power value, but rather the deviation within the specified span.

"Power" The result is an absolute power level.

The power unit depends on the Unit setting.

"Relative-Power" This setting is only available for a delta band power marker.

The result is the difference between the absolute power in the band around the delta marker and the absolute power for the reference marker (see "Reference Marker" on page 75). The powers are sub-

tracted logarithmically, so the result is a dB value.

[Relative band power (Delta2) in dB] = [absolute band power (Delta2)

in dBm] - [absolute (band) power of reference marker in dBm] For details see "Relative band power markers" on page 89

Marker Usage

"Density" The result is a power level in relation to the bandwidth, displayed in dBm/Hz.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:MODE on page 199
CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:MODE on page 201
```

#### **Switching All Band Power Measurements Off**

Deactivates band power measurement for all markers.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:BPOWer[:STATe] on page 200
CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer[:STATe] on page 202
```

#### 6.4.4.2 Marker Peak List

Access: "Overview" > "Analysis" > "Marker Functions" > "Marker Peak List"

Or: [MKR] > "Select Marker Function" > "Marker Peak List"

A common measurement task is to determine peak values, i.e. maximum or minimum signal levels. The R&S ZNL provides various peak search functions and applications:

- Setting a marker to a peak value once (Peak Search)
- Searching for a peak value within a restricted search area (Search Limits)
- Creating a marker table with all or a defined number of peak values for one sweep (Marker Peak List)
- Updating the marker position to the current peak value automatically after each sweep (Auto Peak Search)

#### **Peak search limits**

The peak search can be restricted to a search area. The search area is defined by limit lines which are also indicated in the diagram. In addition, a minimum value (threshold) can be defined as a further search condition.

#### When is a peak a peak? - Peak excursion

During a peak search, for example when a marker peak table is displayed, noise values may be detected as a peak if the signal is very flat or does not contain many peaks. Therefore, you can define a relative threshold ("Peak Excursion"). The signal level must increase by the threshold value before falling again before a peak is detected. To avoid identifying noise peaks as maxima or minima, enter a peak excursion value that is higher than the difference between the highest and the lowest value measured for the displayed inherent noise.

#### Effect of peak excursion settings (example)

The following figure shows a trace to be analyzed.

Marker Usage




Figure 6-2: Trace example

The following table lists the peaks as indicated by the marker numbers in the diagram above, as well as the minimum decrease in amplitude to either side of the peak:


Marker #	Min. amplitude decrease to either side of the signal
1	80 dB
2	80 dB
3	55 dB
4	39 dB
5	32 dB

In order to eliminate the smaller peaks M3, M4 and M5 in the example above, a peak excursion of at least 60 dB is required. In this case, the amplitude must rise at least 60 dB before falling again before a peak is detected.

#### Marker peak list

The marker peak list determines the frequencies and levels of peaks in the spectrum. It is updated automatically after each sweep. How many peaks are displayed can be defined, as well as the sort order. In addition, the detected peaks can be indicated in the diagram. The peak list can also be exported to a file for analysis in an external application.

Marker Usage



#### Remote commands:

CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:STATe on page 205

TRAC? LIST, see TRACe<n>[:DATA]? on page 211

Peak List State	94
Sort Mode	94
Maximum Numberof Peaks	95
Peak Excursion	95
Display MarkerNumbers	95
Export Peak List	

#### **Peak List State**

Activates/deactivates the marker peak list. If activated, the peak list is displayed and the peaks are indicated in the trace display.

For each listed peak the frequency/time ("X-value") and level ("Y-Value") values are given.

#### Remote command:

CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:STATe on page 205

#### **Sort Mode**

Defines whether the peak list is sorted according to the x-values or y-values. In either case the values are sorted in ascending order.

Marker Usage

#### Remote command:

CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:SORT on page 205

#### **Maximum Number of Peaks**

Defines the maximum number of peaks to be determined and displayed.

#### Remote command:

CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:LIST:SIZE on page 204

#### **Peak Excursion**

Defines the minimum level value by which a signal must rise or fall so that it is identified as a maximum or a minimum by the search functions.

Entries from 0 dB to 80 dB are allowed; the resolution is 0.1 dB. The default setting for the peak excursion is 6 dB.

For Analog Modulation Analysis, the unit and value range depend on the selected result display type.

For more information, see Chapter 6.4.4.2, "Marker Peak List", on page 92.

#### Remote command:

CALCulate<n>:MARKer<m>:PEXCursion on page 179

#### **Display MarkerNumbers**

By default, the marker numbers are indicated in the diagram so you can find the peaks from the list. However, for large numbers of peaks the marker numbers may decrease readability; in this case, deactivate the marker number display.

#### Remote command:

```
CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:ANNotation:LABel[:STATe] on page 203
```

#### **Export Peak List**

The peak list can be exported to an ASCII file (.DAT) for analysis in an external application.

#### Remote command:

```
MMEMory:STORe<n>:PEAK on page 206
FORMat:DEXPort:DSEParator on page 214
```

#### **6.4.4.3 Deactivating All Marker Functions**

Access: "Overview" > "Analysis" > "Marker Functions" > "All Functions Off"

Or: [MKR] > "All Functions Off"

All special marker functions can be deactivated in one step.

#### Remote command:

# 7 How to Perform Measurements in the I/Q Analyzer Application

The following step-by-step instructions demonstrate how to capture I/Q data on the R&S ZNL and how to analyze data in the I/Q Analyzer application.

•	How to Capture Baseband (I/Q) Data as RF Input	.96
•	How to Analyze Data in the I/Q Analyzer	97

## 7.1 How to Capture Baseband (I/Q) Data as RF Input

By default, the I/Q Analyzer assumes the I/Q data is modulated on a carrier frequency and input via the "RF Input" connector on the R&S ZNL.

- 1. Select the [MODE] key and select the "I/Q Analyzer" application.
- 2. Select the "Overview" softkey to display the "Overview" for an I/Q Analyzer measurement.
- 3. Select the "Input" button to select and configure the "RF Input" signal source.
- Select the "Amplitude" button to define the attenuation, reference level or other settings that affect the input signal's amplitude and scaling.
- 5. Select the "Frequency" button to define the input signal's center frequency.
- Optionally, select the "Trigger" button and define a trigger for data acquisition, for example an I/Q Power trigger to start capturing data only when a specific power is exceeded.
- 7. Select the "Bandwidth" button and define the bandwidth parameters for data acquisition:
  - "Sample Rate" or "Analysis Bandwidth" the span of the input signal to be captured for analysis, or the rate at which samples are captured (both values are correlated)
  - "Measurement Time" how long the data is to be captured
  - "Record Length": the number of samples to be captured (also defined by sample rate and measurement time)
- 8. Select the "Display Config" button and select up to six displays that are of interest to you.
  - Arrange them on the display to suit your preferences.
- 9. Exit the SmartGrid mode.
- 10. Start a new sweep with the defined settings.
  - a) Select the Sequencer icon ( from the toolbar.
  - b) Set the Sequencer state to "Off".

How to Analyze Data in the I/Q Analyzer

c) Select the [RUN SINGLE] key.

### 7.2 How to Analyze Data in the I/Q Analyzer

- 1. Select the [MODE] key and select the "I/Q Analyzer" application.
- 2. Select the "Overview" softkey to display the "Overview" for an I/Q Analyzer measurement.
- 3. Select the "Display Config" button and select up to six displays that are of interest to you.
  - Arrange them on the display to suit your preferences.
- 4. Exit the SmartGrid mode and select the "Overview" softkey to display the "Overview" again.
- 5. Select the "Analysis" button in the "Overview" to make use of the advanced analysis functions in the displays.
  - Configure a trace to display the average over a series of sweeps (on the "Trace" tab; if necessary, increase the "Average Count").
  - Configure markers and delta markers to determine deviations and offsets within the signal (on the "Marker" tab).

# 8 How to Export and Import I/Q Data



I/Q data can only be exported in applications that process I/Q data, such as the I/Q Analyzer or optional applications.

#### Capturing and exporting I/Q data

- 1. Press the [PRESET] key.
- 2. Press the [MODE] key and select the I/Q Analyzer application or any other application that supports I/Q data.
- 3. Configure the data acquisition.
- 4. Press the [RUN SINGLE] key to perform a single sweep measurement.
- 5. Select the "Save" icon in the toolbar.
- 6. Select the "I/Q Export" softkey.
- 7. In the file selection dialog box, select a storage location and enter a file name.
- 8. Select "Save".

The captured data is stored to a file with the extension .iq.tar.

#### Importing I/Q data

- 1. Press the [MODE] key and select the "I/Q Analyzer" or any other application that supports I/Q data.
- If necessary, switch to single sweep mode by pressing the [RUN SINGLE] key.
- 3. Select the 

   "Open" icon in the toolbar.
- 4. Select the "I/Q Import" softkey.
- 5. Select the storage location and the file name with the .iq.tar file extension.
- 6. Select "Open".

The stored data is loaded from the file and displayed in the current application.

#### Previewing the I/Q data in a web browser

The iq-tar file format allows you to preview the I/Q data in a web browser.

- 1. Use an archive tool (e.g. WinZip® or PowerArchiver®) to unpack the iq-tar file into a folder.
- 2. Locate the folder using Windows Explorer.
- 3. Open your web browser.

xzy.xml **4** ► + 🕙 file:///D:/xzy.xml **♂** Google <u>□</u>- #xzy.xml xzy.xml (of .iq.tar file) Description Saved by FSV IQ Analyzer Comment Here is a comment Date & Time 2011-03-03 14:33:05 Sample rate 6.5 MHz Number of samples 65000 Duration of signal 10 ms Data format complex, float32 Data filename xzy.complex.1ch.float32 Scaling factor Channel 1 Comment Channel 1 of 1 Power vs time y-axis: 10 dB /div x-axis: 1 ms /div Spectrum y-axis: 20 dB /div x-axis: 500 kHz /div E-mail: info@rohde-schwarz.com

Internet: http://www.rohde-schwarz.com

Fileformat version: 1

4. Drag the I/Q parameter XML file, e.g. example.xml, into your web browser.

# 9 Remote Commands to Perform Measurements with I/Q Data

The following commands are specific to performing measurements in the I/Q Analyzer application in a remote environment. The R&S ZNL must already be set up for remote operation in a network as described in the base unit manual.



Note that basic tasks that are also performed in the base unit in the same way are not described here. For a description of such tasks, see the R&S ZNL User Manual.

In particular, this includes:

- Basic instrument configuration, e.g. checking the system configuration, customizing the screen layout, or configuring networks and remote operation
- Using the common status registers

The following tasks specific to the I/Q Analyzer application are described here:

•	Introduction	100
•	Common Suffixes.	105
•	Activating I/Q Analyzer Measurements	105
•	Configuring I/Q Analyzer Measurements	110
•	Configuring the Result Display	145
•	Capturing Data and Performing Sweeps	152
•	I/Q Analysis	158
	Retrieving Results	
•	Importing and Exporting I/Q Data and Results	217
•	Programming Examples	218

#### 9.1 Introduction

Commands are program messages that a controller (e.g. a PC) sends to the instrument or software. They operate its functions ('setting commands' or 'events') and request information ('query commands'). Some commands can only be used in one way, others work in two ways (setting and query). If not indicated otherwise, the commands can be used for settings and queries.

The syntax of a SCPI command consists of a header and, in most cases, one or more parameters. To use a command as a query, you have to append a question mark after the last header element, even if the command contains a parameter.

A header contains one or more keywords, separated by a colon. Header and parameters are separated by a "white space" (ASCII code 0 to 9, 11 to 32 decimal, e.g. blank). If there is more than one parameter for a command, these are separated by a comma from one another.

Only the most important characteristics that you need to know when working with SCPI commands are described here. For a more complete description, refer to the User Manual of the R&S ZNL.



#### Remote command examples

Note that some remote command examples mentioned in this general introduction may not be supported by this particular application.

#### 9.1.1 Conventions used in Descriptions

Note the following conventions used in the remote command descriptions:

#### Command usage

If not specified otherwise, commands can be used both for setting and for querying parameters.

If a command can be used for setting or querying only, or if it initiates an event, the usage is stated explicitly.

#### Parameter usage

If not specified otherwise, a parameter can be used to set a value and it is the result of a query.

Parameters required only for setting are indicated as **Setting parameters**. Parameters required only to refine a query are indicated as **Query parameters**. Parameters that are only returned as the result of a query are indicated as **Return values**.

#### Conformity

Commands that are taken from the SCPI standard are indicated as **SCPI confirmed**. All commands used by the R&S ZNL follow the SCPI syntax rules.

#### Asynchronous commands

A command which does not automatically finish executing before the next command starts executing (overlapping command) is indicated as an **Asynchronous command**.

#### Reset values (\*RST)

Default parameter values that are used directly after resetting the instrument (\*RST command) are indicated as \*RST values, if available.

#### Default unit

The default unit is used for numeric values if no other unit is provided with the parameter.

#### 9.1.2 Long and Short Form

The keywords have a long and a short form. You can use either the long or the short form, but no other abbreviations of the keywords.

The short form is emphasized in upper case letters. Note however, that this emphasis only serves the purpose to distinguish the short from the long form in the manual. For the instrument, the case does not matter.

#### **Example:**

SENSe: FREQuency: CENTer is the same as SENS: FREQ: CENT.

#### 9.1.3 Numeric Suffixes

Some keywords have a numeric suffix if the command can be applied to multiple instances of an object. In that case, the suffix selects a particular instance (e.g. a measurement window).

Numeric suffixes are indicated by angular brackets (<n>) next to the keyword.

If you don't quote a suffix for keywords that support one, a 1 is assumed.

#### **Example:**

DISPlay [: WINDow<1...4>]: ZOOM: STATe enables the zoom in a particular measurement window, selected by the suffix at WINDow.

DISPlay: WINDow4: ZOOM: STATe ON refers to window 4.

#### 9.1.4 Optional Keywords

Some keywords are optional and are only part of the syntax because of SCPI compliance. You can include them in the header or not.

Note that if an optional keyword has a numeric suffix and you need to use the suffix, you have to include the optional keyword. Otherwise, the suffix of the missing keyword is assumed to be the value 1.

Optional keywords are emphasized with square brackets.

#### **Example:**

Without a numeric suffix in the optional keyword:

[SENSe:] FREQuency: CENTer is the same as FREQuency: CENTer

With a numeric suffix in the optional keyword:

DISPlay[:WINDow<1...4>]:ZOOM:STATe

DISPlay: ZOOM: STATE ON enables the zoom in window 1 (no suffix).

DISPlay: WINDow4: ZOOM: STATE ON enables the zoom in window 4.

#### 9.1.5 Alternative Keywords

A vertical stroke indicates alternatives for a specific keyword. You can use both keywords to the same effect.

#### Example:

[SENSe:]BANDwidth|BWIDth[:RESolution]

In the short form without optional keywords, BAND 1MHZ would have the same effect as BWID 1MHZ.

#### 9.1.6 SCPI Parameters

Many commands feature one or more parameters.

If a command supports more than one parameter, these are separated by a comma.

#### Example:

LAYout: ADD: WINDow Spectrum, LEFT, MTABle

Parameters may have different forms of values.

•	Numeric Values	. 103
•	Boolean	.104
	Character Data	
	Character Strings	
	Block Data	

#### 9.1.6.1 Numeric Values

Numeric values can be entered in any form, i.e. with sign, decimal point or exponent. In case of physical quantities, you can also add the unit. If the unit is missing, the command uses the basic unit.

#### Example:

With unit: SENSe: FREQuency: CENTer 1GHZ

Without unit: SENSe: FREQuency: CENTer 1E9 would also set a frequency of 1 GHz.

Values exceeding the resolution of the instrument are rounded up or down.

If the number you have entered is not supported (e.g. in case of discrete steps), the command returns an error.

Instead of a number, you can also set numeric values with a text parameter in special cases.

#### MIN/MAX

Defines the minimum or maximum numeric value that is supported.

DEF

Defines the default value.

#### UP/DOWN

Increases or decreases the numeric value by one step. The step size depends on the setting. In some cases you can customize the step size with a corresponding command.

#### Querying numeric values

When you query numeric values, the system returns a number. In case of physical quantities, it applies the basic unit (e.g. Hz in case of frequencies). The number of digits after the decimal point depends on the type of numeric value.

#### Example:

Setting: SENSe: FREQuency: CENTer 1GHZ

Query: SENSe: FREQuency: CENTer? would return 1E9

In some cases, numeric values may be returned as text.

INF/NINF
 Infinity or negative infinity. Represents the numeric values 9.9E37 or -9.9E37.

NAN

Not a number. Represents the numeric value 9.91E37. NAN is returned in case of errors.

#### 9.1.6.2 Boolean

Boolean parameters represent two states. The "ON" state (logically true) is represented by "ON" or a numeric value 1. The "OFF" state (logically untrue) is represented by "OFF" or the numeric value 0.

#### **Querying Boolean parameters**

When you query Boolean parameters, the system returns either the value 1 ("ON") or the value 0 ("OFF").

#### **Example:**

Setting: DISPlay: WINDow: ZOOM: STATE ON

Query: DISPlay: WINDow: ZOOM: STATe? would return 1

#### 9.1.6.3 Character Data

Character data follows the syntactic rules of keywords. You can enter text using a short or a long form. For more information see Chapter 9.1.2, "Long and Short Form", on page 101.

#### **Querying text parameters**

When you query text parameters, the system returns its short form.

#### Example:

Setting: SENSe: BANDwidth: RESolution: TYPE NORMal

Query: SENSe: BANDwidth: RESolution: TYPE? would return NORM

#### 9.1.6.4 Character Strings

Strings are alphanumeric characters. They have to be in straight quotation marks. You can use a single quotation mark ( ' ) or a double quotation mark ( " ).

#### **Example:**

INSTRument:DELete 'Spectrum'

#### 9.1.6.5 Block Data

Block data is a format which is suitable for the transmission of large amounts of data.

The ASCII character # introduces the data block. The next number indicates how many of the following digits describe the length of the data block. In the example the 4 following digits indicate the length to be 5168 bytes. The data bytes follow. During the transmission of these data bytes all end or other control signs are ignored until all bytes are transmitted. #0 specifies a data block of indefinite length. The use of the indefinite format requires an NL^END message to terminate the data block. This format is useful when the length of the transmission is not known or if speed or other considerations prevent segmentation of the data into blocks of definite length.

#### 9.2 Common Suffixes

In the I/Q Analyzer application, the following common suffixes are used in remote commands:

Table 9-1: Common suffixes used in remote commands in the I/Q Analyzer application

Suffix	Value range	Description
<m></m>	1 to 16	Marker
<n></n>	1 to 6	Window (in the currently selected channel setup)
<t></t>	1 to 6	Trace
< i>	1 to 8	Limit line

# 9.3 Activating I/Q Analyzer Measurements

I/Q Analyzer measurements require a special channel setup on the R&S ZNL. It can be activated using the common INSTrument:CREate[:NEW] or INSTrument:CREate:REPLace commands. In this case, some - but not all - parameters from the previously selected application are passed on to the I/Q Analyzer channel setup. In order to retain all relevant parameters from the current application for the I/Q measurement, use the TRACe:IQ[:STATe] command to change the application of the current channel setup.

A measurement is started immediately with the default settings when the channel setup is activated.



#### Different remote modes available

In remote control, two different modes for the I/Q Analyzer measurements are available:

- A quick mode for pure data acquisition
   This mode is activated by default with the TRACe:IQ[:STATe] command. The evaluation functions are not available; however, performance is slightly improved.
- A more sophisticated mode for acquisition and analysis.
   This mode is activated when a new channel setup is opened for the I/Q Analyzer application (INST:CRE:NEW/ INST:CRE:REPL) or by an additional command (see TRACe:IQ:EVAL on page 109).

INSTrument:CREate:DUPLicate	106
INSTrument:CREate[:NEW]	106
INSTrument:CREate:REPLace	
INSTrument:DELete	107
INSTrument:LIST?	107
INSTrument:REName	108
INSTrument[:SELect]	109
SYSTem:PRESet:CHANnel[:EXEC]	109
TRACe:IQ:EVAL	109
TRACe:IQ[:STATe]	110

#### INSTrument: CREate: DUPLicate

This command duplicates the currently selected channel setup, i.e creates a new channel setup of the same type and with the identical measurement settings. The name of the new channel setup is the same as the copied channel setup, extended by a consecutive number (e.g. "IQAnalyzer" -> "IQAnalyzer 2").

The channel setup to be duplicated must be selected first using the INST: SEL command.

Usage: Event

#### INSTrument:CREate[:NEW] < Channel Type>, < Channel Name>

This command adds an additional measurement channel. You can configure up to 10 measurement channels at the same time (depending on available memory).

#### Parameters:

<ChannelType> Channel type of the new channel.

For a list of available channel types see INSTrument:LIST?

on page 107.

Activating I/Q Analyzer Measurements

<ChannelName> String containing the name of the channel.

Note that you can not assign an existing channel name to a new

channel; this will cause an error.

Example: INST:CRE SAN, 'Spectrum 2'

Adds an additional spectrum display named "Spectrum 2".

INSTrument:CREate:REPLace < ChannelName1>, < ChannelType>, < ChannelName2>

This command replaces a channel setup with another one.

**Setting parameters:** 

<ChannelName1> String containing the name of the channel setup you want to

replace.

<ChannelType> Channel type of the new channel setup.

For a list of available channel setup types see INSTrument:

LIST? on page 107.

<ChannelName2> String containing the name of the new channel setup.

Note: If the specified name for a new channel setup already exists, the default name, extended by a sequential number, is used for the new channel setup (see INSTrument:LIST?

on page 107).

Channel names can have a maximum of 31 characters, and must be compatible with the Windows conventions for file names. In particular, they must not contain special characters

such as ":", "\*", "?".

Usage: Setting only

INSTrument: DELete < Channel Name >

This command deletes a channel setup.

**Setting parameters:** 

<ChannelName> String containing the name of the channel setup you want to

delete.

A channel setup must exist in order to be able delete it.

**Usage:** Setting only

#### **INSTrument:LIST?**

This command queries all active channel setups. This is useful in order to obtain the names of the existing channel setups, which are required in order to replace or delete the channel setups.

Activating I/Q Analyzer Measurements

Return values:

<ChannelType>, For each channel setup, the command returns the channel setup

<ChannelName> type and channel setup name (see tables below).

Tip: to change the channel setup name, use the INSTrument:

REName command.

**Example:** INST:LIST?

Result for 3 channel setups:

'ADEM', 'Analog Demod', 'IQ', 'IQ Analyzer', 'IQ', 'IQ Analyzer2'

Usage: Query only

Table 9-2: Available channel setup types and default channel setup names

Application	<channeltype> Parameter</channeltype>	Default Channel Setup Name*)
Spectrum	SANALYZER	Spectrum
Analog Modulation Analysis	ADEM	Analog Demod
I/Q Analyzer	IQ	IQ Analyzer
Noise Figure Measure- ments	NOISE	Noise
Vector Signal Analysis (VSA)	DDEM	VSA
Network analysis	Vna	VNA

Note: the default channel setup name is also listed in the table. If the specified name for a new channel setup already exists, the default name, extended by a sequential number, is used for the new channel setup.

INSTrument:REName < ChannelName1>, < ChannelName2>

This command renames a channel setup.

**Setting parameters:** 

<ChannelName1> String containing the name of the channel setup you want to

rename.

<ChannelName2> String containing the new channel setup name.

Note that you cannot assign an existing channel setup name to

a new channel setup; this will cause an error.

Channel names can have a maximum of 31 characters, and must be compatible with the Windows conventions for file names. In particular, they must not contain special characters

such as ":", "\*", "?".

Usage: Setting only

## INSTrument[:SELect] < Channel Type> | < Channel Name>

This command activates a new channel setup with the defined channel setup type, or selects an existing channel setup with the specified name.

#### Also see

• INSTrument:CREate[:NEW] on page 106

#### Parameters:

<ChannelType> Channel type of the new channel setup.

For a list of available channel setup types see INSTrument:

LIST? on page 107.

<ChannelName> String containing the name of the channel setup.

Example: INST IQ

INST 'MyIQSpectrum'

Selects the channel setup named 'MylQSpectrum' (for example before executing further commands for that channel setup).

#### SYSTem:PRESet:CHANnel[:EXEC]

This command restores the default instrument settings in the current channel setup.

Use INST: SEL to select the channel setup.

Example: INST:SEL 'Spectrum2'

Selects the channel setup for "Spectrum2".

SYST: PRES: CHAN: EXEC

Restores the factory default settings to the "Spectrum2" channel

setup.

Usage: Event

Manual operation: See "Preset Channel Setup" on page 30

## TRACe:IQ:EVAL <State>

This command turns I/Q data analysis on and off.

Before you can use this command, you have to turn on the I/Q data acquisition using INST:CRE:NEW IQ or INST:CRE:REPL, or using the TRACe:IQ[:STATe] command to replace the current channel setup while retaining the settings.

#### Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: TRAC: IQ ON

Enables I/Q data acquisition

TRAC: IQ: EVAL ON

Enables the I/Q data analysis mode.

#### TRACe:IQ[:STATe] <State>

Executing this command also has the following effects:

- The sweep, amplitude, input and trigger settings from the previous application are retained
- All measurements from the previous application (e.g. Spectrum) are turned off
- All traces are set to "Blank" mode
- The I/Q data analysis mode is turned off (TRAC: IQ: EVAL OFF, if previous application was also I/Q Analyzer)

**Note:** To turn trace display back on or to enable the evaluation functions of the I/Q Analyzer, execute the TRAC: IQ: EVAL ON command (see TRACe: IQ: EVAL on page 109).

#### Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

**ON I 1** 

Switches the function on

Example: TRAC: IQ ON

Switches on I/Q data acquisition

## 9.4 Configuring I/Q Analyzer Measurements

The following commands configure the I/Q Analyzer measurements.

•	Configuring the Data Input and Output	110
•	Configuring the Vertical Axis (Amplitude, Scaling)	122
•	Frequency	127
	Triggering	
	Configuring Data Acquisition	
	Adjusting Settings Automatically	

## 9.4.1 Configuring the Data Input and Output

The following commands are required to configure data input and output.

9.4.1.1

#### Configuring I/Q Analyzer Measurements

RF Input	111
Input from I/Q Data Files	
Working with Power Sensors	
Configuring the Outputs	
RF Input	
INPut <ip>:ATTenuation:PROTection:RESet</ip>	
INPut <ip>:IMPedance</ip>	111
INPut <ip>:SELect</ip>	

#### INPut<ip>:ATTenuation:PROTection:RESet

This command resets the attenuator and reconnects the RF input with the input mixer for the R&S ZNL after an overload condition occurred and the protection mechanism intervened. The error status bit (bit 3 in the STAT: QUES: POW status register) and the INPUT OVLD message in the status bar are cleared.

The command works only if the overload condition has been eliminated first.

For details on the protection mechanism see "RF Input Protection" on page 34.

### Suffix:

<ip> 1 | 2 irrelevant

**Example:** INP:ATT:PROT:RES

#### INPut<ip>:IMPedance < Impedance>

This command selects the nominal input impedance of the RF input. In some applications, only 50  $\Omega$  are supported.

## Suffix:

<ip> 1 | 2 irrelevant

#### Parameters:

<Impedance> 50 | 75

\*RST:  $50 \Omega$  Default unit: OHM

**Example:** INP:IMP 75

Manual operation: See "Impedance" on page 34

See "Unit" on page 43

#### INPut<ip>:SELect <Source>

This command selects the signal source for measurements, i.e. it defines which connector is used to input data to the R&S ZNL.

Suffix:

<ip> 1 | 2

irrelevant

Parameters:

<Source> RF

Radio Frequency ("RF INPUT" connector)

\*RST: RF

Manual operation: See "Radio Frequency State" on page 34

## 9.4.1.2 Input from I/Q Data Files

The input for measurements can be provided from I/Q data files. The commands required to configure the use of such files are described here.

For details see Chapter 4.3, "Basics on Input from I/Q Data Files", on page 26.

Useful commands for retrieving results described elsewhere:

• INPut<ip>: SELect on page 111

## Remote commands exclusive to input from I/Q data files:

#### INPut<ip>:FILE:PATH <FileName>[, <AnalysisBW>]

This command selects the I/Q data file to be used as input for further measurements.

The I/Q data must have a specific format as described in Chapter C, "I/Q Data File Format (iq-tar)", on page 225.

## Suffix:

<ip> 1 | 2

irrelevant

Parameters:

<FileName> String containing the path and name of the source file. The file

extension is \*.iq.tar.

<AnalysisBW> Optionally: The analysis bandwidth to be used by the measure-

ment. The bandwidth must be smaller than or equal to the band-

width of the data that was stored in the file.

Default unit: HZ

**Example:** INP:FILE:PATH 'C:\R\_S\Instr\user\data.iq.tar'

Uses I/Q data from the specified file as input.

## 9.4.1.3 Working with Power Sensors

The following commands describe how to work with power sensors.

These commands require the use of a Rohde & Schwarz power sensor. For a list of supported sensors, see the data sheet.



The [Sensor] connector is provided by the "Additional Interfaces" option R&S FPL1-B5. Additionally, the power sensor measurement requires the option R&S FPL1-K9.

Configuring Power Sensors	113
Configuring Power Sensor Measurements	114
Configuring Power Sensors	
SYSTem:COMMunicate:RDEVice:PMETer:CONFigure:AUTO[:STATe]	113
SYSTem:COMMunicate:RDEVice:PMETer:COUNt?	113

## SYSTem:COMMunicate:RDEVice:PMETer:CONFigure:AUTO[:STATe] <State>

This command turns automatic assignment of a power sensor to the power sensor index on and off.

#### Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

**Example:** SYST:COMM:RDEV:PMET:CONF:AUTO OFF

Manual operation: See "Select" on page 37

## SYSTem:COMMunicate:RDEVice:PMETer:COUNt?

This command queries the number of power sensors currently connected to the R&S ZNL.

#### Suffix:

Power sensor index

Return values:

<NumberSensors> Number of connected power sensors.
Example: SYST:COMM:RDEV:PMET:COUN?

Usage: Query only

Manual operation: See "Select" on page 37

# **SYSTem:COMMunicate:RDEVice:PMETer:DEFine** <Placeholder>, <Type>, <Interface>, <SerialNo>

This command assigns the power sensor with the specified serial number to the selected power sensor index (configuration).

The query returns the power sensor type and serial number of the sensor assigned to the specified index.

Suffix:

Power sensor index

Parameters:

<Placeholder> Currently not used

<Type> Detected power sensor type, e.g. "NRP-Z81".

<Interface> Interface the power sensor is connected to; always "USB"

<SerialNo> Serial number of the power sensor assigned to the specified

index

Example: SYST:COMM:RDEV:PMET2:DEF '','NRP-Z81','',

'123456'

Assigns the power sensor with the serial number '123456' to the

configuration "Power Sensor 2".
SYST:COMM:RDEV:PMET2:DEF?

Queries the sensor assigned to "Power Sensor 2".

Result:

'','NRP-Z81','USB','123456'

The NRP-Z81 power sensor with the serial number '123456' is

assigned to the "Power Sensor 2".

Manual operation: See "Select" on page 37

#### **Configuring Power Sensor Measurements**

CALIBRATION:PMETER:ZERO:AUTO ONCE	113
CALCulate <n>:PMETer:RELative[:MAGNitude]</n>	115
CALCulate <n>:PMETer:RELative[:MAGNitude]:AUTO ONCE</n>	115
CALCulate <n>:PMETer:RELative:STATe</n>	116
FETCh:PMETer?	
READ:PMETer?	116
[SENSe:]PMETer:DCYCle[:STATe]	116
[SENSe:]PMETer:DCYCle:VALue	117
[SENSe:]PMETer:FREQuency	117
[SENSe:]PMETer:FREQuency:LINK	117
[SENSe:]PMETer:MTIMe	118
[SENSe:]PMETer:MTIMe:AVERage:COUNt	118
[SENSe:]PMETer:MTIMe:AVERage[:STATe]	119
[SENSe:]PMETer:ROFFset[:STATe]	119
[SENSe:]PMETer:SOFFset	119
[SENSe:]PMETer[:STATe]	120
[SENSe:]PMETer:UPDate[:STATe]	120
UNIT <n>:PMETer:POWer</n>	120
UNIT <n>:PMETer:POWer:RATio.</n>	121

445

## CALibration:PMETer:ZERO:AUTO ONCE

This command zeroes the power sensor.

Note that you have to disconnect the signals from the power sensor input before you start to zero the power sensor. Otherwise, results are invalid.

Suffix:

Power sensor index

**Example:** CAL: PMET2: ZERO: AUTO ONCE; \*WAI

Starts zeroing the power sensor 2 and delays the execution of

further commands until zeroing is concluded.

Usage: Event

Manual operation: See "Zeroing Power Sensor" on page 37

## CALCulate<n>:PMETer:RELative[:MAGNitude] <RefValue>

This command defines the reference value for relative measurements.

Suffix:

<n> Window

Power sensor index

Parameters:

<RefValue> Range: -200 dBm to 200 dBm

\*RST: 0
Default unit: DBM

**Example:** CALC:PMET2:REL -30

Sets the reference value for relative measurements to -30 dBm

for power sensor 2.

Manual operation: See "Reference Value" on page 38

## CALCulate<n>:PMETer:RELative[:MAGNitude]:AUTO ONCE

This command sets the current measurement result as the reference level for relative measurements.

Suffix:

<n> Window

Power sensor index

**Example:** CALC:PMET2:REL:AUTO ONCE

Takes the current measurement value as reference value for rel-

ative measurements for power sensor 2.

Usage: Event

Manual operation: See "Setting the Reference Level from the Measurement Meas -

> Ref" on page 38

## CALCulate<n>:PMETer:RELative:STATe <State>

This command turns relative power sensor measurements on and off.

Suffix:

<n> Window

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:PMET2:REL:STAT ON

Activates the relative display of the measured value for power

sensor 2.

#### FETCh:PMETer?

This command queries the results of power sensor measurements.

Suffix:

Power sensor index

Usage: Query only

#### READ:PMETer?

This command initiates a power sensor measurement and queries the results.

Suffix:

Power sensor index

Usage: Query only

### [SENSe:]PMETer:DCYCle[:STATe] <State>

This command turns the duty cycle correction on and off.

Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** PMET2:DCYC:STAT ON

Manual operation: See "Duty Cycle" on page 39

## [SENSe:]PMETer:DCYCle:VALue <Percentage>

This command defines the duty cycle for the correction of pulse signals.

The power sensor uses the duty cycle in combination with the mean power to calculate the power of the pulse.

Suffix:

Power sensor

Parameters:

<Percentage> Range: 0.001 to 99.999

\*RST: 99.999 Default unit: %

**Example:** PMET2:DCYC:STAT ON

Activates the duty cycle correction.

PMET2:DCYC:VAL 0.5

Sets the correction value to 0.5%.

Manual operation: See "Duty Cycle" on page 39

#### [SENSe:]PMETer:FREQuency <Frequency>

This command defines the frequency of the power sensor.

Suffix:

Power sensor index

Parameters:

<Frequency> The available value range is specified in the data sheet of the

power sensor in use. \*RST: 50 MHz Default unit: HZ

**Example:** PMET2:FREQ 1GHZ

Sets the frequency of the power sensor to 1 GHz.

Manual operation: See "Frequency Manual" on page 37

#### [SENSe:]PMETer:FREQuency:LINK <Coupling>

This command selects the frequency coupling for power sensor measurements.

Suffix:

Power sensor index

Parameters:

<Coupling> CENTer

Couples the frequency to the center frequency of the analyzer

MARKer1

Couples the frequency to the position of marker 1

**OFF** 

Switches the frequency coupling off

\*RST: CENTer

**Example:** PMET2:FREQ:LINK CENT

Couples the frequency to the center frequency of the analyzer

Manual operation: See "Frequency Coupling" on page 38

#### [SENSe:]PMETer:MTIMe <Duration>

This command selects the duration of power sensor measurements.

Suffix:

Power sensor index

Parameters:

<Duration> SHORt | NORMal | LONG

\*RST: NORMal

**Example:** PMET2:MTIM SHOR

Sets a short measurement duration for measurements of station-

ary high power signals for the selected power sensor.

Manual operation: See "Meas Time/Average" on page 38

## [SENSe:]PMETer:MTIMe:AVERage:COUNt <NumberReadings>

This command sets the number of power readings included in the averaging process of power sensor measurements.

Extended averaging yields more stable results for power sensor measurements, especially for measurements on signals with a low power, because it minimizes the effects of noise.

Suffix:

Power sensor index

Parameters:

<NumberReadings> An average count of 0 or 1 performs one power reading.

Range: 0 to 256

Increment: binary steps (1, 2, 4, 8, ...)

**Example:** PMET2:MTIM:AVER ON

Activates manual averaging.

PMET2:MTIM:AVER:COUN 8

Sets the number of readings to 8.

Manual operation: See "Average Count (Number of Readings)" on page 39

## [SENSe:]PMETer:MTIMe:AVERage[:STATe] <State>

This command turns averaging for power sensor measurements on and off.

Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** PMET2:MTIM:AVER ON

Activates manual averaging.

Manual operation: See "Meas Time/Average" on page 38

#### [SENSe:]PMETer:ROFFset[:STATe] <State>

This command includes or excludes the reference level offset of the analyzer for power sensor measurements.

Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** PMET2:ROFF OFF

Takes no offset into account for the measured power.

Manual operation: See "Use Ref Level Offset" on page 38

#### [SENSe:]PMETer:SOFFset <SensorOffset>

Takes the specified offset into account for the measured power. Only available if [SENSe:]PMETer:ROFFset[:STATe] is disabled.

Suffix:

Power sensor index

Parameters:

<SensorOffset> Default unit: DB

**Example:** PMET2:TRIG:SOFF 0.001

Manual operation: See "Sensor Level Offset" on page 39

## [SENSe:]PMETer[:STATe] <State>

This command turns a power sensor on and off.

Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: PMET1 ON

Switches the power sensor measurements on.

Manual operation: See "State" on page 37

See "Select" on page 37

## [SENSe:]PMETer:UPDate[:STATe] <State>

This command turns continuous update of power sensor measurements on and off.

If on, the results are update even if a single sweep is complete.

Suffix:

Power sensor index

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: PMET1:UPD ON

The data from power sensor 1 is updated continuously.

Manual operation: See "Continuous Value Update" on page 37

#### UNIT<n>:PMETer:POWer <Unit>

This command selects the unit for absolute power sensor measurements.

Suffix:

<n> irrelevant

Power sensor index

Parameters:

<Unit> DBM | WATT | W | DB | PCT

\*RST: DBM

**Example:** UNIT: PMET: POW DBM

Manual operation: See "Unit/Scale" on page 38

## UNIT<n>:PMETer:POWer:RATio <Unit>

This command selects the unit for relative power sensor measurements.

Suffix:

<n> irrelevant

Power sensor index

Parameters:

<Unit> DB | PCT

\*RST: DB

Example: UNIT: PMET: POW: RAT DB

Manual operation: See "Unit/Scale" on page 38

#### 9.4.1.4 Configuring the Outputs

The following commands are required to provide output from the R&S ZNL.

DIAGnostic:SERVice:NSOurce	121
SYSTem:SPEaker[:STATe]	121
SYSTem:SPEaker:VOLume	122

#### DIAGnostic:SERVice:NSOurce <State>

This command turns the 28 V supply of the BNC connector labeled [noise source control] on the R&S ZNL on and off.

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: DIAG:SERV:NSO ON

Manual operation: See "Noise Source Control" on page 41

#### SYSTem:SPEaker[:STATe] <State>

This command switches the built-in loudspeaker on or off for demodulated signals. This setting applies only to the current application.

The command is available in the time domain in Spectrum mode and in Analog Modulation Analysis mode.

To set the volume, use the SYSTem: SPEaker: VOLume command.

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

**ON I 1** 

Switches the function on

Example: SYST: SPE ON

SYST:SPE:VOL 0.5

Sets the loudspeaker to half the full volume.

#### SYSTem:SPEaker:VOLume < Volume >

This command defines the volume of the built-in loudspeaker for demodulated signals. This setting is maintained for all applications.

The command is available in the time domain in Spectrum mode and in Analog Modulation Analysis mode.

Note that you must switch the loudspeaker on first, using the SYSTem: SPEaker[: STATe] command.

#### Parameters:

<Volume> Percentage of the maximum possible volume.

Range: 0 to 1 \*RST: 0.5

**Example:** SYST:SPE:VOL 0

Switches the loudspeaker to mute.

## 9.4.2 Configuring the Vertical Axis (Amplitude, Scaling)

The following commands are required to configure the amplitude and vertical axis settings in a remote environment.

•	Amplitude Settings	122
•	Configuring the Attenuation	.124
•	Scaling the Y-Axis.	125

## 9.4.2.1 Amplitude Settings

Useful commands for amplitude configuration described elsewhere:

• [SENSe:]ADJust:LEVel on page 144

## Remote commands exclusive to amplitude configuration:

CALCulate <n>:MARKer<m>:FUNCtion:REFerence</m></n>	123
CALCulate <n>:UNIT:POWer</n>	123
UNIT <n>:POWer</n>	123
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RLEVel</t></n>	123
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RLEVel:OFFSet</t></n>	124

#### CALCulate<n>:MARKer<m>:FUNCtion:REFerence

This command matches the reference level to the power level of a marker.

If you use the command in combination with a delta marker, that delta marker is turned into a normal marker.

#### Suffix:

<n> Window <m> Marker

**Example:** CALC:MARK2:FUNC:REF

Sets the reference level to the level of marker 2.

**Manual operation:** See "Reference Level = Marker Level" on page 85

## CALCulate<n>:UNIT:POWer <Unit>

UNIT<n>:POWer <Unit>

This command selects the unit of the y-axis.

The unit applies to all power-based measurement windows with absolute values.

#### Suffix:

<n> irrelevant

## Parameters:

<Unit> (Units based on 1 MHz require installed R&S FPL1-K54 (EMI

measurements) option.)

\*RST: dBm

Example: UNIT: POW DBM

Sets the power unit to dBm.

## DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RLEVel <ReferenceLevel>

This command defines the reference level (for all traces in all windows).

With a reference level offset ≠ 0, the value range of the reference level is modified by the offset.

#### Suffix:

<n> irrelevant <t> irrelevant

Parameters:

<ReferenceLevel> The unit is variable.

Range: see datasheet

\*RST: 0 dBm Default unit: DBM

**Example:** DISP:TRAC:Y:RLEV -60dBm

Manual operation: See "Reference Level" on page 43

#### DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RLEVel:OFFSet <Offset>

This command defines a reference level offset (for all traces in all windows).

Suffix:

<n> irrelevant <t> irrelevant

Parameters:

<Offset> Range: -200 dB to 200 dB

\*RST: 0dB Default unit: DB

**Example:** DISP:TRAC:Y:RLEV:OFFS -10dB

Manual operation: See "Shifting the Display (Offset)" on page 43

#### 9.4.2.2 Configuring the Attenuation

INPut <ip>:ATTenuation</ip>	124
INPut <ip>:EATT:AUTO</ip>	125
INPut <ip>:ATTenuation:AUTO</ip>	125

#### INPut<ip>:ATTenuation < Attenuation>

This command defines the total attenuation for RF input.

If you set the attenuation manually, it is no longer coupled to the reference level, but the reference level is coupled to the attenuation. Thus, if the current reference level is not compatible with an attenuation that has been set manually, the command also adjusts the reference level.

Suffix:

<ip> 1 | 2

irrelevant

Parameters:

<a href="#"><Attenuation></a> Range: see data sheet

Increment: 5 dB (with optional electr. attenuator: 1 dB)

\*RST: 10 dB (AUTO is set to ON)

Default unit: DB

**Example:** INP:ATT 30dB

Defines a 30 dB attenuation and decouples the attenuation from

the reference level.

Manual operation: See "Attenuation Mode / Value" on page 44

INPut<ip>:EATT:AUTO <State>
INPut<ip>:ATTenuation:AUTO <State>

This command couples or decouples the attenuation to the reference level. Thus, when the reference level is changed, the R&S ZNL determines the signal level for optimal internal data processing and sets the required attenuation accordingly.

For the R&S ZNL, these commands are identical.

Suffix:

<ip> 1 | 2 irrelevant

Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

Example: INP:ATT:AUTO ON

Couples the attenuation to the reference level.

Manual operation: See "Attenuation Mode / Value" on page 44

#### 9.4.2.3 Scaling the Y-Axis

DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]</t></n>	125
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:AUTO ONCE</t></n>	
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:Y[:SCALe]:MODE</t></w></n>	126
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RPOSition</t></n>	126
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing</t></w></n>	127

#### DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe] <Range>

This command defines the display range of the y-axis (for all traces).

Note that the command works only for a logarithmic scaling. You can select the scaling with DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing.

Suffix:

<n> Window <t> irrelevant

Parameters:

<Range> Range: 1 dB to 200 dB

\*RST: 100 dB Default unit: HZ

**Example:** DISP:TRAC:Y 110dB

Manual operation: See "Range" on page 45

See "Y-Axis Max" on page 46

## DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:AUTO ONCE

Automatic scaling of the y-axis is performed once, then switched off again (for all traces).

Suffix:

<n> Window <t> irrelevant

## DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y[:SCALe]:MODE <Mode>

This command selects the type of scaling of the y-axis (for all traces).

When the display update during remote control is off, this command has no immediate effect.

Suffix:

<n> window
<w> subwindow
<t> irrelevant

Parameters:

<Mode> ABSolute

absolute scaling of the y-axis

**RELative** 

relative scaling of the y-axis \*RST: ABSolute

**Example:** DISP:TRAC:Y:MODE REL

Manual operation: See "Scaling" on page 45

## DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe]:RPOSition < Position>

This command defines the vertical position of the reference level on the display grid (for all traces).

The R&S ZNL adjusts the scaling of the y-axis accordingly.

Suffix:

<n> Window <t> irrelevant

**Example:** DISP:TRAC:Y:RPOS 50PCT

Manual operation: See "Ref Level Position" on page 45

## DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing <ScalingType>

This command selects the scaling of the y-axis (for all traces, <t> is irrelevant).

#### Suffix:

<n> Window

<w> subwindow

<t> Trace

Parameters:

<ScalingType> LOGarithmic

Logarithmic scaling.

LINear

Linear scaling in %.

**LDB** 

Linear scaling in the specified unit.

**PERCent** 

Linear scaling in %.

\*RST: LOGarithmic

**Example:** DISP:TRAC:Y:SPAC LIN

Selects linear scaling in %.

Manual operation: See "Scaling" on page 45

## 9.4.3 Frequency

CALCulate <n>:MARKer<m>:FUNCtion:CENTer</m></n>	127
[SENSe:]FREQuency:CENTer	128
[SENSe:]FREQuency:CENTer:STEP	
[SENSe:]FREQuency:CENTer:STEP:AUTO	128
ISENSe:IFREQuency:OFFSet	129

#### CALCulate<n>:MARKer<m>:FUNCtion:CENTer

This command matches the center frequency to the frequency of a marker.

If you use the command in combination with a delta marker, that delta marker is turned into a normal marker.

#### Suffix:

<n> Window <m> Marker

**Example:** CALC:MARK2:FUNC:CENT

Sets the center frequency to the frequency of marker 2.

Manual operation: See "Center Frequency = Marker Frequency" on page 85

#### [SENSe:]FREQuency:CENTer <Frequency>

This command defines the center frequency.

Parameters:

<Frequency> The allowed range and f<sub>max</sub> is specified in the data sheet.

\*RST: fmax/2 Default unit: Hz

**Example:** FREQ:CENT 100 MHz

FREQ:CENT:STEP 10 MHz

FREQ:CENT UP

Sets the center frequency to 110 MHz.

Manual operation: See "Center Frequency" on page 47

## [SENSe:]FREQuency:CENTer:STEP <StepSize>

This command defines the center frequency step size.

You can increase or decrease the center frequency quickly in fixed steps using the SENS: FREQ UP AND SENS: FREQ DOWN commands, see [SENSe:] FREQuency: CENTer on page 128.

#### Parameters:

<StepSize> f<sub>max</sub> is specified in the data sheet.

Range: 1 to fMAX \*RST: 0.1 x span

Default unit: Hz

**Example:** //Set the center frequency to 110 MHz.

FREQ:CENT 100 MHz
FREQ:CENT:STEP 10 MHz

FREQ:CENT UP

Manual operation: See "Center Frequency Stepsize" on page 47

## [SENSe:]FREQuency:CENTer:STEP:AUTO <State>

This command couples or decouples the center frequency step size to the span.

In time domain (zero span) measurements, the center frequency is coupled to the RBW.

#### Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

**Example:** FREQ:CENT:STEP:AUTO ON

Activates the coupling of the step size to the span.

## [SENSe:]FREQuency:OFFSet <Offset>

This command defines a frequency offset.

If this value is not 0 Hz, the application assumes that the input signal was frequency shifted outside the application. All results of type "frequency" will be corrected for this shift numerically by the application.

See also "Frequency Offset" on page 47.

#### Parameters:

<Offset> Range: -1 THz to 1 THz

\*RST: 0 Hz Default unit: HZ

**Example:** FREQ:OFFS 1GHZ

Manual operation: See "Frequency Offset" on page 47

## 9.4.4 Triggering

The following remote commands are required to configure a triggered measurement in a remote environment. More details are described for manual operation in Chapter 5.6, "Trigger Settings", on page 48.



\*OPC should be used after requesting data. This will hold off any subsequent changes to the selected trigger source, until after the sweep is completed and the data is returned.

- 9.4.4.1 Configuring the Triggering Conditions

The following commands are required to configure a triggered measurement.

TRIGger[:SEQuence]:DTIMe	129
TRIGger[:SEQuence]:HOLDoff[:TIME]	130
TRIGger[:SEQuence]:IFPower:HOLDoff	130
TRIGger[:SEQuence]:IFPower:HYSTeresis	130
TRIGger[:SEQuence]:LEVel[:EXTernal <port>]</port>	131
TRIGger[:SEQuence]:LEVel:IFPower	131
TRIGger[:SEQuence]:LEVel:IQPower	131
TRIGger[:SEQuence]:SLOPe	132
TRIGger[:SEQuence]:SOURce	132
TRIGger[:SEQuence]:TIME:RINTerval	133

## TRIGger[:SEQuence]:DTIMe < DropoutTime>

Defines the time the input signal must stay below the trigger level before a trigger is detected again.

Parameters:

<DropoutTime> Dropout time of the trigger.

Range: 0 s to 10.0 s

\*RST: 0 s Default unit: S

Manual operation: See "Drop-Out Time" on page 50

## TRIGger[:SEQuence]:HOLDoff[:TIME] <Offset>

Defines the time offset between the trigger event and the start of the sweep.

Parameters:

<Offset> For measurements in the frequency domain, the range is 0 s to

30 s.

For measurements in the time domain, the range is the negative

sweep time to 30 s.

\*RST: 0 s Default unit: S

**Example:** TRIG: HOLD 500us

Manual operation: See "Trigger Offset" on page 50

#### TRIGger[:SEQuence]:IFPower:HOLDoff < Period >

This command defines the holding time before the next trigger event.

Note that this command can be used for **any trigger source**, not just IF Power (despite the legacy keyword).

Parameters:

<Period> Range: 0 s to 10 s

\*RST: 0 s
Default unit: S

**Example:** TRIG:SOUR EXT

Sets an external trigger source. TRIG: IFP: HOLD 200 ns Sets the holding time to 200 ns.

Manual operation: See "Trigger Holdoff" on page 51

#### TRIGger[:SEQuence]:IFPower:HYSTeresis < Hysteresis >

This command defines the trigger hysteresis, which is only available for "IF Power" trigger sources.

Parameters:

<Hysteresis> Range: 3 dB to 50 dB

\*RST: 3 dB Default unit: DB

Example: TRIG:SOUR IFP

Sets the IF power trigger source.

TRIG: IFP: HYST 10DB

Sets the hysteresis limit value.

Manual operation: See "Hysteresis" on page 50

#### TRIGger[:SEQuence]:LEVel[:EXTernal<port>] < TriggerLevel>

This command defines the level the external signal must exceed to cause a trigger event.

In the I/Q Analyzer application, only EXTernal1 is supported.

#### Parameters:

<TriggerLevel> For the R&S ZNL, the external trigger level is always 1.4 V. It

cannot be changed.

\*RST: 1.4 V

Manual operation: See "Trigger Level" on page 50

#### TRIGger[:SEQuence]:LEVel:IFPower < TriggerLevel>

This command defines the power level at the third intermediate frequency that must be exceeded to cause a trigger event.

Note that any RF attenuation is considered when the trigger level is analyzed. If defined, a reference level offset is also considered.

#### Parameters:

<TriggerLevel> For details on available trigger levels and trigger bandwidths see

the data sheet.

\*RST: -10 dBm Default unit: DBM

**Example:** TRIG:LEV:IFP -30DBM

Manual operation: See "Trigger Level" on page 50

## TRIGger[:SEQuence]:LEVel:IQPower < TriggerLevel>

This command defines the magnitude the I/Q data must exceed to cause a trigger event.

Note that any RF attenuation is considered when the trigger level is analyzed. If defined, a reference level offset is also considered.

#### Parameters:

<TriggerLevel> Range: -130 dBm to 30 dBm

\*RST: -20 dBm Default unit: DBM

**Example:** TRIG:LEV:IQP -30DBM

Manual operation: See "Trigger Level" on page 50

TRIGger[:SEQuence]:SLOPe <Type>

Parameters:

<Type> POSitive | NEGative

**POSitive** 

Triggers when the signal rises to the trigger level (rising edge).

**NEGative** 

Triggers when the signal drops to the trigger level (falling edge).

\*RST: POSitive

Example: TRIG:SLOP NEG

Manual operation: See "Slope" on page 51

#### TRIGger[:SEQuence]:SOURce <Source>

This command selects the trigger source.

For details on trigger sources see "Trigger Source" on page 49.

## Note on external triggers:

If a measurement is configured to wait for an external trigger signal in a remote control program, remote control is blocked until the trigger is received and the program can continue. Make sure this situation is avoided in your remote control programs.

#### Parameters:

<Source> IMMediate

Free Run

IFPower

Second intermediate frequency

**IQPower** 

Magnitude of sampled I/Q data

For applications that process I/Q data, such as the I/Q Analyzer

or optional applications.

**VIDeo** 

Video mode is available in the time domain and only in the

Spectrum application.

**BBPower** 

Baseband power (for digital input via the optional Digital Base-

band Interface

\*RST: IMMediate

**Example:** TRIG:SOUR EXT

Selects the external trigger input as source of the trigger signal

Manual operation: See "Trigger Source" on page 49

See "Free Run" on page 49

See "ExternalTrigger 1" on page 49

See "IF Power" on page 49 See "I/Q Power" on page 49 See "Time" on page 49

## TRIGger[:SEQuence]:TIME:RINTerval <Interval>

This command defines the repetition interval for the time trigger.

Parameters:

<Interval> 2.0 ms to 5000

Range: 2 ms to 5000 s

\*RST: 1.0 s Default unit: S

**Example:** TRIG:SOUR TIME

Selects the time trigger input for triggering.

TRIG:TIME:RINT 50
The sweep starts every 50 s.

Manual operation: See "Repetition Interval" on page 50

#### 9.4.4.2 Configuring I/Q Gating

Usually in spectrum analysis, measurements are based on a certain length of time called the gate area. With I/Q gating, you can define the gate area using the gate length, the distance between the capture periods and the number of periods. The gate length and the distance between the capture periods are specified in samples.




I/Q gating is only available using remote commands; manual configuration is not possible

It is only possible up to a bandwidth of 12.8 MHz.


Using I/Q gating, the gate area can be defined using the following methods:

Edge triggered capturing
 After a trigger signal, the gate period is defined by a gate length and a gate distance. All data in the gate period is captured until the required number of samples has been captured.



## Level triggered capturing

After a trigger signal, all data is captured in which the gate signal is set to 1, which means it has exceeded a level. In this case, the gate signal can be generated by the IFP trigger, for example: each time the IFP level is exceeded, the IFP trigger signal is set to 1 and the samples in this area are captured as gate samples.



The number of complex samples to be captured prior to the trigger event can be selected (see TRACe: IQ: SET on page 140) for all available trigger sources, except for "Free Run".

#### TRACe:IQ:EGATe[:STATe] <State>

This command turns gated measurements with the I/Q analyzer on and off.

Before you can use the command you have to turn on the I/Q analyzer and select an external or IF power trigger source.

## Parameters:

<State> ON | OFF

**Example:** TRAC:IQ:EGAT ON

### TRACe:IQ:EGATe:GAP <Samples>

This command defines the interval between several gate periods for gated measurements with the I/Q analyzer.

Parameters:

<Samples> <numeric value>

Max = (440 MS \* sample rate/200MHz) -1 pretrigger samples defined by TRACe:IQ:SET; sample rate defined by TRACe:IQ:SRATe)

Range: 1...Max (samples)

\*RST: 1

**Example:** TRAC:IQ:EGAT:GAP 2

#### TRACe:IQ:EGATe:LENGth < GateLength>

This command defines the gate length for gated measurements with the I/Q analyzer.

Parameters:

<GateLength> <numeric value>

Max = (440 MS \* sample rate/200MHz) -1
pretrigger samples defined by TRACe:IQ:SET;
sample rate defined by TRACe:IQ:SRATe)

Range: 1...Max (samples)

\*RST: 100

**Example:** TRAC: IQ:EGAT: LENG 2000

### TRACe:IQ:EGATe:NOF < Number>

This command defines the number of gate periods after the trigger signal for gated measurements with the I/Q analyzer.

Parameters:

<Number> Range: 1 to 1023

\*RST: 1

**Example:** TRAC:IQ:EGAT:NOF 2

## TRACe:IQ:EGATe:TYPE <Type>

This command selects the gate mode for gated measurements with the I/Q analyzer.

**Note**: The IF power trigger holdoff time is ignored if you are using the "Level" gate mode in combination with an IF Power trigger.

Parameters:

<Type> LEVel

**EDGE** 

\*RST: EDGE

**Example:** TRAC:IQ:EGAT:TYPE LEV

## 9.4.5 Configuring Data Acquisition

The following commands are required to capture data in the I/Q Analyzer.

#### Useful commands for I/Q data acquisition described elsewhere

- [SENSe:] SWEep:COUNt on page 156
- [SENSe:]SWEep[:WINDow<n>]:POINts on page 156
- [SENSe:] SWEep:TIME on page 157

## Remote commands exclusive to I/Q data acquisition

[SENSe:]IQ:BANDwidth:MODE	136
[SENSe:]IQ:BWIDth:MODE	136
[SENSe:]IQ:BANDwidth:RESolution	137
[SENSe:]IQ:BWIDth:RESolution	137
[SENSe:]IQ:FFT:ALGorithm	137
[SENSe:]IQ:FFT:LENGth	
[SENSe:]IQ:FFT:WINDow:LENGth	
[SENSe:]IQ:FFT:WINDow:OVERlap	138
[SENSe:]IQ:FFT:WINDow:TYPE	138
[SENSe:]SWAPiq	139
TRACe:IQ:BWIDth	
TRACe:IQ:RLENgth	139
TRACe:IQ:SET	
TRACe:IQ:SRATe	141
TRACe:IQ:TPISample?	

[SENSe:]IQ:BANDwidth:MODE <Mode>
[SENSe:]IQ:BWIDth:MODE <Mode>

This command defines how the resolution bandwidth is determined.

#### Parameters:

<Mode> AUTO | MANual | FFT

#### **AUTO**

(Default) The RBW is determined automatically depending on the sample rate and record length.

#### **MANual**

The user-defined RBW is used and the (FFT) window length (and possibly the sample rate) are adapted accordingly. The RBW is defined using the [SENSe:]IQ:BWIDth:RESolution command.

#### **FFT**

The RBW is determined by the FFT parameters.

\*RST: AUTO

**Example:** IQ:BAND:MODE MAN

Switches to manual RBW mode.

IQ:BAND:RES 120000 Sets the RBW to 120 kHz.

Manual operation: See "RBW" on page 53

[SENSe:]IQ:BANDwidth:RESolution <Bandwidth> [SENSe:]IQ:BWIDth:RESolution <Bandwidth>

This command defines the resolution bandwidth manually if [SENSe:]IQ:BWIDth: MODE is set to MAN.

Defines the resolution bandwidth. The available RBW values depend on the sample rate and record length.

Parameters:

<Bandwidth> refer to data sheet

\*RST: RBW: AUTO mode is used

Default unit: HZ

**Example:** IQ:BAND:MODE MAN

Switches to manual RBW mode.

IQ:BAND:RES 120000 Sets the RBW to 120 kHz.

Manual operation: See "RBW" on page 53

## [SENSe:]IQ:FFT:ALGorithm < Method>

Defines the FFT calculation method.

Parameters:

<Method> SINGle

One FFT is calculated for the entire record length; if the FFT length is larger than the record length (see [SENSe:]IQ:FFT: LENGth and TRACe:IQ:RLENgth), zeros are appended to the

captured data.

**AVERage** 

Several overlapping FFTs are calculated for each record; the results are averaged to determine the final FFT result for the

record.

The user-defined window length and window overlap are used (see [SENSe:]IQ:FFT:WINDow:LENGth and [SENSe:]IQ:

FFT:WINDow:OVERlap).

\*RST: AVER

**Example:** IQ:FFT:ALG SING

Manual operation: See "TransformationAlgorithm" on page 54

## [SENSe:]IQ:FFT:LENGth < NoOfBins>

Defines the number of frequency points determined by each FFT calculation. The more points are used, the higher the resolution in the spectrum becomes, but the longer the calculation takes.

Parameters:

<NoOfBins> integer value

Range: 3 to 524288

\*RST: 4096

**Example:** IQ:FFT:LENG 2048

Manual operation: See "FFT Length" on page 54

#### [SENSe:]IQ:FFT:WINDow:LENGth < NoOfFFT>

Defines the number of samples to be included in a single FFT window when multiple FFT windows are used.

Parameters:

<NoOfFFT> integer value

Range: 3 to 1001 \*RST: 1001

**Example:** IQ:FFT:WIND:LENG 500

Manual operation: See "Window Length" on page 55

#### [SENSe:]IQ:FFT:WINDow:OVERIap <Rate>

Defines the part of a single FFT window that is re-calculated by the next FFT calculation.

Parameters:

<Rate> double value

Percentage rate
Range: 0 to 1
\*RST: 0.75

**Example:** IQ:FFT:WIND:OVER 0.5

Half of each window overlaps the previous window in FFT calcu-

lation.

Manual operation: See "Window Overlap" on page 55

## [SENSe:]IQ:FFT:WINDow:TYPE <Function>

In the I/Q Analyzer you can select one of several FFT window types.

Parameters:

<Function> BLACkharris

Blackman-Harris

FLATtop Flattop GAUSsian Gauss

**RECTangular** Rectangular

P5 5-Term

\*RST: FLAT

**Example:** IQ:FFT:WIND:TYPE GAUS

Manual operation: See "Window Function" on page 54

#### [SENSe:]SWAPiq <State>

This command defines whether or not the recorded I/Q pairs should be swapped (I<>Q) before being processed. Swapping I and Q inverts the sideband.

This is useful if the DUT interchanged the I and Q parts of the signal; then the R&S ZNL can do the same to compensate for it.

#### Parameters:

<State> ON | 1

I and Q signals are interchanged

Inverted sideband, Q+j\*I

OFF | 0

I and Q signals are not interchanged

Normal sideband, I+j\*Q

\*RST: 0

Manual operation: See "Swap I/Q" on page 53

#### TRACe:IQ:BWIDth

This command defines or queries the bandwidth of the resampling filter.

The bandwidth of the resampling filter depends on the sample rate.

Parameters:

<Bandwidth> Default unit: HZ

Manual operation: See "Analysis Bandwidth" on page 52

## TRACe:IQ:RLENgth < NoOfSamples>

This command sets the record length for the acquired I/Q data.

Increasing the record length also increases the measurement time.

**Note**: Alternatively, you can define the measurement time using the SENS: SWE: TIME command.

Parameters:

<NoOfSamples> Number of samples to record.

\*RST: 1001

**Example:** TRAC:IQ:RLEN 256

Manual operation: See "Record Length" on page 53

**TRACe:IQ:SET** <NORM>, <0>, <SampleRate>, <TriggerMode>, <TriggerSlope>, <PretriggerSamp>, <NumberSamples>

This command sets up the R&S ZNL for I/Q measurements.

If you do not use this command to set up I/Q measurements, the R&S ZNL will use its current settings for I/Q measurements.

If the I/Q Analyzer has not been turned on previously, the command also switches to the I/Q Analyzer.

**Note:** If you use the default settings with TRACe:IQ:DATA?, the following minimum buffer sizes for the response data are recommended:

ASCII format: 10 kBytes Binary format: 2 kBytes

Parameters:

Norm This value is always NORM.

0 Default unit: HZ

This value is always 0.

<SampleRate> Sample rate for the data acquisition.

Range: 100 Hz to 10 GHz, continuously adjustable

\*RST: 32000000 Default unit: HZ

<TriggerMode> Selection of the trigger source used for the measurement.

IMMediate | EXTernal | EXT2 | EXT3 | IFPower For IMM mode, gating is automatically deactivated.

\*RST: IMM

<TriggerSlope> Used trigger slope.

POSitive | NEGative

\*RST: POS

<PretriggerSamp> Defines the trigger offset in terms of pretrigger samples. Nega-

tive values correspond to a trigger delay.

This value also defines the interval between the trigger signal

and the gate edge in samples.

Range: -1399999999 to 1399999999

\*RST: 0

<NumberSamples> Number of measurement values to record (including the pretrig-

ger samples).

\*RST: 1001

Example: TRAC: IQ: SET NORM, 0, 32MHz, EXT, POS, 0, 2048

Reads 2048 I/Q-values starting at the trigger point.

sample rate = 32 MHz trigger = External slope = Positive

TRAC: IQ: SET NORM, 0, 4 MHz, EXT, POS, 1024, 512

Reads 512 I/Q-values from 1024 measurement points before the

trigger point.

filter type = NORMAL sample rate = 4 MHz trigger = External slope = Positive

Manual operation: See "Record Length" on page 53

#### TRACe:IQ:SRATe <SampleRate>

This command sets the final user sample rate for the acquired I/Q data. Thus, the user sample rate can be modified without affecting the actual data capturing settings on the R&S ZNL.

#### Parameters:


<SampleRate> \*RST: 32 MHz

Default unit: HZ

Manual operation: See "Sample Rate" on page 52

#### TRACe:IQ:TPISample?

This command queries the time offset between the sample start and the trigger event (trigger point in sample = TPIS). Since the R&S ZNL usually samples with a much higher sample rate than the specific application actually requires, the trigger point determined internally is much more precise than the one determined from the (downsampled) data in the application. Thus, the TPIS indicates the offset between the sample start and the actual trigger event.



This value can only be determined in triggered measurements using external or IFPower triggers, otherwise the value is 0.

Return values:

<TPIS> numeric value

Default unit: s

**Example:** TRAC: IQ: TPIS?

Result for a sample rate of 1 MHz: between 0 and 1/1 MHz, i.e.

between 0 and 1  $\mu$ s (the duration of 1 sample).

Usage: Query only

Manual operation: See "Trigger Offset" on page 50

## 9.4.6 Adjusting Settings Automatically

The commands required to adjust settings automatically in a remote environment are described here.

[SENSe:]ADJust:ALL	.142
[SENSe:]ADJust:CONFigure:DURation	
[SENSe:]ADJust:CONFigure:DURation:MODE	.143
[SENSe:]ADJust:CONFigure:HYSTeresis:LOWer	143
[SENSe:]ADJust:CONFigure:HYSTeresis:UPPer	. 144
[SENSe:]ADJust:CONFigure:TRIGger	.144
[SENSe:]ADJust:FREQuency	. 144
[SENSe:]ADJust:LEVel	. 144

## [SENSe:]ADJust:ALL

This command initiates a measurement to determine and set the ideal settings for the current task automatically (only once for the current measurement).

This includes:

Reference level

**Example:** ADJ:ALL

Manual operation: See "Adjusting all Determinable Settings Automatically (Auto

All)" on page 58

#### [SENSe:]ADJust:CONFigure:DURation < Duration>

In order to determine the ideal reference level, the R&S ZNL performs a measurement on the current input data. This command defines the length of the measurement if [SENSe:] ADJust:CONFigure:DURation:MODE is set to MANual.

Parameters:

<Duration> Numeric value in seconds

Range: 0.001 to 16000.0

\*RST: 0.001 Default unit: s

**Example:** ADJ:CONF:DUR:MODE MAN

Selects manual definition of the measurement length.

ADJ:CONF:LEV:DUR 5ms

Length of the measurement is 5 ms.

Manual operation: See "Changing the Automatic Measurement Time (MeastimeMa-

nual)" on page 59

#### [SENSe:]ADJust:CONFigure:DURation:MODE < Mode>

In order to determine the ideal reference level, the R&S ZNL performs a measurement on the current input data. This command selects the way the R&S ZNL determines the length of the measurement .

#### Parameters:

<Mode> AUTO

The R&S ZNL determines the measurement length automatically

according to the current input data.

**MANual** 

The R&S ZNL uses the measurement length defined by [SENSe:] ADJust:CONFigure:DURation on page 142.

\*RST: AUTO

Manual operation: See "Resetting the Automatic Measurement Time (Measti-

meAuto)" on page 59

See "Changing the Automatic Measurement Time (MeastimeMa-

nual)" on page 59

#### [SENSe:]ADJust:CONFigure:HYSTeresis:LOWer <Threshold>

When the reference level is adjusted automatically using the [SENSe:]ADJust: LEVel on page 144 command, the internal attenuators are also adjusted. In order to avoid frequent adaptation due to small changes in the input signal, you can define a hysteresis. This setting defines a lower threshold the signal must fall below (compared to the last measurement) before the reference level is adapted automatically.

#### Parameters:

<Threshold> Range: 0 dB to 200 dB

\*RST: +1 dB Default unit: dB

**Example:** SENS:ADJ:CONF:HYST:LOW 2

For an input signal level of currently 20 dBm, the reference level will only be adjusted when the signal level falls below 18 dBm.

Manual operation: See "Lower Level Hysteresis" on page 60

#### [SENSe:]ADJust:CONFigure:HYSTeresis:UPPer <Threshold>

When the reference level is adjusted automatically using the [SENSe:]ADJust:
LEVel on page 144 command, the internal attenuators are also adjusted. In order to
avoid frequent adaptation due to small changes in the input signal, you can define a
hysteresis. This setting defines an upper threshold the signal must exceed (compared
to the last measurement) before the reference level is adapted automatically.

Parameters:

<Threshold> Range: 0 dB to 200 dB

\*RST: +1 dB Default unit: dB

**Example:** SENS:ADJ:CONF:HYST:UPP 2

**Example:** For an input signal level of currently 20 dBm, the reference level

will only be adjusted when the signal level rises above 22 dBm.

Manual operation: See "Upper Level Hysteresis" on page 60

#### [SENSe:]ADJust:CONFigure:TRIGger <State>

Defines the behavior of the measurement when adjusting a setting automatically (using SENS:ADJ:LEV ON, for example).

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

## [SENSe:]ADJust:FREQuency

This command sets the center frequency to the frequency with the highest signal level in the current frequency range.

**Example:** ADJ: FREQ

Manual operation: See "Adjusting the Center Frequency Automatically (Auto Fre-

quency)" on page 59

#### [SENSe:]ADJust:LEVel

This command initiates a single (internal) measurement that evaluates and sets the ideal reference level for the current input data and measurement settings. This ensures that the settings of the RF attenuation and the reference level are optimally adjusted to the signal level without overloading the R&S ZNL or limiting the dynamic range by an S/N ratio that is too small.

**Example:** ADJ:LEV

Manual operation: See "Setting the Reference Level Automatically (Auto Level)"

on page 43

# 9.5 Configuring the Result Display

The commands required to configure the screen display in a remote environment are described here.

•	General Window Commands	145
•	Working with Windows in the Display	145

## 9.5.1 General Window Commands

The following commands are required to configure general window layout, independent of the application.

Note that the suffix <n> always refers to the window *in the currently selected channel* setup (see INSTrument[:SELect] on page 109).

DISPlay[:WINDow <n>]:SIZE</n>	145
-------------------------------	-----

#### DISPlay[:WINDow<n>]:SIZE <Size>

This command maximizes the size of the selected result display window *temporarily*. To change the size of several windows on the screen permanently, use the LAY: SPL command (see LAYout: SPLitter on page 149).

#### Suffix:

<n> Window

#### Parameters:

<Size> LARGe

Maximizes the selected window to full screen. Other windows are still active in the background.

**SMALI** 

Reduces the size of the selected window to its original size. If more than one measurement window was displayed originally,

these are visible again.

\*RST: SMALI

**Example:** DISP:WIND2:SIZE LARG

## 9.5.2 Working with Windows in the Display

The following commands are required to change the evaluation type and rearrange the screen layout for a channel setup as you do using the SmartGrid in manual operation.

Since the available evaluation types depend on the selected application, some parameters for the following commands also depend on the selected channel setup.

Note that the suffix <n> always refers to the window *in the currently selected channel* setup (see INSTrument[:SELect] on page 109).

_AYout:ADD[:WINDow]?	. 146
_AYout:CATalog[:WINDow]?	
_AYout:IDENtify[:WINDow]?	. 147
_AYout:MOVE[:WINDow]	148
_AYout:REMove[:WINDow]	148
_AYout:REPLace[:WINDow]	. 149
_AYout:SPLitter	.149
_AYout:WINDow <n>:ADD?</n>	150
_AYout:WINDow <n>:IDENtify?</n>	151
_AYout:WINDow <n>:REMove</n>	.151
_AYout:WINDow <n>:REPLace</n>	151

## LAYout:ADD[:WINDow]? <WindowName>, <Direction>, <WindowType>

This command adds a window to the display in the active channel setup.

This command is always used as a query so that you immediately obtain the name of the new window as a result.

To replace an existing window, use the LAYout:REPLace[:WINDow] command.

#### **Query parameters:**

<WindowName> String containing

String containing the name of the existing window the new win-

dow is inserted next to.

By default, the name of a window is the same as its index. To determine the name and index of all active windows, use the

LAYout: CATalog[:WINDow]? query.

Direction the new window is added relative to the existing win-

dow.

<WindowType> text value

Type of result display (evaluation method) you want to add.

See the table below for available parameter values.

#### Return values:

<NewWindowName> When adding a new window, the command returns its name (by

default the same as its number) as a result.

Example: LAY:ADD? '1', LEFT, MTAB

Result:

Adds a new window named '2' with a marker table to the left of

window 1.

Usage: Query only

Manual operation: See "Magnitude" on page 13

See "Spectrum" on page 13
See "I/Q-Vector" on page 14
See "Real/Imag (I/Q)" on page 15
See "Marker Table" on page 15
See "Marker Peak List" on page 16

Table 9-3: <WindowType> parameter values for IQ Analyzer application

Parameter value	Window type
FREQ	Spectrum
MAGN	Magnitude
MTABle	Marker table
PEAKlist	Marker peak list
RIMAG	Real/Imag (I/Q)
VECT	I/Q Vector

## LAYout:CATalog[:WINDow]?

This command queries the name and index of all active windows in the active channel setup from top left to bottom right. The result is a comma-separated list of values for each window, with the syntax:

<WindowName\_1>,<WindowIndex\_1>..<WindowName\_n>,<WindowIndex\_n>

#### Return values:

<WindowName> string

Name of the window.

In the default state, the name of the window is its index.

<WindowIndex> numeric value

Index of the window.

**Example:** LAY: CAT?

Result:

'2',2,'1',1

Two windows are displayed, named '2' (at the top or left), and '1'

(at the bottom or right).

Usage: Query only

## LAYout:IDENtify[:WINDow]? <WindowName>

This command queries the **index** of a particular display window in the active channel setup.

**Note**: to query the **name** of a particular window, use the LAYout:WINDow<n>: IDENtify? query.

**Query parameters:** 

<WindowName> String containing the name of a window.

Return values:

<WindowIndex>
Index number of the window.

Example: LAY:WIND:IDEN? '2'

Queries the index of the result display named '2'.

Response:

2

Usage: Query only

LAYout:MOVE[:WINDow] <WindowName>, <WindowName>, <Direction>

Setting parameters:

<WindowName> String containing the name of an existing window that is to be

moved.

By default, the name of a window is the same as its index. To determine the name and index of all active windows in the active channel setup, use the LAYout: CATalog[:WINDow]? query.

<WindowName> String containing the name of an existing window the selected

window is placed next to or replaces.

By default, the name of a window is the same as its index. To determine the name and index of all active windows in the active channel setup, use the LAYout:CATalog[:WINDow]? query.

<Direction> LEFT | RIGHt | ABOVe | BELow | REPLace

Destination the selected window is moved to, relative to the ref-

erence window.

Example: LAY:MOVE '4', '1', LEFT

Moves the window named '4' to the left of window 1.

**Example:** LAY:MOVE '1', '3', REPL

Replaces the window named '3' by window 1. Window 3 is

deleted.

**Usage:** Setting only

LAYout:REMove[:WINDow] <WindowName>

This command removes a window from the display in the active channel.

Setting parameters:

<WindowName> String containing the name of the window. In the default state,

the name of the window is its index.

Example: LAY: REM '2'

Removes the result display in the window named '2'.

**Usage:** Setting only

## LAYout:REPLace[:WINDow] <WindowName>,<WindowType>

This command replaces the window type (for example from "Diagram" to "Result Summary") of an already existing window in the active channel setup while keeping its position, index and window name.

To add a new window, use the LAYout:ADD[:WINDow]? command.

#### Setting parameters:

<WindowName> String containing the name of the existing window.

By default, the name of a window is the same as its index. To determine the name and index of all active windows in the active channel setup, use the LAYout:CATalog[:WINDow]? query.

<WindowType> Type of result display you want to use in the existing window.

See LAYout: ADD[:WINDow]? on page 146 for a list of availa-

ble window types.

Example: LAY:REPL:WIND '1', MTAB

Replaces the result display in window 1 with a marker table.

**Usage:** Setting only

#### LAYout:SPLitter < Index1>, < Index2>, < Position>

This command changes the position of a splitter and thus controls the size of the windows on each side of the splitter.

Note that windows must have a certain minimum size. If the position you define conflicts with the minimum size of any of the affected windows, the command will not work, but does not return an error.



Figure 9-1: SmartGrid coordinates for remote control of the splitters

#### Setting parameters:

<Index1> The index of one window the splitter controls.

<Index2> The index of a window on the other side of the splitter.

<Position> New vertical or horizontal position of the splitter as a fraction of

the screen area (without channel and status bar and softkey

menu).

The point of origin (x = 0, y = 0) is in the lower left corner of the screen. The end point (x = 100, y = 100) is in the upper right cor-

ner of the screen. (See Figure 9-1.)

The direction in which the splitter is moved depends on the screen layout. If the windows are positioned horizontally, the splitter also moves horizontally. If the windows are positioned

vertically, the splitter also moves vertically.

Range: 0 to 100

Example: LAY:SPL 1,3,50

Moves the splitter between window 1 ('Frequency Sweep') and 3 ('Marker Table') to the center (50%) of the screen, i.e. in the fig-

ure above, to the left.

Example: LAY:SPL 1,4,70

Moves the splitter between window 1 ('Frequency Sweep') and 3

('Marker Peak List') towards the top (70%) of the screen. The following commands have the exact same effect, as any combination of windows above and below the splitter moves the

splitter vertically.
LAY:SPL 3,2,70
LAY:SPL 4,1,70
LAY:SPL 2,1,70

**Usage:** Setting only

#### LAYout:WINDow<n>:ADD? <Direction>,<WindowType>

This command adds a measurement window to the display. Note that with this command, the suffix <n> determines the existing window next to which the new window is added, as opposed to LAYout:ADD[:WINDow]?, for which the existing window is defined by a parameter.

To replace an existing window, use the LAYout:WINDow<n>:REPLace command.

This command is always used as a query so that you immediately obtain the name of the new window as a result.

Suffix:

<n> Window

**Query parameters:** 

<WindowType> Type of measurement window you want to add.

See LAYout: ADD [:WINDow]? on page 146 for a list of availa-

ble window types.

Return values:

<NewWindowName> When adding a new window, the command returns its name (by

default the same as its number) as a result.

**Example:** LAY:WIND1:ADD? LEFT, MTAB

Result:

Adds a new window named '2' with a marker table to the left of

window 1.

Usage: Query only

## LAYout:WINDow<n>:IDENtify?

This command queries the **name** of a particular display window (indicated by the <n> suffix) in the active channel setup.

**Note**: to query the **index** of a particular window, use the LAYout:IDENtify[: WINDow]? command.

Suffix:

<n> Window

Return values:

<WindowName> String containing the name of a window.

In the default state, the name of the window is its index.

**Example:** LAY:WIND2:IDEN?

Queries the name of the result display in window 2.

Response:

121

Usage: Query only

#### LAYout:WINDow<n>:REMove

This command removes the window specified by the suffix <n> from the display in the active channel setup.

The result of this command is identical to the LAYout: REMOVE [:WINDOW] command.

Suffix:

<n> Window

**Example:** LAY:WIND2:REM

Removes the result display in window 2.

Usage: Event

## LAYout:WINDow<n>:REPLace <WindowType>

This command changes the window type of an existing window (specified by the suffix <n>) in the active channel setup.

The effect of this command is identical to the LAYout:REPLace[:WINDow] command.

To add a new window, use the LAYout: WINDow<n>: ADD? command.

Suffix:

<n> Window

**Setting parameters:** 

<WindowType> Type of measurement window you want to replace another one

with.

See LAYout: ADD[:WINDow]? on page 146 for a list of availa-

ble window types.

**Example:** LAY:WIND2:REPL MTAB

Replaces the result display in window 2 with a marker table.

**Usage:** Setting only

# 9.6 Capturing Data and Performing Sweeps



#### Different measurement procedures

Two different procedures to capture I/Q data remotely are available:

- Measurement and result query with one command (see TRACe: IQ: DATA on page 207)
  - This method causes the least delay between measurement and output of the result data, but it requires the control computer to wait actively for the response data.
- Setting up the instrument, starting the measurement via INIT and querying the
  result list at the end of the measurement (see TRACe:IQ:DATA:MEMory?
  on page 208)

With this method, the control computer can be used for other activities during the measurement. However, the additional time needed for synchronization via service request must be taken into account.

ABORt	153
INITiate <n>:CONMeas</n>	153
INITiate <n>:CONTinuous</n>	154
INITiate <n>[:IMMediate]</n>	154
INITiate:SEQuencer:ABORt.	155
INITiate:SEQuencer:IMMediate	155
INITiate:SEQuencer:MODE	155
[SENSe:]SWEep:COUNt	156
[SENSe:]SWEep:COUNt:CURRent?	
[SENSe:]SWEep[:WINDow <n>]:POINts</n>	
[SENSe:]SWEep:TIME	
SYSTem:SFOuencer	

#### **ABORt**

This command aborts the measurement in the current channel setup and resets the trigger system.

To prevent overlapping execution of the subsequent command before the measurement has been aborted successfully, use the \*OPC? or \*WAI command after ABOR and before the next command.

#### Note on blocked remote control programs:

If a sequential command cannot be completed, for example because a triggered sweep never receives a trigger, the remote control program will never finish and the remote channel to the R&S ZNL is blocked for further commands. In this case, you must interrupt processing on the remote channel first in order to abort the measurement.

To do so, send a "Device Clear" command from the control instrument to the R&S ZNL on a parallel channel to clear all currently active remote channels. Depending on the used interface and protocol, send the following commands:

• **Visa**: viClear()

Now you can send the ABORt command on the remote channel performing the measurement.

**Example:** ABOR;:INIT:IMM

Aborts the current measurement and immediately starts a new

one.

**Example:** ABOR; \*WAI

INIT: IMM

Aborts the current measurement and starts a new one once

abortion has been completed.

Usage: Event

## INITiate<n>:CONMeas

This command restarts a (single) measurement that has been stopped (using ABORt) or finished in single sweep mode.

The measurement is restarted at the beginning, not where the previous measurement was stopped.

#### Suffix:

<n> irrelevant

Example: INIT: CONT OFF

Switches to single sweep mode. DISP:WIND:TRAC:MODE AVER Switches on trace averaging.

SWE: COUN 20

Setting the sweep counter to 20 sweeps.

INIT; \*WAI

Starts the measurement and waits for the end of the 20 sweeps.

INIT:CONM; \*WAI

Continues the measurement (next 20 sweeps) and waits for the

end.

Result: Averaging is performed over 40 sweeps.

Manual operation: See "ContinueSingleSweep" on page 57

#### INITiate<n>:CONTinuous <State>

This command controls the sweep mode for an individual channel setup.

Note that in single sweep mode, you can synchronize to the end of the measurement with \*OPC, \*OPC? or \*WAI. In continuous sweep mode, synchronization to the end of the measurement is not possible. Thus, it is not recommended that you use continuous sweep mode in remote control, as results like trace data or markers are only valid after a single sweep end synchronization.

Example: INIT: CONT OFF

Switches the sweep mode to single sweep.

INIT: CONT ON

Switches the sweep mode to continuous sweep.

Manual operation: See "Continuous Sweep / Run Cont" on page 56

#### INITiate<n>[:IMMediate]

This command starts a (single) new measurement.

With sweep count or average count > 0, this means a restart of the corresponding number of measurements. With trace mode MAXHold, MINHold and AVERage, the previous results are reset on restarting the measurement.

You can synchronize to the end of the measurement with \*OPC, \*OPC? or \*WAI.

#### Suffix:

<n> irrelevant

**Example:** INIT:CONT OFF

Switches to single sweep mode.

DISP:WIND:TRAC:MODE AVER

Switches on trace averaging.

SWE: COUN 20

Sets the sweep counter to 20 sweeps.

INIT; \*WAI

Starts the measurement and waits for the end of the 20 sweeps.

Manual operation: See "Single Sweep / Run Single" on page 56

#### INITiate:SEQuencer:ABORt

This command stops the currently active sequence of measurements.

You can start a new sequence any time using INITiate: SEQuencer: IMMediate on page 155.

Usage: Event

#### INITiate:SEQuencer:IMMediate

This command starts a new sequence of measurements by the Sequencer.

Before this command can be executed, the Sequencer must be activated (see SYSTem: SEQuencer on page 157).

Example: SYST:SEQ ON

Activates the Sequencer. INIT:SEQ:MODE SING

Sets single sequence mode so each active measurement will be

performed once.
INIT:SEQ:IMM

Starts the sequential measurements.

#### INITiate:SEQuencer:MODE < Mode>

Defines the capture mode for the entire measurement sequence and all measurement groups and channels it contains.

**Note:** In order to synchronize to the end of a measurement sequence using \*OPC, \*OPC? or \*WAI you must use SINGle Sequence mode.

#### Parameters:

<Mode> SINGle

Each measurement group is started one after the other in the order of definition. All measurement channels in a group are started simultaneously and performed once. After *all* measurements are completed, the next group is started. After the last group, the measurement sequence is finished.

## **CONTinuous**

Each measurement group is started one after the other in the order of definition. All measurement channels in a group are started simultaneously and performed once. After *all* measurements are completed, the next group is started. After the last group, the measurement sequence restarts with the first one and continues until it is stopped explicitely.

\*RST: CONTinuous

## [SENSe:]SWEep:COUNt <SweepCount>

This command defines the number of sweeps that the application uses to average traces.

In continuous sweep mode, the application calculates the moving average over the average count.

In single sweep mode, the application stops the measurement and calculates the average after the average count has been reached.

Example: SWE:COUN 64

Sets the number of sweeps to 64.

INIT:CONT OFF

Switches to single sweep mode.

INIT; \*WAI

Starts a sweep and waits for its end.

Manual operation: See "Sweep/Average Count" on page 56

#### [SENSe:]SWEep:COUNt:CURRent?

This query returns the current number of started sweeps or measurements. This command is only available if a sweep count value is defined and the instrument is in single sweep mode.

## Return values:

<CurrentCount>

Example: SWE:COUNt 64

Sets sweep count to 64 INIT: CONT OFF

Switches to single sweep mode

INIT

Starts a sweep (without waiting for the sweep end!)

SWE: COUN: CURR?

Queries the number of started sweeps

**Usage:** Query only

#### [SENSe:]SWEep[:WINDow<n>]:POINts <SweepPoints>

This command defines the number of sweep points to analyze after a sweep.

Note that the number of sweep points is limited to 10001 when measuring spurious emissions.

#### Suffix:

<n>

#### Parameters:

<SweepPoints> Range: 101 to 100001

\*RST: 1001

Example: SWE:POIN 251

Manual operation: See "Sweep Points" on page 55

#### [SENSe:]SWEep:TIME <Time>

This command defines the sweep time. It automatically decouples the time from any other settings.

#### Parameters:

<Time> refer to data sheet

\*RST: depends on current settings (determined automati-

cally)

Default unit: S

Manual operation: See "Meas Time" on page 53

#### SYSTem:SEQuencer <State>

This command turns the Sequencer on and off. The Sequencer must be active before any other Sequencer commands (INIT:SEQ...) are executed, otherwise an error will occur.

A detailed programming example is provided in the "Operating Modes" chapter in the R&S ZNL User Manual.

#### Parameters:

<State> ON | OFF | 0 | 1

ON | 1

The Sequencer is activated and a sequential measurement is started immediately.

OFF | 0

The Sequencer is deactivated. Any running sequential measure-

ments are stopped. Further Sequencer commands

(INIT: SEQ...) are not available.

\*RST: 0

Example: SYST:SEQ ON

Activates the Sequencer. INIT: SEQ: MODE SING

Sets single Sequencer mode so each active measurement will

be performed once. INIT: SEQ: IMM

Starts the sequential measurements.

SYST:SEQ OFF

# 9.7 I/Q Analysis

General result analysis settings concerning the trace, markers, etc. can be configured using the following commands. They are identical to the analysis functions in the Spectrum application except for the special marker functions.

•	Configuring Standard Traces	158
•	Configuring Spectrograms	164
•	Using Markers.	171

# 9.7.1 Configuring Standard Traces

## Useful commands for trace configuration described elsewhere

- DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing on page 127
- DISPlay[:WINDow<n>]:TRACe<t>:Y[:SCALe] on page 125

## Remote commands exclusive to trace configuration

DISPlay[:WINDow <n>]:TRACe<t>:MODE</t></n>	158
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:MODE:HCONtinuous</t></w></n>	159
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>[:STATe]</t></w></n>	160
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:SMOothing:APERture</t></w></n>	160
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:SMOothing[:STATe]</t></w></n>	161
[SENSe:]AVERage <n>:TYPE</n>	161
[SENSe:][WINDow <n>:]DETector<t>[:FUNCtion]</t></n>	162
[SENSe:][WINDow <n>:]DETector<t>[:FUNCtion]:AUTO</t></n>	162
TRACe <n>:COPY</n>	163
[SENSe:]AVERage <n>:COUNt</n>	163
TRACe:IQ:AVERage:COUNt	163
[SENSe:]AVERage <n>[:STATe<t>]</t></n>	163
TRACe:IQ:AVERage[:STATe]	

## DISPlay[:WINDow<n>]:TRACe<t>:MODE < Mode>

This command selects the trace mode. If necessary, the selected trace is also activated

In case of max hold, min hold or average trace mode, you can set the number of single measurements with <code>[SENSe:]SWEep:COUNt</code>. Note that synchronization to the end of the measurement is possible only in single sweep mode.

#### Suffix:

<n> Window

<t> Trace

Parameters:

<Mode> WRITe

Overwrite mode: the trace is overwritten by each sweep. This is

the default setting.

**AVERage** 

The average is formed over several sweeps. The "Sweep/Average Count" determines the number of averaging procedures.

MAXHold

The maximum value is determined over several sweeps and displayed. The R&S ZNL saves the sweep result in the trace memory only if the new value is greater than the previous one.

**MINHold** 

The minimum value is determined from several measurements and displayed. The R&S ZNL saves the sweep result in the trace memory only if the new value is lower than the previous one.

**VIFW** 

The current contents of the trace memory are frozen and displayed.

**BLANk** 

Hides the selected trace.

\*RST: Trace 1: WRITe, Trace 2-6: BLANk

**Example:** INIT:CONT OFF

Switching to single sweep mode.

SWE: COUN 16

Sets the number of measurements to 16.

DISP:TRAC3:MODE WRIT

Selects clear/write mode for trace 3.

INIT; \*WAI

Starts the measurement and waits for the end of the measure-

ment.

Manual operation: See "TraceMode" on page 62

# DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:MODE:HCONtinuous <State>

This command turns an automatic reset of a trace on and off after a parameter has changed.

The reset works for trace modes min hold, max hold and average.

Note that the command has no effect if critical parameters like the span have been changed to avoid invalid measurement results

Suffix:

<n> Window

<w> subwindow

<t> Trace

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** DISP:WIND:TRAC3:MODE:HCON ON

Switches off the reset function.

Manual operation: See "Hold" on page 63

## DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>[:STATe] <State>

This command turns a trace on and off.

The measurement continues in the background.

Suffix:

<n> Window

<w> subwindow

Not supported by all applications

<t> Trace

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** DISP:TRAC3 ON

Manual operation: See "Trace 1/Trace 2/Trace 3/Trace 4/Trace 5/Trace 6"

on page 62

See "Trace 1/ Trace 2/ Trace 3/ Trace 4 (Softkeys)" on page 64

# DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:SMOothing:APERture <Aperture>

This command defines the degree (aperture) of the trace smoothing, if DISPlay[: WINDow<n>][:SUBWindow<w>]:TRACe<t>:SMOothing[:STATe]TRUE.

Suffix:

<n> Window <w> subwindow

<t> Trace

Parameters:

<Aperture> Range: 1 to 50

\*RST: 2
Default unit: PCT

**Example:** DISP3:TRAC2:SMO:APER 5

Defines an aperture of 5% for trace 2 in window 3

## DISPlay[:WINDow<n>][:SUBWindow<w>]:TRACe<t>:SMOothing[:STATe] <State>

This command turns trace smoothing for a particular trace on and off.

If enabled, the trace is smoothed by the value specified using DISPlay[: WINDow<n>][:SUBWindow<w>]:TRACe<t>:SMOothing:APERture on page 160.

For more information see the R&S ZNL User Manual.

Suffix:

<n> Window

<w> subwindow

<t> Trace

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: DISP3:TRAC2:SMO ON

Turns on trace smoothing for trace 2 in window 3

## [SENSe:]AVERage<n>:TYPE <Mode>

This command selects the trace averaging mode.

Suffix:

<n> 1..n

Window

Parameters:

<Mode> VIDeo

The logarithmic power values are averaged.

LINear

The power values are averaged before they are converted to

logarithmic values.

**POWer** 

The power level values are converted into unit Watt prior to averaging. After the averaging, the data is converted back into

its original unit.

\*RST: VIDeo

**Example:** AVER: TYPE LIN

Switches to linear average calculation.

Manual operation: See "Average Mode" on page 63

## [SENSe:][WINDow<n>:]DETector<t>[:FUNCtion] < Detector>

Defines the trace detector to be used for trace analysis.

Suffix:

<n> Window <t> Trace

Parameters:

<Detector> APEak

Autopeak

NEGative

Negative peak

POSitive

Positive peak

SAMPle

First value detected per trace point

RMS value AVERage Average

\*RST: APEak

**Example:** DET POS

Sets the detector to "positive peak".

Manual operation: See "Detector" on page 63

## [SENSe:][WINDow<n>:]DETector<t>[:FUNCtion]:AUTO <State>

This command couples and decouples the detector to the trace mode.

Suffix:

<n> Window <t> Trace

Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

**Example:** DET:AUTO OFF

The selection of the detector is not coupled to the trace mode.

Manual operation: See "Detector" on page 63

TRACe<n>:COPY <TraceNumber>, <TraceNumber>

This command copies data from one trace to another.

Suffix:

<n> Window

Parameters:

<TraceNumber> TRACE1 | TRACE2 | TRACE3 | TRACE4 | TRACE5 | TRACE6

The first parameter is the destination trace, the second parame-

ter is the source.

(Note the 'e' in the parameter is required!)

**Example:** TRAC:COPY TRACE1, TRACE2

Copies the data from trace 2 to trace 1.

Manual operation: See "Copy Trace" on page 64

[SENSe:]AVERage<n>:COUNt <AverageCount> TRACe:IQ:AVERage:COUNt <NumberSets>

This command defines the number of I/Q data sets that the averaging is based on.

Parameters:

<NumberSets> Range: 0 to 32767

\*RST: 0

Example: TRAC: IQ ON

Switches on acquisition of I/Q data.

TRAC: IQ: AVER ON

Enables averaging of the I/Q measurement data

TRAC: IQ: AVER: COUN 10

Selects averaging over 10 data sets

TRAC: IQ: DATA?

Starts the measurement and reads out the averaged data.

[SENSe:]AVERage<n>[:STATe<t>] <State>
TRACe:IQ:AVERage[:STATe] <State>

This command turns averaging of the I/Q data on and off.

Before you can use the command you have to turn the I/Q data acquisition on with TRACe:IQ[:STATe].

If averaging is on, the maximum amount of I/Q data that can be recorded is 512kS (524288 samples).

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: TRAC: IQ ON

Switches on acquisition of I/Q data.

TRAC: IQ: AVER ON

Enables averaging of the I/Q measurement data.

TRAC: IQ: AVER: COUN 10

Selects averaging over 10 data sets.

TRAC: IQ: DATA?

Starts the measurement and reads out the averaged data.

## 9.7.2 Configuring Spectrograms

In addition to the standard "level versus frequency" or "level versus time" spectrum traces, the R&S ZNL also provides a spectrogram display of the measured data. A spectrogram shows how the spectral density of a signal varies over time. The x-axis shows the frequency, the y-axis shows the time. The commands required to configure spectrograms in a remote environment are described here. For details and manual operation see Chapter 6.2, "Spectrogram Settings", on page 65.



When configuring spectrograms, the window suffix is irrelevant. The settings are always applied to the spectrogram window, or to all spectrogram windows, if several are active for the same channel setup.

For commands to set markers in spectrograms, see Chapter 9.7.3.4, "Marker Search (Spectrograms)", on page 183.

9.7.2.1 9.7.2.2 

#### 9.7.2.1 **Configuring a Spectrogram Measurement**

CALCulate <n>:SGRam:CLEar[:IMMediate]</n>	165
CALCulate <n>:SPECtrogram:CLEar[:IMMediate]</n>	165
CALCulate <n>:SGRam:CONTinuous</n>	165
CALCulate <n>:SPECtrogram:CONTinuous</n>	165
CALCulate <n>:SGRam:FRAMe:COUNt</n>	165
CALCulate <n>:SPECtrogram:FRAMe:COUNt</n>	165
CALCulate <n>:SGRam:FRAMe:SELect</n>	166
CALCulate <n>:SPECtrogram:FRAMe:SELect</n>	166
CALCulate <n>:SGRam:HDEPth</n>	166
CALCulate <n>:SPECtrogram:HDEPth</n>	166
CALCulate <n>:SGRam:LAYout</n>	
CALCulate <n>:SPECtrogram:LAYout</n>	167
CALCulate <n>:SGRam[:STATe]</n>	167
CALCulate <n>:SPECtrogram[:STATe]</n>	167
CALCulate <n>:SGRam:THReedim[:STATe]</n>	167
CALCulate <n>:SPECtrogram:THReedim[:STATe]</n>	167
CALCulate <n>:SGRam:TRACe</n>	168
CAL Culatoon>:SPECtrogram:TPACo	169

165

CALCulate<n>:SGRam:CLEar[:IMMediate]
CALCulate<n>:SPECtrogram:CLEar[:IMMediate]

This command resets the spectrogram and clears the history buffer.

Suffix:

<n> Window

**Example:** //Reset the result display and clear the memory

CALC:SGR:CLE

Manual operation: See "Clear Spectrogram" on page 68

CALCulate<n>:SGRam:CONTinuous <State>
CALCulate<n>:SPECtrogram:CONTinuous <State>

This command determines whether the results of the last measurement are deleted before starting a new measurement in single sweep mode.

This setting applies to all spectrograms in the channel setup.

Suffix:

<n> Window

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** INIT:CONT OFF

Selects single sweep mode.

INIT; \*WAI

Starts the sweep and waits for the end of the sweep.

CALC:SGR:CONT ON

Repeats the single sweep measurement without deleting the

results of the last measurement.

CALCulate<n>:SGRam:FRAMe:COUNt <Frames>
CALCulate<n>:SPECtrogram:FRAMe:COUNt <Frames>

This command defines the number of frames to be recorded in a single sweep.

This value applies to all spectrograms in the channel setup.

Suffix:

<n> Window

Parameters:

<Frames> The maximum number of frames depends on the history depth.

Range: 1 to history depth

Increment: 1 \*RST: 1

**Example:** //Select single sweep mode

INIT: CONT OFF

//Set the number of frames to 200 CALC:SGR:FRAM:COUN 200

CALCulate<n>:SGRam:FRAMe:SELect <Frame> | <Time> CALCulate<n>:SPECtrogram:FRAMe:SELect <Frame> | <Time>

This command selects a specific frame for further analysis.

The command is available if no measurement is running or after a single sweep has ended.

Suffix:

<n> Window

Parameters:

<Frame> Selects a frame directly by the frame number. Valid if the time

stamp is off.

The range depends on the history depth.

Default unit: S

<Time> Selects a frame via its time stamp. Valid if the time stamp is on.

The number is the distance to frame 0 in seconds. The range

depends on the history depth.

Example: INIT: CONT OFF

Stop the continuous sweep. CALC: SGR: FRAM: SEL -25 Selects frame number -25.

Manual operation: See "Select Frame" on page 67

CALCulate<n>:SGRam:HDEPth <History>
CALCulate<n>:SPECtrogram:HDEPth <History>

This command defines the number of frames to be stored in the R&S ZNL memory.

Suffix:

<n> Window

Parameters:

<History> The maximum number of frames depends on the number of

sweep points.

Range: 781 to 20000

Increment: 1 \*RST: 3000

**Example:** //Set the history depth to 1500

CALC:SGR:SPEC 1500

Manual operation: See "History Depth" on page 67

CALCulate<n>:SGRam:LAYout <State>
CALCulate<n>:SPECtrogram:LAYout <State>

This command selects the state and size of spectrograms.

The command is available for result displays that support spectrograms.

Suffix:

<n> Window

Parameters:

<State>

Spectrogram and trace diagram share a window.

**OFF** 

Only the trace diagram is displayed, the spectrogram is not.

\*RST: OFF

**Example:** CALC4:SPEC:LAY FULL

Shows the spectrogram in window 4. The corresponding trace

diagram is hidden.

Manual operation: See "State" on page 66

CALCulate<n>:SGRam[:STATe] <State>
CALCulate<n>:SPECtrogram[:STATe] <State>

This command turns the spectrogram on and off.

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: CALC:SGR ON

Activates the Spectrogram result display.

CALCulate<n>:SGRam:THReedim[:STATe] <State>

**CALCulate<n>:SPECtrogram:THReedim[:STATe]** <State>

Activates or deactivates a 3-dimensional spectrogram for the selected result display.

Suffix:

<n> Window

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

\*RST: 0

**Example:** CALC:SPEC:THR:STAT ON

Manual operation: See "3D Spectrogram State" on page 66

CALCulate<n>:SGRam:TRACe <Trace>
CALCulate<n>:SPECtrogram:TRACe <Trace>

This command determines the trace in the result display the Spectrogram is based on.

Suffix:

<n> Window

**Parameters:** 

<Trace> TRACE1 | TRACE2 | TRACE3 | TRACE4 | TRACE5 | TRACE6

How many traces are available depends on the selected result

display.

**Example:** CALC2:SPEC:TRAC TRACE3

CALCulate<n>:SGRam:TSTamp:DATA? <Frames>
CALCulate<n>:SPECtrogram:TSTamp:DATA? <Frames>

This command queries the starting time of the frames.

The return values consist of four values for each frame. If the Spectrogram is empty, the command returns '0,0,0,0'. The times are given as delta values, which simplifies evaluating relative results; however, you can also calculate the absolute date and time as displayed on the screen.

The frame results themselves are returned with TRAC: DATA? SGR

Suffix:

<n> Window

**Query parameters:** 

<Frames> CURRent

Returns the starting time of the current frame.

ALL

Returns the starting time for all frames. The results are sorted in

descending order, beginning with the current frame.

Return values:

<Seconds> Number of seconds that have passed since 01.01.1970 till the

frame start

<Nanoseconds> Number of nanoseconds that have passed in addition to the

<Seconds> since 01.01.1970 till the frame start.

<Reserved> The third value is reserved for future uses.
<Reserved> The fourth value is reserved for future uses.

**Example:** CALC:SGR:TST ON

Activates the time stamp.
CALC:SGR:TST:DATA? ALL

Returns the starting times of all frames sorted in a descending

order.

Usage: Query only

Manual operation: See "Time Stamp" on page 67

# CALCulate<n>:SGRam:TSTamp[:STATe] <State> CALCulate<n>:SPECtrogram:TSTamp[:STATe] <State>

This command activates and deactivates the time stamp.

If the time stamp is active, some commands do not address frames as numbers, but as (relative) time values:

- CALCulate<n>:DELTamarker<m>:SPECtrogram:FRAMe on page 189
- CALCulate<n>:MARKer<m>:SPECtrogram:FRAMe on page 184
- CALCulate<n>:SPECtrogram:FRAMe:SELect on page 166

#### Suffix:

<n> 1..n

Window

## Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** //Activates the time stamp

CALC:SGR:TST ON

Manual operation: See "Time Stamp" on page 67

## 9.7.2.2 Configuring the Color Map

DISPlay[:WINDow <n>]:SGRam:COLor:DEFault</n>	170
DISPlay[:WINDow <n>]:SPECtrogram:COLor:DEFault</n>	170
DISPlay[:WINDow <n>]:SGRam:COLor:LOWer</n>	170
DISPlay[:WINDow <n>]:SPECtrogram:COLor:LOWer</n>	170
DISPlay[:WINDow <n>]:SGRam:COLor:SHAPe</n>	170
DISPlay[:WINDow <n>]:SPECtrogram:COLor:SHAPe</n>	170
DISPlay[:WINDow <n>]:SGRam:COLor:UPPer</n>	170
DISPlay[:WINDow <n>]:SPECtrogram:COLor:UPPer</n>	170

DISPlay[:WINDow<n>]:SGRam:COLor:DEFault DISPlay[:WINDow<n>]:SPECtrogram:COLor:DEFault

This command restores the original color map.

Suffix:

<n> Window

Manual operation: See "Set to Default" on page 70

DISPlay[:WINDow<n>]:SGRam:COLor:LOWer <Percentage>
DISPlay[:WINDow<n>]:SPECtrogram:COLor:LOWer <Percentage>

This command defines the starting point of the color map.

Suffix:

<n> Window

Parameters:

<Percentage> Statistical frequency percentage.

Range: 0 to 66 \*RST: 0 Default unit: %

**Example:** DISP:WIND:SGR:COL:LOW 10

Sets the start of the color map to 10%.

Manual operation: See "Start / Stop" on page 69

DISPlay[:WINDow<n>]:SGRam:COLor:SHAPe <Shape>
DISPlay[:WINDow<n>]:SPECtrogram:COLor:SHAPe <Shape>

This command defines the shape and focus of the color curve for the spectrogram result display.

Suffix:

<n> Window

Parameters:

<Shape> Shape of the color curve.

Range: -1 to 1 \*RST: 0

Manual operation: See "Shape" on page 69

DISPlay[:WINDow<n>]:SGRam:COLor:UPPer <Percentage>
DISPlay[:WINDow<n>]:SPECtrogram:COLor:UPPer <Percentage>

This command defines the end point of the color map.

Suffix:

<n> Window

Parameters:

<Percentage> Statistical frequency percentage.

Range: 0 to 66

\*RST: 0
Default unit: %

**Example:** DISP:WIND:SGR:COL:UPP 95

Sets the start of the color map to 95%.

Manual operation: See "Start / Stop" on page 69

DISPlay[:WINDow<n>]:SGRam:COLor[:STYLe] <ColorScheme>
DISPlay[:WINDow<n>]:SPECtrogram:COLor[:STYLe] <ColorScheme>

This command selects the color scheme.

Parameters:

<ColorScheme> HOT

Uses a color range from blue to red. Blue colors indicate low lev-

els, red colors indicate high ones.

COLD

Uses a color range from red to blue. Red colors indicate low lev-

els, blue colors indicate high ones.

**RADar** 

Uses a color range from black over green to light turquoise with

shades of green in between.

**GRAYscale** 

Shows the results in shades of gray.

\*RST: HOT

**Example:** DISP:WIND:SPEC:COL GRAY

Changes the color scheme of the spectrogram to black and

white.

Manual operation: See "Hot/Cold/Radar/Grayscale" on page 70

## 9.7.3 Using Markers

The following commands are available for marker settings and functions in the I/Q Analyzer application.



For "I/Q Vector" displays markers are not available.

Setting Up Individual Markers	172
General Marker Settings	177
Configuring and Performing a Marker Search	179
Marker Search (Spectrograms)	183
Positioning the Marker	193
Band Power Marker	199
Marker Peak Lists	203
Setting Up Individual Markers	

# 9.7.3.1

The following commands define the position of markers in the diagram.

CALCulate <n>:DELTamarker<m>:AOFF</m></n>	172
CALCulate <n>:DELTamarker<m>:LINK</m></n>	172
CALCulate <n>:DELTamarker<ms>:LINK:TO:MARKer<md></md></ms></n>	173
CALCulate <n>:DELTamarker<m>:MODE</m></n>	173
CALCulate <n>:DELTamarker<m>:MREFerence</m></n>	174
CALCulate <n>:DELTamarker<m>[:STATe]</m></n>	174
CALCulate <n>:DELTamarker<m>:TRACe</m></n>	175
CALCulate <n>:DELTamarker<m>:X</m></n>	175
CALCulate <n>:MARKer<m>:AOFF</m></n>	175
CALCulate <n>:MARKer<ms>:LINK:TO:MARKer<md></md></ms></n>	176
CALCulate <n>:MARKer<m>[:STATe]</m></n>	176
CALCulate <n>:MARKer<m>:TRACe</m></n>	177
CALCulate <n>:MARKer<m>:X</m></n>	177

## CALCulate<n>:DELTamarker<m>:AOFF

This command turns off all delta markers.

Suffix:

<n> Window <m> irrelevant

CALC: DELT: AOFF **Example:** 

Turns off all delta markers.

## CALCulate<n>:DELTamarker<m>:LINK <State>

This command links delta marker <m> to marker 1.

If you change the horizontal position (x-value) of marker 1, delta marker <m> changes its horizontal position to the same value.

**Tip**: to link any marker to a different marker than marker 1, use the CALCulate<n>: DELTamarker<ms>:LINK:TO:MARKer<md> or CALCulate<n>:MARKer<ms>: LINK:TO:MARKer<md> commands.

#### Suffix:

<n> Window

<m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: CALC:DELT2:LINK ON

Manual operation: See "Linking to Another Marker" on page 75

#### CALCulate<n>:DELTamarker<ms>:LINK:TO:MARKer<md> <State>

This command links delta marker <m1> to any active normal marker <m2>.

If you change the horizontal position of marker <m2>, delta marker <m1> changes its horizontal position to the same value.

Suffix:

<n> Window

<ms> source marker, see Marker

<md> destination marker, see Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:DELT4:LINK:TO:MARK2 ON

Links the delta marker 4 to the marker 2.

Manual operation: See "Linking to Another Marker" on page 75

#### CALCulate<n>:DELTamarker<m>:MODE < Mode>

This command defines whether the position of a delta marker is provided as an absolute value or relative to a reference marker.

Note that when the position of a delta marker is *queried*, the result is always an absolute value (see CALCulate<n>: DELTamarker<m>: X on page 175)!

Suffix:

<n> Window <m> irrelevant

Parameters:

<Mode> ABSolute

Delta marker position in absolute terms.

**RELative** 

Delta marker position in relation to a reference marker.

\*RST: RELative

**Example:** CALC:DELT:MODE ABS

Absolute delta marker position.

## CALCulate<n>:DELTamarker<m>:MREFerence < Reference>

This command selects a reference marker for a delta marker other than marker 1.

The reference may be another marker or the fixed reference.

Suffix:

<n> Window <m> Marker

Parameters:

<Reference> 1 to 16

Selects markers 1 to 16 as the reference.

FIXed

Selects the fixed reference as the reference.

**Example:** CALC:DELT3:MREF 2

Specifies that the values of delta marker 3 are relative to marker

2.

Manual operation: See "Reference Marker" on page 75

# CALCulate<n>:DELTamarker<m>[:STATe] <State>

This command turns delta markers on and off.

If necessary, the command activates the delta marker first.

No suffix at DELTamarker turns on delta marker 1.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: CALC: DELT2 ON

Turns on delta marker 2.

Manual operation: See "Marker State" on page 74

See "Marker Type" on page 75 See "Select Marker" on page 76

#### CALCulate<n>:DELTamarker<m>:TRACe <Trace>

This command selects the trace a delta marker is positioned on.

Note that the corresponding trace must have a trace mode other than "Blank".

If necessary, the command activates the marker first.

Suffix:

<n> Window <m> Marker

Parameters:

<Trace> Trace number the marker is assigned to.

**Example:** CALC:DELT2:TRAC 2

Positions delta marker 2 on trace 2.

#### CALCulate<n>:DELTamarker<m>:X <Position>

This command moves a delta marker to a particular coordinate on the x-axis.

If necessary, the command activates the delta marker and positions a reference marker to the peak power.

Suffix:

<n> Window <m> Marker

Parameters:

<Position> Numeric value that defines the marker position on the x-axis.

Range: The value range and unit depend on the measure-

ment and scale of the x-axis.

**Example:** CALC: DELT: X?

Outputs the absolute x-value of delta marker 1.

Manual operation: See "Marker Position X-value" on page 75

## CALCulate<n>:MARKer<m>:AOFF

This command turns off all markers.

Suffix:

<n> Window <m> Marker

**Example:** CALC:MARK:AOFF

Switches off all markers.

Manual operation: See "All Markers Off" on page 76

#### CALCulate<n>:MARKer<ms>:LINK:TO:MARKer<md> <State>

This command links normal marker <m1> to any active normal marker <m2>.

If you change the horizontal position of marker <m2>, marker <m1> changes its horizontal position to the same value.

Suffix:

<n> Window

<ms> source marker, see Marker

<md> destination marker, see Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK4:LINK:TO:MARK2 ON

Links marker 4 to marker 2.

Manual operation: See "Linking to Another Marker" on page 75

## CALCulate<n>:MARKer<m>[:STATe] <State>

This command turns markers on and off. If the corresponding marker number is currently active as a delta marker, it is turned into a normal marker.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK3 ON

Switches on marker 3.

Manual operation: See "Marker State" on page 74

See "Marker Type" on page 75 See "Select Marker" on page 76

#### CALCulate<n>:MARKer<m>:TRACe <Trace>

This command selects the trace the marker is positioned on.

Note that the corresponding trace must have a trace mode other than "Blank".

If necessary, the command activates the marker first.

Suffix:

<n> Window <m> Marker

Parameters: <Trace>

**Example:** //Assign marker to trace 1

CALC:MARK3:TRAC 2

Manual operation: See "Assigning the Marker to a Trace" on page 76

#### CALCulate<n>:MARKer<m>:X <Position>

This command moves a marker to a specific coordinate on the x-axis.

If necessary, the command activates the marker.

If the marker has been used as a delta marker, the command turns it into a normal marker.

Suffix:

<n> Window <m> Marker

Parameters:

<Position> Numeric value that defines the marker position on the x-axis.

The unit depends on the result display.

Range: The range depends on the current x-axis range.

Default unit: Hz

**Example:** CALC:MARK2:X 1.7MHz

Positions marker 2 to frequency 1.7 MHz.

Manual operation: See "Marker Table" on page 15

See "Marker Peak List" on page 16

See "Marker Position X-value" on page 75

### 9.7.3.2 General Marker Settings

The following commands control general marker functionality.

## Remote commands exclusive to general marker functionality

DISPlay[:WINDow <n>]:MTABle</n>	178
DISPlay[:WINDow <n>]:MINFo[:STATe]</n>	178
CAI Culate <n>:MARKer<m>:X:SSI7e</m></n>	178

## DISPlay[:WINDow<n>]:MTABle <DisplayMode>

This command turns the marker table on and off.

Suffix:

<n> irrelevant

Parameters:

<DisplayMode> ON | 1

Turns on the marker table.

OFF | 0

Turns off the marker table.

**AUTO** 

Turns on the marker table if 3 or more markers are active.

\*RST: AUTO

**Example:** DISP:MTAB ON

Activates the marker table.

Manual operation: See "Marker Table Display" on page 77

## DISPlay[:WINDow<n>]:MINFo[:STATe] <State>

This command turns the marker information in all diagrams on and off.

Suffix:

<n> irrelevant

Parameters:

<State> ON | 1

Displays the marker information in the diagrams.

OFF | 0

Hides the marker information in the diagrams.

\*RST: 1

**Example:** DISP:MINF OFF

Hides the marker information.

Manual operation: See "Marker Info" on page 77

## CALCulate<n>:MARKer<m>:X:SSIZe <StepSize>

This command selects the marker step size mode for all markers in all windows.

The step size defines the distance the marker moves when you move it with the rotary knob.

It therefore takes effect in manual operation only.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<StepSize> STANdard

the marker moves from one pixel to the next

**POINts** 

the marker moves from one sweep point to the next

\*RST: POINts

**Example:** CALC:MARK:X:SSIZ STAN

Sets the marker step size to one pixel.

Manual operation: See "Marker Stepsize" on page 78

## 9.7.3.3 Configuring and Performing a Marker Search

The following commands control the marker search.

CALCulate <n>:MARKer<m>:LOEXclude</m></n>	179
CALCulate <n>:MARKer<m>:PEXCursion</m></n>	179
CALCulate <n>:MARKer<m>:SEARch</m></n>	180
CALCulate <n>:MARKer<m>:X:SLIMits[:STATe]</m></n>	181
CALCulate <n>:MARKer<m>:X:SLIMits:LEFT</m></n>	181
CALCulate <n>:MARKer<m>:X:SLIMits:RIGHt</m></n>	182
CALCulate <n>:MARKer<m>:X:SLIMits:ZOOM[:STATe]</m></n>	182
CALCulate <n>:THReshold</n>	183
CALCulate <n>:THReshold:STATe</n>	183

#### CALCulate<n>:MARKer<m>:LOEXclude <State>

This command turns the suppression of the local oscillator during automatic marker positioning on and off (for *all* markers in *all* windows).

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

Example: CALC:MARK:LOEX ON

Manual operation: See "Exclude LO" on page 80

#### CALCulate<n>:MARKer<m>:PEXCursion < Excursion>

This command defines the peak excursion (for all markers in all windows).

The peak excursion sets the requirements for a peak to be detected during a peak search.

The unit depends on the measurement.

Application/Result display	Unit
Spectrum	dB

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<Excursion> The excursion is the distance to a trace maximum that must be

attained before a new maximum is recognized, or the distance to a trace minimum that must be attained before a new minimum is

recognized

\*RST: 6 dB in the Spectrum application and RF displays

Default unit: DB

**Example:** CALC:MARK:PEXC 10dB

Defines peak excursion as 10 dB.

Manual operation: See "Peak Excursion" on page 80

## CALCulate<n>:MARKer<m>:SEARch < MarkRealImag>

This command selects the trace type a marker search is performed on.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<MarkRealImag> REAL

Marker search functions are performed on the real trace of the

"I/Q" measurement.

**IMAG** 

Marker search functions are performed on the imaginary trace of

the "I/Q" measurement.

MAGN

Marker search functions are performed on the magnitude of the I

and Q data.

\*RST: REAL

**Example:** CALC4:MARK:SEAR IMAG

Manual operation: See "Branch for Peaksearch" on page 81

## CALCulate<n>:MARKer<m>:X:SLIMits[:STATe] <State>

This command turns marker search limits on and off for all markers in all windows.

If you perform a measurement in the time domain, this command limits the range of the trace to be analyzed.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK:X:SLIM ON

Switches on search limitation.

**Manual operation:** See "Search Limits (Left / Right)" on page 80

See "Deactivating All Search Limits" on page 81

#### CALCulate<n>:MARKer<m>:X:SLIMits:LEFT <SearchLimit>

This command defines the left limit of the marker search range for *all* markers in *all* windows.

If you perform a measurement in the time domain, this command limits the range of the trace to be analyzed.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<SearchLimit> The value range depends on the frequency range or sweep

time.

The unit is Hz for frequency domain measurements and s for

time domain measurements.
\*RST: left diagram border

Default unit: HZ

**Example:** CALC:MARK:X:SLIM ON

Switches the search limit function on. CALC:MARK:X:SLIM:LEFT 10MHz

Sets the left limit of the search range to 10 MHz.

Manual operation: See "Search Limits (Left / Right)" on page 80

#### CALCulate<n>:MARKer<m>:X:SLIMits:RIGHt <SearchLimit>

This command defines the right limit of the marker search range for *all* markers in *all* windows.

If you perform a measurement in the time domain, this command limits the range of the trace to be analyzed.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<Limit> The value range depends on the frequency range or sweep

time.

The unit is Hz for frequency domain measurements and s for

time domain measurements.
\*RST: right diagram border

Default unit: HZ

**Example:** CALC:MARK:X:SLIM ON

Switches the search limit function on. CALC:MARK:X:SLIM:RIGH 20MHz

Sets the right limit of the search range to 20 MHz.

Manual operation: See "Search Limits (Left / Right)" on page 80

## CALCulate<n>:MARKer<m>:X:SLIMits:ZOOM[:STATe] <State>

This command adjusts the marker search range to the zoom area for *all* markers in *all* windows.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK:X:SLIM:ZOOM ON

Switches the search limit function on. CALC:MARK:X:SLIM:RIGH 20MHz

Sets the right limit of the search range to 20 MHz.

Manual operation: See "Use Zoom Limits" on page 81

#### CALCulate<n>:THReshold <Level>

This command defines a threshold level for the marker peak search (for *all* markers in *all* windows).

Suffix:

<n> irrelevant

Parameters:

<Level> Numeric value. The value range and unit are variable.

\*RST: -120 dBm Default unit: DBM

**Example:** CALC:THR -82DBM

Sets the threshold value to -82 dBm.

Manual operation: See "Search Threshold" on page 81

#### CALCulate<n>:THReshold:STATe <State>

This command turns a threshold for the marker peak search on and off (for *all* markers in *all* windows).

Suffix:

<n> irrelevant

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Example: CALC:THR:STAT ON

Switches on the threshold line.

Manual operation: See "Deactivating All Search Limits" on page 81

### 9.7.3.4 Marker Search (Spectrograms)

The following commands automatically define the marker and delta marker position in the spectrogram.

#### **Using Markers**

The following commands control spectrogram markers.

#### Useful commands for spectrogram markers described elsewhere

The following commands define the horizontal position of the markers.

- CALCulate<n>:MARKer<m>:MAXimum:LEFT on page 193
- CALCulate<n>:MARKer<m>:MAXimum:NEXT on page 194

•	<pre>CALCulate<n>:MARKer<m>:MAXimum[:PEAK] on page 194</m></n></pre>
•	CALCulate <n>:MARKer<m>:MAXimum:RIGHt on page 194</m></n>
•	CALCulate <n>:MARKer<m>:MINimum:LEFT on page 195</m></n>
•	CALCulate <n>:MARKer<m>:MINimum:NEXT on page 195</m></n>
•	CALCulate <n>:MARKer<m>:MINimum[:PEAK] on page 196</m></n>
•	CALCulate <n>:MARKer<m>:MINimum:RIGHt on page 196</m></n>

#### Remote commands exclusive to spectrogram markers

CALCulate <n>:MARKer<m>:SGRam:FRAMe</m></n>	. 184
CALCulate <n>:MARKer<m>:SPECtrogram:FRAMe</m></n>	.184
CALCulate <n>:MARKer<m>:SGRam:SARea</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:SARea</m></n>	. 185
CALCulate <n>:MARKer<m>:SGRam:XY:MAXimum[:PEAK]</m></n>	.185
CALCulate <n>:MARKer<m>:SPECtrogram:XY:MAXimum[:PEAK]</m></n>	. 185
CALCulate <n>:MARKer<m>:SGRam:XY:MINimum[:PEAK]</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:XY:MINimum[:PEAK]</m></n>	. 185
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:ABOVe</m></n>	.186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:ABOVe</m></n>	. 186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:BELow</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:BELow</m></n>	.186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:NEXT</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:NEXT</m></n>	. 186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum[:PEAK]</m></n>	. 186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum[:PEAK]</m></n>	186
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:ABOVe</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:ABOVe</m></n>	. 187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:BELow</m></n>	. 187
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:BELow</m></n>	.187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:NEXT</m></n>	.187
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:NEXT</m></n>	. 187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum[:PEAK]</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum[:PEAK]</m></n>	188

CALCulate<n>:MARKer<m>:SGRam:FRAMe <Frame>
CALCulate<n>:MARKer<m>:SPECtrogram:FRAMe <Frame> | <Time>

This command positions a marker on a particular frame.

#### Suffix:

<n> Window <m> Marker

## Parameters:

<Frame> Selects a frame directly by the frame number. Valid if the time

stamp is off.

The range depends on the history depth.

Default unit: S

<Time> Selects a frame via its time stamp. Valid if the time stamp is on.

The number is the (negative) distance to frame 0 in seconds.

The range depends on the history depth.

Example: CALC:MARK:SGR:FRAM -20

Sets the marker on the 20th frame before the present.

CALC:MARK2:SGR:FRAM -2s

Sets second marker on the frame 2 seconds ago.

Manual operation: See "Frame (Spectrogram only)" on page 75

CALCulate<n>:MARKer<m>:SGRam:SARea <SearchArea>
CALCulate<n>:MARKer<m>:SPECtrogram:SARea <SearchArea>

This command defines the marker search area for all spectrogram markers in the channel setup.

Suffix:

<n> irrelevant <m> irrelevant

Parameters:

<SearchArea> VISible

Performs a search within the visible frames.

Note that the command does not work if the spectrogram is not

visible for any reason (e.g. if the display update is off).

**MEMory** 

Performs a search within all frames in the memory.

\*RST: VISible

Manual operation: See "Marker Search Area" on page 83

CALCulate<n>:MARKer<m>:SGRam:XY:MAXimum[:PEAK]
CALCulate<n>:MARKer<m>:SPECtrogram:XY:MAXimum[:PEAK]

This command moves a marker to the highest level of the spectrogram.

Suffix:

<n> Window <m> Marker

CALCulate<n>:MARKer<m>:SGRam:XY:MINimum[:PEAK]
CALCulate<n>:MARKer<m>:SPECtrogram:XY:MINimum[:PEAK]

This command moves a marker to the minimum level of the spectrogram.

Suffix:

<n> Window <m> Marker

CALCulate<n>:MARKer<m>:SGRam:Y:MAXimum:ABOVe CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:ABOVe

This command moves a marker vertically to the next lower peak level for the current frequency.

The search includes only frames above the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

CALCulate<n>:MARKer<m>:SGRam:Y:MAXimum:BELow CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:BELow

This command moves a marker vertically to the next lower peak level for the current frequency.

The search includes only frames below the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

CALCulate<n>:MARKer<m>:SGRam:Y:MAXimum:NEXT CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum:NEXT

This command moves a marker vertically to the next lower peak level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

CALCulate<n>:MARKer<m>:SGRam:Y:MAXimum[:PEAK]
CALCulate<n>:MARKer<m>:SPECtrogram:Y:MAXimum[:PEAK]

This command moves a marker vertically to the highest level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

If the marker hasn't been active yet, the command looks for the peak level in the whole spectrogram.

Suffix:

<n> Window <m> Marker

# CALCulate<n>:MARKer<m>:SGRam:Y:MINimum:ABOVe CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:ABOVe

This command moves a marker vertically to the next higher minimum level for the current frequency.

The search includes only frames above the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:MARKer<m>:SGRam:Y:MINimum:BELow CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:BELow

This command moves a marker vertically to the next higher minimum level for the current frequency.

The search includes only frames below the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:MARKer<m>:SGRam:Y:MINimum:NEXT CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum:NEXT

This command moves a marker vertically to the next higher minimum level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:MARKer<m>:SGRam:Y:MINimum[:PEAK] CALCulate<n>:MARKer<m>:SPECtrogram:Y:MINimum[:PEAK]

This command moves a marker vertically to the minimum level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

If the marker hasn't been active yet, the command first looks for the peak level for all frequencies and moves the marker vertically to the minimum level.

#### Suffix:

<n> Window <m> Marker

## **Using Delta Markers**

The following commands control spectrogram delta markers.

### Useful commands for spectrogram markers described elsewhere

The following commands define the horizontal position of the delta markers.

- CALCulate<n>:DELTamarker<m>:MAXimum:LEFT on page 196
- CALCulate<n>:DELTamarker<m>:MAXimum:NEXT on page 197
- CALCulate<n>:DELTamarker<m>:MAXimum[:PEAK] on page 197
- CALCulate<n>:DELTamarker<m>:MAXimum:RIGHt on page 197
- CALCulate<n>:DELTamarker<m>:MINimum:LEFT on page 198
- CALCulate<n>:DELTamarker<m>:MINimum:NEXT on page 198
- CALCulate<n>:DELTamarker<m>:MINimum[:PEAK] on page 198
- CALCulate<n>:DELTamarker<m>:MINimum:RIGHt on page 198

## Remote commands exclusive to spectrogram markers

CAL Culata and DEL Tamandan and COD and ED AMa

CALCUlate(1)2.DELTatilatke(1)12.SGRaffi.FRAMe	109
CALCulate <n>:DELTamarker<m>:SPECtrogram:FRAMe</m></n>	189
CALCulate <n>:DELTamarker<m>:SGRam:SARea</m></n>	189
CALCulate <n>:DELTamarker<m>:SPECtrogram:SARea</m></n>	189
CALCulate <n>:DELTamarker<m>:SGRam:XY:MAXimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SPECtrogram:XY:MAXimum[:PEAK]</m></n>	
CALCulate <n>:DELTamarker<m>:SGRam:XY:MINimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SPECtrogram:XY:MINimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:ABOVe</m></n>	
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:ABOVe</m></n>	190
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:BELow</m></n>	
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:BELow</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:NEXT</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:NEXT</m></n>	191
CAL Culate <n>·DELTamarker<m>·SGRam·V·MAXimum[·PEAK]</m></n>	

100

CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum[:PEAK]</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:ABOVe</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:ABOVe</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:BELow</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:BELow</m></n>	192
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:NEXT</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:NEXT</m></n>	192
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum[:PEAK]</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum[:PEAK]</m></n>	192

# CALCulate<n>:DELTamarker<m>:SGRam:FRAMe <Frame> CALCulate<n>:DELTamarker<m>:SPECtrogram:FRAMe <Frame>

This command positions a delta marker on a particular frame. The frame is relative to the position of marker 1.

The command is available for the spectrogram.

Suffix:

<n> Window <m> Marker

Parameters:

<Frame> Selects a frame either by its frame number or time stamp.

The frame number is available if the time stamp is off. The range

depends on the history depth.

The time stamp is available if the time stamp is on. The number is the distance to frame 0 in seconds. The range depends on the

history depth.

Default unit: S

**Example:** CALC:DELT4:SGR:FRAM -20

Sets fourth deltamarker 20 frames below marker 1.

CALC:DELT4:SGR:FRAM 2 s

Sets fourth deltamarker 2 seconds above the position of marker

1.

Manual operation: See "Frame (Spectrogram only)" on page 75

CALCulate<n>:DELTamarker<m>:SGRam:SARea <SearchArea>
CALCulate<n>:DELTamarker<m>:SPECtrogram:SARea <SearchArea>

This command defines the marker search area for *all* spectrogram markers in the channel setup.

Suffix:

<n> irrelevant

<m> irrelevant

Parameters:

<SearchArea> VISible

Performs a search within the visible frames.

Note that the command does not work if the spectrogram is not

visible for any reason (e.g. if the display update is off).

**MEMory** 

Performs a search within all frames in the memory.

\*RST: VISible

Manual operation: See "Marker Search Area" on page 83

# CALCulate<n>:DELTamarker<m>:SGRam:XY:MAXimum[:PEAK] CALCulate<n>:DELTamarker<m>:SPECtrogram:XY:MAXimum[:PEAK]

This command moves a marker to the highest level of the spectrogram over all frequencies.

#### Suffix:

<n> Window <m> Marker

# CALCulate<n>:DELTamarker<m>:SGRam:XY:MINimum[:PEAK] CALCulate<n>:DELTamarker<m>:SPECtrogram:XY:MINimum[:PEAK]

This command moves a delta marker to the minimum level of the spectrogram over all frequencies.

#### Suffix:

<n> Window <m> Marker

## CALCulate<n>:DELTamarker<m>:SGRam:Y:MAXimum:ABOVe CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:ABOVe

This command moves a marker vertically to the next higher level for the current frequency.

The search includes only frames above the current marker position. It does not change the horizontal position of the marker.

## Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:DELTamarker<m>:SGRam:Y:MAXimum:BELow CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:BELow

This command moves a marker vertically to the next higher level for the current frequency.

The search includes only frames below the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

## CALCulate<n>:DELTamarker<m>:SGRam:Y:MAXimum:NEXT CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:NEXT

This command moves a delta marker vertically to the next higher level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:DELTamarker<m>:SGRam:Y:MAXimum[:PEAK] CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MAXimum[:PEAK]

This command moves a delta marker vertically to the highest level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

If the marker hasn't been active yet, the command looks for the peak level in the whole spectrogram.

#### Suffix:

<n> Window <m> Marker

## CALCulate<n>:DELTamarker<m>:SGRam:Y:MINimum:ABOVe CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:ABOVe

This command moves a delta marker vertically to the next minimum level for the current frequency.

The search includes only frames above the current marker position. It does not change the horizontal position of the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:DELTamarker<m>:SGRam:Y:MINimum:BELow CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:BELow

This command moves a delta marker vertically to the next minimum level for the current frequency.

The search includes only frames below the current marker position. It does not change the horizontal position of the marker.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

## CALCulate<n>:DELTamarker<m>:SGRam:Y:MINimum:NEXT CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum:NEXT

This command moves a delta marker vertically to the next minimum level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Mode for Next Peak in Y-Direction" on page 82

# CALCulate<n>:DELTamarker<m>:SGRam:Y:MINimum[:PEAK] CALCulate<n>:DELTamarker<m>:SPECtrogram:Y:MINimum[:PEAK]

This command moves a delta marker vertically to the minimum level for the current frequency.

The search includes all frames. It does not change the horizontal position of the marker.

If the marker hasn't been active yet, the command first looks for the peak level in the whole spectrogram and moves the marker vertically to the minimum level.

## Suffix:

<n> Window

<m> Marker

#### 9.7.3.5 Positioning the Marker

This chapter contains remote commands necessary to position the marker on a trace.

•	Positioning Normal Markers	193
•	Positioning Delta Markers	196

## **Positioning Normal Markers**

The following commands position markers on the trace.

CALCulate <n>:MARKer<m>:MAXimum:AUTO19</m></n>	93
CALCulate <n>:MARKer<m>:MAXimum:LEFT19</m></n>	93
CALCulate <n>:MARKer<m>:MAXimum:NEXT19</m></n>	94
CALCulate <n>:MARKer<m>:MAXimum[:PEAK]19</m></n>	94
CALCulate <n>:MARKer<m>:MAXimum:RIGHt19</m></n>	94
CALCulate <n>:MARKer<m>:MINimum:AUTO19</m></n>	95
CALCulate <n>:MARKer<m>:MINimum:LEFT</m></n>	95
CALCulate <n>:MARKer<m>:MINimum:NEXT</m></n>	95
CALCulate <n>:MARKer<m>:MINimum[:PEAK]</m></n>	96
CALCulate <n>:MARKer<m>:MINimum:RIGHt</m></n>	96

#### CALCulate<n>:MARKer<m>:MAXimum:AUTO <State>

This command turns an automatic marker peak search for a trace maximum on and off. The R&S ZNL performs the peak search after each sweep.

# Suffix:

<n> Window <m> Marker

#### Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK:MAX:AUTO ON

Activates the automatic peak search function for marker 1 at the

end of each particular sweep.

Manual operation: See "Auto Max Peak Search / Auto Min Peak Search"

on page 80

#### CALCulate<n>:MARKer<m>:MAXimum:LEFT

This command moves a marker to the next lower peak.

The search includes only measurement values to the left of the current marker position.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Peak" on page 85

#### CALCulate<n>:MARKer<m>:MAXimum:NEXT

This command moves a marker to the next lower peak.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Peak" on page 85

#### CALCulate<n>:MARKer<m>:MAXimum[:PEAK]

This command moves a marker to the highest level.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

If the marker is not yet active, the command first activates the marker.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Peak Search" on page 85

### CALCulate<n>:MARKer<m>:MAXimum:RIGHt

This command moves a marker to the next lower peak.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Peak" on page 85

#### CALCulate<n>:MARKer<m>:MINimum:AUTO <State>

This command turns an automatic marker peak search for a trace minimum on and off. The R&S ZNL performs the peak search after each sweep.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK:MIN:AUTO ON

Activates the automatic minimum value search function for

marker 1 at the end of each particular sweep.

Manual operation: See "Auto Max Peak Search / Auto Min Peak Search"

on page 80

#### CALCulate<n>:MARKer<m>:MINimum:LEFT

This command moves a marker to the next minimum value.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

### CALCulate<n>:MARKer<m>:MINimum:NEXT

This command moves a marker to the next minimum value.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

#### CALCulate<n>:MARKer<m>:MINimum[:PEAK]

This command moves a marker to the minimum level.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

If the marker is not yet active, the command first activates the marker.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Minimum" on page 85

#### CALCulate<n>:MARKer<m>:MINimum:RIGHt

This command moves a marker to the next minimum value.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

## Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

#### **Positioning Delta Markers**

The following commands position delta markers on the trace.

CALCulate <n>:DELTamarker<m>:MAXimum:LEFT</m></n>	196
CALCulate <n>:DELTamarker<m>:MAXimum:NEXT</m></n>	197
CALCulate <n>:DELTamarker<m>:MAXimum[:PEAK]</m></n>	197
CALCulate <n>:DELTamarker<m>:MAXimum:RIGHt</m></n>	197
CALCulate <n>:DELTamarker<m>:MINimum:LEFT</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum:NEXT</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum[:PEAK]</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum:RIGHt</m></n>	198

#### CALCulate<n>:DELTamarker<m>:MAXimum:LEFT

This command moves a delta marker to the next higher value.

The search includes only measurement values to the left of the current marker position.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Peak" on page 85

## CALCulate<n>:DELTamarker<m>:MAXimum:NEXT

This command moves a marker to the next higher value.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> 1..n

Window

<m> 1..n

Marker

Manual operation: See "Search Next Peak" on page 85

#### CALCulate<n>:DELTamarker<m>:MAXimum[:PEAK]

This command moves a delta marker to the highest level.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

If the marker is not yet active, the command first activates the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Peak Search" on page 85

#### CALCulate<n>:DELTamarker<m>:MAXimum:RIGHt

This command moves a delta marker to the next higher value.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the maximum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Peak" on page 85

#### CALCulate<n>:DELTamarker<m>:MINimum:LEFT

This command moves a delta marker to the next higher minimum value.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

## CALCulate<n>:DELTamarker<m>:MINimum:NEXT

This command moves a marker to the next higher minimum value.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

#### CALCulate<n>:DELTamarker<m>:MINimum[:PEAK]

This command moves a delta marker to the minimum level.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

If the marker is not yet active, the command first activates the marker.

Suffix:

<n> Window <m> Marker

Manual operation: See "Search Minimum" on page 85

#### CALCulate<n>:DELTamarker<m>:MINimum:RIGHt

This command moves a delta marker to the next higher minimum value.

The search includes only measurement values to the right of the current marker position.

In the spectrogram, the command moves a marker horizontally to the minimum level in the currently selected frame. The vertical marker position remains the same.

#### Suffix:

<n> Window <m> Marker

Manual operation: See "Search Next Minimum" on page 85

#### 9.7.3.6 Band Power Marker

The following commands control the marker for band power measurements.

#### **Using Markers**

CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:AOFF</m></n>	199
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:MODE</m></n>	199
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:RESult?</m></n>	200
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:SPAN</m></n>	200
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer[:STATe]</m></n>	200

#### CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:AOFF

Removes all band power markers in the specified window.

#### Suffix:

<n> Window <m> irrelevant

**Example:** CALC:MARK:FUNC:BPOW:AOFF

#### CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:MODE < Mode>

This command selects the way the results for a band power marker are displayed.

(Note: relative power results are only available for delta markers,

see .CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:MODE on page 201

## Suffix:

<n> Window <m> Marker

#### Parameters:

<Mode> POWer

Result is displayed as an absolute power. The power unit depends on the CALCulate<n>:UNIT:POWer setting.

#### **DENSity**

Result is displayed as a density in dBm/Hz.

\*RST: POWer

**Example:** CALC:MARK4:FUNC:BPOW:MODE DENS

Configures marker 4 to show the measurement results in

dBm/Hz.

Manual operation: See "Power Mode" on page 91

#### CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:RESult?

This command queries the results of the band power measurement.

Suffix:

<n> Window <m> Marker

Return values:

<Power> Signal power over the marker bandwidth.

**Example:** Activate the band power marker:

CALC:MARK:FUNC:BPOW:STAT ON
Select the density mode for the result:
CALC:MARK:FUNC:BPOW:MODE DENS

Query the result:

CALC:MARK:FUNC:BPOW:RES?

Response: 20dBm/Hz

Usage: Query only

# CALCulate<n>:MARKer<m>:FUNCtion:BPOWer:SPAN <Span>

This command defines the bandwidth around the marker position.

Suffix:

<n> Window <m> Marker

Parameters:

<Span> Frequency. The maximum span depends on the marker position

and R&S ZNL model.

\*RST: 5% of current span

Default unit: Hz

**Example:** CALC:MARK:FUNC:BPOW:SPAN 2MHz

Measures the band power over 2 MHz around the marker.

Manual operation: See "Span" on page 91

### CALCulate<n>:MARKer<m>:FUNCtion:BPOWer[:STATe] <State>

This command turns markers for band power measurements on and off.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK4:FUNC:BPOW:STAT ON

Activates or turns marker 4 into a band power marker.

Manual operation: See "Band Power Measurement State" on page 91

See "Switching All Band Power Measurements Off" on page 92

#### **Using Delta Markers**

CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer:MODE</m></n>	201
CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer:RESult?</m></n>	202
CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer:SPAN</m></n>	202
CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer[:STATe]</m></n>	202

## CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:MODE < Mode>

This command selects the way the results for a band power delta marker are displayed.

Suffix:

<n> Window <m> Marker

Parameters:

<Mode> POWer

Result is displayed as an absolute power. The power unit depends on the CALCulate<n>:UNIT:POWer setting.

**DENSity** 

Result is displayed as a density in dBm/Hz.

# **RPOWer**

This setting is only available for a delta band power marker. The result is the difference between the absolute power in the band around the delta marker and the absolute power for the reference marker. The powers are subtracted logarithmically, so the result is a dB value.

[Relative band power (Delta2) in dB] = [absolute band power (Delta2) in dBm] - [absolute (band) power of reference marker in

dBm1

For details see "Relative band power markers" on page 89.

\*RST: POWer

Manual operation: See "Power Mode" on page 91

#### CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:RESult?

This command queries the results of the band power measurement.

Suffix:

<n> Window <m> Marker

Return values:

<Power> Signal power over the delta marker bandwidth.

Usage: Query only

### CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer:SPAN <Span>

This command defines the bandwidth around the delta marker position.

Suffix:

<n> Window <m> Marker

Parameters:

<Span> Frequency. The maximum span depends on the marker position

and R&S ZNL model.

\*RST: 5% of current span

Default unit: Hz

Manual operation: See "Span" on page 91

#### CALCulate<n>:DELTamarker<m>:FUNCtion:BPOWer[:STATe] <State>

This command turns delta markers for band power measurements on and off.

If neccessary, the command also turns on a reference marker.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

Manual operation: See "Band Power Measurement State" on page 91

See "Switching All Band Power Measurements Off" on page 92

#### 9.7.3.7 Marker Peak Lists

### Useful commands for peak lists described elsewhere

- CALCulate<n>:MARKer<m>:PEXCursion on page 179
- MMEMory:STORe<n>:PEAK on page 206

#### Remote commands exclusive to peak lists

CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:ANNotation:LABel[:STATe]</m></n>	203
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:COUNt?</m></n>	203
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks[:IMMediate]</m></n>	204
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:LIST:SIZE</m></n>	204
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:SORT</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:STATe</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:X?</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:Y?</m></n>	206
MMEMory:STORe <n>:PEAK</n>	206

# CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:ANNotation:LABel[:STATe]

This command turns labels for peaks found during a peak search on and off.

The labels correspond to the marker number in the marker peak list.

# Suffix:

<n> Window <m> Marker

#### Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

**Example:** CALC:MARK:FUNC:FPE:ANN:LAB:STAT OFF

Removes the peak labels from the diagram

Manual operation: See "Display MarkerNumbers" on page 95

#### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:COUNt?

This command queries the number of peaks that have been found during a peak search.

The actual number of peaks that have been found may differ from the number of peaks you have set to be found because of the peak excursion.

#### Suffix:

<n> irrelevant <m> irrelevant

Return values: <NumberOfPeaks>

**Example:** CALC:MARK:FUNC:FPE:COUN?

Queries the number of peaks.

Usage: Query only

#### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks[:IMMediate] <Peaks>

This command initiates a peak search.

Suffix:

<n> Window <m> Marker

Parameters:

<Peaks> This parameter defines the number of peaks to find during the

search.

Note that the actual number of peaks found during the search

also depends on the peak excursion you have set with

CALCulate<n>:MARKer<m>:PEXCursion.

Range: 1 to 200

**Example:** CALC:MARK:PEXC 5

Defines a peak excursion of 5 dB, i.e. peaks must be at least 5

dB apart to be detected as a peak. CALC:MARK:FUNC:FPE 10

Initiates a search for 10 peaks on the current trace.

### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:LIST:SIZE <MaxNoPeaks>

This command defines the maximum number of peaks that the R&S ZNL looks for during a peak search.

Suffix:

<n> Window <m> Marker

Parameters:

<MaxNoPeaks> Maximum number of peaks to be determined.

Range: 1 to 200 \*RST: 50

**Example:** CALC:MARK:FUNC:FPE:LIST:SIZE 10

The marker peak list will contain a maximum of 10 peaks.

Manual operation: See "Maximum Number of Peaks" on page 95

#### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:SORT <SortMode>

This command selects the order in which the results of a peak search are returned.

Suffix:

<n> Window <m> Marker

Parameters:

<SortMode> X

Sorts the peaks according to increasing position on the x-axis.

Υ

Sorts the peaks according to decreasing position on the y-axis.

\*RST: X

**Example:** CALC:MARK:FUNC:FPE:SORT Y

Sets the sort mode to decreasing y values

Manual operation: See "Sort Mode" on page 94

#### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:STATe <State>

This command turns a peak search on and off.

Suffix:

<n> Window <m> Marker

Parameters:

<State> ON | OFF | 0 | 1

OFF | 0

Switches the function off

ON | 1

Switches the function on

**Example:** CALC:MARK:FUNC:FPE:STAT ON

Activates marker peak search

Manual operation: See "Peak List State" on page 94

## CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:X?

This command queries the position of the peaks on the x-axis.

The order depends on the sort order that has been set with CALCulate<n>: MARKer<m>: FUNCtion: FPEaks: SORT.

Suffix:

<n> irrelevant <m> irrelevant

Return values:

<PeakPosition> Position of the peaks on the x-axis. The unit depends on the

measurement.

Usage: Query only

#### CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:Y?

This command queries the position of the peaks on the y-axis.

The order depends on the sort order that has been set with CALCulate<n>: MARKer<m>: FUNCtion: FPEaks: SORT.

Suffix:

<n> irrelevant <m> irrelevant

Return values:

<PeakPosition> Position of the peaks on the y-axis. The unit depends on the

measurement.

Usage: Query only

#### MMEMory:STORe<n>:PEAK <FileName>

This command exports the marker peak list to a file.

Suffix:

<n> Window

Parameters:

<FileName> String containing the path,name and extension of the target file.

**Example:** MMEM:STOR:PEAK 'test.dat'

Saves the current marker peak list in the file test.dat.

Manual operation: See "Export Peak List" on page 95

# 9.8 Retrieving Results

The following commands can be used to retrieve the results of the I/Q Analyzer measurement.



## Storing large amounts of I/Q data

When storing large amounts of I/Q data to a file, consider the following tips to improve performance:

- If capturing and storing the I/Q data is the main goal of the measurement and evaluation functions are not required, use the basic I/Q data acquisition mode (see TRACe: IQ[:STATe] on page 110).
- Use a HiSlip or raw socket connection to export the data from the R&S ZNL to a PC.
- Export the data in binary format rather than ASCII format (see Chapter A, "Formats for Returned Values: ASCII Format and Binary Format", on page 222).
- Use the "Compatible" or "IQPair" data mode (see Chapter B, "Reference: Format Description for I/Q Data Files", on page 223).
- If only an extract of the available data is relevant, use the TRACe<n>[:DATA]: MEMory? command to store only the required section of data.

•	Retrieving Captured I/Q Data	207
•	Retrieving I/Q Trace Data	. 210
•	Exporting Traces and Data	. 213
	Retrieving Marker Results.	

# 9.8.1 Retrieving Captured I/Q Data

The raw captured I/Q data is output in the form of a list.

TRACe:IQ:DATA	207
TRACe:IQ:DATA:FORMat	208
TRACe:IQ:DATA:MEMory?	208

#### TRACe:IQ:DATA

This command initiates a measurement with the current settings and returns the captured data from I/Q measurements.

This command corresponds to:

```
INIT:IMM; *WAI;:TRACe:IQ:DATA:MEMory?
```

However, the TRACe: IQ: DATA? command is quicker in comparison.

**Note:** Using the command with the \*RST values for the TRACe: IQ: SET command, the following minimum buffer sizes for the response data are recommended: ASCII format 10 kBytes, binary format: 2 kBytes

Return values:

<Results> Measured voltage for I and Q component for each sample that

has been captured during the measurement.

The number of samples depends on  $\mathtt{TRACe}: \mathtt{IQ}: \mathtt{SET}.$  In ASCII format, the number of results is  $2^*$  the number of samples. The data format depends on  $\mathtt{TRACe}: \mathtt{IQ}: \mathtt{DATA}: \mathtt{FORMat}$ 

on page 208. Default unit: V

**Example:** TRAC:IQ:STAT ON

Enables acquisition of I/Q data

TRAC: IQ: SET NORM, 10MHz, 32MHz, EXT, POS, 0, 4096

Measurement configuration: Sample Rate = 32 MHz Trigger Source = External Trigger Slope = Positive Pretrigger Samples = 0 Number of Samples = 4096

FORMat REAL, 32

Selects format of response data

TRAC: IQ: DATA?

Starts measurement and reads results

#### TRACe:IQ:DATA:FORMat <Format>

This command selects the order of the I/Q data.

For details see Chapter B, "Reference: Format Description for I/Q Data Files", on page 223.

#### Parameters:

**COMPatible** 

I and Q values are separated and collected in blocks: A block (512k) of I values is followed by a block (512k) of Q values, followed by a block of I values, followed by a block of Q values etc.

(I,I,I,I,Q,Q,Q,Q,I,I,I,I,Q,Q,Q,Q,Q...)

**IQBLock** 

First all I-values are listed, then the Q-values

(I,I,I,I,I,I,...Q,Q,Q,Q,Q,Q)

**IQPair** 

One pair of I/Q values after the other is listed

(I,Q,I,Q,I,Q...). \*RST: IQBL

## TRACe:IQ:DATA:MEMory? [<OffsetSamples>,<NoOfSamples>]

This command queries the I/Q data currently stored in the capture buffer of the R&S ZNL.

By default, the command returns all I/Q data in the memory. You can, however, narrow down the amount of data that the command returns using the optional parameters.

If no parameters are specified with the command, the entire trace data is retrieved; in this case, the command returns the same results as TRACe:IQ:DATA. (Note, however, that the TRAC:IQ:DATA? command initiates a new measurement before returning the captured values, rather than returning the existing data in the memory.)

The command returns a comma-separated list of the measured values in floating point format (comma-separated values = CSV). The number of values returned is 2 \* the number of complex samples.

The total number of complex samples is displayed in the channel bar in manual operation and can be calculated as:

<SampleRate> \* <CaptureTime>

(See TRACe:IQ:SET, TRACe:IQ:SRATe on page 141 and [SENSe:]SWEep:TIME on page 157)

#### **Query parameters:**

<OffsetSamples>

Selects an offset at which the output of data should start in relation to the first data. If omitted, all captured samples are output, starting with the first sample.

Range: 0 to <# of samples> – 1, with <# of samples> being

the maximum number of captured values

\*RST: 0

<NoOfSamples>

Number of samples you want to query, beginning at the offset you have defined. If omitted, all captured samples (starting at offset) are output.

Range: 1 to <# of samples> - <offset samples> with <# of

samples> maximum number of captured values

\*RST: <# of samples>

#### Return values:

<IQData>

Measured value pair (I,Q) for each sample that has been recor-

ded.

By default, the first half of the list contains the I values, the second half the Q values. The order can be configured using

TRACe:IQ:DATA:FORMat.

The data format of the individual values depends on FORMat [:

DATA] on page 210.

Default unit: V

**Example:** TRAC:IQ:STAT ON

Enables acquisition of I/Q data

TRAC: IQ: SET NORM, 10MHz, 32MHz, EXT, POS, 100, 4096

Measurement configuration:

Sample Rate = 32 MHz Trigger Source = External Trigger Slope = Positive Pretrigger Samples = 100 Number of Samples = 4096

INIT; \*WAI

Starts measurement and wait for sync

FORMat REAL, 32

Determines output format

To read the results: TRAC: IQ: DATA: MEM? Reads all 4096 I/Q data

TRAC: IQ: DATA: MEM? 0,2048

Reads 2048 I/Q data starting at the beginning of data acquisition

TRAC: IQ: DATA: MEM? 2048, 1024

Reads 1024 I/Q data from half of the recorded data

TRAC: IQ: DATA: MEM? 100,512

Reads 512 I/Q data starting at the trigger point (<Pretrigger

Samples> was 100)

**Example:** // Perform a single I/Q capture.

INIT; \*WAI

// Determine output format (binary float32)

FORMat REAL, 32

// Read 1024 I/Q samples starting at sample 2048.

TRAC: IQ: DATA: MEM? 2048, 1024

Usage: Query only

## 9.8.2 Retrieving I/Q Trace Data

In addition to the raw captured I/Q data, the results from I/Q analysis as shown in the result displays can also be retrieved.

FORMat[:DATA]	210
TRACe <n>[:DATA]?</n>	
TRACe <n>[:DATA]:MEMory?</n>	
TRACe <n>[:DATA]:X?</n>	

#### FORMat[:DATA] <Format>[, <BitLength>]

This command selects the data format that is used for transmission of trace data from the R&S ZNL to the controlling computer.

Note that the command has no effect for data that you send to the R&S ZNL. The R&S ZNL automatically recognizes the data it receives, regardless of the format.

#### Parameters:

<Format> ASCii | REAL | UINT | MATLab

**ASCII** 

ASCii format, separated by commas.

This format is almost always suitable, regardless of the actual data format. However, the data is not as compact as other for-

mats may be.

**REAL** 

Floating-point numbers (according to IEEE 754) in the "definite

length block format".

In the Spectrum application, the format setting REAL is used for

the binary transmission of trace data.

<BitLength> 16 | 32 | 64

Length in bits for floating-point results

32

32-bit floating-point numbers

For I/Q data, 8 bytes per sample are returned for this format set-

ting.

**Example:** FORM REAL, 32

#### TRACe<n>[:DATA]? <ResultType>

This command queries current trace data and measurement results.

If you use it as a setting command, it transfers trace data from an external source to the R&S ZNL.

The data format depends on FORMat [:DATA] on page 210.

## Suffix:

<n> Window

### **Query parameters:**

<ResultType> Selects the type of result to be returned.

TRACE1 | ... | TRACE6

Returns the trace data for the corresponding trace.

For details see Table 9-4.

LIST

Returns the results of the peak list evaluation for Spurious Emis-

sion and Spectrum Emission Mask measurements.

For SEM measurements, one peak per range is returned.

For details see Table 9-5.

#### **SPURious**

Returns the peak list of Spurious Emission measurements.

## SPECtrogram | SGRam

Returns the results of the spectrogram result display.

For details see Table 9-6.

#### Return values:

<TraceData>

Returns the sweep point values as shown in the result display. If you are measuring with the auto peak detector, the command returns positive peak values only. (To retrieve negative peak values, define a second trace with a negative peak detector.) For the Magnitude and Spectrum result displays in the I/Q Analyzer application, this command returns the magnitude of the I and Q values (I+jQ) for each sweep point (=1001 values). For the Real/Imag (I/Q) result display, the command returns first the real parts for each trace point, then the imaginary parts

the real parts for each trace point, then the imaginary parts

 $(I_1,...,I_{1001}, Q_1,...,Q_{1001}).$ 

For the I/Q Vector result display, the I and Q values for each trace point are returned (1001 pairs of I and Q values).

**Example:** TRAC? TRACE3

Queries the data of trace 3.

Manual operation: See "Magnitude" on page 13

See "Spectrum" on page 13 See "I/Q-Vector" on page 14 See "Real/Imag (I/Q)" on page 15

#### Table 9-4: Return values for TRACE1 to TRACE6 parameter

The trace data consists of a list of power levels that have been measured. The number of power levels in the list depends on the currently selected number of sweep points. The unit depends on the measurement and on the unit you have currently set.

If you are measuring with the auto peak detector, the command returns positive peak values only. (To retrieve negative peak values, define a second trace with a negative peak detector.)

#### Table 9-5: Return values for LIST parameter

For each peak, the command returns 11 values in the following order:

<No>,<StartFreq>,<StopFreq>,<RBW>,<PeakFreq>,<PowerAbs>,<PowerRel>,<PowerDelta>,<LimitCheck>,<Unused1>,<Unused2>

- <No>: range number
- StartFreq>,<StopFreq>: start and stop frequency of the range
- <RBW>: resolution bandwidth
- <PeakFreq>: frequency of the peak in a range
- <PowerAbs>: absolute power of the peak in dBm
- PowerRel>: power of the peak in relation to the channel power in dBc
- PowerDelta>: distance from the peak to the limit line in dB, positive values indicate a failed limit check
- <LimitCheck>: state of the limit check (0 = PASS, 1 = FAIL)
- <Unused1>,<Unused2>: reserved (0.0)

#### Table 9-6: Return values for SPECtrogram parameter

For every frame in the spectrogram, the command returns the power levels that have been measured, one for each sweep point. The number of frames depends on the size of the history depth. The power level depends on the unit you have currently set.

## TRACe<n>[:DATA]:MEMory? <Trace>,<OffsSwPoint>,<NoOfSwPoints>

This command queries the previously captured trace data for the specified trace from the memory. As an offset and number of sweep points to be retrieved can be specified, the trace data can be retrieved in smaller portions, making the command faster than the TRAC: DATA? command. This is useful if only specific parts of the trace data are of interest.

If no parameters are specified with the command, the entire trace data is retrieved; in this case, the command returns the same results as TRAC: DATA? TRACE1.

Suffix:

<n> Window

**Query parameters:** 

<Trace> TRACE1 | TRACE2 | TRACE3 | TRACE4 | TRACE5 | TRACE6

<OffsSwPoint> The offset in sweep points related to the start of the measure-

ment at which data retrieval is to start.

<NoOfSwPoints> Number of sweep points to be retrieved from the trace.

Return values: <SweepPointValues>

**Example:** TRAC:DATA:MEM? TRACE1,25,100

Retrieves 100 sweep points from trace 1, starting at sweep point

25.

**Usage:** Query only

#### TRACe<n>[:DATA]:X? <TraceNumber>

This command queries the horizontal trace data for each sweep point in the specified window, for example the frequency in frequency domain or the time in time domain measurements

This is especially useful for traces with non-equidistant x-values.

Suffix:

<n> Window

**Query parameters:** 

<TraceNumber> Trace number.

TRACE1 | ... | TRACE6

**Example:** TRAC3:X? TRACE1

Returns the x-values for trace 1 in window 3.

Usage: Query only

## 9.8.3 Exporting Traces and Data

The following commands are required to export traces and spectrograms.

FORMat:DEXPort:DSEParator	214
FORMat:DEXPort:FORMat	214
FORMat:DEXPort:HEADer	214
FORMat:DEXPort:TRACes	215
MMEMory:STORe <n>:TRACe</n>	215

#### FORMat:DEXPort:DSEParator < Separator >

This command selects the decimal separator for data exported in ASCII format.

#### Parameters:

<Separator> POINt | COMMa

**COMMa** 

Uses a comma as decimal separator, e.g. 4,05.

**POINt** 

Uses a point as decimal separator, e.g. 4.05.

\*RST: \*RST has no effect on the decimal separator.

Default is POINt.

**Example:** FORM: DEXP: DSEP POIN

Sets the decimal point as separator.

Manual operation: See "Decimal Separator" on page 32

See "Export Peak List" on page 95

## FORMat: DEXPort: FORMat < File Format >

Determines the format of the ASCII file to be imported or exported. Depending on the external program in which the data file was created or will be evaluated, a comma-separated list (CSV) or a plain data format (DAT) file may be required.

#### Parameters:

<FileFormat> CSV | DAT

\*RST: DAT

**Example:** FORM: DEXP: FORM CSV

Manual operation: See "File Type" on page 32

#### FORMat:DEXPort:HEADer <State>

If enabled, additional instrument and measurement settings are included in the header of the export file for result data. If disabled, only the pure result data from the selected traces and tables is exported.

## Parameters:

<State> ON | OFF | 0 | 1

\*RST: 1

Manual operation: See "Include Instrument & Measurement Settings" on page 71

## FORMat:DEXPort:TRACes <Selection>

This command selects the data to be included in a data export file (see MMEMory: STORe<n>: TRACe on page 215).

Parameters:

<Selection> SINGle | ALL

**SINGle** 

Only a single trace is selected for export, namely the one speci-

fied by the MMEMory: STORe<n>: TRACe command.

**ALL** 

Selects all active traces and result tables (e.g. Result Summary, marker peak list etc.) in the current application for export to an

ASCII file.

\*RST:

The <trace> parameter for the MMEMory:STORe<n>:TRACe

command is ignored.

**SINGle** Manual operation: See "Export all Traces and all Table Results" on page 71

## MMEMory:STORe<n>:TRACe <Trace>, <FileName>

This command exports trace data from the specified window to an ASCII file.

Suffix:

<n> Window

Parameters:

Number of the trace to be stored <Trace>

<FileName> String containing the path and name of the target file.

MMEM:STOR1:TRAC 1, 'C:\TEST.ASC' Example:

Stores trace 1 from window 1 in the file TEST.ASC.

Manual operation: See "Export Trace to ASCII File" on page 31

# 9.8.4 Retrieving Marker Results

The following commands are required to retrieve the results of markers.

Useful commands for retrieving marker results described elsewhere:

- CALCulate<n>:DELTamarker<m>:X on page 175
- CALCulate<n>:MARKer<m>:X on page 177
- CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:X? on page 205
- CALCulate<n>:MARKer<m>:FUNCtion:FPEaks:Y? on page 206

#### Remote commands exclusive to retrieving marker results:

CALCulate <n>:DELTamarker<m>:X:RELative?</m></n>	
CALCulate <n>:DELTamarker<m>:Y</m></n>	216
CALCulate <n>:MARKer<m>:Y</m></n>	216
MMEMory:STORe <n>:LIST</n>	217

#### CALCulate<n>:DELTamarker<m>:X:RELative?

This command queries the relative position of a delta marker on the x-axis.

If necessary, the command activates the delta marker first.

Suffix:

<n> Window <m> Marker

Return values:

<Position> Position of the delta marker in relation to the reference marker.

**Example:** CALC:DELT3:X:REL?

Outputs the frequency of delta marker 3 relative to marker 1 or

relative to the reference position.

Usage: Query only

#### CALCulate<n>:DELTamarker<m>:Y

Queries the result at the position of the specified delta marker.

Suffix:

<n> 1..n <m> 1..n

Return values:

<Result> Result at the position of the delta marker.

The unit is variable and depends on the one you have currently

set.

Default unit: DBM

#### CALCulate<n>:MARKer<m>:Y

Queries the result at the position of the specified marker.

Suffix:

<n> 1..n <m> 1..n

Return values:

<Result> Default unit: DBM

Manual operation: See "Marker Table" on page 15

See "Marker Peak List" on page 16

Importing and Exporting I/Q Data and Results

#### MMEMory:STORe<n>:LIST <FileName>

This command exports the SEM and spurious emission list evaluation to a file.

The file format is \*.dat.

Suffix:

<n> Window

Parameters:

<FileName> String containing the path and name of the target file.

**Example:** MMEM:STOR:LIST 'test'

Stores the current list evaluation results in the test.dat file.

# 9.9 Importing and Exporting I/Q Data and Results

Alternatively to capturing I/Q data by the I/Q Analyzer itself, stored I/Q data from previous measurements or other applications can be imported to the I/Q Analyzer. Furthermore, I/Q data processed in the I/Q Analyzer can be stored to a file for further evaluation in other applications.



I/Q data can only be exported in applications that process I/Q data, such as the I/Q Analyzer or optional applications.

MMEMory:STORe <n>:IQ:COMMent</n>	217
MMEMory:STORe <n>:IQ:FORMat</n>	217
MMEMory:STORe <n>:IQ:STATe</n>	218

## MMEMory:STORe<n>:IQ:COMMent < Comment>

This command adds a comment to a file that contains I/Q data.

Suffix:

<n> irrelevant

Parameters:

<Comment> String containing the comment.

**Example:** MMEM:STOR:IQ:COMM 'Device test 1b'

Creates a description for the export file.
MMEM:STOR:IQ:STAT 1, 'C:
\R S\Instr\user\data.iq.tar'

Stores I/Q data and the comment to the specified file.

Manual operation: See "I/Q Export" on page 33

# **MMEMory:STORe<n>:IQ:FORMat** <Format>,<DataFormat>

This command sets or queries the format of the I/Q data to be stored.

Suffix:

<n> irrelevant

Parameters:

<Format> FLOat32

32-bit floating point format.

INT32

32-bit integer format.\*RST: FLOat32

Exports complex data.

**REAL** 

Exports real data.

\*RST: COMPlex

**Example:** MMEM:STOR:IQ:FORM INT32, REAL

# MMEMory:STORe<n>:IQ:STATe 1, <FileName>

This command writes the captured I/Q data to a file.

The file extension is \*.iq.tar. By default, the contents of the file are in 32-bit floating point format.

Suffix:

<n> 1..n

Parameters:

<FileName> String containing the path and name of the target file.

**Example:** MMEM:STOR:IQ:STAT 1, 'C:

\R S\Instr\user\data.iq.tar'

Stores the captured I/Q data to the specified file.

Manual operation: See "I/Q Export" on page 33

# 9.10 Programming Examples

The following programming examples demonstrate how to capture I/Q data and perform I/Q data analysis using the I/Q Analyzer in a remote environment.

•	I/Q Analysis with Graphical Evaluation	218
•	Basic I/Q Analysis with Improved Performance	. 220

# 9.10.1 I/Q Analysis with Graphical Evaluation

This example demonstrates how to configure and perform a basic I/Q data acquisition and analyze the data using the I/Q Analyzer in a remote environment.

```
//-----Activating the I/Q Analyzer application ------
*RST
//Reset the instrument
INST: CRE IQ, 'IQANALYZER'
//Creates a new measurement channel named 'IQANALYZER'.
INIT: CONT OFF
//Switches to single sweep mode
//-----Configuring Data Acquisition-----
TRAC: IQ: SRAT 32MHZ
//Defines the sample rate.
TRAC: IQ: RLEN 1000
//Sets the record length (number of samples to capture) to 1000 samples.
TRAC: IO: BWID?
//Queries the bandwidth of the resampling filter, determined by the sample rate
FORM: DATA REAL, 32
//Formats the data as 32-byte real values.
TRAC: IQ: DATA: FORM IQBL
//Lists all I values first, then all Q values in the trace results.
//-----Configuring the Trace-----
TRAC: IQ: AVER ON
//Defines averaging for the I/Q trace.
TRAC: IQ: AVER: COUN 10
//Defines an average over 10 sweeps.
DISP:TRAC1:MODE WRIT
DISP:TRAC2:MODE MAXH
DISP:TRAC3:MODE MINH
//Changes the trace modes.
//----Performing the Measurement-----
TNTT: *WAT
//Initiates a new measurement and waits until the sweep has finished.
//-----Retrieving Results-----
TRAC:DATA? TRACE1
TRAC:DATA? TRACE2
TRAC:DATA? TRACE3
//Returns the magnitude for each sweep point
LAY: REPL: WIND '1', RIMAG
//Changes the result display to Real/Imag (I/Q)
CALC:MARK:SEAR MAGN
//Configures searches to search both I and Q branches.
CALC:MARK:Y?
//Queries the result of the peak search on both branches.
```

```
TRAC:IQ:DATA:MEM? 0,500

//Returns the first 500 samples of the stored I/Q data for the measurement.

//For each sample, first the I-value, then the Q-value is listed.

TRAC:IQ:DATA:MEM? 500,500

//Returns the second half of the 1000 captured sample values.
```

# 9.10.2 Basic I/Q Analysis with Improved Performance

This example demonstrates how to configure and perform a basic I/Q data acquisition and analyze the data using the I/Q Analyzer in a remote environment.

```
//-----Activating the I/Q Analyzer application ------
*RST
//Reset the instrument
INIT: CONT OFF
//Switches to single sweep mode
TRACE: IO ON
//Switches the operating mode of the current measurement channel to I/Q Analyzer
//while retaining the relevant parameters from the Spectrum mode.
//-----Configuring Data Acquisition-----
TRACE: IQ: SET NORM, 0, 32000000, IQP, POS, 0, 1000
//Configures the sample rate as 32 MHz, IQP trigger, positive trigger slope,
//no pretrigger samples, 1000 samples to capture
FORM REAL, 32
//The data is formatted as real values.
//-----Configuring I/Q Gating-----
TRAC: IQ: EGAT ON
//Turns on gated measurement.
TRAC: IQ: EGAT: TYPE LEV
//Select the level gate type.
TRAC: IQ: EGAT: LENG 20
//Sets the gate length to 20 samples.
TRAC: IO: EGAT: GAP 20
//Sets the interval between gate periods to 20 samples.
TRAC: IQ: EGAT: NOF 2
//Sets the number of gate periods after the trigger signal to 2.
TRIG:SOUR IQP
//Defines the magnitude of the sampled I/Q data to be used as a trigger.
TRIG:LEV:IQP -30dbm
//Sets the trigger level.
//-----Performing the Measurement and Retrieving Results-----
TRAC: IQ: DATA?; *WAI;
//Performs a measurement and returns the RF input voltage at each sample point
```

```
//(first 1000 I-values, then 1000 Q-values).
TRAC:IQ:DATA:MEM? 0,500
//Returns the first 500 samples of the stored trace data for the measurement.
//For each sample, first the I-value, then the Q-value is listed.
TRAC:IQ:DATA:MEM? 500,500
//Returns the second half of the 1000 captured sample values.
```

# Annex

# A Formats for Returned Values: ASCII Format and Binary Format

When trace data is retrieved using the TRAC: DATA or TRAC: IQ: DATA command, the data is returned in the format defined using the FORMat[:DATA] on page 210. The possible formats are described here.

- ASCII Format (FORMat ASCII):
   The data is stored as a list of comma-separated values (CSV) of the measured values in floating point format.
- Binary Format (FORMat REAL,32):

The data is stored as binary data (Definite Length Block Data according to IEEE 488.2), each measurement value being formatted in 32-Bit IEEE 754 Floating-Point-Format.

The schema of the result string is as follows:

#41024<value1><value2>...<value n> with

#4	Number of digits (= 4 in the example) of the following number of data bytes
1024	Number of following data bytes (= 1024 in the example)
<value></value>	4-byte floating point value



Reading out data in binary format is quicker than in ASCII format. Thus, binary format is recommended for large amounts of data.

# B Reference: Format Description for I/Q Data Files

This section describes how I/Q data is transferred to the memory during remote control (see TRACe: IQ: DATA: FORMat command).

For details on the format of the individual values, see Chapter A, "Formats for Returned Values: ASCII Format and Binary Format", on page 222.




Figure B-1: I/Q data formats

Note: 512k corresponds to 524288 samples

For maximum performance, the formats "Compatible" or "IQPair" should be used. Furthermore, for large amounts of data, the data should be in binary format to improve performance.

In binary format, the number of I- and Q-data can be calculated as follows:

$$\#of\ I-Data = \#of\ Q-Data = \frac{\#of\ DataBytes}{8}$$

For the format "QBLock", the offset of Q-data in the output buffer can be calculated as follows:

$$Q-Data-Offset = \frac{(\# of \ DataBytes)}{2} + LengthIndicatorDigits$$

with "LengthIndicatorDigits" being the number of digits of the length indicator including the #. In the example above (#41024...), this results in a value of 6 for "LengthIndicatorDigits" and the offset for the Q-data results in 512 + 6 = 518.

# C I/Q Data File Format (iq-tar)

I/Q data is packed in a file with the extension <code>.iq.tar</code>. An iq-tar file contains I/Q data in binary format together with meta information that describes the nature and the source of data, e.g. the sample rate. The objective of the iq-tar file format is to separate I/Q data from the meta information while still having both inside one file. In addition, the file format allows you to preview the I/Q data in a web browser, and allows you to include user-specific data.

The iq-tar container packs several files into a single .tar archive file. Files in .tar format can be unpacked using standard archive tools (see <a href="http://en.wikipedia.org/wiki/Comparison\_of\_file\_archivers">http://en.wikipedia.org/wiki/Comparison\_of\_file\_archivers</a>) available for most operating systems. The advantage of .tar files is that the archived files inside the .tar file are not changed (not compressed) and thus it is possible to read the I/Q data directly within the archive without the need to unpack (untar) the .tar file first.



An application note on converting Rohde & Schwarz I/Q data files is available from the Rohde & Schwarz website:

1EF85: Converting R&S I/Q data files

#### **Contained files**

An iq-tar file must contain the following files:

- I/Q parameter XML file, e.g. xyz.xml
   Contains meta information about the I/Q data (e.g. sample rate). The filename can be defined freely, but there must be only one single I/Q parameter XML file inside an iq-tar file.
- I/Q data binary file, e.g. xyz.complex.float32

  Contains the binary I/Q data of all channels. There must be only one single I/Q data binary file inside an iq-tar file.

Optionally, an iq-tar file can contain the following file:

I/Q preview XSLT file, e.g. open\_IqTar\_xml\_file\_in\_web\_browser.xslt
 Contains a stylesheet to display the I/Q parameter XML file and a preview of the I/Q data in a web browser.

A sample stylesheet is available at http://www.rohde-schwarz.com/file/open\_lqTar\_xml\_file\_in\_web\_browser.xslt.

# C.1 I/Q Parameter XML File Specification



The content of the I/Q parameter XML file must comply with the XML schema RsIqTar.xsd available at: http://www.rohde-schwarz.com/file/RsIqTar.xsd.

In particular, the order of the XML elements must be respected, i.e. iq-tar uses an "ordered XML schema". For your own implementation of the iq-tar file format make sure to validate your XML file against the given schema.

The following example shows an I/Q parameter XML file. The XML elements and attributes are explained in the following sections.

### Sample I/Q parameter XML file: xyz.xml

```
<?xml version="1.0" encoding="UTF-8"?>
<?xml-stylesheet type="text/xsl"</pre>
href="open_IqTar_xml_file_in_web_browser.xslt"?>
<RS IQ TAR FileFormat fileFormatVersion="1"</pre>
xsi:noNamespaceSchemaLocation="RsIqTar.xsd"
xmlns:xsi="http://www.w3.org/2001/XMLSchema-instance">
 <Name>R&S ZNL</Name>
 <Comment>Here is a comment
 <DateTime>2011-01-24T14:02:49
 <Samples>68751</Samples>
 <Clock unit="Hz">6.5e+006</Clock>
 <Format>complex</Format>
 <DataType>float32
 <ScalingFactor unit="V">1</ScalingFactor>
 <NumberOfChannels>1</NumberOfChannels>
<DataFilename>xyz.complex.float32
<UserData>
 <UserDefinedElement>Example/UserDefinedElement>
</UserData>
 <PreviewData>...</PreviewData>
</RS IQ TAR FileFormat>
```

Element	Description
RS_IQ_TAR_File- Format	The root element of the XML file. It must contain the attribute fileFormatVersion that contains the number of the file format definition. Currently, fileFormatVersion "2" is used.
Name	Optional: describes the device or application that created the file.
Comment	Optional: contains text that further describes the contents of the file.
DateTime	Contains the date and time of the creation of the file. Its type is xs:dateTime (see RsIqTar.xsd).

I/Q Parameter XML File Specification

Element	Description
Samples	Contains the number of samples of the I/Q data. For multi-channel signals all channels have the same number of samples. One sample can be:  A complex number represented as a pair of I and Q values  A complex number represented as a pair of magnitude and phase values  A real number represented as a single real value  See also Format element.
Clock	Contains the clock frequency in Hz, i.e. the sample rate of the I/Q data. A signal generator typically outputs the I/Q data at a rate that equals the clock frequency. If the I/Q data was captured with a signal analyzer, the signal analyzer used the clock frequency as the sample rate. The attribute unit must be set to "Hz".
Format	Specifies how the binary data is saved in the I/Q data binary file (see DataFilename element). Every sample must be in the same format. The format can be one of the following:  complex: Complex number in cartesian format, i.e. I and Q values interleaved. I and Q are unitless  real: Real number (unitless)  polar: Complex number in polar format, i.e. magnitude (unitless) and phase (rad) values interleaved. Requires DataType = float32 or float64
DataType	Specifies the binary format used for samples in the I/Q data binary file (see DataFilename element and Chapter C.2, "I/Q Data Binary File", on page 229). The following data types are allowed:  int8: 8 bit signed integer data  int16: 16 bit signed integer data  int32: 32 bit signed integer data  float32: 32 bit floating point data (IEEE 754)  float64: 64 bit floating point data (IEEE 754)
ScalingFactor	Optional: describes how the binary data can be transformed into values in the unit Volt. The binary I/Q data itself has no unit. To get an I/Q sample in the unit Volt the saved samples have to be multiplied by the value of the ScalingFactor. For polar data only the magnitude value has to be multiplied. For multi-channel signals the ScalingFactor must be applied to all channels.
	The attribute unit must be set to "v".
	The ScalingFactor must be > 0. If the ScalingFactor element is not defined, a value of 1 V is assumed.
NumberOfChan- nels	Optional: specifies the number of channels, e.g. of a MIMO signal, contained in the I/Q data binary file. For multi-channels, the I/Q samples of the channels are expected to be interleaved within the I/Q data file (see Chapter C.2, "I/Q Data Binary File", on page 229). If the NumberOfChannels element is not defined, one channel is assumed.
DataFilename	Contains the filename of the I/Q data binary file that is part of the iq-tar file.  It is recommended that the filename uses the following convention: <xyz>.<format>.<channels>ch.<type> <xyz> = a valid Windows file name  <format> = complex, polar or real (see Format element)  <format> = channels (see NumberOfChannels element)  <format> = float32, float64, int8, int16, int32 or int64 (see DataType element)  Examples:  xyz.complex.1ch.float32  xyz.polar.1ch.float64  xyz.real.1ch.int16  xyz.complex.16ch.int8</format></format></format></xyz></type></channels></format></xyz>

I/Q Parameter XML File Specification

Element	Description
UserData	Optional: contains user, application or device-specific XML data which is not part of the iq-tar specification. This element can be used to store additional information, e.g. the hardware configuration. User data must be valid XML content.
PreviewData	Optional: contains further XML elements that provide a preview of the I/Q data. The preview data is determined by the routine that saves an iq-tar file (e.g. R&S ZNL). For the definition of this element refer to the RsIqTar.xsd schema. Note that the preview can be only displayed by current web browsers that have JavaScript enabled and if the XSLT stylesheet open_IqTar_xml_file_in_web_browser.xslt is available.

# **Example: ScalingFactor**

Data stored as int16 and a desired full scale voltage of 1 V

ScalingFactor = 1 V / maximum int16 value = 1 V /  $2^{15}$  = 3.0517578125e-5 V

Scaling Factor	Numerical value	Numerical value x ScalingFactor
Minimum (negative) int16 value	- 2 <sup>15</sup> = - 32768	-1 V
Maximum (positive) int16 value	215-1= 32767	0.999969482421875 V

### **Example: PreviewData in XML**

```
<PreviewData>
   <ArrayOfChannel length="1">
     <Channel>
       <PowerVsTime>
          <Min>
           <ArrayOfFloat length="256">
             <float>-134</float>
             <float>-142</float>
             <float>-140</float>
           </ArrayOfFloat>
          </{\rm Min}>
          <Max>
           <ArrayOfFloat length="256">
             <float>-70</float>
             <float>-71</float>
             <float>-69</float>
            </ArrayOfFloat>
          </Max>
        </PowerVsTime>
        <Spectrum>
          <Min>
           <ArrayOfFloat length="256">
             <float>-133</float>
             <float>-111</float>
```

I/Q Data Binary File

```
<float>-111</float>
          </ArrayOfFloat>
       </Min>
        <Max>
          <ArrayOfFloat length="256">
           <float>-67</float>
           <float>-69</float>
           <float>-70</float>
           <float>-69</float>
          </ArrayOfFloat>
       </Max>
      </Spectrum>
       <Histogram width="64" height="64">0123456789...0/Histogram>
      </IQ>
   </Channel>
 </ArrayOfChannel>
</PreviewData>
```

# C.2 I/Q Data Binary File

The I/Q data is saved in binary format according to the format and data type specified in the XML file (see Format element and DataType element). To allow reading and writing of streamed I/Q data, all data is interleaved, i.e. complex values are interleaved pairs of I and Q values and multi-channel signals contain interleaved (complex) samples for channel 0, channel 1, channel 2 etc. If the NumberOfChannels element is not defined, one channel is presumed.

### Example: Element order for real data (1 channel)

### Example: Element order for complex cartesian data (1 channel)

```
I[0], Q[0], // Real and imaginary part of complex sample 0 I[1], Q[1], // Real and imaginary part of complex sample 1 I[2], Q[2], // Real and imaginary part of complex sample 2
```

# Example: Element order for complex polar data (1 channel)

I/Q Data Binary File

### Example: Element order for complex cartesian data (3 channels)

Complex data: I[channel no][time index], Q[channel no][time index]

```
I[0][0], Q[0][0],
                           // Channel 0, Complex sample 0
                           // Channel 1, Complex sample 0
I[1][0], Q[1][0],
I[2][0], Q[2][0],
                           // Channel 2, Complex sample 0
I[0][1], Q[0][1],
                          // Channel 0, Complex sample 1
I[1][1], Q[1][1],
                          // Channel 1, Complex sample 1
I[2][1], Q[2][1],
                           // Channel 2, Complex sample 1
I[0][2], Q[0][2],
                          // Channel 0, Complex sample 2
                          // Channel 1, Complex sample 2
I[1][2], Q[1][2],
I[2][2], Q[2][2],
                           // Channel 2, Complex sample 2
```

# Example: Element order for complex cartesian data (1 channel)

This example demonstrates how to store complex cartesian data in float32 format using MATLAB<sup>®</sup>.

```
% Save vector of complex cartesian I/Q data, i.e. iqiqiq...
N = 100
iq = randn(1,N)+1j*randn(1,N)
fid = fopen('xyz.complex.float32','w');
for k=1:length(iq)
   fwrite(fid,single(real(iq(k))),'float32');
   fwrite(fid,single(imag(iq(k))),'float32');
end
fclose(fid)
```

# **List of Commands**

[SENSe:][WINDow <n>:]DETector<t>[:FUNCtion]</t></n>	162
[SENSe:][WINDow <n>:]DETector<t>[:FUNCtion]:AUTO</t></n>	162
[SENSe:]ADJust:ALL	142
[SENSe:]ADJust:CONFigure:DURation	142
[SENSe:]ADJust:CONFigure:DURation:MODE	143
[SENSe:]ADJust:CONFigure:HYSTeresis:LOWer	143
[SENSe:]ADJust:CONFigure:HYSTeresis:UPPer	144
[SENSe:]ADJust:CONFigure:TRIGger	144
[SENSe:]ADJust:FREQuency	144
[SENSe:]ADJust:LEVel	144
[SENSe:]AVERage <n>:COUNt</n>	163
[SENSe:]AVERage <n>:TYPE</n>	161
[SENSe:]AVERage <n>[:STATe<t>]</t></n>	163
[SENSe:]FREQuency:CENTer	128
[SENSe:]FREQuency:CENTer:STEP	128
[SENSe:]FREQuency:CENTer:STEP:AUTO	128
[SENSe:]FREQuency:OFFSet	129
[SENSe:]IQ:BANDwidth:MODE	136
[SENSe:]IQ:BANDwidth:RESolution	137
[SENSe:]IQ:BWIDth:MODE	136
[SENSe:]IQ:BWIDth:RESolution	137
[SENSe:]IQ:FFT:ALGorithm	137
[SENSe:]IQ:FFT:LENGth	138
[SENSe:]IQ:FFT:WINDow:LENGth	138
[SENSe:]IQ:FFT:WINDow:OVERlap	138
[SENSe:]IQ:FFT:WINDow:TYPE	138
[SENSe:]PMETer:DCYCle:VALue	117
[SENSe:]PMETer:DCYCle[:STATe]	116
[SENSe:]PMETer:FREQuency	117
[SENSe:]PMETer:FREQuency:LINK	117
[SENSe:]PMETer:MTIMe	118
[SENSe:]PMETer:MTIMe:AVERage:COUNt	118
[SENSe:]PMETer:MTIMe:AVERage[:STATe]	119
[SENSe:]PMETer:ROFFset[:STATe]	119
[SENSe:]PMETer:SOFFset	119
[SENSe:]PMETer:UPDate[:STATe]	120
[SENSe:]PMETer[:STATe]	120
[SENSe:]SWAPiq	139
[SENSe:]SWEep:COUNt	156
[SENSe:]SWEep:COUNt:CURRent?	156
[SENSe:]SWEep:TIME	157
[SENSe:]SWEep[:WINDow <n>]:POINts</n>	156
ABORt	153
CALCulate <n>:DELTamarker<m>:AOFF</m></n>	
CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer:MODE</m></n>	201
CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer:RESult?</m></n>	202
CAL Culates no DEL Tamarkers mo ELINCtion : RPOWer: SPAN	202

CALCulate <n>:DELTamarker<m>:FUNCtion:BPOWer[:STATe]</m></n>	202
CALCulate <n>:DELTamarker<m>:LINK</m></n>	
CALCulate <n>:DELTamarker<m>:MAXimum:LEFT</m></n>	196
CALCulate <n>:DELTamarker<m>:MAXimum:NEXT</m></n>	197
CALCulate <n>:DELTamarker<m>:MAXimum:RIGHt</m></n>	197
CALCulate <n>:DELTamarker<m>:MAXimum[:PEAK]</m></n>	197
CALCulate <n>:DELTamarker<m>:MINimum:LEFT</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum:NEXT</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum:RIGHt</m></n>	198
CALCulate <n>:DELTamarker<m>:MINimum[:PEAK]</m></n>	198
CALCulate <n>:DELTamarker<m>:MODE</m></n>	173
CALCulate <n>:DELTamarker<m>:MREFerence</m></n>	174
CALCulate <n>:DELTamarker<m>:SGRam:FRAMe</m></n>	189
CALCulate <n>:DELTamarker<m>:SGRam:SARea</m></n>	189
CALCulate <n>:DELTamarker<m>:SGRam:XY:MAXimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SGRam:XY:MINimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:ABOVe</m></n>	190
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:BELow</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum:NEXT</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MAXimum[:PEAK]</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:ABOVe</m></n>	191
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:BELow</m></n>	192
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum:NEXT</m></n>	192
CALCulate <n>:DELTamarker<m>:SGRam:Y:MINimum[:PEAK]</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:FRAMe</m></n>	189
CALCulate <n>:DELTamarker<m>:SPECtrogram:SARea</m></n>	189
CALCulate <n>:DELTamarker<m>:SPECtrogram:XY:MAXimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SPECtrogram:XY:MINimum[:PEAK]</m></n>	190
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:ABOVe</m></n>	190
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:BELow</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum:NEXT</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MAXimum[:PEAK]</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:ABOVe</m></n>	191
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:BELow</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum:NEXT</m></n>	192
CALCulate <n>:DELTamarker<m>:SPECtrogram:Y:MINimum[:PEAK]</m></n>	192
CALCulate <n>:DELTamarker<m>:TRACe</m></n>	175
CALCulate <n>:DELTamarker<m>:X</m></n>	175
CALCulate <n>:DELTamarker<m>:X:RELative?</m></n>	216
CALCulate <n>:DELTamarker<m>:Y</m></n>	216
CALCulate <n>:DELTamarker<m>[:STATe]</m></n>	174
CALCulate <n>:DELTamarker<ms>:LINK:TO:MARKer<md></md></ms></n>	173
CALCulate <n>:MARKer<m>:AOFF</m></n>	175
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:AOFF</m></n>	199
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:MODE</m></n>	199
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:RESult?</m></n>	200
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer:SPAN</m></n>	200
CALCulate <n>:MARKer<m>:FUNCtion:BPOWer[:STATe]</m></n>	200
CALCulate <n>:MARKer<m>:FUNCtion:CENTer</m></n>	127
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:ANNotation:LABel[:STATe]</m></n>	203

CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:COUNt?</m></n>	203
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:LIST:SIZE</m></n>	204
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:SORT</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:STATe</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:X?</m></n>	205
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks:Y?</m></n>	206
CALCulate <n>:MARKer<m>:FUNCtion:FPEaks[:IMMediate]</m></n>	204
CALCulate <n>:MARKer<m>:FUNCtion:REFerence</m></n>	123
CALCulate <n>:MARKer<m>:LOEXclude</m></n>	179
CALCulate <n>:MARKer<m>:MAXimum:AUTO</m></n>	193
CALCulate <n>:MARKer<m>:MAXimum:LEFT</m></n>	193
CALCulate <n>:MARKer<m>:MAXimum:NEXT</m></n>	194
CALCulate <n>:MARKer<m>:MAXimum:RIGHt</m></n>	194
CALCulate <n>:MARKer<m>:MAXimum[:PEAK]</m></n>	194
CALCulate <n>:MARKer<m>:MINimum:AUTO</m></n>	195
CALCulate <n>:MARKer<m>:MINimum:LEFT</m></n>	195
CALCulate <n>:MARKer<m>:MINimum:NEXT</m></n>	195
CALCulate <n>:MARKer<m>:MINimum:RIGHt</m></n>	196
CALCulate <n>:MARKer<m>:MINimum[:PEAK]</m></n>	196
CALCulate <n>:MARKer<m>:PEXCursion</m></n>	179
CALCulate <n>:MARKer<m>:SEARch</m></n>	180
CALCulate <n>:MARKer<m>:SGRam:FRAMe</m></n>	184
CALCulate <n>:MARKer<m>:SGRam:SARea</m></n>	185
CALCulate <n>:MARKer<m>:SGRam:XY:MAXimum[:PEAK]</m></n>	185
CALCulate <n>:MARKer<m>:SGRam:XY:MINimum[:PEAK]</m></n>	185
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:ABOVe</m></n>	186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:BELow</m></n>	186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum:NEXT</m></n>	186
CALCulate <n>:MARKer<m>:SGRam:Y:MAXimum[:PEAK]</m></n>	186
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:ABOVe</m></n>	187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:BELow</m></n>	187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum:NEXT</m></n>	187
CALCulate <n>:MARKer<m>:SGRam:Y:MINimum[:PEAK]</m></n>	188
CALCulate <n>:MARKer<m>:SPECtrogram:FRAMe</m></n>	184
CALCulate <n>:MARKer<m>:SPECtrogram:SARea</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:XY:MAXimum[:PEAK]</m></n>	185
CALCulate <n>:MARKer<m>:SPECtrogram:XY:MINimum[:PEAK]</m></n>	185
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:ABOVe</m></n>	186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:BELow</m></n>	186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum:NEXT</m></n>	186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MAXimum[:PEAK]</m></n>	186
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:ABOVe</m></n>	187
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:BELow</m></n>	187
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum:NEXT</m></n>	
CALCulate <n>:MARKer<m>:SPECtrogram:Y:MINimum[:PEAK]</m></n>	188
CALCulate <n>:MARKer<m>:TRACe</m></n>	
CALCulate <n>:MARKer<m>:X</m></n>	177
CALCulate <n>:MARKer<m>:X:SLIMits:LEFT</m></n>	181
CALCulate <n>:MARKer<m>:X:SLIMits:RIGHt</m></n>	182
CAL Culate < n >: MAPKer < m >: Y:SLIMite: 700M[:STATe]	182

CALCulate <n>:MARKer<m>:X:SLIMits[:STATe]</m></n>	181
CALCulate <n>:MARKer<m>:X:SSIZe</m></n>	178
CALCulate <n>:MARKer<m>:Y</m></n>	216
CALCulate <n>:MARKer<m>[:STATe]</m></n>	176
CALCulate <n>:MARKer<ms>:LINK:TO:MARKer<md></md></ms></n>	176
CALCulate <n>:PMETer:RELative:STATe</n>	
CALCulate <n>:PMETer:RELative[:MAGNitude]</n>	
CALCulate <n>:PMETer:RELative[:MAGNitude]:AUTO ONCE</n>	115
CALCulate <n>:SGRam:CLEar[:IMMediate]</n>	
CALCulate <n>:SGRam:CONTinuous</n>	165
CALCulate <n>:SGRam:FRAMe:COUNt</n>	165
CALCulate <n>:SGRam:FRAMe:SELect</n>	166
CALCulate <n>:SGRam:HDEPth</n>	166
CALCulate <n>:SGRam:LAYout</n>	
CALCulate <n>:SGRam:THReedim[:STATe]</n>	
CALCulate <n>:SGRam:TRACe</n>	
CALCulate <n>:SGRam:TSTamp:DATA?</n>	
CALCulate <n>:SGRam:TSTamp[:STATe]</n>	
CALCulate <n>:SGRam[:STATe]</n>	
CALCulate <n>:SPECtrogram:CLEar[:IMMediate]</n>	
CALCulate <n>:SPECtrogram:CONTinuous</n>	
CALCulate <n>:SPECtrogram:FRAMe:COUNt</n>	
CALCulate <n>:SPECtrogram:FRAMe:SELect</n>	
CALCulate <n>:SPECtrogram:HDEPth</n>	
CALCulate <n>:SPECtrogram:LAYout</n>	
CALCulate <n>:SPECtrogram:THReedim[:STATe]</n>	
CALCulate <n>:SPECtrogram:TRACe</n>	
CALCulate <n>:SPECtrogram:TSTamp:DATA?</n>	
CALCulate <n>:SPECtrogram:TSTamp[:STATe]</n>	
CALCulate <n>:SPECtrogram[:STATe]</n>	
CALCulate <n>:THReshold</n>	
CALCulate <n>:THReshold:STATe</n>	
CALCulate <n>:UNIT:POWer</n>	
CALibration:PMETer:ZERO:AUTO ONCE	
DIAGnostic:SERVice:NSOurce	
DISPlay[:WINDow <n>]:MINFo[:STATe]</n>	
DISPlay[:WINDow <n>]:MTABle</n>	
DISPlay[:WINDow <n>]:SGRam:COLor:DEFault</n>	
DISPlay[:WINDow <n>]:SGRam:COLor:LOWer</n>	
DISPlay[:WINDow <n>]:SGRam:COLor:SHAPe</n>	
DISPlay[:WINDow <n>]:SGRam:COLor:UPPer</n>	
DISPlay[:WINDow <n>]:SIZE</n>	
DISPlay[:WINDow <n>]:SPECtrogram:COLor:DEFault</n>	
DISPlay[:WINDow <n>]:SPECtrogram:COLor:LOWer</n>	
DISPlay[:WINDow <n>]:SPECtrogram:COLor:SHAPe</n>	
DISPlay[:WINDow <n>]:SPECtrogram:COLor:UPPer</n>	
DISPlay[:WINDow <n>]:SPECtrogram:COLor[:STYLe]</n>	
DISPlay[:WINDow <n>]:TRACe<t>:MODE</t></n>	
DISPlay[:WINDow <n>]:TRACe<t>:WIODL</t></n>	

DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:AUTO ONCE</t></n>	126
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RLEVel</t></n>	123
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RLEVel:OFFSet</t></n>	124
DISPlay[:WINDow <n>]:TRACe<t>:Y[:SCALe]:RPOSition</t></n>	
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:MODE:HCONtinuous</t></w></n>	159
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:SMOothing:APERture</t></w></n>	160
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:SMOothing[:STATe]</t></w></n>	161
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:Y:SPACing</t></w></n>	127
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>:Y[:SCALe]:MODE</t></w></n>	126
DISPlay[:WINDow <n>][:SUBWindow<w>]:TRACe<t>[:STATe]</t></w></n>	
FETCh:PMETer?	
FORMat:DEXPort:DSEParator	214
FORMat:DEXPort:FORMat	
FORMat:DEXPort:HEADer	
FORMat:DEXPort:TRACes	
FORMat[:DATA]	
INITiate:SEQuencer:ABORt	
INITiate:SEQuencer:IMMediate	
INITiate:SEQuencer:MODE	
INITiate <n>:CONMeas</n>	
INITiate <n>:CONTinuous</n>	
INITiate <n>[:IMMediate]</n>	
INPut <ip>:ATTenuation</ip>	
INPut <ip>:ATTenuation:AUTO</ip>	
INPut <ip>:ATTenuation:PROTection:RESet</ip>	
INPut <ip>:EATT:AUTO</ip>	
INPut <ip>:FILE:PATH</ip>	
INPut <ip>:IMPedance</ip>	
INPut <ip>:SELect</ip>	
INSTrument:CREate:DUPLicate	
INSTrument:CREate:REPLace	
INSTrument:CREate[:NEW]	
INSTrument:DELete	
INSTrument:LIST?	
INSTrument:REName	
INSTrument[:SELect]	
LAYout:ADD[:WINDow]?	
LAYout:CATalog[:WINDow]?	
LAYout:IDENtify[:WINDow]?	
LAYout:MOVE[:WINDow]	
LAYout:REMove[:WINDow]	
LAYout:REPLace[:WINDow]	
LAYout:SPLitter	
LAYout:WINDow <n>:ADD?</n>	
LAYout:WINDow <n>:IDENtify?</n>	
LAYout:WINDow <n>:REMove</n>	
LAYout:WINDow <n>:REPLace</n>	
MMEMory:STORe <n>:IQ:COMMent</n>	
MMEMory:STORe <n>:IQ:FORMat</n>	
MMEMory:STORe <n>:IQ:STATe</n>	218

MMEMory:STORe <n>:LIST</n>	217
MMEMory:STORe <n>:PEAK</n>	206
MMEMory:STORe <n>:TRACe</n>	215
READ:PMETer?	116
SYSTem:COMMunicate:RDEVice:PMETer:CONFigure:AUTO[:STATe]	113
SYSTem:COMMunicate:RDEVice:PMETer:COUNt?	113
SYSTem:COMMunicate:RDEVice:PMETer:DEFine	113
SYSTem:PRESet:CHANnel[:EXEC]	109
SYSTem:SEQuencer	157
SYSTem:SPEaker:VOLume	122
SYSTem:SPEaker[:STATe]	121
TRACe:IQ:AVERage:COUNt	163
TRACe:IQ:AVERage[:STATe]	163
TRACe:IQ:BWIDth	139
TRACe:IQ:DATA	207
TRACe:IQ:DATA:FORMat	208
TRACe:IQ:DATA:MEMory?	208
TRACe:IQ:EGATe:GAP	134
TRACe:IQ:EGATe:LENGth	135
TRACe:IQ:EGATe:NOF	135
TRACe:IQ:EGATe:TYPE	135
TRACe:IQ:EGATe[:STATe]	134
TRACe:IQ:EVAL	109
TRACe:IQ:RLENgth	139
TRACe:IQ:SET	140
TRACe:IQ:SRATe	141
TRACe:IQ:TPISample?	141
TRACe:IQ[:STATe]	110
TRACe <n>:COPY</n>	163
TRACe <n>[:DATA]:MEMory?</n>	213
TRACe <n>[:DATA]:X?</n>	
TRACe <n>[:DATA]?</n>	
TRIGger[:SEQuence]:DTIMe	129
TRIGger[:SEQuence]:HOLDoff[:TIME]	130
TRIGger[:SEQuence]:IFPower:HOLDoff	
TRIGger[:SEQuence]:IFPower:HYSTeresis	130
TRIGger[:SEQuence]:LEVel:IFPower	131
TRIGger[:SEQuence]:LEVel:IQPower	131
TRIGger[:SEQuence]:LEVel[:EXTernal <port>]</port>	131
TRIGger[:SEQuence]:SLOPe	132
TRIGger[:SEQuence]:SOURce	132
TRIGger[:SEQuence]:TIME:RINTerval	133
UNIT <n>:PMETer:POWer</n>	
UNIT <n>:PMETer:POWer:RATio</n>	121
UNIT <n>:POWer</n>	123

# Index

Symbols		Relationship to sample rateSettings	
*OPC	129	Basic Measurement Examples	
•		see User Manual	5
A		Branch for peak search	
Aborting		I/Q Analyzer	
Aborting Sweep	56 57 67 68	Brochures	t
Activating	. 50, 57, 67, 66	С	
I/Q Analyzer (remote)	105	· ·	
All Functions Off		Calibration certificate	-
Amplitude		Capture time	
Configuration	42	see also Measurement time	157
Scaling		Capturing	
Settings		I/Q data, see Data acquisition	152
Analysis		Center = Mkr Freq	
Bandwidth	52	Center frequency	
Bandwidth, definition		Automatic configuration	
I/Q data (remote)		Displayed	
Settings		Setting to marker	
Application cards		Softkey	
Application notes		Step size	
Applications	•	Channel Setup	
I/Q Analyzer (remote)	105	Creating (remote)	107 109
Att (hardware setting)		Deleting (remote)	
Attenuation		Duplicating (remote)	
Auto	44	Querying (remote)	
Manual		Renaming (remote)	
Protective (remote)		Replacing (remote)	
Audio demodulation		Selecting (remote)	
Volume (remote control)	121, 122	Closing	
Auto adjustment	,	Channel Setups (remote)	107
Triggered measurement	144	Windows (remote)	
Auto all		Color curve	
Auto frequency		Shape	69
Auto level		Color mapping	
Hysteresis	60	Color curve	69
Reference level		Color range	
Softkey		Color scheme	
Auto settings	.,	Softkey	
Meastime Auto	59	Spectrograms	
Meastime Manual		Color scheme	,
Average count		Spectrogram	70
Power sensor		Configuring	
Average mode		Data acquisition (remote)	136
Traces	63	I/Q Analyzer (remote)	
Averaging		Markers (remote)	
Traces (remote control)	161	Continue single sweep	
		Softkey	57
В		Continuous sweep	-
		Softkey	56. 67
Band power measurement		Conventions	
Activating/Deactivating	91	SCPI commands	101
Deactivating	92	Copying	
Power mode		Channel Setup (remote)	106
Span	91	Traces	
Band power measurement (remote control)	199		
Bandwidth		D	
Analysis	52		
Extension options		Data acquisition	
I/Q Analyzer		Configuring (remote)	136
Maximum usable	18	I/Q Analyzer	17

I/Q data (remote) 152	Format	
Settings51	Data	222
Data format	Data (remote)	214, 215
ASCII 222	I/Q data files	223
Binary222	Frames	
Remote 214, 215	Spectrogram marker	75
Data sheets6	Free Run	
Decimal separator	Trigger	49
Trace export	Frequency	
Decimation	Configuration	46
Data processing17	Configuration (remote)	
Delta markers	Coupling (power sensor)	
Defining75	Offset	
Demodulation	Power sensor	
Display57	1 OWOI OCITOOI	
Detectors	G	
Remote control	•	
Trace	Gating	
	I/Q data	133
Diagram area	Source	
Hardware settings	Getting started	
Diagram footer information	Cotting started	
Display configuration	Н	
Softkey	••	
Drop-out time	Hardware settings	
Trigger50	Displayed	14
Duplicating	History	
Channel Setup (remote)	Spectrograms	67
Duty cycle	History Depth	
Power sensor39	Softkey	67
-	Hold	
E	Trace setting	61
Educate	Hysteresis	
Edge gate	Lower (Auto level)	60
Triggering133	Trigger	
Equalizer	Upper (Auto level)	
Data processing	Opper (Auto lever)	
Errors	1	
IF OVLD43	'	
Evaluation methods	I/Q Analyzer	
Remote	Data acquisition	17
Exclude LO80	Evaluation	
Remote 179	I/Q Vector evaluation	
Exporting	Magnitude evaluation	
Data 33	Maximum bandwidth	
I/Q data26, 28, 33, 98, 225, 229		
I/Q data (remote) 217	Modes	
Measurement settings71	Programming example	
Peak list95	Real/Imag (I/Q) evaluation	
Softkey31	Results	
Traces	Sample rate	
External trigger	Spectrum evaluation	13
Level (remote)	I/Q data	
(	Analog, processing	
F	Export file binary data description	
	Export file parameter description	
FFT	Exporting	28, 33
Fundamentals21	Exporting (remote)	217
Measurement speed	Exporting/Importing	98
Window functions	File format description	
Files	Importing	
Format, I/Q data225	Importing (remote)	
I/Q data binary XML	Importing/Exporting	
I/Q data input	Input files	
I/Q parameter XML	Maximum bandwidth	
Filters	Sample rate	
	Trigger point in sample (TPIS)	
Bandwidth, I/Q data	mggor point in sample (11 10)	171
Equalizer17		

I/Q gating		Marker peak list	
Edge triggered	133	see Peak list	94
Level triggered	133	Marker search area	
I/Q measurements		Remote control	179
Methods	152	Marker table	
I/Q Power		Evaluation method	15
Trigger	49	Marker to Trace	76
Trigger level (remote)	131	Markers	
I/Q Vector		Assigned trace	76
Evaluation method	14	Band power (remote control)	199
I/Q Analyzer	14	Basic settings	
Markers	73, 171	Configuration	
Y-axis scaling	46	Configuration (remote control)	172
IF Power		Deactivating	
Trigger	49	Delta markers	
Trigger level (remote)		Fixed reference (remote control)	
Impedance		I/Q vector	
Setting	34 44	Linking	,
Importing		Minimum	
I/Q data	26 28 98 226	Minimum (remote control)	
I/Q data (remote)		Next minimum	·
Softkey		Next minimum (remote control)	
	31		
Input	444	Next peak	
Overload (remote)		Next peak (remote control)	
RF		Peak	
Signal, parameters	33	Peak (remote control)	
Input sample rate (ISR)		Peak list (remote control)	
Definition	18	Position	75
Input sources		Positioning	84
I/Q data files	26	Positioning (remote control)	172
Installation	9	Retrieving results (remote)	215
Instrument security procedures	6	Search (remote control)	179
IQBlock		Setting center frequency	
I/Q data files	223	Setting reference level	
IQPair		Spectrograms (remote control)	
I/Q data files	223	State	
i/ & data iiico	220	Step size	
K		Step size (remote control)	
TX.			
Keys		Table Table (evaluation method)	
LINES (not used)	28	,	
MKR		Table (remote control)	
MKR ->		Type	
RUN CONT	-, -	X-value	/5
	,	Maximizing	
RUN SINGLE	50, 57, 66	Windows (remote)	
L		Meas Time (hardware setting)	11
L		Measurement time	
Lovel		Auto settings	
Level	133	Displayed	11
Triggered gate	133	I/Q data	53
Limit lines	00 04 00	Power sensor	38
OBW		Remote	157
Peak search	80, 84, 88	Minimum	85
Linking		Marker positioning	85
Markers		Next	
Lower Level Hysteresis	60	MKR	
		Key	73
M		MKR ->	70
		Kev	70 01
Magnitude		- 7	10, 84
Evaluation method	13	Modulation	400
I/Q Analyzer	13	Inverted (I/Q, remote)	
Marker		Inverted (I/Q)	53
Search area (softkey)	83 87	Multiple	
Search type (softkey)		Channel Setups	10
Marker functions			
Deactivating	95		

N		Peaks	
		Marker positioning	
Next Minimum		Next	85
Marker positioning	85	Performance	
Next Mode X		FFT parameters	24
Softkey	82, 86	Performing	
Next Mode Y		I/Q Analyzer measurement	96
Softkey	·	Power mode	
Next Peak	85	Band power measurement	91
Marker positioning	85	Power sensors	
Noise		Activating/Deactivating	
Source	41	Applications	
Number of Readings		Average count	
Power sensor	39	Configuration (softkey)	
		Continuous Value Update	37
0		Duty cycle	
0.5147		Frequency	
OBW	00.04.00	Frequency Coupling	
Limits	80, 84, 88	Measurement time	38
Offset		Number of readings	39
Displayed		R&S Power Viewer	35
Frequency		Reference level	
Reference level	43	Reference level offset	38
Options	4.0	Results	36
Bandwidth extension	19	Selecting	37
Output		Setting up	39
Configuration (remote)		Settings	36
Noise source		Unit/Scale	38
Parameters		Using	39
Sample rate, definition	18	Zeroing	37, 40
Overload		Presetting	
RF input (remote)	111	Channels	30
Overview		Pretrigger	50
Configuration	28	Programming examples	
5		I/Q Analyzer	218, 220
P		Protection	
Davasastava		RF input (remote)	111
Parameters	22		
Input signal		Q	
Output			
Peak excursion		Quick Config	
Peak list Configuring		Traces	64
		В	
Displaying Evaluation method		R	
		D. C. Davier Viewer Dive	25
Exporting		R&S Power Viewer Plus	
Marker numbers		Range	
Maximum number of peaks  Peak excursion		RBW (hardware setting)	11
Remote control		Real/Imag (I/Q)	45
Sort mode		Evaluation method	
State		I/Q Analyzer	
Peak search	94	Rec Length (hardware setting)	11
Area (spectrograms)	02 07	Record length	10
		Definition I/O data	
Automatic			
Deactivating limits		Relationship to sample rate	
Excursion		Ref Level (hardware setting)	
Limits		Ref LvI = Mkr LvI	
List		Reference level	
Mode (anastrograms)	-, - ,	Auto level	-,
Mode (spectrograms)		Offset (Payer sansar)	
Retrieving results (remote)		Offset (Power sensor)	
Threshold		Position	
Type (spectrograms)		Power sensor	
Zoom limits	81, 84, 88	Setting to marker	
		Unit	
		Value	43

Reference marker	75	Search settings	
Release notes	6	I/Q Analyzer	81
Remote commands		Searching	
Basics on syntax	100	Configuration	78
Boolean values		Configuration (softkey)	
Capitalization		Security procedures	
Character data		Select Frame	
Data blocks		Softkey	6-
Numeric values		Select Marker	
Optional keywords		Sequencer	
Parameters	103	Activating (remote)	155
Strings	105	Sequences	
Suffixes	102	Aborting (remote)	155
Remote control		Mode (remote)	
Modes	106	Service manual	
Repetition interval		Signal capturing	
Resampler		Duration (remote)	157
Data processing	17	` ,	101
	17	Signal processing	47
Resetting	***	Diagram	18
RF input protection	111	Single sweep	
Restoring		Softkey	56, 68
Channel settings	30	Slope	
Result displays		Trigger	51, 132
I/Q Vector	14	Softkeys	
Magnitude		All Functions Off	95
Marker table		Amplitude Config	
Peak list		Auto Level	
			· ·
Real/Imag (I/Q)		Center	
Spectrum	13	Center = Mkr Freq	
Results		Clear Spectrogram	
Analyzing	61	Color Mapping	
Data format (remote)	214, 215	Continue Single Sweep	57
Exporting	71	Continuous Sweep	56, 67
I/Q Analyzer (remote)	206	Display Config	
Retrieving (remote)		Export	
RF attenuation		Export config	
Auto	44	External	
Manual	44	Free Run	
RF input	***	History Depth	
Overload protection (remote)		I/Q Export	
Remote	111	Import	
RUN CONT		Marker Config	73, 77
Key	56, 67	Marker Search Area	83, 87
RUN SINGLE		Marker Search Type	83. 87
Key	56 57 68	Next Mode X	
1.07		Next Mode Y	
S		Next Peak	
•			
Safety instructions	6	Power Sensor Config	
	0	Ref Level	
Sample rate	40	Search Config	
Definition		Select Frame	67
Displayed	11	Select Marker	76
I/Q Analyzer	18	Single Sweep	56, 68
I/Q data	52	Time	
Maximum	18	Timestamp	
Relationship to bandwidth		•	
Remote		Trace 1/2/3/4	
		Trace Config	
Scaling	4.4	Trigger Config	48
Configuration		Sort mode	
Y-axis		Peak list	94
Y-axis (remote control)	127	Span	
Search limits		Band power measurement	91
Deactivating	81, 84, 88	Speaker	
Search Limits		Remote control	101 100
Activating	80 84 88	Specifics for	121, 122
Search Mode			0/
Spectrogram markers	01 06	Configuration	3۱
ODECTIONIATI HIGINETS	0 1. 00		

Spectrograms		Mode	62
3-dimensional	66. 67	Mode (remote)	
Activating/Deactivating		Retrieving (remote)	
Clearing		Settings (remote control)	
Color curve		Settings, predefined	
Color mapping		Trigger	
Color mapping (remote control)		Configuration (softkey)	48
Color scheme		Drop-out time	
Configuring (remote control)		External (remote)	
Display depth (3-D)		Holdoff	
Frames (remote control)		Hysteresis	
History depth		Offset	
Markers (remote control)	183	Remote control	
Selecting frames	67	Slope	
Settings	65	Trigger level	50
Size	66	External trigger (remote)	13 <sup>2</sup>
Timestamps	67	I/Q Power (remote)	
Spectrum		IF Power (remote)	
I/Q Analyzer	13	Trigger source	
I/Q Evaluation method		External	
SRate (hardware setting)		Free Run	
Status registers		I/Q Power	
	444		
STAT:QUES:POW	111	IF Power	
Step size		Time	48
Markers		Troubleshooting	
Markers (remote control)	177	Input overload	111
Subwindows			
Spectrogram	66	U	
Suffixes			
Common	105	Units	
Remote commands	102	Power sensor	38
Swap I/Q	53	Reference level	43
Remote		Upper Level Hysteresis	60
Sweep		Usable I/Q bandwidth	
Aborting	56 57 67 68	Definition	18
Performing (remote)		User sample rate	
		Definition	18
Points (I/Q Analyzer)		Delimition	
Settings		V	
Time (remote)		•	
Sweep Count	56	Volume	
-		Remote control	121 123
Т		remote control	121, 122
Thereshald		W	
Threshold		**	
Peak search	81, 84, 88	White papers	e
Time frames		Window functions	
Selecting	67		24
Time trigger		Characteristics	
Repetition interval	50	FFT	
Softkey	49	Window title bar information	12
Timestamps		Windows	
Softkey (Spectrogram)	67	Adding (remote)	
Spectrograms		Closing (remote)	15′
TPIS		Configuring	30
	1.1.1	Layout (remote)	
I/Q data		Maximizing (remote)	
Traces		Querying (remote)	
Average mode		Replacing (remote)	
Averaging (remote control)		Splitting (remote)	
Configuration		Types (remote)	
Configuring (remote control)	158	1 ypes (16111016)	140
Copying	64	V	
Copying (remote control)	163	X	
Detector		Y value	
Detector (remote control)		X-value	
Export format		Marker	/5
Exporting			
Hold	63		

R&S®ZNL Index

٠,			
	٦	ø	,
	П	ı	

Y-axis Scaling Scaling (I/Q Vector)	46
z	
Zeroing Power sensor	37
Zoom limits Using for searches81, 84, 8	88