

Firmware Release Notes

AP-3064

Release Firmware Version 1.0.13 - Recommended Update

Note: It is NOT recommended to update the firmware wirelessly.

Enhancements:

- 1. Help menu clarifications
- 2. Quick Setup IP validation improvements
- 3. Captive Portal updates
- 4. Minor UI fixes and improvements

Known Limitations:

 Use of SSID Scheduling may cause wireless client connection issues within 24 hours on the scheduled SSID

Access Point Upgrade Instructions

- 1. In the admin interface, go to Advanced > Update Firmware.
- Select the firmware location. Normally, Auto is preferred, as it compares the device's current firmware with the latest version available in the specified repository. If necessary, download the firmware to your computer: <u>Firmware Version 1.0.13</u>.
- 3. If you selected Auto, select the Release firmware repository unless you have been directed to do otherwise by Luxul staff. Then select Check.
- 4. If the Server Firmware Version field shows a later version than the Current Firmware Version field, select Install. The firmware updates and the access point reboots.

The access point does not provide connectivity during the update. Devices automatically reconnect after the access point reboots.

Note: As part of Luxul's ongoing commitment to product security, firmware updates will support a cryptoraphic signature. Implementing signed firmware will enable the product to verify that the firmware update came from Luxul.

Downloads

Current Version:

Firmware Version 1.0.13

For questions regarding firmware updates: contact support