

FIRMWARE RELEASE NOTES

AP-3064

RELEASE FIRMWARE VERSION 1.1.6 RECOMMENDED UPDATE

ENHANCEMENTS

- Added Wi-Fi Extension functionality
 - Allows for up to 2 AP-3064s to be connected to the root node via the 2.4GHz or 5GHz radio
- Added capability for additional users, User and Audit
 - **User:** allows for access to Status, Logs, and Change SSID Password for SSID1
 - **Audit:** allows for access to Status and Logs
- Minor UI fixes and improvements

KNOWN LIMITATIONS

- None

ACCESS POINT UPDATE INSTRUCTIONS

- Login to your access point using the IP address of the access point and browse to Advanced >> Update Firmware.
- Ensure "Update Firmware from" is set to "Auto" and "Firmware Repository" is set to "Release".
- Click the "Check" button.
- If a new firmware is discovered and listed under "Server Firmware Version", click the "Update" button. When prompted to proceed, click "OK".
- After a 90 second download and install process, log back into your access point.

Alternatively, you may download the latest firmware release for your access point from the bottom of the product page on LegrandAV.com and choose "a file on your PC" under the "Firmware Location" section of the Update Firmware page.

Note: As part of Luxul's ongoing commitment to product security, firmware updates will support a cryptographic signature. Implementing signed firmware will enable the product to verify that the firmware update came from Luxul.

DOWNLOAD FIRMWARE

VISIT PRODUCT PAGE

USA 866.977.3901 av.support@legrand.com
CANADA 877.345.4329 av.support@legrand.com

CHIEF | CONNECTRAC | DA-LITE | LUXUL | MIDDLE ATLANTIC | ON-Q | SANUS | VADDIO | WIREMOLD