

 Reference No.
 481

 Date of
 10/06/2022

 Date of Issue:
 10/06/2022

Inspection Result



Vehicle Information

Brand / Model (Year)	VW Passat (2011)
Registration (KXX)	KCS
Mileage on Odometer	139,949 Km
Engine Type / Size	I4TSI / 1400 CC
Transmission / Type of WD	AT/ 2WD
Fuel	Petrol

Recommended Immediate Repairs

Suspension/Steering/Powerflow

- RHS Shocks making knocking noise
- Front lower arm bushings worn out, need replacement
- Rear stabilizer bushings, front links and shock mounts need replacement

Brake System

Brake discs warped, skimming required

General service recommended for new owner

Future Maintenance Requirements

Suspension/Steering/PowerFlow

- Turbo has minor lag
- Fan belt worn, replacement required
- Battery tester weak
- Oil pan sweating
- Steering noise while turning
- Vehicle has minor pull to the LHS, alignment required

Lighting System

- Headlights are foggy, buffing required
- Rear RHS brake light has minor crack

<u>Our rating method</u>: Vehicle scores reflect the condition of the car set against the following benchmarks

- Brand new vehicle

- New import, never driven in Kenya

- Kenyan market average

5.0 $\star \star \star \star \star$ 4.5 $\star \star \star \star \star$ 2.5 $\star \star \star$

Chege

Laban

There are no express or implied warranties or guarantees of any kind in connection to or with this vehicle inspection Result Certificate. The vehicle inspection is intended solely as an evaluation of the said motor vehicle's condition at the date and time of the inspection. Peach, its affiliated inspectors specifically disclaims any and all liability or any loss or damage arising out of or in connection with the operation of the said motor vehicle. The items indicated in the report were inspected at the time of inspection only. PLEASE NOTE that the cortexts of this Inspection Result Certificate at the time of inspection and with the motor vehicle does not remain in the custody or possession of Peach or Peach's efficient third (3rd) parties. Peach does not warrant for the condition of the motor vehicle after inspection is undertaken nor does it have any control over or custody in the motor vehicle or any of its constituent parts. The inspection is for informational purposes only and shall not be deemed to be a recommendation for or against purchase of the motor vehicle. Peach will not reimburse any expenses borne after purchase in relation to any repairs undertaken on the motor vehicle nor be responsible for any mechanical failure.

11/06/2022



Tire Condition (% shows remaining tire tread)

3.8 ****

FR: 60%	RR :70%	S1 : 10%
FL: 60%	RL :70%	S2 : N/A

All four tires – Chengshan Spare – Michelin

Accessories

Overall

Frame / Body		Chass	Chassis damage			
None						
Exterior Scratch Rust	/ Pa ⊠	int Dent Peeling	Origina IX	al Paint Crack Blistering	×	
Scratches, Dent and minor crack						
Interior Scratch Sunburn		Gap Stain		Crack Tear		
None						
Anti-theft device?						
Inspection conducted by:						