

INSTALLATION DATA SHEET

BRASS PEX FITTINGS

Applications:

Water. Pipe threads must be sealed using approved thread sealant.

Working Temperature: -65°F (-54°C) to 250°F (120°C)



BRASS PEX FITTINGS KITS

ASTM B 1807 & cNSF-pw us
FOR PEX WATER VALVES SEE PAGE 186



CONNECTING PEX TUBE TO BRASS INSERT FITTINGS:


1. Cut Pex pipe squarely. Check pipe I.D. and O.D. and remove any burrs.
2. Apply copper ring or PEX clamp on top of PEX pipe.
3. Insert fitting into the end of the pipe and pull clamp or ring over the fitting within 1/8 to 1/4 inch from the end of the tube. This process presses the fitting ribs into the pipe.
4. Crimp copper ring or PEX clamp using the required Fairview tool.
5. Check crimp using the Go-No-Go Gauge to determine if the crimp connection was properly made.
6. The GO opening should go freely across a crimped ring. The No-Go opening should not go across a crimped ring.



STEP 1



STEP 2



STEP 3



STEP 4



STEP 5



STEP 6