WO# 19327437
already in BGE Syste

Inspections: Damaged Pole Report

Service Request: 25-00466638 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: W. North Ave @ N. Howard St

Grid : 1010120 LLC: 7819

Descriptive Location and Comments:

Street: N. Howard St

Side of Street: N/S _____ E/S ✓ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: W. North Ave

Condition of Pole:		Pole Size :		Type of Pole:	
Deteriorated		11'6"		Aluminum	✓
Missing	✓	12'		Steel	
Damaged		25'		Galvanized Steel	
Arm/Fixture Missing		30'	✓	Fiberglass	
Other		40'		Bolton Hill	
		Other		Otterbein	
				Homeland	
				Wooden	
				Other	

Fixture Type:		Lamp Type:		Wattage:		Arm:		Arm Condition:	
Cobra Head	✓	HPS Vapor		100		6'	✓	Damaged	
PMA		Mercury Vapor		150		10'		Missing	
Otterbein		Metal Halide		175		15'			
Homeland		LED	✓	200		20'			
Bolton Hill		Other		250		Other			
Victorian Acorn				400	✓				
Other				1000					

Pedestal Base:		Base Condition:	Good	Bad:	Base Type:	
Yes		Bolts	✓		Metal	
No	✓	Wires	✓		Concrete	✓
		Conduit	✓			

Date: 1 / 2025 Inspector's Signature G. Crowder - 8512


Falls Rd
BYP
40
W North Ave
BYP
40
U.S. Rte 1
BYP
40
Falls Rd
Jones Falls
N Howard St
N Howard St
Howard St
Falls Rd
W Trenton St
W Trenton

Service Request Summary Report
25-00466638
Printed Date: Aug 8, 2025 - 10:52:46 AM

Type:	BGE-StLight Pole Installation	**SR #:**	25-00466638
Created By:	citizen Site Guest User	**Prority:**	Urgent
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	Phone	**Status Date:**	Aug 08, 2025 10:49:09 AM
SLA Detail:	45 Business Days	**Created Date:**	Jun 03, 2025 9:59:55 PM
		Overdue on:	Aug 07, 2025 3:37:30 PM
		Closed on:	
Location:	W NORTH AVE & N HOWARD ST, BC, 21201		
Location Details:			
Description:	Hi. In the middle of the bridge on North Ave (halfway between the 83 ramp before Howard St going eastbound) on the bridges public sidewalk is metal sticking upward and towards traffic also. This area of the sidewalk has heavy foot traffic & vehicle traffic due to construction near by.		

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		8/8/2025 10:49 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010120
Assign inspector	LLC / POLE #	7819
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Already In BGE System for	Gregory Crowder	8/8/2025 10:52 AM	Private