Inspections: Damaged Pole Report

Service Request: 26-01018509 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 501 Saint Paul Pl

Grid : 4010110 LLC: 6362

Descriptive Location and Comments:

Street: E. Franklin St

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ✓ S/O _____ W/O _____

Street or Landmark: Saint Paul Pl

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' ✓
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein ✓
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head _____
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn ✓
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 ✓
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:


6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts	✓	_____	Metal ✓
No ✓	Wires	✓	_____	Concrete _____
	Conduit	✓	_____	

Date: 11/5/2026 Inspector's Signature T. Blackmon



Otterbein

Acorn Fixture