


GENERAL NOTES

1. ALWAYS PROTECT THE WORKSURFACE DURING INSTALLATION.
2. ALWAYS LEVEL UNITS(S) AT FINAL LOCATION.

1 LEG ASSEMBLY




- LAY WORKSURFACE FACE DOWN (PROTECT THE FACE OF THE WORKSURFACE)
- SLIDE LEG ASSEMBLY BOLTS THROUGH RAILS UNDER WORKSURFACE
- ATTACH EACH BOLT WITH FLAT WASHER, LOCK WASHER, & NUT (DETAIL A)
- SCREW GLIDE INTO BOTTOM OF EACH LEG



DETAIL A
SCALE 0.160

2 STRETCHER ASSEMBLY

- SET TABLE UPRIGHT ON GLIDES
- SLIDE STRETCHER (A) DOWN ONTO SCREWS (B)
- ENGAGE BRACKETS ON STRETCHER TO SCREWS ON CROSS RAIL
- STRETCHER SHOULD END UP CENTERED ON CROSS RAIL (DETAIL B)



DETAIL B
SCALE 0.300