
Storm water standing and does not drain at end of Arbuton ave.



Debris and dirt blocking the drainage inlet for storm water to enter. The inlet needs to be cleaned