

Inspections: Damaged Pole Report

Service Request: 25-00695479 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: RACE St & W. Randall St

Grid : 3020140 LLC: 7027

Descriptive Location and Comments:

Street: RANDALL St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: RACE St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' ☒

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing ☒

Otterbein _____

Metal Halide ☒

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 ☒

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes _____
No ☒

Bolts
Wires
Conduit

☒
☒
☒

Metal ☒
Concrete _____

Date: 8 / 14 / 2025 Inspector's Signature: T. Blackman



25 Foot Aluminum
pole
Cobra Head
LED