

Waiting BGE System Down

Inspections: Damaged Pole Report

Service Request: 25-00692451 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 3503 Rosedale Rd
Grid : 1620 310 LLC: 7106

Descriptive Location and Comments:

Street: Rosedale Rd
Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O ☒ E/O _____ S/O _____ W/O _____
Street or Landmark: Dorchester Rd

Condition of Pole:

Deteriorated ☒

Missing _____

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No ☒

Base Condition:

Good

Bad:

Base Type:

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 8 / 22 / 2025 Inspector's Signature: G. Crowder 8512



3503 Rosedale Kd

Service Request Summary Report
25-00692451
Printed Date: Aug 22, 2025 - 2:02:48 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 25-00692451
Priority: Standard
Status: Pending
Status Date: Aug 22, 2025 10:56:32 AM
Created Date: Aug 12, 2025 11:41:54 PM
Overdue on: Oct 15, 2025 10:06:20 AM
Closed on:

Location: 3503 ROSEDALE RD, Baltimore City, 21215

Location Details:

Description: in 2023, every single light on the street was replaced with a sleek, modern stainless steel lamp post except 3503 Rosedale Road. This is an injustice that this is the only one that has not been corrected and updated. I demand this is done immediately. My mom, Victoria Merritt, the owner, is 93 years old and fights dementia. She deserves proper city maintenance. Thank you for your immediate attention.

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Brenda Merritt		bpmvision3ktam@gmail.com	+1 (443) 922-0742

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		8/22/2025 2:00 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020310
Assign inspector	LLC / POLE #	7106
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------