

Inspections: Damaged Pole Report

Service Request: 25-00728494 Sector: Gateway: Primary: Location on Service Request: 306 W. Bruce St Grid : 3010210 LLC: 7285

Descriptive Location and Comments:

Street: W. Bruce St

Side of Street: N/S E/S S/S W/S

Pole location: 1st 2nd 3rd 4th 5th 6th Other

Direction : N/O E/O S/O W/O

Street or Landmark: W. Sanatoga St

Condition of Pole: Pole Size : Type of Pole:

Deteriorated 11'6" Aluminum

Missing 12' Steel

Damaged 25' Galvanized Steel

Arm/Fixture Missing 30' Fiberglass

Other 40' Bolton Hill

Other Otterbein

Homeland

Wooden

Other

Need new base
Wood Street

Fixture Type: Lamp Type: Wattage: Arm: Arm Condition:

Cobra Head HPS Vapor 100 6' Damaged

PMA Mercury Vapor 150 10' Missing

Otterbein Metal Halide 175 15'

Homeland LED 200 20'

Bolton Hill Other 250 Other

Victorian Acorn 400


Other 1000

Pedestal Base: Base Condition: Good Bad: Base Type:

Yes Bolts V Metal V
No Wires V Concrete
Conduit V

Date: 8/27/2025 Inspector's Signature J. Gordon 8512

11/6 PM A (E9)



Service Request Summary Report
25-00728494
Printed Date: Aug 27, 2025 - 2:15:49 PM

Type: BGE-SL,Light Pole Installation

Created By: Robin Gilliam

Service Request Owner: BGE

Method Received: Phone

SLA Detail: 45 Business Days

SR #: 25-00728494

Priority: Urgent

Status: Pending

Status Date: Aug 27, 2025 2:14:26 PM

Created Date: Aug 25, 2025 6:59:08 AM

Overdue on: Oct 27, 2025 3:03:29 PM

Closed on:

Location: 306 N BRUCE ST, Baltimore City, 21223

Location Details:
Description:

Service Questions				
Questions		Answers		
Contact Information				
Name		Address	Email	Phones/Extensions
Ms Davis				+1 (443) 484-6601

Service Activities				
Activity Name	Status	Assigned To	Outcome	Outcome Reason
Assign inspector	Complete	Assigned		8/27/2025 2:14 PM
Service Response				
Not Started				

Resolution Questions		
Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010210
Assign inspector	LLC / POLE #	7285
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments			
Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder 8-27-25	Gregory Crowder	8/27/2025 2:15 PM	Private

Related Child Service Requests