Inspections: Damaged Pole Report

Service Request 25-00880198 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 742 S. Potomac St

Grid : 4010330 LLC: 7231

Descriptive Location and Comments:

Street: Fort Ave

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓


Street or Landmark: S. Potomac St

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ✓
Missing ✓	12' _____	Steel _____
Damaged _____	25' ✓	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ✓	HPS Vapor _____	100 _____	6' ✓	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing ✓
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ✓	200 _____	20' _____	
Bolton Hill _____	Other _____	250 ✓	Other _____	
Victorian Acorn _____		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts	✓	_____	Metal ✓
No ✓	Wires	✓	_____	Concrete _____
	Conduit	✓	_____	

Date: 10/14/2025 Inspector's Signature T. Blackmon



25 Foot
Aluminum
pole
Cobra Head
LED