Inspections Damaged Pole Report

Service Request 25-00900557 Sector ____ Gateway ____ Primary: ____

Location on Service Request: 3143 Dillon St

Grid : 4020310 LLC: 7049

Descriptive Location and Comments:

Street: Dillon St

Side of Street: N/S ✓ E/S ____ S/S ____ W/S ____

Pole location: 1st ✓ 2nd ____ 3rd ____ 4th ____ 5th ____ 6th ____ Other ____

Direction : N/O ____ E/O ____ S/O ____ W/O ✓


Street or Landmark: So. East St

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated ____	11'6" ____	Aluminum ✓
Missing ✓	12' ____	Steel ____
Damaged ____	25' ✓	Galvanized Steel ____
Arm/Fixture Missing ____	30' ____	Fiberglass ____
Other ____	40' ____	Bolton Hill ____
	Other ____	Otterbein ____
		Homeland ____
		Wooden ____
		Other ____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ✓	HPS Vapor ____	100 ____	6' ✓	Damaged ____
PMA ____	Mercury Vapor ____	150 ____	10' ____	Missing ✓
Otterbein ____	Metal Halide ____	175 ____	15' ____	
Homeland ____	LED ✓	200 ____	20' ____	
Bolton Hill ____	Other ____	250 ✓	Other ____	
Victorian Acorn ____		400 ____		
Other ____		1000 ____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ____	Bolts	✓	____	Metal ✓
No ✓	Wires	✓	____	Concrete ____
	Conduit	✓	____	

Date: 10/17/2025 Inspector's Signature T. Blackmon



25 Foot Aluminum Pole
Cobra Head
LED