The Best in Pests™



Prepared For

Catherine Medina

December 4, 2025

Charlie Peacher

Orkin Residential Services

Phone: (443) 567-2380

Email: Charles.Peacher@Orkin.com

This report is limited to a visual inspection of the structure. There may be hidden infestations and/or areas of access that are not evident from a visual inspection. The purpose of this report is to document areas of concern from the interior and exterior inspection. Specifically: 1.) visible evidence of pest infection or damage; 2.) visible conditions conducive to infestations; 3.) visible areas of potential pest access to the structure.

© 2026 Orkin, LLC

The Best in Pests

CUSTOMER INFORMATION

SERVICE INFORMATION

Catherine Medina

Customer Name

3225 Woodring Ave	Parkville	MD	21234
Address	City	State	Zip

Email

Home Phone Number	Business Phone Number	Extension

BILLING INFORMATION

		MD	
Billing Address	City	State	Zip

Notes

© 2026 Orkin, LLC

TREATMENT/INSPECTION REPORT

Graph Description: Main

Name Catherine Medina
Email
Treating Address 3225 Woodring Ave
City/State Parkville, MD Zip 21234
Home Phone
Business Phone
Inspected By Charlie Peacher


Pest Control ☑ Yes ☐ No Treatment Scheduled Date Date Inspected Dec 4, 2025

This report is limited to a visual inspection of the exposed structure. There may be hidden infestations and/or damage that are not evident from a visual inspection. The purpose of this treatment/inspection report is to document areas of concern from the interior and exterior inspection. Specifically: (1) Visible conditions conducive to infestation; (2) Visible evidence of infestation, damage or past infestations. This report is not valid for real estate transactions. This report DOES NOT INCLUDE MOLD or any mold-like conditions. Mold is generally not a wood destroying organism and is outside the scope of this report. If you wish your property to be inspected for mold or mold-like conditions, please contact the appropriate mold professional.

GRAPH KEY

Key indicated general area and is not precise. Insect evidence and conditions may be widespread.

Structure LF | Treatment LF 560 | Square F | 1 Block= 2 Feet



IMPORTANT: If visible evidence of active or previous infestation or damage is noted by the inspector during the inspection of your property, it should be evaluated by a licensed building contractor of customer's choice for damage. BECAUSE IT IS HIGHLY PROBABLE CUSTOMER COULD HAVE HIDDEN DAMAGE IN THE STRUCTURE. ORKIN IS NOT RESPONSIBLE FOR PRE-EXISTING DAMAGE. This treatment/inspection report is based on visible evidence of readily accessible areas and does not make any attempt to reveal damage which may be present. No attempt to remove insulation, carpeting, paneling, etc. to search for hidden damage was made. IF VISIBLE EVIDENCE OF ACTIVE OR PREVIOUS INFESTATION IS REPORTED, IT SHOULD BE ASSUMED THAT SOME DEGREE OF DAMAGE IS PRESENT. Placement of the bait stations is for the initial service and may change during future monitoring service (if applicable). This treatment/inspection report may be updated at the time of treatment reinspection.

© 2026 Orkin, LLC

The Best in Pests

MAP LEGEND

- Attic Access
- Door
- Gap
- Hedge
- Shrub
- Stairs
- Tree
- Vent Exists
- Window
- A — Active Infestation
- 40 — Foam treatment for wall voids
- 60 — Foam walls voids
- I — Install insulation
- 56 — Mask or caulk exit holes
- R — Remove Insulation
- 57 — Remove pellets
- 65 — Treat soffits
- Orkin Therm Attic

© 2026 Orkin, LLC

The Best in Pests

EXTERIOR–TREATMENT/INSPECTION REPORT

Graph Description: Main

Customer Name	Date
Catherine Medina	December 4, 2025

Address	City	State	Zip
3225 Woodring Ave	Parkville	MD	21234

FUMIGATION ONLY

Roof Type
Eave Height (ft) Square Feet
Peak Height (ft) Cubic Feet
Distance to Closest Building (ft)

MOISTURE READING % – BASEMENT/CRAWL

Left Front Right Rear
Right Front Ctr Front
Left Rear Ctr Back

1. TYPE FOUNDATION:

☐ Hollow Block ☐ Double Brick ☐ Triple Brick ☐ Foam (ICF) ☐ Wood
☐ Tile Block ☐ Hollow with Brick ☐ Solid Pour ☐ Stone ☐ Brick Veneer

2. TYPE CONSTRUCTION:

☐ Basement ☐ Supported Slab ☐ Monolithic Slab ☐ Combination ☐ Crawlspace
☐ Stem Wall ☐ Manufactured Home ☐ Floating Slab ☐ Piers Only

3. TYPE SIDING:

☐ Shingle ☐ Wood ☐ Vinyl ☐ Stucco on Block Pour ☐ Stucco on Frame or Wire Mesh
☐ Metal ☐ EIFS ☐ Brick Veneer ☐ Other

4. CLEARANCE FROM SOIL (IN INCHES):

Front Right Left Rear

☐ Yes ☑ No Well, cistern, pond, lake or spring located within 25 feet of the structure to be treated

If yes, indicate on this inspection/treatment report (graph) and follow the treatment protocol for well(s), cistern(s), lake(s) or spring(s) as detailed in the special treatment protocols section of the termite treatment expectations manual.

© 2026 Orkin, LLC

The Best in Pests

INTERIOR–TREATMENT/INSPECTION REPORT

Graph Description: Main

Customer Name	Date
Catherine Medina	December 4, 2025

Address	City	State	Zip
3225 Woodring Ave	Parkville	MD	21234

1. HEATING SYSTEM DESIGN:

☐ Plenum ☐ Sub-Slab Ducts ☐ Overhead ☐ Radiant ☐ Conventional

2. HVAC LOADED IN ATTIC:

☐ Yes ☐ No

3. IS THE ATTIC ACCESSIBLE:

☐ Yes ☐ No

4. INSULATION (IN APPROVED MARKETS)

	Attic	Crawl Space
Current R-value		
Type		
Additional Insulation Recommended	☐ Yes	☐ Yes

5. OTHER

☐ Recessed Lighting ☐ Soffit Venting ☐ Tube/Knob Wiring

☐ Exposed Exhaust Fan ☐ Whole House Fan ☐ Chimney or Flue ☐ Kneewall ☐ Open Area or Cavity

☐ Water Supply ☐ Sump Pump

☐ Powerbox

© 2026 Orkin, LLC

INSPECTION IMAGES– TREATMENT/INSPECTION REPORT

Graph Description: Main



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion



Attic / Exclusion

© 2026 Orkin, LLC

INSPECTION IMAGES– TREATMENT/INSPECTION REPORT

Graph Description: Main



Roof



Roof



Roof




Roof



Roof



Roof



Roof



Solution




Solution


© 2026 Orkin, LLC

INSPECTION IMAGES–TREATMENT/INSPECTION REPORT


Graph Description: Main




Solution



Solution



Solution



Solution



Solution

© 2026 Orkin, LLC

The Best in Pests™

ADDITIONAL SERVICES & MONEY BACK GUARANTEE

ADDITIONAL SERVICES

We would be happy to submit a proposal for any of the additional services below, upon your request.

- Termite Control
- Carpenter Ant Control
- Orkin Leaf Stopper®
- ComfortZone®
- OrkinTherm®
- Bed Bug Control
- Mosquito Control
- Wildlife Control
- DryZone®

A separate service agreement would be required for the above additional pests and services.

MONEY BACK GUARANTEE*

At Orkin, we customize every solution to meet the unique needs of your home, using scientifically backed methods. Your peace of mind is our priority, which is why we offer a 30-day money-back guarantee. If you're not completely satisfied, simply contact your local office in writing within 30 days of your initial treatment. We'll respond promptly to resolve your concerns. If we're unable to address the issue within 30 days of receiving your request, we'll refund your initial charge, including any prepaid renewals.

*See agreement for details, terms, and limitations.

© 2026 Orkin, LLC

The Best in Pests™

ORKIN: WHY CHOOSE US

Founded in 1901, Atlanta-based Orkin, LLC serves more than 1.7 million clients through more than 400 locations across the world. We'd like to put our century of pest research and real-world results to work for you. Our goal is to get to know your property inside and out in order to customize an Integrated Pest Management (IPM) program to fit the unique needs of your home – so you can breathe easier when it comes to pest control.



WHY CHOOSE ORKIN?

Our Orkin Pros have extensive experience and receive world-class training so they understand the unique challenges you face.

- **Expertly Trained** – Your Orkin Pro stays up to speed on the latest technology and treatments through rigorous training at the Rollins Learning Center.
- **Customized Solutions** – We design a program tailored to your specific needs and the specific condition of your property.
- **Our Service Philosophy** – Every treatment your Orkin Pro performs is held to the standards of the Orkin Points of Service to ensure you complete satisfaction.
- **Security** – Orkin is bonded, and our Orkin Pros are screened and randomly drug tested to allay security concerns.

ROLLINS ACCEPTANCE COMPANY

To help protect your home, Rollins Acceptance Company (A Division of Rollins, Inc.) is happy to service your loan for services rendered by Orkin.

BENEFITS

- Affordable monthly payments
- Immediate approval at your home
- 90-days-same-as-cash available upon approval
- 100% financing available upon approval

Some of these services are not eligible for financing, so ask your Orkin Pro for more details.

© 2026 Orkin, LLC