Inspections: Damaged Pole Report

Service Request: 26-00655226 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 602 S. East Ave

Grid : 4010330 LLC: 7123

Descriptive Location and Comments:

Street: East Ave

Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ✓ W/O _____

Street or Landmark: Fleet St

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Work order # 20467042

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 ✓
400 _____
1000 _____

Arm:

6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ✓

Pedestal Base:

Yes _____
No ✓


Base Condition:

	Good	Bad:
Bolts	✓	_____
Wires	✓	_____
Conduit	✓	_____

Base Type:

Metal ✓
Concrete _____

Date: 6/16/2026 Inspector's Signature T. Blackmon



25 Foot aluminum
Pole
cobra-Head
LED