Water/Driveway issues

Ticket # 26-00787864


Debbie Bittner
2208 Spring Lake Drive
Timonium, MD 21093
410-303-9638

8/21/26

Concern: Erosion under 2208 Spring Lake Drive driveway.


Situation: I believe there are water issues somewhere above 2208 which are creating issues for my driveway at 2208. The following set of pictures describes the issues. As you will see, I believe the water issues are flowing beneath the sidewalk and under my driveway causing erosion and ultimately cracking and repositioning my driveway & mailbox.

Picture 1. Overview of driveway issues.




Red arrows indicate cracks in driveway, curb & sidewalk.


Picture 2. This picture shows a concerning water issue. This area is **ALWAYS** wet – even hot, sunny, summer days. This area is in front of the neighbor, 2210 Spring Lake Drive.



Picture 3. Driveway at 2208.




Picture 4. Cracking along the curb. This chunk of curb is between the water mess and my driveway.




2


Picture 5. Erosion alongside of sidewalk This portion of the sidewalk is between the water mess and my driveway.



Picture 6. Erosion below my driveway. Causing a shift in my mailbox. It used to be perfectly straight.



Picture 7. Below the driveway. Further erosion issues.



Summary: There is something happening under the driveway, curb, and sidewalk at 2208 Spring Lake Drive. Seems like the source is up the hill. Perhaps the source is even further up the hill, but I can only point to the area that's obvious to my eye. Please review and let me know your thoughts.

Thank you for looking into this matter. I look forward to hearing from you.

Debbie Bittner