Inspections: Damaged Pole Report

Service Request: 26-00865842 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 5230 Harford Rd

Grid : 2040320 LLC: 7003

Descriptive Location and Comments:

Street: Harford Rd

Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓

Pole location: 1st _____ 2nd ✓ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ✓ W/O _____

Street or Landmark: Echodale Ave

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' _____
30' ✓
40' _____
Other _____

Work order # 2190163

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn ____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
250 _____
400 ✓
1000 _____
Other _____

Arm:


6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ✓

Pedestal Base:		Base Condition:	Good	Bad:	Base Type:	
Yes	_____	Bolts	✓	_____	Metal	_____
No	✓	Wires	✓	_____	Concrete	✓
		Conduit	✓	_____		

Date: 9-15-26 Inspector's Signature Tyrone Blackburn



30 Foot Aluminum Pole Cobra Head LED