Inspections: Damaged Pole Report

Service Request: 26-00863328 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 331 E. HAMBURG st

Grid : 4020110 LLC: 7038

Descriptive Location and Comments:

Street: HAMBURG st

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: Henry St

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

NEEDS New Base

Pole Size :

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
250 ✓
400 _____
1000 _____
Other _____

Arm:

6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ✓

Pedestal Base:

Yes _____
No _____


Base Condition: **Good** **Bad:**

Bolts _____ _____
Wires _____ _____
Conduit _____ _____

Base Type:

Metal _____
Concrete _____

Date: 9-17-26 Inspector's Signature: Byron Blackmon



25 Foot Aluminum
pole
Cobra Head
LED