



Service Request Summary

SERVICE REQUEST #:	515427	SERVICE DESCRIPTION:	Sink Hole
--------------------	--------	----------------------	-----------

Date:	10/15/2026 1:16:55 PM	Subdivision:	6
Initiated By:	Citysourced, Admin	Schedule:	646
Dispatched To:	Dorsey, Nyrah	District:	
Status:	COMPLETE	Supervisor:	Tormey, Joshua

Locate Information

Ticket No.:

Address:	6700 OLD PIMLICO RD
Location:	6700 OLD PIMLICO RD, PIKESVILLE, MD, 21209

Details:	Created By: Tori Sauter Description: Caller reports a hydrant has been leaking here and the city has done nothing for it. He knows its the City's responsibility but he would like the county to come out and investigate the roadway at this hydrant as it is sinking from all the water.
----------	---

CALLER INFORMATION

First Name:	PAUL	Email:	4104841664@CITYSOURCED.ORG
Last Name:	ABRAMS	Phone:	
Call Time:	10/15/2026 1:17:21 PM	Cell Phone:	4104841664
Caller Type:			

ADDITIONAL INFORMATION

Comments

Related Work Order No(s):

<u><u>Id:</u></u>	<u><u>Description</u></u>	<u><u>Status:</u></u>
1386182	Road-Road Inspections (2004)	WORK COMPLETE (READY FOR QA)



Service Request Summary

SERVICE REQUEST #: 515427

SERVICE DESCRIPTION: Sink Hole

10/15/2026 1:17:45 PM

Description: Caller reports a hydrant has been leaking here and the city has done nothing for it. He knows its the City's responsibility but he would like the county to come out and investigate the roadway at this hydrant as it is sinking from all the water.

OneView Id: 315009

Device Type: Console

Device Model: Unknown

Approximate Address: 6700 OLD PIMLICO RD, PIKESVILLE, MD, 21209

Lat/Lng Coordinates: 39.3752253, -76.677869

OriginationIpAddress: 172.71.194.245

OneViewIsRequestTypeIntegrated: True

OneViewDynamicsCreateJobCompleted: True

OneViewIntegrationId: 2

OneViewPostReport: SOAP Url=https://baltimorecountymd-oneview.rocksolid.com/XRMServices/2011/Organization.svc

OneViewTicketDisplay: CAS-4999334-R5F0H2

OneViewTicketId: 54ee6b3e-bcc8-f111-a8a9-000d3a0f8a39

10/16/2026 12:51:09 PM

the road is safe and this needs to be sent to city water for the hydrante leaking .