PANDUIT

CAGE NUT RAIL KIT FOR STRAIN RELIEF BARS*

Part Number(s): CNSRBKIT-C

INSTALLATION INSTRUCTIONS **V00029VV**

Required tools - not included

Phillips head driver

3/8" Hex driver

Required hardware - included

#12-24 nut

#12-24 x 1" screw

#12-24 cage nut

Step 1

1. Install cage nut in proper cage nut hole ensuring it aligns with the bottom mounting hole of the patch panel.
2. Align bottom mounting hole with cage nut and secure with enclosed #12-24 screw

#12-24 cage nut

#12-24 screw

Step 2

1. Slide strain relief bar (sold separately) on the end of the screw protruding behind the patch panel.
2. Use #12-24 hex nut to secure the strain relief bar in place by using a 3/8" Hex driver.

*For recommended strain relief bars, refer to the specification sheet at Panduit.com

#12-24 cage nut

Strain Relief bar

#12-24 nut

For Instructions in Local Languages and Technical Support:
www.panduit.com/resources/install_maintain.asp

PANDUIT
www.panduit.com

E-mail:
techsupport@panduit.com

Phone:
866-405-6654