




Modèle gauche



J530.. Paumelle bouts ronds

Code Sens gauche	Code Sens droite		Dim	Poids
J530050	J530040	Z.BLANC	80 x 40	0,077
J530090	J530080	Z.BLANC	80 x 45	0,080
J530170	J530160	Z.BLANC	95 x 45	0,088
J530230	J530220	Z.BLANC	110 x 50	0,130
J530330	J530300	Z.BLANC	110 x 55	0,133
J530410	J530380	Z.BLANC	110 x 60	0,144
J530470	J530460	Z.BLANC	110 x 70	0,156
J530570	J530540	Z.BLANC	140 x 55	0,164
J530670	J530640	Z.BLANC	140 x 60	0,205
J530760	J530740	Z.BLANC	140 x 70	0,210
J530820	J530800	Z.BLANC	140 x 80	0,212
J530910	J530900	Z.BLANC	160 x 60	0,253
J530930	J530920	Z.BLANC	160 x 80	0,233


J530.. Paumelle bouts carrés

Code Sens gauche	Code Sens droite		Dim	Poids
J530030	J530020	Z.BLANC	80 x 40	0,077
J530290	J530280	Z.BLANC	110 x 55	0,133
J530530	J530520	Z.BLANC	140 x 55	0,164
J530630	J530620	Z.BLANC	140 x 60	0,210
J530730	J530720	Z.BLANC	140 x 70	0,212

Code Sens gauche	Code Sens droite		Dim	Poids
J530070	J530060	Z.BLANC	80 x 45	0,080
J530150	J530140	Z.BLANC	95 x 45	0,088
J530210	J530200	Z.BLANC	110 x 50	0,130
J530370	J530360	Z.BLANC	110 x 60	0,144
J530890	J530880	Z.BLANC	160 x 60	0,233
J530931	J530921	Z.BLANC	160 x 80	0,283



Modèle gauche



Plans et dimensions : voir P.601
Graisser régulièrement les axes.
Visserie non fournie.