



XWR-3100

Release Firmware Version 6.4.2 - Recommended Update

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Enhancements:

- You will now have the ability to "Auto Add" an AP onto the network.
- A banner was also added to the UI showing you when the "Auto-Add" feature was successful.
- You will now be able to back up your router configuration and restore those configurations with or without the Domotz account information. This will allow you to "copy" a configuration from one router to another without causing a duplicate Domotz agent.

Release Firmware Version 6.3.1

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Issues Resolved:

- QoS fixes
- Security fixes for L2TP/IPsec
- Improvements to help text
- VLAN fixes
- Resolves Western Digital MyCloud NAS remote access

Release Firmware Version 6.0.0

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Enhancements:

- Added Router Limits functionality
- Updated UI functionality

Downloads

Current Version:

- [Firmware Version 6.4.2](#)

Previous Version:

- [Firmware Version 6.3.1](#)
- [Firmware Version 6.0.0](#)
- [Firmware Version 5.0.4.3](#)
- [Firmware Version 5.0.4](#)
- [Firmware Version 5.0.2](#)

Firmware Version 5.0.4.3

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Enhancements:

- Support for the XAP-810 and XAP-1440
- KRACK vulnerability patch

Issues Resolved:

- None

Known Issues:

- None

Firmware Version 5.0.4

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Enhancements:

- Firmware support for EU, UK, and AU geographic regions

Issues Resolved:

- A scroll bar was added to Static Leases allowing users to see all saved static lease entries.
- Port Forwarding Table adjusted for better information display and user experience.
- VPN Password Special Characters full list now works as described in the online help message.
- USB Password Special Characters now works as described in the online help message.
- Minor UI adjustments and online Help updates.

Known Issues:

- After initial configuration of USB > Media Server Name, if you then change that name, a router reboot will be required for DLNA clients to see the new name.

Firmware Version 5.0.2 (Release Version of Firmware)

Note: It is NOT recommended to update the firmware wirelessly as damage to the router may occur.

Enhancements:

- None

Issues Resolved:

- None

Known Issues:

- The Characters ^ { } cannot be used in VPN User Password
- Auto Update page shows connected when it has no Internet connection

Copyright and Trademark Notices

No part of this document may be modified or adapted in any way, for any purposes without permission in writing from Luxul. The material in this document is subject to change without notice. Luxul reserves the right to make changes to any product to improve reliability, function, or design. No license is granted, either expressly or by implication or otherwise under any Luxul intellectual property rights. An implied license only exists for equipment, circuits and subsystems contained in this or any Luxul product.

© Copyright 2020 Legrand AV Inc. All rights reserved. The name Luxul, the Luxul logo, the Luxul logo mark and Simply Connected are all trademarks and or registered trademarks of Legrand AV Inc.

All other trademarks and registered trademarks are property of their respective holders.