

Inspections: Damaged Pole Report

Service Request: 25-00392619 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1600 N. Caroline St

Grid : 2010120 LLC: 7463

Descriptive Location and Comments:

Street: Caroline St

Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ✓ E/O _____ S/O _____ W/O _____

Street or Landmark: Frederick St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ✓

11'6" _____

Aluminum ✓

Missing ✓

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ✓

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ✓

HPS Vapor _____

100 _____

6' ✓

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing ✓

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ✓

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ✓

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ✓
No _____

Bolts ✓
Wires ✓
Conduit ✓

Metal ✓
Concrete _____

Date: 5/13/2025 Inspector's Signature: T. Blackman



30 Foot Aluminum pole
Cobra Head
LED