

Inspections: Damaged Pole Report

Service Request: 25-00237472 Sector: 2 Gateway: _____ Primary: _____
 Location on Service Request: 1000 Druid Hill Ave Side
 Grid : 1010130 LLC: 7432

Descriptive Location and Comments:

Street: W. Preston St
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: Druid Hill Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 3/25/2025 Inspector's Signature: G. Crowder 8512

1600 Druid Hill Ave (side of lot)



25 ft CH LED 400 Watt

Service Request Summary Report

25-00237472

Printed Date: Mar 25, 2025 - 2:52:08 PM

Type: BGE-StLight Pole Installation
 Created By: Jasmine Hyman
 Service Request Owner: BGE
 Method Received: Internal
 SLA Detail: 45 Business Days

SR #: 25-00237472
 Priority: Standard
 Status: Pending
 Status Date: Mar 25, 2025 2:50:33 PM
 Created Date: Mar 20, 2025 2:39:13 PM
 Overdue on: May 26, 2025 2:57:28 PM
 Closed on:

Location: 1000 DRUID HILL AVE, Baltimore City,
 21201

Location Details:

Description: base is sticking out of the sidewalk causing a tripping hazard

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Deborah Pittman		deborah.pittman@habc.org	

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/25/2025 2:50 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010130
Assign inspector	LLC / POLE #	7432
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------