

Inspections: Damaged Pole Report

Service Request: 26-00054236 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2810 W. Franklin St

Grid : 3010310 LLC: 7210

Descriptive Location and Comments:

Street: Franklin St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____


Street or Landmark: Lametta Ave

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts ☒	_____	Metal ☒	
No ☒	Wires ☒	_____	Concrete ☒	
	Conduit ☒	_____		

Date: 1/21/2026 Inspector's Signature: G. Crowder 8512



30-4 CH LED

Service Request Summary Report
26-00054236
Printed Date: Jan 21, 2026 - 2:32:32 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00054236
Priority: Standard
Status: Pending
Status Date: Jan 21, 2026 2:29:26 PM
Created Date: Jan 21, 2026 2:28:57 PM
Overdue on: Mar 25, 2026 3:28:57 PM
Closed on:

Location: 2810 W FRANKLIN ST, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		1/21/2026 2:30 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010310
Assign inspector	LLC / POLE #	7210
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder 1-21-26	Gregory Crowder	1/21/2026 2:32 PM	Private