

Waiting 4 work order

Inspections: Damaged Pole Report

Service Request: 26-06272688 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 301 W. Madison St

Grid: 1010140 LLC: 5062

Descriptive Location and Comments:

Street: W. Madison St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: N. Howard St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size:

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 ☒

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good ☒
Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 3/25/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
26-00272688
Printed Date: Mar 26, 2026 - 8:01:35 AM

Type: BGE-StLight Pole Installation
Created By: Delphine Smith
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00272688
Priority: Urgent
Status: Pending
Status Date: Mar 26, 2026 7:59:14 AM
Created Date: Mar 23, 2026 11:57:18 AM
Overdue on: May 26, 2026 3:51:07 PM
Closed on:

Location: 301 W MADISON ST, Baltimore City,
21201
Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Ricard Conway			+1 (443) 915-5775

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/26/2026 7:59 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010140
Assign inspector	LLC / POLE #	5062
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Acom
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-3-25-26	Gregory Crowder	3/26/2026 8:01 AM	Private

