

Inspections: Damaged Pole Report

Service Request 26-00526886 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3006 O'donnell St

Grid : 4020310 LLC: 7317

Descriptive Location and Comments:

Street: O'donnell St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: S. Potomac St

Condition of Pole:

Deteriorated ☐

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other ☐

Pole Size :

11'6" ☐

12' ☐

25' ☒

30' ☐

40' ☐

Other ☐

Type of Pole:

Aluminum ☒

Steel ☐

Galvanized Steel ☐

Fiberglass ☐

Bolton Hill ☐

Otterbein ☐

Homeland ☐

Wooden ☐

Other ☐

Fixture Type:

Cobra Head ☒

PMA ☐

Otterbein ☐

Homeland ☐

Bolton Hill ☐

Victorian Acorn ☐

Other ☐

Lamp Type:

HPS Vapor ☐

Mercury Vapor ☐

Metal Halide ☐

LED ☒

Other ☐

Wattage:

100 ☐

150 ☐

175 ☐

200 ☐

250 ☒

400 ☐

1000 ☐

Arm:

6' ☒

10' ☐

15' ☐

20' ☐

Other ☐

Arm Condition:

Damaged ☐

Missing ☒

Pedestal Base:

Yes ☐
No ☒

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good

☒
☒
☒

Bad:

☐
☐
☐

Base Type:

Metal ☒
Concrete ☐

Date: 6/10/2026 Inspector's Signature: T. Blackman

NEEDS
New
Base

