

2009 LINKBELT RTC8050 SERIES 2
50 TON ROUGH TERRAIN CRANE
S/N J6J91513
110' + 51' JIB
BLOCK & BALL
GREER LMI SYSTEM
4X4X4 DRIVE/STEER
CATERPILLAR ENGINE
POWER SHIFT TRANSMISSION

RECENTLY PERFORMED MAINTENANCE (April, 2023): \$71,000 Value in Service & Parts

- Hoist Brake
 - o Rebuilt all clutches
 - o Rebuilt all stators
 - o Replaced all seals
 - o Replaced all O-rings
 - o Fluid change
- Outrigger Beams & Jack Cylinders
 - o All Outrigger Cylinder assemblies removed from beams
 - Full rebuild on all cylinders, glands, & pistons
 - Cylinders cleaned with new O-rings
 - o All new Jack Cylinders
- Steering Orbital
 - o New unit and new O-rings
- Parking Brake
 - o Rebuilt brake assembly
 - New piston
 - New slide ring
 - New spring
 - New lining and carrier assembly
- Rear Axle Oscillation Cylinders
 - o Complete tear down and rebuild
- Telescope Cylinder
 - o O-rings and seals replaced
- 1000hr Service (Manufacturer Standards)
 - o New fuel filter
 - o New element upper A/C
 - o New trans. filter
 - o New primary fuel element
 - o New oil element
 - o New secondary fuel element
 - o New Hydraulic filter