



ITEM	DESCRIPTION	1117L
1	STRAINER, WASTE ASSY	6462
2	BUTTON, PUSH, FLANGED, PCP W/ VALVE	5874PBF
3	VALVE REPAIR KIT	VRK5874
4	PUSH BUTTON ASSY	PBA6
5	BUBBLER HEAD ASSY, PCP	5703M
6	PLATE, BOTTOM	PBM1107
7	PLATE, MOUNTING	6717
8	TRAP	0005982900
9	PANEL, BACK, SMALL, 1117L	0004023567
10	PANEL, BACK	0004023590

NOTES:


- 1 5874PBF (ITEM 2) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 3) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.



- 2 REMOVE INSERT WITH 5/16 HEX SOCKET (NOT SUPPLIED)




DETAIL A
ROTATED 90° INTO VIEW



PARTS BREAKDOWN

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

		Haws®		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
ECN NO.	REVISED PER	BY	MODEL(S)		PART NUMBER
ECN: 5124	DATE	CHKD			0002080223
DRAWN	DATE	CHKD	1117L		REVISION
C.FENNER	10/28/06	VWC			14
APPROVED	DATE	SCALE: 1:1	DRAWING TYPE:	PARTS BREAKDOWN	SHEET 1 OF 1
FV	07/06/17				