

Height Adjust Table Hanging Ped

Tools Required

- Tape Measure
- Cordless Drill
- #2 Phillips Tip

Hardware Required

- #8 x 5/8" pan head Phillips (qty 6)

Installation

1. Place height adjust table upside down on clean soft surface.
2. Locate hanging ped so that it is 4" off of the leg column and parallel to front edge of surface.
3. Attach ped with #8 x 5/8" pan head Phillips screws. Two in each side and two in the back.

Figure A




Figure B




Figure C

