



---

# Energy Performance Certificate

---

The Former BHL Unit  
Parkside Industrial Estate  
Middleton Grove  
LEEDS  
LS11 5BX

---

---

## Index

### **Section**

**1** - Executive Summary

**2** - Address Details

**3** - Accredited Assessor Details

### **Appendices**

**A** - Energy Performance Certificate

**B** - Recommendation Report

## **1. Executive Summary**

Our Assessor completed a survey of the Former BHL Unit, Middleton Grove, Leeds on 1st February 2011.

The survey related to establishing the details of the fixed internal building services, building fabric and geometrical data.

The information gathered by the surveying team has since been processed using CLG Accredited software, by one of our Accredited Energy Assessors, in order to produce the required Energy Performance Certificate (EPC) and Recommendation Report (RR).

Both the EPC and RR are appended below.

The EPC and Recommendation Report were lodged onto the Landmark Register on 08 February 2011.

The unique Report Reference Numbers (RRN) for each of the documents are as follows;

EPC: 0020-6928-0399-8340-3014

RR: 9681-4042-0299-0300-3805

## **2. Address Details**

The following address is taken from the CLG approved Landmark register and is shown in the approved format along with the Unique Property Reference Number (UPRN);

UPRN: 619283480000

LINE 1: The Former BHL Unit

LINE 2: Parkside Industrial Estate

LINE 3: Middleton Grove

LINE 4:

CITY: LEEDS

POSTCODE: LS11 5BX

### **3. Assessor Details**

The Energy Assessment was undertaken by Firefly Risk Solutions Ltd. The following information relates to the Energy Assessor that completed and subsequently lodged the EPC onto the Landmark Register;

Assessor Name: Jonathan Parkes

Assessor Number: EES/005659

Accreditation Scheme: Elmhurst Energy Systems Ltd

## **Appendix A**

EPC Certificate

# Energy Performance Certificate

## Non-Domestic Building



The Former BHL Unit  
Parkside Industrial Estate  
Middleton Grove  
LEEDS  
LS11 5BX

Certificate Reference Number:  
0020-6928-0399-8340-3014

This certificate shows the energy rating of this building. It indicates the energy efficiency of the building fabric and the heating, ventilation, cooling and lighting systems. The rating is compared to two benchmarks for this type of building: one appropriate for new buildings and one appropriate for existing buildings. There is more advice on how to interpret this information on the Government's website [www.communities.gov.uk/epbd](http://www.communities.gov.uk/epbd).

### Energy Performance Asset Rating

More energy efficient

A+

Net zero CO<sub>2</sub> emissions

A 0-25

B 26-50

C 51-75

D 76-100

79

This is how energy efficient the building is.

E 101-125

F 126-150

G Over 150

Less energy efficient

### Technical information

Main heating fuel:	Natural Gas
Building environment:	Air Conditioning
Total useful floor area (m <sup>2</sup> ):	3504
Building complexity (NOS level):	3
Building emission rate (kgCO <sub>2</sub> /m <sup>2</sup> ):	30.49

### Benchmarks

Buildings similar to this one could have ratings as follows:

52 If newly built

112 If typical of the existing stock

## Administrative information

This is an Energy Performance Certificate as defined in SI2007:991 as amended

<b>Assessment Software:</b>	Lifespan SBEM v3.5.b using calculation engine SBEM v3.5.b.0
<b>Property Reference:</b>	619283480000
<b>Assessor Name:</b>	Jonathan Parkes
<b>Assessor Number:</b>	EES/005659
<b>Accreditation Scheme:</b>	Elmhurst Energy Systems Ltd
<b>Employer/Trading Name:</b>	Midland Assess Energy Ltd
<b>Employer/Trading Address:</b>	68 Jesson Road, Highgate, Walsall, West Midlands, WS1 3AX
<b>Issue Date:</b>	08 Feb 2011
<b>Valid Until:</b>	07 Feb 2021 (unless superseded by a later certificate)
<b>Related Party Disclosure:</b>	Not related to the owner
<b>Recommendations for improving the property are contained in Report Reference Number: 9681-4042-0299-0300-3805</b>	

## If you have a complaint or wish to confirm that the certificate is genuine

Details of the assessor and the relevant accreditation scheme are on the certificate. You can get contact details of the accreditation scheme from the Government's website at [www.communities.gov.uk/epbd](http://www.communities.gov.uk/epbd), together with details of the procedures for confirming authenticity of a certificate and for making a complaint.



For advice on how to take action and to find out about technical and financial assistance schemes to help make buildings more energy efficient visit [www.carbontrust.co.uk](http://www.carbontrust.co.uk) or call us on **0800 085 2005**



## **Appendix B**

### Recommendation Report

# Recommendation Report



**Report Reference Number: 9681-4042-0299-0300-3805**

The Former BHL Unit  
 Parkside Industrial Estate  
 Middleton Grove  
 LEEDS  
 LS11 5BX

Building Type(s): Warehouse and storage

<b>ADMINISTRATIVE INFORMATION</b>	
Issue Date:	08 Feb 2011
Valid Until:	07 Feb 2021 (*)
Total Useful Floor Area (m <sup>2</sup> ):	3504
Calculation Tool Used:	Lifespan SBEM v3.5.b using calculation engine SBEM v3.5.b.0
Property Reference:	619283480000
Energy Performance Certificate for the property is contained in Report Reference Number: 0020-6928-0399-8340-3014	

<b>ENERGY ASSESSOR DETAILS</b>	
Assessor Name:	Jonathan Parkes
Employer/Trading Name:	Midland Assess Energy Ltd
Employer/Trading Address:	68 Jesson Road, Highgate, Walsall, West Midlands, WS1 3AX
Assessor Number:	EES/005659
Accreditation scheme:	Elmhurst Energy Systems Ltd
Related Party Disclosure:	Not related to the owner

# Table of Contents

- 1. Background..... 3
- 2. Introduction..... 3
- 3. Recommendations..... 4
- 4. Next Steps..... 6
- 5. Glossary..... 8

## 1. Background

Statutory Instrument 2007 No. 991, *The Energy Performance of Buildings (Certificates and Inspections) (England and Wales) Regulations 2007*, as amended, transposes the requirements of Articles 7.2 and 7.3 of the Energy Performance of Buildings Directive 2002/91/EC.

This report is a Recommendation Report as required under regulations 16(2)(a) and 19 of the Statutory Instrument SI 2007:991.

This section provides general information regarding the building:

Total Useful Floor Area (m <sup>2</sup> ):	3504
Building Environment:	Air Conditioning

## 2. Introduction

This Recommendation Report was produced in line with the Government's approved methodology and is based on calculation tool Lifespan SBEM v3.5.b using calculation engine SBEM v3.5.b.0 .

In accordance with Government's current guidance, the Energy Assessor did undertake a walk around survey of the building prior to producing this Recommendation Report.

### 3. Recommendations

The following sections list recommendations selected by the energy assessor for the improvement of the energy performance of the building. The recommendations are listed under four headings: short payback, medium payback, long payback, and other measures.

#### ***a) Recommendations with a short payback***

This section lists recommendations with a payback of less than 3 years:

<b>Recommendation</b>	<b>Potential impact</b>
Consider replacing T8 lamps with retrofit T5 conversion kit.	MEDIUM
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	LOW

#### ***b) Recommendations with a medium payback***

This section lists recommendations with a payback of between 3 and 7 years:

No recommendations of medium term payback have been identified

#### ***c) Recommendations with a long payback***

This section lists recommendations with a payback of more than 7 years:

<b>Recommendation</b>	<b>Potential impact</b>
Consider installing building mounted wind turbine(s).	LOW
The default chiller efficiency is chosen. It is recommended that the chiller system be investigated to gain an understanding of its efficiency and possible improvements.	LOW
Consider installing solar water heating.	LOW
Consider installing PV.	LOW
Consider replacing heating boiler plant with a condensing type.	MEDIUM

***d) Other recommendations***

This section lists other recommendations selected by the energy assessor, based on an understanding of the building, and / or based on a valid existing energy report.

No recommendations defined by the energy assessor have been identified

## 4. Next steps

### ***a) Your Recommendation Report***

As the building occupier, regulation 10(1) of SI 2007:991 requires that an Energy Performance Certificate "*must be accompanied by a recommendation report*".

You must be able to produce a copy of this Recommendation Report within seven days if requested by an Enforcement Authority under regulation 39 of SI 2007:991.

This Recommendation Report has also been lodged on the Government's central register. Access to the report, to the data used to compile the report, and to previous similar documents relating to the same building can be obtained by request through the Non-Dwellings Register ([www.epcregister.com](http://www.epcregister.com)) using the report reference number of this document.

### ***b) Implementing recommendations***

The recommendations are provided as an indication of opportunities that appear to exist to improve the building's energy efficiency.

The calculation tool has automatically produced a set of recommendations, which the Energy Assessor has reviewed in the light of his / her knowledge of the building and its use. The Energy Assessor may have comments on the recommendations based on his / her knowledge of the building and its use. The Energy Assessor may have inserted additional measures in section 3d (Other Recommendations). He / she may have removed some automatically generated recommendations or added additional recommendations.

These recommendations do not include matters relating to operation and maintenance which cannot be identified from the calculation procedure.

***c) Legal disclaimer***

The advice provided in this Recommendation Report is intended to be for information only. Recipients of this Recommendation Report are advised to seek further detailed professional advice before reaching any decision on how to improve the energy performance of the building.

***d) Complaints***

Details of the assessor and the relevant accreditation scheme are on this report and the energy performance certificate. You can get contact details of the accreditation scheme from our website at [www.communities.gov.uk/epbd](http://www.communities.gov.uk/epbd), together with details of their procedures for confirming authenticity of a certificate and for making a complaint.



## 5. Glossary

### **a) Payback**

The payback periods are based on data provided by Good Practice Guides and Carbon Trust energy survey reports and are average figures calculated using a simple payback method. It is assumed that the source data is correct and accurate using up to date information.

The figures have been calculated as an average across a range of buildings and may differ from the actual payback period for the building being assessed. Therefore, it is recommended that each suggested measure be further investigated before reaching any decision on how to improve the energy efficiency of the building.

### **b) Carbon impact**

The High / Medium / Low carbon impact indicators against each recommendation are provided to distinguish, between the suggested recommendations, those that would have most impact on carbon emissions from the building. For automatically generated recommendations, the carbon impact indicators are determined by software, but may have been adjusted by the Energy Assessor based on his / her knowledge of the building. The impact of other recommendations are determined by the assessor.

### **c) Valid report**

A valid report is a report that has been:

- Produced within the past 10 years
- Produced by an Energy Assessor who is accredited to produce Recommendation Reports through a Government Approved Accreditation Scheme
- Lodged on the Register operated by or on behalf of the Secretary of State.