

1 Battery contents

The battery delivery contains all required components. However, there are a few **important points of attention** for the installer.

1.1 General inspection

All components are present in the packaging.

Please note: **the power cable is not yet complete**

1.2 Power cable (inverter ↔ battery)

Battery side: fitted with a plug.

Inverter side: M8 cable lug (not supplied with the first shipment)

1.3 Issue with first deliveries

The cable lugs on the inverter side are missing from the first shipments.


As a result, the cable cannot be used directly without modification.

1.4 Action for installers

Installers must fit the cable lugs to the cable themselves.

Required specification: M8 cable lugs.

These must be provided by the installer.



2 Software

In addition to the hardware, there are also important points of attention regarding the software of the inverters.

<p>S6 inverters</p>	<p>All S6 inverters shipped before May 2026 require a software update. The update can be carried out by the installer or via Solis Service. Netherlands: +31 850 48 13 00 France: +33 9 71 07 87 36</p>
<p>S5 inverters</p>	<p>The correct software is currently not yet available and is expected after 30 July 2026. Installers are advised to postpone the installation until the software is available.</p>