

Assembly Instructions

Xtra Long Presentation Cart

Part	Drawing I	Description (Qty	Part	Drawi	ng Description	Qty
P1		Leg Assembly Right	1 EA	P-9		Right Shelf Brack	et 1 EA
P2		Leg Assembly Left	1 EA	P-1	0	Left Shelf Bracket Hardware List	1 EA
P3		LCD Platform	1 EA	А		9/16"Socket Screw	22 EA
P4		Laptop Shelf	1 EA	В		2-1/2" Socket Screw	6 EA
P5		Lower Shelf	1 EA	C D-1		Square Nut 3" Locking Caster	4 EA 2 EA
P6		Middle Shelf	1 EA	D-2		3" Caster	2 EA
P7		Stability Panel	1 EA	E		Plastic Grommet	2 EA
P8		Angle Bracket	4 EA	F G		Allen Wrench Caster Wrench	1 EA 1 EA
Miss	sing Parts or UI For Your Conve EMAIL furniture @k 24HOURS 7 D	us at Saltinc.com	5	We recommend that you assemble this unit on a table. Tools required: Adjustable Crescent Wrench			


Do not use unless all screws are tight. At least every six months, check all screws to be sure they are tight. If parts are missing, broken, damaged, or worn, stop use of the product until repairs are made by your dealer using factory authorized parts.


#27521 Assembly Diagram

READ THROUGH INSTRUCTIONS FROM BEGINNING TO END <u>BEFORE</u> STARTING TO ASSEMBLE UNIT.

- 1.) Identify and Separate all the Parts and Hardware.
- 2.) Place the LCD Platform (P-3) with the insert nuts facing up. Attach 1 Right Leg Assembly (P-1) and 1 Left Leg Assembly (P-2) using 4 each (A) screws. (Finger tighten only)

Should you require assistance during assembly, please call our Customer Service Department Monday - Friday 8 a.m. - 5 p.m. Central Standard Time 1-800-749-2258 3.) Attach Stability Panel (P-7) to Right & Left Leg Assemblies (P-1 & P-2) using 4 (A) Screws as shown in illustration #1. (Finger tighten only)








6.) Attach Lower Shelf (P-5) to the Right & Left Leg Assemblies (P1 & P2) using 4 each (B) screws as shown in illustration # 4.


(Finger tighten only)



7.) Attach 2 Locking Casters (D-1) to the front of the unit. Attach 2 Casters (D-2) to the back of the unit. Tighten all Casters using Caster Wrench (G).

- 8.) Slide Middle Shelf (P-6) Between Right & Left Leg Assemblies (P-1 & P-2) and attach Middle Shelf (P-6) using 4 each (A) screws and 4 each (C) Square Nuts as shown in illustration # 4. Secure Middle Shelf (P-6) to Stability Panel (P-7) using two screws (A).
- 9.) (Tighten all the screws at this time using Allen Wrench (F)).

10.) To install Grommets (E) in LCD Platform (P-3) and Middle Shelf (P-6), separate parts and press Grommet Sleeve in rectangular openings as shown in illustration # 5.



The Balt product you have purchased is guaranteed against material and workmanship defects. This guarantee extends 1 year from date of purchase. Should this product fail to function satisfactorily under normal use due to defect or imperfection, the defective part or product will be replaced. Damage caused by common carriers during shipment is not included in this guarantee.

This guarantee sets forth all applicable guarantees and remedies. No other warranty, expressed or implied shall apply. Failure to follow instructions found in Important Information Section of Owner Sheet shall void the guarantee. Consequential or incidental damages and or costs are not refundable.

6 27521-02/24/10

#66450 4 Outlet Electrical Assembly Diagram


This 4 Outlet Electrical is Part # 66450 and must be purchased separately. Please contact our Customer Service Department Monday - Friday 8 a.m. - 5 p.m. Central Standard Time 1-800-749-2258 Parts/Hardware List

EL-1 Electric Outlet 1 EA

EL-2 Metal Bracket w/Cord Winder 1 EA

EL-3 Phillips Head Screw 2 EA

EL-4 Hex Nut 2 EA



#66572 7 Outlet Electrical Assembly Diagram

This 7 Outlet electrical is Part # 66572 and must be purchased separately. Please contact our Customer Service Department Monday - Friday 8 a.m. - 5 p.m. Central Standard Time 1-800-749-2258 Parts/Hardware List

7 Outlet Electrical 1 EA

EL-2 Metal Bracket w/Cord Winder 1 EA

EL-3 Phillips Head Screw 2 EA

EL-4 Hex Nut 2 EA

1.)Identify and Separate all the Parts and Hardware.

2.) Slide Metal Bracket over the Electrical Outlet (EL-1) as shown. (note that Metal Stop is at the end with the electrical Plug-in.)

3.)Attach Metal Bracket (EL-2) to the Right or Left Leg Assembly (P-1 or P-2) using 2 Phillips Head Screws (EL-3) and 2 Hex Nuts (EL-4) as shown in Optional Electrical illustration.

Metal Stop

Optional Electrical Illustration



205 Westwood Ave, Long Branch, NJ 07740 Phone: 866-94 BOARDS (26273) / (732)-222-1511 Fax: (732)-222-7088 | E-mail: sales@touchboards.com

