

# JBC

www.jbctools.com

## Cable collector

Ref. CC1001

### Assembly for AD, HD, DN, PA, HT and AP stands



Recommended cable length 50 cm.  
(From cable collector to the end of the tool)

Place the cable and slide the black piece upwards to hold it.



### Assembly for DR and DS stands



Recommended cable length 50 cm.  
(From cable collector to the end of the tool)

Use the flange to adapt both cables.

**Flange**  
Ref. 0024028



### Assembly for COMPACT line

Recommended cable length 50 cm.  
(From cable collector to the end of the tool)



Turn the knob to hold the cable collector to the desired position.

