




## Unbalanced Zone Temperature Verification

Comfort at work is an important concern whether you work in an office or factory. A suitable physical climate is needed in order to feel comfortable and to maintain productivity at work.

In office environments the preferred temperature is approximately 20 to 24°C (68 to 75°F). In the winter when heavy clothing is being worn, a comfortable temperature is 20 to 22°C (68 to 72°F). Factory workers often prefer cooler conditions than office workers because their tasks are more physical and may require protective clothing.



### Challenge:

#### Are you faced with?

- Proving to Staff, Management or the Technician that the adverse temperature condition does exist
- Validating the corrective action taken to remedy the situation
- Ongoing validation so that the conditions remain adequate

### Solution:

- Acquire an ACR JR-1000 Temperature Data Logger
- Position one or more JR-1000 Data Loggers in the areas of concern
- Compare the logged temperature data to the complaint/standards
- Utilize the ongoing data collection to prove the situation has been rectified

**T**equipment  
.NET




205 Westwood Ave  
Long Branch, NJ 07740  
1-877-742-TEST (8378)  
Fax: (732) 222-7088  
salesteam@Tequipment.NET



## Obtaining proof of temperature over time is as easy as 1, 2, 3

1. Simply place the ACR JR-1000 data logger in the area you want to monitor. No set-up is required.
2. After a few weeks, connect the logger to your PC or laptop.
3. Insert the software CD into the CD ROM drive of your computer and download the information collected by the data logger.



## Ordering Info:

### Recommended Product

Equipment	Description	Catalog #
JR-1000	Single channel temperature data logger	01-0192
USB Adapter Cable	USB to 9-pin RS-232 Serial Adapter Cable	01-0080

### Optional Product

Equipment	Description	Catalog #
SmartReader 1	2 channel, temperature data logger	01-0024
SmartReader Plus 1	2 channel, temperature data logger	01-0008

**T**equipment  
**.NET**



205 Westwood Ave  
 Long Branch, NJ 07740  
 1-877-742-TEST (8378)  
 Fax: (732) 222-7088  
 salesteam@Tequipment.NET

